CAMP Aviation from the ground up

Status Report

FALCON 2000EX EASY
S/N 112 N619SM

OWNER:	DEUX AVIAN PARTNERS LLC	**OPERATOR:**	CORTLAND DEVELOPMENT
ADDRESS:	3424 PEACHTREE RD NE STE 300 ATLANTA GA 30326-2818	**ADDRESS:**	2021 FLIGHTWAY DR. CHAMBLEE GA 30341
PHONE:		**PHONE:**	470-548-6081
FAX:		**FAX:**	

ANALYST:	WALTER GLENN	877-411-CAMP (2267) (OFFICE)	800-787-9749 (EFAX-CARDS)	PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.
EMAIL:	WGLENN@CAMPSYSTEMS.COM	631-588-3200 (OFFICE) WWW.CAMPSYSTEMS.COM	631-980-4222 (FAX)	

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT **SERIAL/REGNO:** 112/N619SM **MODEL:** FALCON 2000EX EASY **MANUFACTURER:** DASSAULT AVIATION S.A.

DATES	LAST ACTUALS			CURRENT ACTUAL		
CERTIFICATION DATE: 13-DEC-2006 INSERVICE DATE: 04-MAY-2007	3041.8	A/C HRS	as of 25-MAY-2018	_____	A/C HRS	as of ___/___/_____
	2328	AFL	as of 25-MAY-2018	_____	AFL	as of ___/___/_____
	1042	APH	as of 21-MAY-2018	_____	APH	as of ___/___/_____
	2865	APS	as of 21-MAY-2018	_____	APS	as of ___/___/_____

APU **SERIAL/PART:** P-469/3800548-2 **MODEL:** GTCP36-150(F2M) **MANUFACTURER:** HONEYWELL

INSTALLED ON 31-AUG-2006		LAST ACTUALS			CURRENT ACTUAL		
0	APU HRS	1042	APU HRS	as of 21-MAY-2018	_____	APU HRS	as of ___/___/_____
0	APUS	2865	APUS	as of 21-MAY-2018	_____	APUS	as of ___/___/_____

ENGINE NO. 1 **SERIAL/PART:** PCE-CF0251/30C3205-02 BS 1047 **MODEL:** PW308C **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 10-MAY-2018			LAST ACTUALS			CURRENT ACTUAL		
2947.9	ENG. HRS	3041.8 A/C HRS	2960.5	ENG. HRS	as of 25-MAY-2018	_____	ENG. HRS	as of ___/___/_____
2266	ENC		2266	ENC	as of 25-MAY-2018	_____	ENC	as of ___/___/_____

ENGINE NO. 2 **SERIAL/PART:** PCE-CF0250/30C3205-02 BS 1047 **MODEL:** PW308C **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 01-NOV-2017			LAST ACTUALS			CURRENT ACTUAL		
2832.2	ENG. HRS	2933.3 A/C HRS	2960.5	ENG. HRS	as of 25-MAY-2018	_____	ENG. HRS	as of ___/___/_____
2192	ENC		2266	ENC	as of 25-MAY-2018	_____	ENC	as of ___/___/_____

DASSAULT AND FALCON ARE TRADEMARKS OF DASSAULT AVIATION

© CAMP SYSTEMS

CAMP "Aviation from the ground up"

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL		ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	**TIME LIMITS/MAINTENANCE CHECKS**								
+ 05-08-00-200-800-01	1A INSPECTION								
	PKG 1 in PKG 2 ,31	MOS	8	+1m	-83		18-MAY-2018	**24-OCT-2018**	24-NOV-2018
		HRS/MSC	400	+40			3041.8	**3441.8**	3481.8
	REF:	AFL					2328		
+ 05-08-00-200-800-02	2A INSPECTION								
	PKG 2 in PKG 31	MOS	16	+1m			18-MAY-2018	**18-SEP-2019**	18-OCT-2019
		HRS/MSC	800	+40			3041.8	**3841.8**	3881.8
	REF:	AFL					2328		
+ 05-08-00-200-800-03	3A INSPECTION								
	PKG 3 in PKG 31	MOS	24	+1m			24-JUN-2017	**24-JUN-2019**	24-JUL-2019
		HRS/MSC	1200	+40			2832.2	**4032.2**	4072.2
	REF:	AFL					2192		
+ 05-08-00-200-800-11	1A+ INSPECTION								
	PKG 11 in PKG 12 ,14 ,31	MOS	8	+1m	-67		02-MAY-2018	**24-OCT-2018**	24-NOV-2018
		HRS/MSC					3041.8		
	REF:	AFL					2328		
+ 05-08-00-200-800-12	2A+ INSPECTION								
	PKG 12 in PKG 14 ,31	MOS	16	+1m			02-MAY-2018	**02-SEP-2019**	02-OCT-2019
		HRS/MSC					3041.8		
	REF:	AFL					2328		
+ 05-08-00-200-800-14	4A+ INSPECTION								
	PKG 14 in PKG 31	MOS	32	+1m			02-MAY-2018	**02-JAN-2021**	02-FEB-2021
		HRS/MSC					3041.8		
	REF:	AFL					2328		
05-08-00-200-800-18	Z INSPECTION								
	PKG 18 in PKG 31	MOS	24	+1m			24-JUN-2017	**24-JUN-2019**	24-JUL-2019
		HRS/MSC					2832.2		
	REF:	AFL					2192		
+ 05-08-00-200-800-21	1B INSPECTION								
	PKG 21	MOS					04-MAY-2018		
		HRS/MSC	1600	+40			3041.8	**4641.8**	4681.8
	REF: MPD 05-10-00	AFL					2328		
+ 05-08-00-200-800-22	2B INSPECTION								
	PKG 22	MOS					02-MAY-2018		
		HRS/MSC	3200	+40			3041.8	**6241.8**	6281.8
	REF: MPD 05-10-00	AFL					2328		
+ 05-08-00-200-800-23	3B INSPECTION								
	PKG 23	MOS					13-DEC-2006		
		HRS/MSC	4800	+40	-158.2		0	**4641.8**	4681.8
	REF: MPD 05-10-00	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL		ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-08-00-200-800-24	4B INSPECTION								
	PKG 24	MOS					13-DEC-2006		
		HRS/MSC	6400	+40	-158.2		0	**6241.8**	6281.8
	REF:	AFL					0		
+ 05-08-00-200-800-31	1C INSPECTION								
	PKG 31	MOS	72	+2m			15-JUL-2013	**15-JUL-2019**	15-SEP-2019
		HRS/MSC					1872.8		
	REF: MPD 05-10-00	AFL	3750				1323	**5073**	
+ 05-08-00-200-800-32	2C INSPECTION								
	PKG 32	MOS	144	+2m	71		04-MAY-2007	**14-JUL-2019**	14-SEP-2019
		HRS/MSC					0		
	REF: MPD 05-10-00	AFL	7500		-2427		0	**5073**	
+ 05-08-00-200-800-33	3C INSPECTION								
	PKG 33	MOS	216	+2m	71		04-MAY-2007	**14-JUL-2025**	14-SEP-2025
		HRS/MSC					0		
	REF: MPD 05-10-00	AFL	11250		-2427		0	**8823**	
ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047									
050001	NO. 1 ENGINE - MINOR INSPECTION								
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7	**(3195.7) 3277**	3245.7
	REF: EMM 05-20-00	ENC					1800		
ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047									
050001	NO. 2 ENGINE - MINOR INSPECTION								
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7	**(3195.7) 3277**	3245.7
	REF: EMM 05-20-00	ENC					1800		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	**INFORMATION**								
FA2Z-170222A	REVIEW MPD REVISION 8 DATED DECEMBER 2016								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	**REF:**	AFL							
FA2Z-170222B	REVIEW MPD 5-40 REVISION 10 DATED DECEMBER 2016								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	**REF:**	AFL							
FA2Z-171101	REVIEW MAINTENANCE PLANNING DOCUMENT CHAPTER 5 REVISION 9 DATED NOVEMBER 2017								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	**REF:** RCF FA2Z	AFL							
FA2Z-171101A	REVIEW MAINTENANCE MANUAL CHAPTER 5-40 AIRWORTHINESS LIMITATIONS - REVISION 11 - NOVEMBER 2017								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	**REF:** RCF FA2Z	AFL							

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
FA2Z-180322	REVIEW DOCUMENT DISCREPANCIES DD 1-305056891, 1-310213413, AND 306775364								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	REF: MPD FA2Z	AFL							

APU Model : GTCP36-150(F2M) Serial # P-469 Part # 3800548-2

A008-180112	APU - REVIEW HONEYWELL GTCP 36-150(F) APU-49 SIL REV 10								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	REF: RCF APU-SIL-49	APUS							

ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047

E009-171023	NO. 1 ENGINE - REVIEW PW308C EMM REV 39.0								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	REF: RCF E009	ENC							

E009-180220	NO. 1 ENGINE - REVIEW PW308C EMM REV 39.1								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	REF: RCF E009	ENC							

ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E009-171023	NO. 2 ENGINE - REVIEW PW308C EMM REV 39.0								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	**REF:** RCF E009	ENC							
E009-180220	NO. 2 ENGINE - REVIEW PW308C EMM REV 39.1								
		MOS					(EBT)		
		HRS/MSC	-						
REQUIREMENT CHANGE FORMS	**REF:** RCF E009	ENC							
CHAPTER 05	**TIME LIMITS/MAINTENANCE CHECKS**								
05-50-00-100-801-01	CLEANING AFTER ELECTROLYTE SPILLAGE								
		MOS					13-DEC-2006		
24.155		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-100-801	AFL					0		
		APH					0		
05-50-00-200-801-01	CHECK AFTER A TOWING INCIDENT								
		MOS					13-DEC-2006		
09.010		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-200-801	AFL					0		
		APH					0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-200-802-01	CHECK AFTER HAILSTORM								
		MOS					13-DEC-2006		
51.050		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-200-802	AFL					0		
		APH					0		
05-50-00-200-803-01	CHECK AFTER A LIGHTNING STRIKE								
		MOS					13-DEC-2006		
51.040		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-200-803	AFL					0		
		APH					0		
05-50-00-200-804-01	CHECK AFTER A REJECTED TAKE-OFF OR EMERGENCY BRAKING								
		MOS					13-DEC-2006		
32.840		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-200-804	AFL					0		
		APH					0		
05-50-00-200-805-01	CHECK AFTER FLYING UNDER EXCESSIVE LOAD FACTOR OR THROUGH EXCESSIVE TURBULENCE								
		MOS					13-DEC-2006		
51.030		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-200-805	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-200-806-01	PERFORM CHECK AFTER AIRCRAFT TILTING BACKWARD DURING MAINTENANCE OR POWER BACK OPERATIONS								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-200-806	AFL					0		
05-50-00-200-809-01	INSPECTION AFTER SLAT EXTENSION IN OVERSPEED CONDITION								
		MOS					13-DEC-2006		
57.160		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-200-809	AFL					0		
		APH					0		
05-50-00-200-810-01	INSPECTION AFTER FLAP EXTENSION IN OVERSPEED CONDITION								
		MOS					13-DEC-2006		
57.170		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-200-810	AFL					0		
		APH					0		
05-50-00-200-812-01	INSPECTION AFTER LANDING GEAR EXTENSION IN OVERSPEED CONDITION								
		MOS					13-DEC-2006		
53.470		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-200-812	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-200-813-01	CHECK AFTER WHEEL IMPACT WITH AN OBSTACLE AT TAKE OFF OR LANDING								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-200-813	AFL					0		
05-50-00-620-801-01	PERFORM SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS - INSPECTIONS AND ANTI-CORROSION TREATMENTS AT SHORT TIME INTERVALS								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-620-801	AFL					0		
05-50-00-620-801-02	PERFORM SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS - INSPECTIONS AND ANTI-CORROSION TREATMENTS AT MEDIUM TIME INTERVALS								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-620-801	AFL					0		
05-50-00-620-803-01	ACCOMPLISH SPECIFIC MAINTENANCE FOR A/C OPERATING IN COLD WEATHER								
		MOS					13-DEC-2006		
05.030		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-620-803	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-620-804-01	ACCOMPLISH PROCEDURE FOR AIRCRAFT PROLONGED OPERATION AT LOW TEMPERATURES								
		MOS					13-DEC-2006		
51.080		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-620-804	AFL					0		
		APH					0		
05-50-00-620-805-01	SPECIFIC MAINTENANCE TO PREVENT FUEL CONTAMINATION - CRITERIA TO DEFINE A/C AT RISK OF FUEL CONTAMINATION								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF:	AFL					0		
05-50-00-620-805-02	SPECIFIC MAINTENANCE TO PREVENT FUEL CONTAMINATION - SPECIFIC MAINTENANCE TO PREVENT FUEL CONTAMINATION								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF:	AFL					0		
05-50-00-700-801-01	CHECK AND DECONTAMINATION OF THE AIR CONDITIONING SYSTEM AFTER POLLUTION								
		MOS					13-DEC-2006		
21.510		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-801	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-700-803-01	ACCOMPLISH MEASURES TO BE TAKEN AFTER FIRE EXTINGUISHER PERCUSSION - REFER TO SECTION 5-20-26 (SHUTTLE VALVE REPLACEMENT)								
		MOS					13-DEC-2006		
20.010		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-803	AFL					0		
		APH					0		
05-50-00-700-806-01	CHECK AFTER LANDING ON A TAR-MACADAM RUNWAY IN VERY HOT WEATHER								
		MOS					13-DEC-2006		
32.830		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-806	AFL					0		
		APH					0		
05-50-00-700-807-01	CHECK AFTER LANDING ON A DRY AND DIRTY RUNWAY								
		MOS					13-DEC-2006		
32.810		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-807	AFL					0		
		APH					0		
05-50-00-700-808-01	CHECK AFTER HARD / OVERWEIGHT LANDING								
		MOS					13-DEC-2006		
32.800		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-808	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-700-810-01	PERFORM CHECKS AFTER EACH FLIGHT THROUGH SAND								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-810	AFL					0		
05-50-00-700-810-02	PERFORM FURTHER INSPECTIONS IN CASE OF SAND DEPOSITS AFTER FLIGHT THROUGH SAND								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-810	AFL					0		
05-50-00-700-810-03	PERFORM PERIODIC INSPECTIONS AND CHECKS AFTER FLIGHTS THROUGH SAND								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-810	AFL					0		
05-50-00-700-810-04	PERFORM INSPECTIONS AND CHECKS AFTER A SANDSTORM (AIRCRAFT PARKED)								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-810	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-700-818-01	CHECK AFTER AN ELECTRICAL FIRE								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-818	AFL					0		
05-50-00-700-822-01	PERFORM CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-822	AFL					0		
05-50-00-700-822-02	PERFORM FURTHER CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-822	AFL					0		
05-50-00-700-822-03	PERFORM OPERATIONS AND CHECKS AFTER EXCEPTIONAL FLIGHT THROUGH A HIGH VOLCANIC ASH CONCENTRATION AREA								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-822	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-700-822-04	PERFORM OPERATIONS AND CHECKS ON AN AIRCRAFT PARKED IN A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-822	AFL					0		
05-50-00-700-822-05	PERFORM OPERATIONS AND CHECKS ON AN AIRCRAFT PARKED IN A HEAVY VOLCANIC ASH FALLOUT AREA								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-700-822	AFL					0		
05-50-00-730-801-01	CHECK AFTER AN INCIDENT FOR THE FILTER CLOGGING OF HYDRAULIC SYSTEM								
		MOS					13-DEC-2006		
29.260		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-730-801	AFL					0		
		APH					0		
05-50-00-730-801-02	CHECK AFTER AN INCIDENT FOR THE PUMP FAILURE OF HYDRAULIC SYSTEM								
		MOS					13-DEC-2006		
29.270		HRS/MSC	A/R				0		
	REF: AMM 05-50-00-730-801	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU)	A/C	MAX LIMIT
05-50-00-730-802-01	PERFORM CHECK OF THE BRAKING SYSTEM AT ACCELERATION/STOP AFTER TROUBLESHOOTING										
		MOS						13-DEC-2006			
		HRS/MSC	A/R					0			
	REF: AMM 05-50-00-730-802	AFL						0			
05-50-00-910-801-01 (s)	ACCOMPLISH AIRCRAFT CHECK FLIGHT							PKG			
	PKG 31	MOS	72	+2d				21-NOV-2016			
05.020		HRS/MSC						2676.9			
	REF: AMM 05-50-00-910-801	AFL	3750					2076			
05-60-00-200-801-01	PERFORM BASIC INSPECTION - BASIC CHECK										
		DAYS		+40				18-MAY-2018			
05.010		HRS/MSC	200	+40		-9.6		3041.8	**3232.2**		3272.2
	REF: See Workcard	AFL						2328			
05-60-00-200-801-03	PERFORM BASIC INSPECTION - GROUND SERVICING CHECKS										
		DAYS		+40				18-MAY-2018			
05.010		HRS/MSC	200	+40		-9.6		3041.8	**3232.2**		3272.2
	REF: See Workcard	AFL						2328			

CHAPTER 08 LEVELING AND WEIGHING

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 08-10-00-910-801-01	WEIGHING THE AIRCRAFT								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 08-10-00-910-801	AFL					0		
CHAPTER 09	**TOWING AND TAXING**								
09-10-00-910-810-01	ACCOMPLISH DEBOGGING THE AIRCRAFT								
		MOS					13-DEC-2006		
09.020		HRS/MSC	A/R				0		
	REF: AMM 09-10-00-910-810	AFL					0		
		APH					0		
CHAPTER 10	**PARKING, MOORING, STORE AND RET TO SERV**								
10-10-00-200-801-01	CHECK AFTER PARKING OF THE AIRCRAFT IN HIGH WIND CONDITIONS								
		MOS					13-DEC-2006		
10.020		HRS/MSC	A/R				0		
	REF: AMM 10-10-00-200-801	AFL					0		
		APH					0		
10-10-00-550-801-01	STORAGE OF THE AIRCRAFT FOR A MAXIMUM DURATION OF TWO MONTHS								
		MOS					13-DEC-2006		
20.050		HRS/MSC	O/C				0		
	REF: AMM 10-10-00-550-801	AFL					0		
		APH					0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
10-10-00-550-801-02	STORAGE OF THE AIRCRAFT FOR A MAXIMUM DURATION OF TWO MONTHS TO 12 MONTHS								
		MOS					13-DEC-2006		
20.050		HRS/MSC	O/C				0		
	REF: AMM 10-10-00-550-801	AFL					0		
		APH					0		
10-10-00-550-801-04	PERFORM PERIODIC (STORAGE) CHECKS EVERY MONTH								
		MOS					13-DEC-2006		
20.050		HRS/MSC	O/C				0		
	REF: AMM 10-10-00-550-801	AFL					0		
		APH					0		
10-10-00-550-801-05	PERFORM PERIODIC (STORAGE) CHECKS EVERY TWO MONTHS								
		MOS					13-DEC-2006		
20.050		HRS/MSC	O/C				0		
	REF: AMM 10-10-00-550-801	AFL					0		
		APH					0		
10-10-00-550-801-06	PERFORM PERIODIC (STORAGE) CHECKS EVERY SIX MONTHS								
		MOS					13-DEC-2006		
20.050		HRS/MSC	O/C				0		
	REF: AMM 10-10-00-550-801	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
10-10-00-550-801-07	REMOVAL OF THE AIRCRAFT FROM STORAGE AFTER TWO MONTHS								
		MOS					13-DEC-2006		
20.050		HRS/MSC	O/C				0		
	REF: AMM 10-10-00-550-801	AFL					0		
		APH					0		
10-10-00-550-801-08	REMOVAL OF THE AIRCRAFT FROM STORAGE AFTER MORE THAN TWO MONTHS								
		MOS					13-DEC-2006		
20.050		HRS/MSC	O/C				0		
	REF: AMM 10-10-00-550-801	AFL					0		
		APH					0		
10-20-00-910-802-01	ACCOMPLISH MOORING THE AIRCRAFT IN CASE OF SNOWFALL								
		MOS					13-DEC-2006		
10.010		HRS/MSC	A/R				0		
	REF: AMM 10-20-00-910-802	AFL					0		
		APH					0		
CHAPTER 11	**PLACARDS AND MARKINGS**								
11-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF INTERNAL AND EXTERNAL MARKINGS AND PLACARDS						PKG		
	PKG 31	MOS	72	+2m			13-JUL-2013		
		HRS/MSC					1872.8		
	REF: AMM 11-00-00-210-801	AFL	3750				1323		
CHAPTER 20	**STANDARD PRACTICES - AIRFRAME**								

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
20-30-00-330-801-01	ACCOMPLISH TEMPORARY REPAIR AFTER MINOR DAMAGE TO A COMPOSITE MATERIAL COMPONENT								
		MOS					13-DEC-2006		
51.060		HRS/MSC	A/R				0		
	REF: AMM 20-30-00-330-801	AFL					0		
		APH					0		
20-31-00-140-801-01	RINSING THE AIRCRAFT EXTERIOR								
		MOS					13-DEC-2006		
20.020		HRS/MSC	A/R				0		
	REF: AMM 20-31-00-140-801	AFL					0		
		APH					0		
20-31-00-910-801-01	ACCOMPLISH ON-GROUND DE-ICING TREATMENT								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 20-31-00-910-801	AFL					0		
		APH					0		
20-31-00-910-801-02	ACCOMPLISH ON-GROUND ANTI-ICING TREATMENT								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 20-31-00-910-801	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
20-33-00-300-804-01	ACCOMPLISH TEMPORARY REPAIR OF A HYDRAULIC OR WATER PIPE USING RYNGLOK FITTINGS								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 20-33-00-300-804	AFL					0		
		APH					0		
20-41-00-910-801-01	TIGHTENING TORQUES FOR SINGLE FLARE COUPLINGS								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		
20-60-00-370-813-01	ACCOMPLISH APPLICATION OF PAINT TO COMPOSITE COMPONENTS								
		MOS					13-DEC-2006		
20.030		HRS/MSC	A/R				0		
	REF: AMM 20-60-00-370-803	AFL					0		
		APH					0		
20-60-00-370-816-03	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG LEG (5GA)								
	D23733000-1	MOS					13-DEC-2006		
	B116	HRS/MSC	O/C				0		
	REF:	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
20-60-00-370-816-04	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG LEG (10GA)								
	D23734000-1	MOS					13-DEC-2006		
	B116	HRS/MSC	O/C				0		
	REF:	AFL					0		
20-60-00-370-816-05	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG SHOCK ABSORBER (5GA3)								
	PN	MOS					13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF:	AFL					0		
20-60-00-370-816-06	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG SHOCK ABSORBER (10GA3)								
	PN	MOS					13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF:	AFL					0		
20-60-00-370-816-09	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - NLG LEG (5GB)								
	D23732000-1	MOS					13-DEC-2006		
	B115	HRS/MSC	O/C				0		
	REF:	AFL					0		

CHAPTER 21 AIR CONDITIONING

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-00-00-790-801-01	LEAK CHECK OF THE AIR CONDITIONING SYSTEM									
		MOS						13-DEC-2006		
		HRS/MSC	O/C					0		
	REF: AMM 21-00-00-790-801	AFL						0		
21-30-00-790-801-01	GROUND CHECK OF CABIN SEALING									
		MOS						13-DEC-2006		
		HRS/MSC	O/C					0		
	REF: AMM 21-30-00-790-801	AFL						0		
21-30-00-790-802-01 (s)	IN-FLIGHT CHECK OF CABIN SEALING							PKG		
	PKG 21	MOS						18-APR-2018		
21.120		HRS/MSC	1600	+40				3041.8		
	REF: AMM 21-30-00-790-802	AFL						2328		
21-30-00-790-803-01	PRESSURIZATION LEAK TEST									
		MOS						13-DEC-2006		
		HRS/MSC	O/C					0		
	REF:	AFL						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-30-01-900-801-01	AUTOMATIC PRESSURIZATION CONTROLLER								
	92162B010101	MOS		TSO:0			30-DEC-2009		
21.490	00233	HRS/MSC	O/C	TSN:1405 TSO:0			802.8		
	REF: AMM 21-30-01-900-801	AFL		TSO:0			584		
21-31-00-720-801-01 (s)	FUNCTIONAL TEST OF THE NOSE CONE PNEUMATIC ACTUATOR						PKG		
	PKG 21	MOS					16-APR-2018		
21.150		HRS/MSC	1600	+40			3041.8		
	REF: AMM 21-31-00-720-801	AFL					2328		
21-31-00-720-801-02 (s)	FUNCTIONAL TEST OF THE NOSE CONE OVERPRESSURE CHECK VALVE						PKG		
	PKG 21	MOS					16-APR-2018		
21.150		HRS/MSC	1600	+40			3041.8		
	REF: AMM 21-31-00-720-801	AFL					2328		
21-31-01-720-801-01 (s)	FUNCTIONAL TEST OF THE NOSE CONE OVERHEAT INDICATING SYSTEM						PKG		
	PKG 21	MOS					16-APR-2018		
21.020		HRS/MSC	1600	+40			3041.8		
	REF: AMM 21-31-01-720-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-31-09-350-801-01	RESTORATION NOSE CONE FAN (REPLACEMENT OF BEARINGS)								
	AE1103A01	MOS					13-DEC-2006		
21.040	00509	HRS/MSC	N/A				0		
	REF: AMM 21-31-09-350-801	AFL					0		
21-31-09-900-801-01	NOSE CONE FAN								
	AE1103A01	MOS		TSN:0			13-DEC-2006		
21.040	00509	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 21-31-09-900-801	AFL		TSN:0			0		
21-32-00-710-801-01 (s)	OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM						PKG		
	PKG 21	MOS					19-APR-2018		
21.130		HRS/MSC	1600	+40			3041.8		
	REF: AMM 21-32-00-710-801	AFL					2328		
21-32-00-710-802-01 (s)	OPERATIONAL TEST OF THE PRESSURIZATION SYSTEM EMERGENCY SUPPLY						PKG		
	PKG 21	MOS					19-APR-2018		
21.140		HRS/MSC	1600	+40			3041.8		
	REF: AMM 21-32-00-710-802	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-32-00-790-801-01 (s)	LEAK CHECK AROUND LH STATIC PRESSURE PROBE						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
		HRS/MSC					2832.2		
	REF: AMM 21-32-00-790-801	AFL					2192		
21-32-00-790-801-02 (s)	LEAK CHECK AROUND RH STATIC PRESSURE PROBE						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
		HRS/MSC					2832.2		
	REF: AMM 21-32-00-790-801	AFL					2192		
21-32-00-790-801-03 (s)	LEAK CHECK AROUND THE LEFT STAND-BY STATIC PRESSURE PROBE						PKG		
	PKG 18 ,31,205	MOS	24	+1m			13-DEC-2006		
		HRS/MSC					0		
	REF: AMM 21-32-00-790-801	AFL					0		
21-32-00-790-801-04 (s)	LEAK CHECK AROUND THE RIGHT STAND-BY STATIC PRESSURE PROBE						PKG		
	PKG 18 ,31,205	MOS	24	+1m			13-DEC-2006		
		HRS/MSC					0		
	REF: AMM 21-32-00-790-801	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-32-06-200-801-01	CLEANING ELECTROPNEUMATIC VALVE									
	2097M031300	MOS						04-APR-2012		
21.160	02443	HRS/MSC	1640	+3%				1495.4	**3135.4**	3184.6
	REF: AMM 21-32-06-200-801	AFL						1032		
21-32-06-200-801-02	CLEANING PNEUMATIC VALVE									
	2099N031300	MOS						04-APR-2012		
21.170	02403	HRS/MSC	1640	+3%				1495.4	**3135.4**	3184.6
	REF: AMM 21-32-06-200-801	AFL						1032		
21-32-06-200-801-03	CHECK ELECTROPNEUMATIC VALVE OVERPRESSURE TIGHTNESS									
	2097M031300	MOS						04-APR-2012		
21.160	02443	HRS/MSC	1640					1495.4	**3135.4**	
	REF: AMM 21-32-06-200-801	AFL						1032		
21-32-06-200-801-03A	CHECK ELECTROPNEUMATIC VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)									
	2097M031300	MOS						04-APR-2012		
21.160	02443	HRS/MSC	1640					1495.4	**3135.4**	
CMR	**REF:** AMM 21-32-06-200-801	AFL						1032		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-32-06-200-801-04	CHECK PNEUMATIC VALVE OVERPRESSURE TIGHTNESS								
	2099N031300	MOS					04-APR-2012		
21.170	02403	HRS/MSC	1640				1495.4	**3135.4**	
	REF: AMM 21-32-06-200-801	AFL					1032		
21-32-06-200-801-04A	CHECK PNEUMATIC VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)								
	2099N031300	MOS					04-APR-2012		
21.170	02403	HRS/MSC	1640				1495.4	**3135.4**	
CMR	**REF:** AMM 21-32-06-200-801	AFL					1032		
21-32-06-200-801-05	CHECK OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES								
		MOS					15-DEC-2016		
21.160		HRS/MSC	1640	+3%			2676.9	**4316.9**	4366.1
	REF: AMM 21-32-06-200-801	AFL					2076		
21-32-06-200-801-05A	CHECK OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (MANDATORY 5-40)								
		MOS					15-DEC-2016		
21.160		HRS/MSC	7500				2676.9	**10176.9**	
CMR	**REF:** AMM 21-32-06-200-801	AFL					2076		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-32-06-720-801-01	FUNCTIONAL TEST ELECTROPNEUMATIC VALVE									
	2097M031300	MOS						13-DEC-2006		
21.160	02443	HRS/MSC	4840	+3%				0	**4840**	4985.2
	REF: AMM 21-32-06-720-801	AFL						0		
21-32-06-720-801-01A	FUNCTIONAL TEST ELECTROPNEUMATIC VALVE (MANDATORY 5-40)									
	2097M031300	MOS						13-DEC-2006		
21.160	02443	HRS/MSC	7500					0	**7500**	
CMR	**REF:** AMM 21-32-06-720-801	AFL						0		
21-32-06-720-801-02	FUNCTIONAL TEST PNEUMATIC VALVE									
	2099N031300	MOS						13-DEC-2006		
21.170	02403	HRS/MSC	4840	+3%				0	**4840**	4985.2
	REF: AMM 21-32-06-720-801	AFL						0		
21-32-06-720-801-02A	FUNCTIONAL TEST PNEUMATIC VALVE (MANDATORY 5-40)									
	2099N031300	MOS						13-DEC-2006		
21.170	02403	HRS/MSC	7500					0	**7500**	
CMR	**REF:** AMM 21-32-06-720-801	AFL						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-32-06-900-801-01	ELECTROPNEUMATIC VALVE								
	2097M031300	MOS		TSN:64			04-APR-2012		
21.160	02443	HRS/MSC	O/C	TSN:1495.4			1495.4		
	REF: AMM 21-32-06-900-801	AFL		TSN:1032			1032		
21-32-06-900-802-01	PNEUMATIC VALVE								
	2099N031300	MOS		TSN:64			04-APR-2012		
21.170	02403	HRS/MSC	O/C	TSN:1495.4			1495.4		
	REF: AMM 21-32-06-900-802	AFL		TSN:1032			1032		
21-32-41-200-801-01 (s)	INSPECTION OF THE NICOTINE FILTER CARTRIDGE						PKG		
	PKG 31	MOS	72	+2m			19-JUN-2013		
21.180		HRS/MSC					1872.8		
	REF: AMM 21-32-41-200-801	AFL	3750				1323		
21-51-13-900-801-01	RECIRCULATION VALVE								
	3901-500	MOS		TSN:0			13-DEC-2006		
21.080	383	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 21-51-13-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-52-05-900-801-01	TURBO COOLER									
	3511A020000	MOS			TSN:0			13-DEC-2006		
21.250	E0363	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 21-52-05-900-801	AFL			TSN:0			0		
21-52-11-900-801-01	JET PUMP VALVE									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 21-52-11-900-801	AFL			TSN:0			0		
21-52-13-100-801-01 (s)	CLEANING OF THE CONDENSER							PKG		
	PKG 31	MOS	72	+2m				19-JUN-2013		
21.520		HRS/MSC						1872.8		
	REF: AMM 21-52-13-100-801	AFL	3750					1323		
21-52-13-900-801-01	HOT AIR CONDENSER									
	11-881528	MOS			TSN:0			13-DEC-2006		
21.300	E0363	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 21-52-13-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-52-18-100-801-01 (s)	CLEANING OF THE HIGH PRESSURE WATER SEPARATOR FILTER							PKG		
	PKG 3 ,31	MOS	24	+1m				24-JUN-2017		
21.260		HRS/MSC	1200	+40				2832.2		
	REF: AMM 21-52-18-100-801	AFL						2192		
21-52-33-900-801-01	TURBINE TEMPERATURE CONTROL VALVE									
	785894-5	MOS			TSN:0			13-DEC-2006		
21.310	2106	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 21-52-33-900-801	AFL			TSN:0			0		
21-52-39-900-801-01	NO. 1 TURBINE TEMPERATURE SENSOR									
	785896	MOS			TSN:0			13-DEC-2006		
21.320	2083	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 21-52-39-900-801	AFL			TSN:0			0		
21-52-39-900-801-02	NO. 2 TURBINE TEMPERATURE SENSOR									
	785896	MOS			TSN:0			13-DEC-2006		
21.320	2084	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 21-52-39-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-52-45-900-801-01	COMPRESSOR OVERHEAT SENSOR								
	RP161-00	MOS		TSN:0			13-DEC-2006		
21.320	2926	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 21-52-45-900-801	AFL		TSN:0			0		
21-52-73-100-801-01 (s)	CLEANING OF THE TURBOCOOLER AIR RETURN INLET GRID						PKG		
	PKG 12 ,14 ,31	MOS	16 +1m				16-APR-2018		
21.400		HRS/MSC					3041.8		
	REF: AMM 21-52-73-100-801	AFL					2328		
21-61-02-900-801-01	AIR CONDITIONING COMPUTER								
	774689-2-3	MOS		TSR:0			07-DEC-2007		
21.360	0169	HRS/MSC	O/C	TSN:251.9 TSR:0			251.9		
	REF: AMM 21-61-02-900-801	AFL		TSN:166 TSR:0			166		
21-63-02-900-801-01	COCKPIT HOT TEMPERATURE CONTROL VALVE								
	785894-5	MOS		TSN:0			13-DEC-2006		
21.350	2107	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 21-63-02-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-63-03-900-801-01	COCKPIT COLD TEMPERATURE CONTROL VALVE								
	785894-5	MOS		TSN:0			13-DEC-2006		
21.350	2108	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 21-63-03-900-801	AFL		TSN:0			0		
21-64-02-900-801-01	CABIN HOT TEMPERATURE CONTROL VALVE								
	785894-5	MOS		TSN:0			13-DEC-2006		
21.340	2110	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 21-64-02-900-801	AFL		TSN:0			0		
21-64-03-900-801-01	CABIN COLD TEMPERATURE CONTROL VALVE								
	785894-5	MOS		TSN:0			13-DEC-2006		
21.340	2109	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 21-64-03-900-801	AFL		TSN:0			0		
21-65-13-710-809-01 (s)	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT COCKPIT OVERHEATING DETECTION THERMAL SWITCH						PKG		
	PKG 21	MOS					18-APR-2018		
		HRS/MSC	1600	+40			3041.8		
	REF: AMM 21-65-13-710-809	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-65-13-710-809-02 (s)	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT CABIN OVERHEATING DETECTION THERMAL SWITCH							PKG		
	PKG 21	MOS						18-APR-2018		
		HRS/MSC	1600	+40				3041.8		
	REF: AMM 21-65-13-710-809	AFL						2328		
21-71-01-350-801-01	RESTORATION LH OZONE CONVERTER (FUNCTIONAL TEST AND CLEANING)									
	41098001	MOS						13-DEC-2006		
36.010	6693	HRS/MSC	5000	+3%				0	**5000**	5150
	REF: AMM 21-71-01-350-801	AFL						0		
21-71-01-350-801-02	RESTORATION RH OZONE CONVERTER (FUNCTIONAL TEST AND CLEANING)									
	41098001	MOS						13-DEC-2006		
36.010	6694	HRS/MSC	5000	+3%				0	**5000**	5150
	REF: AMM 21-71-01-350-801	AFL						0		
21-71-01-900-801-01	LH OZONE CONVERTER									
	41098001	MOS			TSN:0			13-DEC-2006		
36.010	6693	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 21-71-01-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-71-01-900-801-02	RH OZONE CONVERTER								
	41098001	MOS		TSN:0			13-DEC-2006		
36.010	6694	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 21-71-01-900-801	AFL		TSN:0			0		
212801	LH COOLING UNIT CHECK VALVE								
	CYLB50419-1H	MOS		TSN:0			13-DEC-2006		
21.050	3193	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
212806	RH COOLING UNIT CHECK VALVE								
	CYLB50419-1H	MOS		TSN:0			13-DEC-2006		
21.050	3194	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
212811	NOSE CONE THERMAL SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
21.210	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212813	NOSE CONE VALVE PROXIMITY DETECTOR								
	PN	MOS		TSN:0			13-DEC-2006		
21.390	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
212816	LH HOT AIR CHECK VALVE								
	CYLB52001	MOS		TSN:0			13-DEC-2006		
21.060	697	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
212821	RH HOT AIR CHECK VALVE								
	CYLB52001	MOS		TSN:0			13-DEC-2006		
21.060	698	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
212826	LH COLD AIR DISTRIBUTION CHECK VALVE								
	7D2W320000	MOS		TSN:0			13-DEC-2006		
21.070	736	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212831	RH COLD AIR DISTRIBUTION CHECK VALVE								
	7D2W320000	MOS		TSN:0			13-DEC-2006		
21.070	715	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
212833	COLD AIR DISTRIBUTION FLEXIBLE CONTROL								
	1VF2152	MOS		TSN:0			13-DEC-2006		
21.480	238	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
212835	COLD AIR DISTRIBUTION CONTROL LEVER								
	200172	MOS		TSN:0			13-DEC-2006		
21.500	265	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
212841	RECIRCULATION VALVE CHECK VALVE								
	CYLB52331	MOS		TSN:0			13-DEC-2006		
21.090	350	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212846	NOSE CONE PNEUMATIC ACTUATOR								
	7021-200	MOS		TSN:0			13-DEC-2006		
21.100	C45916	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
212851	LH COCKPIT DISTRIBUTION SYSTEM - FLEXIBLE CONTROL								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
212852	RH COCKPIT DISTRIBUTION SYSTEM - FLEXIBLE CONTROL								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
212856	CROSSFEED AIR CABIN VALVE								
	VC1005-1	MOS		TSN:0			13-DEC-2006		
21.110	0660	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213801	CABIN PRESSURIZATION SYSTEM VACUUM JET PUMP								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
213811	NOSE CONE OVERPRESSURE CHECK VALVE								
	6025-300	MOS		TSN:0			13-DEC-2006		
21.200	C43803	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
213831	EMERGENCY PRESSURIZATION PANEL								
	912AB0101	MOS		TSN:0			13-DEC-2006		
21.220	00529	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
213836	CABIN AIR FILTER								
	PN	MOS		TSN:0			13-DEC-2006		
21.410	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213841	LEFT ENGINE LOW PRESSURE AIR CHECK VALVE								
	32929001	MOS		TSN:0			13-DEC-2006		
21.230	0362	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
213851	RIGHT ENGINE LOW PRESSURE AIR CHECK VALVE								
	32929001	MOS		TSN:0			13-DEC-2006		
21.230	0363	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
213861	APU LOW PRESSURE AIR CHECK VALVE								
	32929001	MOS		TSN:0			13-DEC-2006		
21.230	0364	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
213881	LEFT ENGINE PRESSURIZATION CONTROL CHECK VALVE								
	35189001	MOS		TSN:0			13-DEC-2006		
21.420	337	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213882	RIGHT ENGINE PRESSURIZATION CONTROL CHECK VALVE								
	35189001	MOS		TSN:0			13-DEC-2006		
21.420	338	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
213886	APU PRESSURIZATION CONTROL CHECK VALVE								
	35189001	MOS		TSN:0			13-DEC-2006		
21.430	339	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
215801	COLD AIR CHECK VALVE								
	CYLB50712	MOS		TSN:0			13-DEC-2006		
21.280	811	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
215811	COLD FAN PRESSURE CONTROL VALVE								
	3313-300	MOS		TSN:0			13-DEC-2006		
21.270	652	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215821	DUAL HEAT EXCHANGER								
	11-811528-3	MOS		TSN:0			13-DEC-2006		
21.290	E0402	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
215831	HIGH PRESSURE WATER SEPARATOR								
	SP0500C01	MOS		TSN:0			13-DEC-2006		
21.260	00384	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
216846	COCKPIT OVERHEATING DETECTION THERMAL SWITCH								
	150T346	MOS		TSN:0			13-DEC-2006		
21.450	1604	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
216848	CABIN OVERHEATING DETECTION THERMAL SWITCH								
	150T346	MOS		TSN:0			13-DEC-2006		
21.450	1603	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216851	CABIN DUCT TEMPERATURE SENSOR								
	785896	MOS		TSN:0			13-DEC-2006		
21.370	02085	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
216861	COCKPIT DUCT TEMPERATURE SENSOR								
	785896	MOS		TSN:0			13-DEC-2006		
21.370	0281	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
216866	CABIN AIR DUCT TEMPERATURE SENSOR								
	785896	MOS		TSN:0			13-DEC-2006		
21.460	0282	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
216871	CABIN TEMPERATURE SENSOR								
	785895	MOS		TSN:0			13-DEC-2006		
21.380	00643	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 21-60-00-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216881	COCKPIT TEMPERATURE SENSOR								
	785895	MOS		TSN:0			13-DEC-2006		
21.380	00789	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 21-60-00-900-801	AFL		TSN:0			0		
216891	CABIN TEMPERATURE INDICATOR								
	PN	MOS		TSN:0			13-DEC-2006		
21.380	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 22	**AUTO FLIGHT**								
22-00-05-900-801-01	ACTUATOR I/O PROCESSOR (AIOP) 2B MODULE								
	7028432-1902	MOS		TSN:0			16-JUN-2015		
22.070	1502L023	HRS/MSC	O/C	TSN:0			2409.6		
	REF:	AFL		TSN:0			1816		
22-00-05-900-801-02	ACTUATOR I/O PROCESSOR (AIOP) 1B MODULE								
	7028432-1902	MOS		TSN:0			16-JUN-2015		
22.070	1503L160	HRS/MSC	O/C	TSN:0			2409.6		
	REF:	AFL		TSN:0			1816		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-00-05-900-801-03	ACTUATOR I/O PROCESSOR (AIOP) 2A MODULE								
	7028432-1902	MOS		TSN:0			16-JUN-2015		
22.080	1503L164	HRS/MSC	O/C	TSN:0			2409.6		
	REF:	AFL		TSN:0			1816		
22-00-05-900-801-04	ACTUATOR I/O PROCESSOR (AIOP) 1A MODULE								
	7028432-1902	MOS		TSN:0			16-JUN-2015		
22.080	1502L010	HRS/MSC	O/C	TSN:0			2409.6		
	REF:	AFL		TSN:0			1816		
22-10-00-710-801-01 (s)	OPERATIONAL TEST OF THE AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS)						PKG		
	PKG 2 ,31	MOS	16	+1m			20-APR-2018		
22.010		HRS/MSC	800	+40			3041.8		
RVSM	**REF:** AMM 22-10-00-710-801	AFL					2328		
22-10-01-900-801-01	GUIDANCE PANEL CONTROLLER								
	7028660-903	MOS		TSR:0			02-DEC-2009		
22.050	05030187	HRS/MSC	O/C	TSR:0			801.3		
	REF: AMM 22-10-01-900-801	AFL		TSR:0			583		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-10-05-900-801-01	AILERON SERVOMOTOR								
	6256-176	MOS					03-MAY-2017		
22.020	3256	HRS/MSC	O/C				2780.3		
	REF: AMM 22-10-05-900-801	AFL					2153		
22-10-05-900-801-02	ELEVATOR SERVOMOTOR								
	6256-176	MOS		TSR:0			08-AUG-2009		
22.030	337	HRS/MSC	O/C	TSR:0			690.1		
	REF: AMM 22-10-05-900-801	AFL		TSR:0			509		
22-10-07-700-801-01 (s)	CHECK OF THE AILERON SERVOMOTOR CABLES AND PULLEYS						PKG		
	PKG 32	MOS	144 +2m				13-DEC-2006		
22.020		HRS/MSC					0		
RVSM	**REF:** AMM 22-10-07-700-801	AFL	7500				0		
22-10-07-700-801-02 (s)	CHECK OF THE ELEVATOR SERVOMOTOR CABLES AND PULLEYS						PKG		
	PKG 32	MOS	144 +2m				08-AUG-2009		
22.030		HRS/MSC					690.1		
RVSM	**REF:** AMM 22-10-07-700-801	AFL	7500				509		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-10-09-900-801-01	AUTOPILOT SERVOMOTOR AILERON SB-1200 BRACKET								
	6256-151-1	MOS		TSN:0			13-DEC-2006		
22.020	1483	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-10-09-900-801	AFL		TSN:0			0		
22-10-09-900-801-02	AUTOPILOT SERVOMOTOR ELEVATOR SB-1200 BRACKET								
	6256-151-1	MOS		TSN:0			08-MAY-2008		
22.030	5293	HRS/MSC	O/C	TSN:0			347.8		
	REF: AMM 22-10-09-900-801	AFL		TSN:0			254		
22-13-01-900-801-01	YAW DAMPER ACTUATOR								
	3-8486-3	MOS		TSN:0			13-DEC-2006		
22.040	1088	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-13-01-900-801	AFL		TSN:0			0		
CHAPTER 23	**COMMUNICATIONS**								
23-11-05-900-801-01	NO. 1 VHF ANTENNA								
	2820-84	MOS		TSN:0			13-DEC-2006		
23.020	347	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 23-11-05-900-801	AFL		TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-11-05-900-801-02	NO. 2 VHF ANTENNA								
	S65-8280-10	MOS		TSN:0			13-DEC-2006		
23.020	14359	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 23-11-05-900-801	AFL		TSN:0			0		
23-11-05-900-801-03	NO. 3 VHF ANTENNA								
	S65-8280-10	MOS					13-DEC-2006		
	31015813	HRS/MSC	O/C				0		
	REF: AMM 23-11-05-900-801	AFL					0		
		APH					0		
23-11-07-900-801-01	NO. 1 VHF DIGITAL RADIO (VDR) MODULE								
	7026201-812	MOS		TSR:72			19-OCT-2015		
23.030	06072365 MOD N	HRS/MSC	O/C	TSR:1730.2			2502.4		
	REF: AMM 23-11-07-900-801	AFL		TSR:1334			1898		
23-11-07-900-801-02	NO. 2 VHF DIGITAL RADIO (VDR) MODULE								
	7026201-812	MOS					26-FEB-2018		
23.030	06072364	HRS/MSC	O/C				2998.6		
	REF: AMM 23-11-07-900-801	AFL					2298		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-11-09-900-801-01	NO. 3 VHF DIGITAL RADIO (VDR) MODULE								
	7026201-814	MOS					30-JUN-2015		
23.030	08044494	HRS/MSC	O/C						
	REF: AMM 23-11-09-900-801	AFL							
23-11-13-900-801-01	VDR 3 MINI CABINET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 23-11-13-900-801	AFL		TSN:0			0		
23-11-17-710-801-01 (s)	OPERATIONAL TEST OF THE "VHF 1 EMERG" RADIO TUNING SWITCH						PKG		
	PKG 21	MOS					16-APR-2018		
23.100		HRS/MSC	1600 +40				3041.8		
	REF: AMM 23-11-17-710-801	AFL					2328		
23-11-17-710-801-01A	OPERATIONAL TEST "VHF 1 EMERG" RADIO TUNING SWITCH (MANDATORY 5-40)								
		MOS					16-APR-2018		
23.100		HRS/MSC	1640				3041.8	**4681.8**	
CMR	**REF:** AMM 23-11-17-710-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-12-00-710-801-01	OPERATIONAL TEST OF NO.1 HF COMMUNICATION SYSTEM								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 23-12-00-710-801	AFL					0		
23-12-00-710-801-02	OPERATIONAL TEST OF NO.2 HF COMMUNICATION SYSTEM								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 23-12-00-710-801	AFL					0		
23-12-01-900-801-01	NO. 1 HF TRANSCEIVER								
	822-0102-001	MOS		TSN:49 TSR:0			25-JAN-2011		
23.050	2821	HRS/MSC	O/C	TSN:1124.8 TSR:0			1144.5		
	REF: AMM 23-12-01-900-801	AFL		TSN:792 TSR:0			806		
23-12-01-900-801-02	NO. 2 HF TRANSCEIVER								
	822-0102-001	MOS		TSN:49			25-JAN-2011		
23.050	2757	HRS/MSC	O/C	TSN:1144.5			1144.5		
	REF: AMM 23-12-01-900-801	AFL		TSN:806			806		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-12-09-900-801-01	NO. 1 HF COUPLER AMPLIFIER								
	622-8114-002	MOS		TSN:0			13-DEC-2006		
23.050	6567	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 23-12-09-900-801	AFL		TSN:0			0		
23-12-09-900-801-02	NO. 2 HF COUPLER AMPLIFIER								
	622-8114-002	MOS		TSN:0			13-DEC-2006		
23.050	6569	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 23-12-09-900-801	AFL		TSN:0			0		
23-12-13-900-801-01	HF ANTENNA								
	PN	MOS		TSN:0			13-DEC-2006		
23.010	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 23-12-13-900-801	AFL		TSN:0			0		
23-15-15-280-801-01S	DETAIL INSPECTION OF THE FUSELAGE SKIN UNDER THE DUAL PATCH SATELLITE TELEPHONE ANTENNA								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: GENERIC CMM	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-15-15-900-801-01	DUAL PATCH SATELLITE TELEPHONE ANTENNA								
	PN	MOS		TSN:0			13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
		APH		TSN:0			0		
23-15-20-280-801-01S	DETAIL INSPECTION OF THE DUAL PATCH SATELLITE TELEPHONE ANTENNA ABOVE THE INTERNAL DOUBLER P/N:F2DJ110051A0001								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: GENERIC CMM	AFL					0		
		APH					0		
23-15-45-900-801-01	CABIN NETWORK WIRELESS ROUTER								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
23-17-47-710-801-01	OPERATIONAL TEST OF THE COCKPIT RINGER INHIBIT FUNCTION								
		MOS					13-APR-2012		
		HRS/MSC	N/A				1495.4		
	REF: AMM 23-17-47-710-801	AFL					1032		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-21-00-710-801-01	OPERATIONAL TEST OF THE ENGINE MONITORING SYSTEM - TEST OF THE MANUAL UPLOAD TRANSMISSION								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 23-21-00-710-801	AFL					0		
23-21-00-710-801-02	OPERATIONAL TEST OF THE ENGINE MONITORING SYSTEM - TEST OF THE AUTOMATIC UPLOAD TRANSMISSION								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 23-21-00-710-801	AFL					0		
23-21-01-900-801-01	DTU PROCESSOR UNIT								
	DTU-A-012-1	MOS		TSN:3			15-DEC-2016		
	1485	HRS/MSC	O/C	TSN:0			2676.9		
	REF: AMM 23-21-01-900-801	AFL		TSN:0			2076		
23-21-01-960-801-01	DISCARD DTU PROCESSOR UNIT BATTERY								
	DTU-A-012-1	MOS	120				15-DEC-2016	**15-DEC-2026**	
	1485	HRS/MSC					2676.9		
LIFE LIMIT	**REF:** AMM 23-21-01-960-801	AFL					2076		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-50-00-710-802-01 (s)	OPERATIONAL TEST PILOT OF THE "BKUP" AUDIO BUTTON SIDE						PKG		
	PKG 21	MOS					16-APR-2018		
23.110		HRS/MSC	1600	+40			3041.8		
	REF: AMM 23-50-00-710-802	AFL					2328		
23-50-00-710-802-01A	OPERATIONAL TEST PILOT "BKUP" AUDIO SWITCH (MANDATORY 05-40)								
		MOS					16-APR-2018		
23.110		HRS/MSC	1640				3041.8	**4681.8**	
CMR	**REF:** AMM 23-50-00-710-802	AFL					2328		
23-50-00-710-802-02 (s)	OPERATIONAL TEST COPILOT OF THE "BKUP" AUDIO BUTTON SIDE						PKG		
	PKG 21	MOS					16-APR-2018		
23.110		HRS/MSC	1600	+40			3041.8		
	REF: AMM 23-50-00-710-802	AFL					2328		
23-50-00-710-802-02A	OPERATIONAL TEST COPILOT "BKUP" AUDIO SWITCH (MANDATORY 05-40)								
		MOS					16-APR-2018		
23.110		HRS/MSC	1640				3041.8	**4681.8**	
CMR	**REF:** AMM 23-50-00-710-802	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-60-00-760-801-01 (s)	VISUAL INSPECTION AND ELECTRICAL BONDING CHECK OF THE STATIC DISCHARGERS							PKG		
	PKG 21	MOS						16-APR-2018		
23.070		HRS/MSC	1600	+40				3041.8		
	REF: AMM 23-60-00-760-801	AFL						2328		
231866	"VHF 1 EMERG" RADIO TUNING SWITCH									
	PN	MOS			TSN:0			13-DEC-2006		
23.100	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	AFL			TSN:0			0		
233801	PILOT AUDIO CONTROL									
	7511900-94101	MOS			TSR:67			20-AUG-2015		
23.060	05071753	HRS/MSC	O/C		TSR:1649			2451.8		
	REF: GENERIC NO REF	AFL			TSR:1269			1853		
233811	COPILOT AUDIO CONTROL									
	7511900-94101	MOS			TSR:84			20-AUG-2015		
23.060	04121194	HRS/MSC	O/C		TSR:2022			2451.8		
	REF: GENERIC NO REF	AFL			TSR:1534			1853		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237831	COCKPIT VOICE RECORDER (CVR) CONTROL BOX								
	PN	MOS		TSN:0			13-DEC-2006		
23.150	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 24	**ELECTRICAL POWER**								
24-20-05-710-801-01 (s)	OPERATIONAL TEST OF THE GROUND FAULT (GFI) INTERRUPTER						PKG		
	PKG 21	MOS					16-APR-2018		
		HRS/MSC	1600	+40			3041.8		
	REF: AMM 24-20-05-710-801	AFL					2328		
24-20-05-900-802-01	GROUND FAULT (GFI) INTERRUPTER								
	106299-1	MOS		TSN:0			29-JUN-2015		
	2190615	HRS/MSC	O/C	TSN:0			2409.6		
	REF: AMM 24-20-05-900-802	AFL		TSN:0			1816		
24-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS						PKG		
	PKG 21	MOS					19-APR-2018		
24.030		HRS/MSC	1600	+40			3041.8		
	REF: AMM 24-30-00-710-801	AFL					2328		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30-00-710-801-01A	OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS (MANDATORY 5-40)								
		MOS					19-APR-2018		
24.030		HRS/MSC	1800				3041.8	**4841.8**	
CMR	**REF:** AMM 24-30-00-710-801	AFL					2328		
24-30-00-710-803-01 (s)	CHECK OF BATTERY 1 REVERSE OVERCURRENT PROTECTION						PKG		
	PKG 24	MOS					13-DEC-2006		
24.060		HRS/MSC	7500				0		
	REF: AMM 24-30-00-710-803	AFL					0		
24-30-00-710-803-01A	CHECK OF CURRENT PROTECTION CIRCUIT BATTERY 1 (MANDATORY 05-40)								
		MOS					13-DEC-2006		
24.060		HRS/MSC	7500				0	**7500**	
CMR	**REF:** AMM 24-30-00-710-803	AFL					0		
24-30-00-710-803-02	CHECK OF BATTERY 2 REVERSE OVERCURRENT PROTECTION								
		MOS					13-DEC-2006		
		HRS/MSC	7500				0	**7500**	
	REF: AMM 24-30-00-710-803	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30-00-710-803-02A	CHECK OF CURRENT PROTECTION CIRCUIT BATTERY 2 (50PC) (MANDATORY 5-40)								
		MOS					13-DEC-2006		
		HRS/MSC	7500				0		**7500**
MANDATORY 5-40	**REF:** AMM 24-30-00-710-803	AFL					0		
		APH					0		
24-30-00-710-803-03	CHECK OF ESS/MD BUSES INTERCONNECTION OVERCURRENT PROTECTION								
		MOS					13-DEC-2006		
		HRS/MSC	7500				0		**7500**
	REF: AMM 24-30-00-710-803	AFL					0		
		APH					0		
24-30-00-710-803-03A	CHECK OF ESS/MD BUSSES INTERCONNECTION CONTACTOR (14PC2) (MANDATORY 5-40)								
		MOS					13-DEC-2006		
		HRS/MSC	7500				0		**7500**
MANDATORY 5-40	**REF:** AMM 24-30-00-710-803	AFL					0		
		APH					0		
24-30-00-710-804-01 (s)	CHECK OF "LH ISOL" AND "RH ISOL" DISCONNECTION						PKG		
	PKG 21	MOS					16-APR-2018		
		HRS/MSC	1600	+40			3041.8		
	REF: AMM 24-30-00-710-804	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30-00-710-804-01A	CHECK OF "LH ISOL" AND "RH ISOL" DISCONNECTION (MANDATORY 5-40)								
		MOS					16-APR-2018		
		HRS/MSC	1800				3041.8	**4841.8**	
MANDATORY 5-40	**REF:** AMM 24-30-00-710-804	AFL					2328		
24-30-00-710-805-01	CHECK OF "LH ISOL" AND "RH ISOL" LOGIC IN FLIGHT CONDITION								
		MOS					13-DEC-2006		
		HRS/MSC	15000				0	**15000**	
	REF: AMM 24-30-00-710-805	AFL					0		
		APH					0		
24-30-00-710-805-01A	CHECK CHECK OF "LH ISOL" AND "RH ISOL" LOGIC IN FLIGHT CONDITION (MANDATORY 5-40)								
		MOS					13-DEC-2006		
		HRS/MSC	15000				0	**15000**	
MANDATORY 5-40	**REF:** AMM 24-30-00-710-805	AFL					0		
		APH					0		
24-30-00-710-806-01	CHECK OF ESS/MD BUSES INTERCONNECTION CURRENT PROTECTION								
		MOS					13-DEC-2006		
		HRS/MSC	30000				0	**30000**	
	REF: AMM 24-30-00-710-806	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-01-350-801-01	RESTORATION NO. 1 DC GENERATOR (OVERHAUL)									
	12800-2-1	MOS						13-DEC-2006		
24.070	1760	HRS/MSC	3240	+3%				0	**3240**	3337.2
OVERHAUL	**REF:** AMM 24-31-01-350-801	AFL						0		
24-31-01-350-801-02	RESTORATION NO. 2 DC GENERATOR (OVERHAUL)									
	12800-2-1	MOS						13-DEC-2006		
24.070	1758	HRS/MSC	3240	+3%				0	**3240**	3337.2
OVERHAUL	**REF:** AMM 24-31-01-350-801	AFL						0		
24-31-01-900-801-01	NO. 1 DC GENERATOR									
	12800-2-1	MOS			TSN:0			13-DEC-2006		
24.070	1760	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 24-31-01-900-801	AFL			TSN:0			0		
24-31-01-900-801-02	NO. 2 DC GENERATOR									
	12800-2-1	MOS			TSN:0			13-DEC-2006		
24.070	1758	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 24-31-01-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-09-900-801-01	APU GENERATOR CONTROL UNIT								
	12900-6	MOS		TSN:0			13-DEC-2006		
24.110	2017	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-31-09-900-801	AFL		TSN:0			0		
24-31-09-900-801-02	NO. 1 GENERATOR CONTROL UNIT								
	12900-6	MOS		TSN:0			13-DEC-2006		
24.110	2091	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-31-09-900-801	AFL		TSN:0			0		
24-31-09-900-801-03	NO. 2 GENERATOR CONTROL UNIT								
	12900-6	MOS		TSN:0			13-DEC-2006		
24.110	2211	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-31-09-900-801	AFL		TSN:0			0		
24-32-01-700-802-01	REGULAR CHECK NO. 1 MAIN BATTERY (CONCORD LEAD/ACID BATTERY ONLY)								
	RG380E/44LS	MOS	24	+3%			29-JUN-2016	**29-JUN-2018**	20-JUL-2018
24.050	40812255	HRS/MSC							
	REF: AMM 24-32-01-700-802	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-01-700-802-02	REGULAR CHECK NO. 2 MAIN BATTERY (CONCORD LEAD/ACID BATTERY ONLY)									
	RG380E/44LS	MOS	24	+3%				04-OCT-2016	**04-OCT-2018**	26-OCT-2018
24.055	40838593	HRS/MSC								
	REF: AMM 24-32-01-700-802	AFL								
24-32-01-900-801-01	NO. 1 MAIN BATTERY									
	RG380E/44LS	MOS			TSN:5			04-NOV-2016		
24.050	40812255	HRS/MSC	O/C		TSN:0			2668.6		
	REF: AMM 24-32-01-900-801	AFL			TSN:0			2070		
24-32-01-900-801-02	NO. 2 MAIN BATTERY									
	RG380E/44LS	MOS			TSN:1			04-NOV-2016		
24.055	40838593	HRS/MSC	O/C		TSN:0			2668.6		
	REF: AMM 24-32-01-900-801	AFL			TSN:0			2070		
24-32-01-960-801-01	DISCARD NO. 1 MAIN BATTERY (CONCORD LEAD/ACID BATTERY ONLY)									
	RG380E/44LS	MOS	60		TSI:0			04-NOV-2016	**04-JUN-2021**	
24.050	40812255	HRS/MSC	5000					2668.6	**7668.6**	
LIFE LIMIT	**REF:** AMM 24-32-01-960-801	AFL						2070		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-01-960-801-02	DISCARD NO. 2 MAIN BATTERY (CONCORD LEAD/ACID BATTERY ONLY)								
	RG380E/44LS	MOS	60	TSI:0			04-NOV-2016	**04-OCT-2021**	
24.055	40838593	HRS/MSC	5000				2668.6	**7668.6**	
LIFE LIMIT	**REF:** AMM 24-32-01-960-801	AFL					2070		
24-32-09-710-801-01	OPERATIONAL TEST STAND-BY INSTRUMENT BATTERY								
	100-0540-02	MOS					24-JUN-2017		
	1410	HRS/MSC	O/C				2832.2		
	REF: AMM 24-32-09-710-801	AFL					2192		
24-32-09-710-801-02	OPERATIONAL TEST NO. 1 MODULAR AVIONICS UNIT (MAU) BATTERY								
	100-0540-06	MOS					24-JUN-2017		
	0706603	HRS/MSC	O/C				2832.2		
	REF: AMM 24-32-09-710-801	AFL					2192		
24-32-09-710-801-03	OPERATIONAL TEST NO. 2 MODULAR AVIONICS UNIT (MAU) BATTERY								
	100-0540-06	MOS					24-JUN-2017		
	0706594	HRS/MSC	O/C				2832.2		
	REF: AMM 24-32-09-710-801	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-09-710-801-04	OPERATIONAL TEST NO. 1 DISPLAY UNIT (DU) STAND-BY BATTERY								
	100-0540-06	MOS					24-JUN-2017		
	0813018	HRS/MSC	O/C				2832.2		
	REF: AMM 24-32-09-710-801	AFL					2192		
24-32-09-710-801-05	OPERATIONAL TEST NO. 2 DISPLAY UNIT (DU) STAND-BY BATTERY								
	100-0540-06	MOS					24-JUN-2017		
	1330	HRS/MSC	O/C				2832.2		
	REF: AMM 24-32-09-710-801	AFL					2192		
24-32-09-710-802-01	OPERATIONAL TEST STAND-BY INSTRUMENT BATTERY (SECURAPLANE BATTERY TYPE XL245 ONLY)								
	100-0540-02	MOS	12	+3%			18-MAY-2018	**18-MAY-2019**	29-MAY-2019
24.140	1410	HRS/MSC					3041.8		
	REF: AMM 24-32-09-710-802	AFL					2328		
24-32-09-710-802-02	OPERATIONAL TEST NO. 1 MODULAR AVIONICS UNIT (MAU) BATTERY (SECURAPLANE BATTERY TYPE XL245 ONLY)								
	100-0540-06	MOS	12	+3%			18-MAY-2018	**18-MAY-2019**	29-MAY-2019
24.165	0706603	HRS/MSC					3041.8		
	REF: AMM 24-32-09-710-802	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-09-710-802-03	OPERATIONAL TEST NO. 2 MODULAR AVIONICS UNIT (MAU) BATTERY (SECURAPLANE BATTERY TYPE XL245 ONLY)									
	100-0540-06	MOS	12	+3%				18-MAY-2018	**18-MAY-2019**	29-MAY-2019
24.170	0706594	HRS/MSC						3041.8		
	REF: AMM 24-32-09-710-802	AFL						2328		
24-32-09-710-802-04	OPERATIONAL TEST NO. 1 DISPLAY UNIT (DU) STAND-BY BATTERY (SECURAPLANE BATTERY TYPE XL245 ONLY)									
	100-0540-06	MOS	12	+3%				18-MAY-2018	**18-MAY-2019**	29-MAY-2019
24.175	0813018	HRS/MSC						3041.8		
	REF: AMM 24-32-09-710-802	AFL						2328		
24-32-09-710-802-05	OPERATIONAL TEST NO. 2 DISPLAY UNIT (DU) STAND-BY BATTERY (SECURAPLANE BATTERY TYPE XL245 ONLY)									
	100-0540-06	MOS	12	+3%				18-MAY-2018	**18-MAY-2019**	29-MAY-2019
24.180	1330	HRS/MSC						3041.8		
	REF: AMM 24-32-09-710-802	AFL						2328		
24-32-09-900-801-01	NO. 1 MODULAR AVIONICS UNIT (MAU) BATTERY									
	100-0540-06	MOS			TSR:0			27-OCT-2014		
24.165	0706603	HRS/MSC	O/C		TSR:0			2225.9		
	REF:	AFL			TSR:0			1645		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-09-900-801-02	NO. 2 MODULAR AVIONICS UNIT (MAU) BATTERY								
	100-0540-06	MOS		TSR:0			27-OCT-2014		
24.170	0706594	HRS/MSC	O/C	TSR:0			2225.9		
	REF:	AFL		TSR:0			1645		
24-32-09-900-801-03	NO. 1 DISPLAY UNIT (DU) STAND-BY BATTERY								
	100-0540-06	MOS		TSR:0			27-OCT-2014		
24.175	0813018	HRS/MSC	O/C	TSR:0			2225.9		
	REF:	AFL		TSR:0			1645		
24-32-09-900-801-04	NO. 2 DISPLAY UNIT (DU) STAND-BY BATTERY								
	100-0540-06	MOS		TSR:0		08/27/2017	27-AUG-2015		
24.180	1330	HRS/MSC	O/C	TSR:0			2454.9		
	REF:	AFL		TSR:0			1857		
24-32-09-900-801-05	STAND-BY INSTRUMENT BATTERY								
	100-0540-02	MOS		TSR:0			27-OCT-2014		
24.140	1410	HRS/MSC	O/C	TSR:0			2225.9		
	REF:	AFL		TSR:0			1645		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-09-960-802-01	DISCARD STAND-BY INSTRUMENT BATTERY OF THE STAND-BY INSTRUMENT STAND-BY BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY ONLY)								
	100-0540-02	MOS	48				24-JUN-2017	**24-JUN-2021**	
24.140	1410	HRS/MSC					2832.2		
LIFE LIMIT	**REF:** AMM 24-32-09-960-802	AFL					2192		
24-32-09-960-802-02	DISCARD NO. 1 MODULAR AVIONICS UNIT (MAU) BATTERY OF THE MAU 1 STAND-BY BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY ONLY)								
	100-0540-06	MOS	48				24-JUN-2017	**24-JUN-2021**	
24.165	0706603	HRS/MSC					2832.2		
LIFE LIMIT	**REF:** AMM 24-32-09-960-802	AFL					2192		
24-32-09-960-802-03	DISCARD NO. 2 MODULAR AVIONICS UNIT (MAU) BATTERY OF THE MAU 2 STAND-BY BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY ONLY)								
	100-0540-06	MOS	48				24-JUN-2017	**24-JUN-2021**	
24.170	0706594	HRS/MSC					2832.2		
LIFE LIMIT	**REF:** AMM 24-32-09-960-802	AFL					2192		
24-32-09-960-802-04	DISCARD NO. 1 DISPLAY UNIT (DU) STAND-BY BATTERY OF THE DU 1 STAND-BY BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY ONLY)								
	100-0540-06	MOS	48				24-JUN-2017	**24-JUN-2021**	
24.175	0813018	HRS/MSC					2832.2		
LIFE LIMIT	**REF:** AMM 24-32-09-960-802	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-09-960-802-05	DISCARD NO. 2 DISPLAY UNIT (DU) STAND-BY BATTERY OF THE DU 2 STAND-BY BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY ONLY)									
	100-0540-06	MOS	48					24-JUN-2017	**24-JUN-2021**	
24.180	1330	HRS/MSC						2832.2		
LIFE LIMIT	**REF:** AMM 24-32-09-960-802	AFL						2192		
24-33-01-350-801-01	RESTORATION APU STARTER/GENERATOR (OVERHAUL)									
	8060-160	MOS						21-MAY-2018		
24.040	2134	HRS/MSC								
OVERHAUL	**REF:** AMM 24-33-01-350-801	AFL								
		APH	1240	+3%				1042	**2282**	2319.2
24-33-01-900-801-01	APU STARTER/GENERATOR									
	8060-160	MOS			TSO:0			21-MAY-2018		
24.040	2134	HRS/MSC	O/C					3041.8		
	REF: AMM 24-33-01-900-801	AFL						2328		
		APH			TSO:0			1042		
24-33-05-220-803-01	CHECK APU STARTER/GENERATOR BRUSHES									
	8060-160	MOS						21-MAY-2018		
24.040	2134	HRS/MSC								
	REF: See Workcard	AFL								
		APH	600	+30				1042	**1642**	1672

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-33-05-960-801-01	REPLACE APU STARTER/GENERATOR BRUSHES								
	8060-160	MOS					21-MAY-2018		
	2134	HRS/MSC	O/C						
	REF: AMM 24-33-05-960-801	AFL							
		APH					1042		
24-36-01-900-801-01	NO. 3 DC GENERATOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	H/T	TSN:0			0		
	REF: AMM 24-36-01-900-801	AFL		TSN:0			0		
24-36-05-900-801-01	NO. 3 GENERATOR CONTROL UNIT								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-36-05-900-801	AFL		TSN:0			0		
24-40-00-720-801-01 (s)	FUNCTIONAL TEST OF THE GROUND EXTERNAL POWER RECEPTACLE OVERVOLTAGE PROTECTION PCB						PKG		
	PKG 21	MOS					16-APR-2018		
24.120		HRS/MSC	1600	+40			3041.8		
	REF: AMM 24-40-00-720-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-41-00-720-801-01	FUNCTIONAL TEST OF BATTERIES CHARGING BY GPU								
		MOS					13-DEC-2006		
24.150		HRS/MSC	N/A				0		
	REF: AMM 24-41-00-720-801	AFL					0		
24-61-01-900-801-01	LH MAIN ELECTRICAL BOX								
	431GC02Y04	MOS		TSN:0			13-DEC-2006		
24.010	187	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-61-01-900-801	AFL		TSN:0			0		
24-61-01-900-801-02	RH MAIN ELECTRICAL BOX								
	441GC02Y04	MOS		TSN:0			13-DEC-2006		
24.010	187	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-61-01-900-801	AFL		TSN:0			0		
24-63-13-710-801-01 (s)	OPERATIONAL TEST OF THE DOME LIGHT PCB						PKG		
	PKG 21	MOS					16-APR-2018		
24.075		HRS/MSC	1600	+40			3041.8		
	REF: AMM 24-63-13-710-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243811	MAIN SUPPLY BATTERIES FAN								
	VA0906XXA	MOS		TSN:0			13-DEC-2006		
24.020	11655	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
243819	NO. 1 ENGINE POSITIVE POWER CABLE								
	06ND80100-9	MOS		TSN:0			13-DEC-2006		
24.130	06069100	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-31-05-900-803	AFL		TSN:0			0		
243820	NO. 2 ENGINE POSITIVE POWER CABLE								
	06ND80100-5	MOS		TSN:0			13-DEC-2006		
24.130	06163059	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-31-05-900-803	AFL		TSN:0			0		
243823	NO. 1 ENGINE NEGATIVE POWER CABLE								
	06ND80100-11	MOS		TSN:0			13-DEC-2006		
24.140	05527117	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-31-05-900-802	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243824	NO. 2 ENGINE NEGATIVE POWER CABLE								
	06ND80100-7	MOS		TSN:0			13-DEC-2006		
24.140	0612973	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-31-05-900-802	AFL		TSN:0			0		
244801	GROUND EXTERNAL POWER RECEPTACLE OVERVOLTAGE PROTECTION PCB								
	C0BAQXH0004	MOS		TSN:0			13-DEC-2006		
24.120	21153	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246801	PRINTED CIRCUIT BOARD (401JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246802	PRINTED CIRCUIT BOARD (402JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246803	PRINTED CIRCUIT BOARD (403JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246804	PRINTED CIRCUIT BOARD (404JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246805	PRINTED CIRCUIT BOARD (405JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246806	PRINTED CIRCUIT BOARD (406JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246808	PRINTED CIRCUIT BOARD (408JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246809	PRINTED CIRCUIT BOARD (409JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246810	PRINTED CIRCUIT BOARD (110CZ) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246811	PRINTED CIRCUIT BOARD (411JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246812	PRINTED CIRCUIT BOARD (412JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246813	PRINTED CIRCUIT BOARD (413JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246814	PRINTED CIRCUIT BOARD (414JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246815	PRINTED CIRCUIT BOARD (415JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246817	PRINTED CIRCUIT BOARD (417JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246818	PRINTED CIRCUIT BOARD (418JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246820	PRINTED CIRCUIT BOARD (120CZ) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246821	PRINTED CIRCUIT BOARD (421JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246822	PRINTED CIRCUIT BOARD (422JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246823	PRINTED CIRCUIT BOARD (423JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246824	PRINTED CIRCUIT BOARD (424JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246825	PRINTED CIRCUIT BOARD (425JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246826	PRINTED CIRCUIT BOARD (426JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246827	PRINTED CIRCUIT BOARD (427JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246828	PRINTED CIRCUIT BOARD (428JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246829	PRINTED CIRCUIT BOARD (429JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246830	PRINTED CIRCUIT BOARD (R430JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246831	PRINTED CIRCUIT BOARD (L431JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246832	PRINTED CIRCUIT BOARD (432JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246833	PRINTED CIRCUIT BOARD (433JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246834	PRINTED CIRCUIT BOARD (434JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246835	PRINTED CIRCUIT BOARD (435JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246837	PRINTED CIRCUIT BOARD (437JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246838	PRINTED CIRCUIT BOARD (438JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246840	PRINTED CIRCUIT BOARD (140CD) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246849	APU PRINTED CIRCUIT BOARD (005KZ) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246850	CROSSBLEED VALVE CONTROL PRINTED CRCUIT BOARD (5HU) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246851	WATER GAUGE PRINTED CIRCUIT BOARD (3MT) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246862	LANDING GEAR CONTROL PRINTER CIRCUIT BOARD (10GW) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246863	PRINTED CIRCUIT BOARD (R200LC) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246864	STANDY-BY INSTRUMENTS PRINTED CIRCUIT BOARD (340NH) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246870	PRINTED CIRCUIT BOARD (410JE) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246871	PRINTED CIRCUIT BOARD (L070WW) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246872	PRINTED CIRCUIT BOARD (R070WW) PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246891	LH CONTACTOR CONTROL BOX								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
246892	RH CONTACTOR CONTROL BOX								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
248801	WATER LEAK DETECTION (PCB) PRINTED CIRCUIT BOARD								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 25	**EQUIPMENT/FURNISHINGS**								
25-00-01-200-801-01 (s)	INSPECTION OF THE ONBOARD KIT						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
25.035		HRS/MSC					3041.8		
	REF: AMM 25-00-01-200-801	AFL					2328		
25-00-05-200-801-01 (s)	INSPECTION OF THE CREW AND PASSENGER SEAT HARNESSES AND SAFETY BELTS						PKG		
	PKG 31	MOS	72	+2m			12-JUN-2013		
25.010		HRS/MSC					1872.8		
	REF: AMM 25-00-05-200-801	AFL	3750				1323		
25-11-01-900-801-01	LH PILOT SEAT								
	1422311-17	MOS		TSN:106 TSR:0			22-OCT-2015		
25.020	06T2739	HRS/MSC	O/C	TSN:2502.4 TSR:0			2502.4		
	REF: AMM 25-11-01-900-801	AFL		TSN:1898 TSR:0			1898		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-11-01-900-801-02	RH PILOT SEAT									
	1422310-17	MOS			TSN:106			23-OCT-2015		
25.020	06T2731	HRS/MSC	O/C		TSN:2502.4			2502.4		
	REF: AMM 25-11-01-900-801	AFL			TSN:1898			1898		
25-11-13-640-801-01 (s)	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTING							PKG		
	PKG 21	MOS						16-APR-2018		
25.030		HRS/MSC	1600	+40				3041.8		
	REF: AMM 25-11-13-640-801	AFL						2328		
25-11-13-640-801-02 (s)	GREASING OF THE COPILOT SEAT ACTUATOR ROD END-FITTING							PKG		
	PKG 21	MOS						16-APR-2018		
25.030		HRS/MSC	1600	+40				3041.8		
	REF: AMM 25-11-13-640-801	AFL						2328		
25-11-19-960-801-01 (s)	REPLACE LH PILOT SEAT LOCKING PIN SPRINGS							PKG		
	1422311-17 PKG 31	MOS	72	+2m	TSI:106			22-OCT-2015		
	06T2739	HRS/MSC			TSI:2502.4			2502.4		
	REF: See Workcard	AFL	3750		TSI:1898			1898		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-11-19-960-801-02 (s)	REPLACE RH PILOT SEAT LOCKING PIN SPRINGS							PKG		
	1422310-17 PKG 31	MOS	72	+2m				23-OCT-2015		
	06T2731	HRS/MSC						2502.4		
	REF: See Workcard	AFL	3750					1898		
25-11-25-200-801-01 (s)	INSPECTION OF THE LH PILOT SEAT ROLLER PINS							PKG		
	PKG 31	MOS	72	+2m	TSI:106			22-OCT-2015		
		HRS/MSC			TSI:2502.4			2502.4		
	REF: AMM 25-11-25-200-801	AFL	3750		TSI:1898			1898		
25-11-25-200-801-02 (s)	INSPECTION OF THE RH PILOT SEAT ROLLER PINS							PKG		
	PKG 31	MOS	72	+2m				23-OCT-2015		
		HRS/MSC						2502.4		
	REF: AMM 25-11-25-200-801	AFL	3750					1898		
25-12-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE THIRD CREW MEMBER SEAT							PKG		
	PKG 2 ,31,39	MOS	16	+1m				16-APR-2018		
		HRS/MSC	800	+40				3041.8		
	REF: AMM 25-12-00-210-801	AFL						2328		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-12-00-900-801-01	THIRD CREW MEMBER SEAT								
	403004-1	MOS		TSN:0			13-DEC-2006		
25.120	35600	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 25-12-00-900-801	AFL		TSN:0			0		
25-20-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER DOOR ASSIST HANDLE						PKG		
	PKG 31	MOS	72	+2m			13-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 25-20-00-210-801	AFL	3750				1323		
+ 25-20-00-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE AFT LAVATORY ASSIST HANDLE						PKG		
	PKG 31	MOS	72	+2m			13-DEC-2006		
		HRS/MSC					0		
	REF: AMM 25-20-00-210-801	AFL	3750				0		
25-20-00-220-801-04 (s)	INSPECTION/TEST OF THE WASTE CONTAINERS						PKG		
	PKG 2 ,31	MOS	16	+1m			16-APR-2018		
		HRS/MSC	800	+40			3041.8		
	REF: AMM 25-20-00-220-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20-00-220-802-01 (s)	INSPECTION OF DOORS, DRAWERS AND THEIR RESPECTIVE LATCHING MECHANISMS						PKG		
	PKG 31	MOS	72	+2m			12-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 25-20-00-220-802	AFL	3750				1323		
25-20-00-220-802-02 (s)	INSPECTION OF THE POP-OUT WORK SURFACE						PKG		
	PKG 31	MOS	72	+2m			12-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 25-20-00-220-802	AFL	3750				1323		
25-20-00-220-802-03 (s)	INSPECTION OF THE ICE DRAWERS						PKG		
	PKG 2 ,31	MOS					16-APR-2018		
		HRS/MSC	O/C				3041.8		
	REF: AMM 25-20-00-220-802	AFL					2328		
25-20-00-220-802-04 (s)	INSPECTION OF THE TRACKING MAGAZINE RACK						PKG		
	PKG 2 ,31	MOS	16	+1m			16-APR-2018		
		HRS/MSC	800	+40			3041.8		
	REF: AMM 25-20-00-220-802	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20-00-220-802-05 (s)	OPERATIONAL TEST OF THE TAMBOUR DOOR POWER CUT OFF FUNCTION						PKG		
	PKG 31	MOS	72	+2m			12-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 25-20-00-220-802	AFL	3750				1323		
25-21-00-220-801-01 (s)	DETAILED INSPECTION OF THE SINGLE AND DOUBLE PASSENGER SEATS						PKG		
	PKG 2 ,31	MOS	16	+1m			16-APR-2018		
		HRS/MSC	800	+40			3041.8		
	REF: AMM 25-21-00-220-801	AFL					2328		
25-21-00-220-801-02	DETAILED INSPECTION OF THE DIVAN(S)								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 25-21-00-220-801	AFL					0		
		APH					0		
25-22-01-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE CONSOLE TABLES - CONSOLE TABLES IN LOCATIONS OTHER THAN EMERGENCY EXIT								
	PKG 31	MOS	72	+2m			13-DEC-2006	**15-JUL-2019 M** 15-SEP-2019	
		HRS/MSC					0		
	REF: AMM 25-22-01-210-801	AFL	3750				0	**5073 M**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-22-05-220-802-01 (s)	DETAILED INSPECTION OF THE DINING TABLE							PKG		
	PKG 12 ,14 ,31	MOS	72	+2m				16-APR-2018		
		HRS/MSC						3041.8		
	REF: AMM 25-22-05-220-802	AFL	3750					2328		
25-30-16-900-801-01	COFFEE MAKER									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	AFL			TSN:0			0		
		APH			TSN:0			0		
25-30-32-900-801-01	CHILLER									
	PN	MOS			TSN:0			13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	AFL			TSN:0			0		
		APH			TSN:0			0		
25-30-33-900-801-01	CONVECTION OVEN									
	400-1629-01-R	MOS						13-DEC-2006		
	06-06-39118	HRS/MSC	O/C					0		
	REF: GENERIC NO REF	AFL						0		
		APH						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-33-00-710-801-01	OPERATIONAL CHECK OF THE GALLEY OPTIONAL EQUIPTMENT								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 25-33-00-710-801	AFL					0		
25-33-09-210-801-01	INSPECTION OF COFFEE MAKER/ESPRESSO MACHINE								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 25-33-09-210-801	AFL					0		
		APH					0		
25-33-17-710-801-01	OPERATIONAL TEST MICROWAVE OVEN DOOR ELECTRICAL POWER CUT-OFF FUNCTION								
		MOS					15-MAY-2015		
		HRS/MSC	2400	+3%			2391.3	**4791.3**	4863.3
	REF: AMM 25-33-17-710-801	AFL					1796		
25-33-29-960-801-01	REPLACEMENT OF THE REFRIGERATOR / FREEZER AIR FILTER								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 25-33-29-960-801	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-33-37-960-801-01	REPLACEMENT OF THE CHILLER AIR FILTER								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 25-33-37-960-801	AFL					0		
		APH					0		
25-60-00-200-801-01 (s)	INSPECTION OF THE SAFETY EQUIPMENT						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
25.040		HRS/MSC					3041.8		
	REF:	AFL					2328		
25-61-00-200-881-01	INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207)								
		MOS	12				24-JUN-2017	**30-JUN-2018**	
		HRS/MSC					2832.2		
MANDATORY	**REF:** GENERIC NO REF	AFL					2192		
+ 25-61-00-710-801-01	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT UNIT CONTROLS								
		MOS					12-JUN-2013		
25.100		HRS/MSC	O/C				1872.8		
	REF: See Workcard	AFL					1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-61-00-710-801-02 (s)	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT COCKPIT CONTROLS						PKG		
	PKG 14 ,31	MOS	32	+1m			16-APR-2018		
		HRS/MSC					3041.8		
	REF: See Workcard	AFL					2328		
25-61-01-900-802-01	EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON								
	01N65900	MOS		TSR:0			20-APR-2011		
25.100	07161396	HRS/MSC	O/C	TSR:0			1238.5		
	REF: AMM 25-61-01-900-802	AFL		TSR:0			863		
25-61-13-960-801-01	DISCARD EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON BATTERY PACK								
	01N65900	MOS					28-APR-2017	**31-JUL-2022 M**	
25.100	07161396	HRS/MSC	DUE				2775.3		
LIFE LIMIT	**REF:** AMM 25-61-13-960-801	AFL					2149		
25-61-21-900-801-01	EMERGENCY LOCATOR TRANSMITTER ANTENNA								
	62080	MOS		TSN:0			13-DEC-2006		
25.130	900	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 25-61-21-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-00-900-801-01	COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATOR BEACON								
	DK140	MOS		TSN:0			02-JUL-2015		
25.150	ST68505	HRS/MSC	O/C	TSN:0			2409.6		
	REF:	AFL		TSN:0			1816		
25-62-00-900-801-02	DIGITAL FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON								
	DK120/90	MOS		TSN:2			18-APR-2018		
25.160	AT106664	HRS/MSC	O/C	TSN:0			3041.8		
	REF:	AFL		TSN:0			2328		
25-62-01-720-801-01	FUNCTIONAL CHECK COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATOR BEACON								
	DK140	MOS	25				18-APR-2018	**18-MAY-2020**	
25.150	ST68505	HRS/MSC					3041.8		
	REF: AMM 25-62-01-720-801	AFL					2328		
25-62-01-720-801-02	FUNCTIONAL CHECK DIGITAL FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON								
	DK120/90	MOS	25	+3%			26-FEB-2018	**26-MAR-2020**	18-APR-2020
25.160	AT106664	HRS/MSC							
	REF: AMM 25-62-01-720-801	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-05-960-801-01	DISCARD COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATOR BEACON BATTERY								
	DK140	MOS					24-JUN-2017	**28-FEB-2021 M**	
25.150	ST68505	HRS/MSC	DUE				2832.2		
LIFE LIMIT	**REF:** AMM 25-62-05-960-801	AFL					2192		
25-62-05-960-801-02	DISCARD DIGITAL FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY								
	DK120/90	MOS					18-APR-2018	**31-MAR-2025 M**	
25.160	AT106664	HRS/MSC	DUE				3041.8		
LIFE LIMIT	**REF:** AMM 25-62-05-960-801	AFL					2328		
25-63-00-350-801-01	RESTORATION NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT (OVERHAUL)								
	PN	MOS							
	NOT INSTALLED	HRS/MSC	N/A						
	REF: AMM 25-63-00-350-801	AFL							
25-63-00-350-801-02	RESTORATION NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT (OVERHAUL)								
	PN	MOS							
	NOT INSTALLED	HRS/MSC	N/A						
	REF: AMM 25-63-00-350-801	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63-00-710-801-01	OPERATIONAL TEST NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT								
	PN NOT INSTALLED **REF:** AMM 25-63-00-710-801	MOS HRS/MSC AFL	N/A						
25-63-00-900-801-01	NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT								
	PN NOT INSTALLED **REF:** AMM 25-63-00-900-801	MOS HRS/MSC AFL	O/C						
25-63-00-900-801-02	NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT								
	PN NOT INSTALLED **REF:** AMM 25-63-00-900-801	MOS HRS/MSC AFL	O/C						
25-63-01-960-801-01	DISCARD NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT BATTERY								
	PN NOT INSTALLED **REF:** AMM 25-63-01-960-801	MOS HRS/MSC AFL	N/A						

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63-01-960-801-02	DISCARD NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT BATTERY								
	PN NOT INSTALLED **REF:** AMM 25-63-01-960-801	MOS HRS/MSC AFL	N/A						
25-64-13-200-801-01	INSPECT NO. 1 LIFE RAFT								
25.090	913-FAUL-790-1-601 9UL-00518 **REF:** AMM 25-64-13-200-801	MOS HRS/MSC AFL	36	+3%			14-APR-2016 2602.4 1981	**14-APR-2019**	16-MAY-2019
25-64-13-200-801-02	INSPECT NO. 2 LIFE RAFT								
25.090	913-FAUL-790-1-601 9UL-00517 **REF:** AMM 25-64-13-200-801	MOS HRS/MSC AFL	36	+3%			14-APR-2016 2602.4 1981	**14-APR-2019**	16-MAY-2019
25-64-13-900-801-01	NO. 1 LIFE RAFT								
25.090	913-FAUL-790-1-601 9UL-00518 **REF:** GENERIC CMM	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			14-APR-2016 2602.4 1981		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-13-900-801-02	NO. 2 LIFE RAFT									
	913-FAUL-790-1-601	MOS			TSO:0			14-APR-2016		
25.090	9UL-00517	HRS/MSC	O/C		TSO:0			2602.4		
	REF: GENERIC CMM	AFL			TSO:0			1981		
25-64-17-200-802-01	INSPECTION PILOT LIFE VEST									
	63600-505	MOS	60	+3%				04-JAN-2018	**04-JAN-2023**	26-FEB-2023
25.045	L3986881	HRS/MSC								
	REF: GENERIC NO REF	AFL								
25-64-17-200-802-02	INSPECTION COPILOT LIFE VEST									
	63600-505	MOS	60	+3%				06-OCT-2016	**06-OCT-2021**	30-NOV-2021
25.046	L3319281	HRS/MSC								
	REF: GENERIC NO REF	AFL								
25-64-17-200-803-02	INSPECTION NO. 2 PASSENGER LIFE VEST									
	63600-105	MOS	60	+3%				04-NOV-2016	**04-NOV-2021**	28-DEC-2021
25.050	L2041334	HRS/MSC						2668.6		
	REF: GENERIC NO REF	AFL						2070		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-200-803-03	INSPECTION NO. 3 PASSENGER LIFE VEST									
25.060	63600-105 L2043722 **REF:** GENERIC NO REF	MOS HRS/MSC AFL	60	+3%				04-NOV-2016 2668.6 2070	**04-NOV-2021**	28-DEC-2021
25-64-17-200-803-04	INSPECTION NO. 4 PASSENGER LIFE VEST									
25.060	63600-105 L2041337 **REF:** GENERIC NO REF	MOS HRS/MSC AFL	60	+3%				04-NOV-2016 2668.6 2070	**04-NOV-2021**	28-DEC-2021
25-64-17-200-803-05	INSPECTION NO. 5 PASSENGER LIFE VEST									
25.070	63600-105 L2041330 **REF:** GENERIC NO REF	MOS HRS/MSC AFL	60	+3%				04-NOV-2016 2668.6 2070	**04-NOV-2021**	28-DEC-2021
25-64-17-200-803-06	INSPECTION NO. 6 PASSENGER LIFE VEST									
25.070	63600-105 L2041339 **REF:** GENERIC NO REF	MOS HRS/MSC AFL	60	+3%				04-NOV-2016 2668.6 2070	**04-NOV-2021**	28-DEC-2021

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-200-803-07	INSPECTION NO. 7 PASSENGER LIFE VEST									
25.080	63600-105 L2041332 **REF:** GENERIC NO REF	MOS HRS/MSC AFL	60	+3%				04-NOV-2016 2668.6 2070	**04-NOV-2021**	28-DEC-2021
25-64-17-200-803-08	INSPECTION NO. 8 PASSENGER LIFE VEST									
25.080	63600-105 L2041333 **REF:** GENERIC NO REF	MOS HRS/MSC AFL	60	+3%				04-NOV-2016 2668.6 2070	**04-NOV-2021**	28-DEC-2021
25-64-17-200-803-09	INSPECTION NO. 9 PASSENGER LIFE VEST									
25.081	63600-105 L2041338 **REF:** GENERIC NO REF	MOS HRS/MSC AFL	60	+3%				04-NOV-2016 2668.6 2070	**04-NOV-2021**	28-DEC-2021
25-64-17-200-803-10	INSPECTION NO. 10 PASSENGER LIFE VEST									
25.081	63600-105 L2041331 **REF:** GENERIC NO REF	MOS HRS/MSC AFL	60	+3%				04-NOV-2016 2668.6 2070	**04-NOV-2021**	28-DEC-2021

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-802-01	RESTORATION PILOT LIFE VEST (OVERHAUL OR DISCARD)								
	63600-505	MOS	120				04-JAN-2018	**04-JAN-2028**	
25.045	L3986881	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-802	AFL							
25-64-17-350-802-02	RESTORATION COPILOT LIFE VEST (OVERHAUL OR DISCARD)								
	63600-505	MOS	120				06-OCT-2016	**01-APR-2026 M**	
25.046	L3319281	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-802	AFL							
25-64-17-350-802-03	RESTORATION THIRD CREW MEMBER LIFE VEST (OVERHAUL OR DISCARD)								
	63600-505	MOS	120				06-OCT-2016	**01-APR-2026 M**	
25.047	L3319282	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-802	AFL							
25-64-17-350-803-01	RESTORATION NO. 1 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
	63600-105	MOS	120				16-JAN-2013	**16-JAN-2023**	
25.050	L2043744	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-803	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-803-02	RESTORATION NO. 2 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
	63600-105	MOS	120				16-JAN-2013	**16-JAN-2023**	
25.050	L2041334	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-803	AFL							
25-64-17-350-803-03	RESTORATION NO. 3 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
	63600-105	MOS	120				16-JAN-2013	**16-JAN-2023**	
25.060	L2043722	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-803	AFL							
25-64-17-350-803-04	RESTORATION NO. 4 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
	63600-105	MOS	120				16-JAN-2013	**16-JAN-2023**	
25.060	L2041337	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-803	AFL							
25-64-17-350-803-05	RESTORATION NO. 5 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
	63600-105	MOS	120				16-JAN-2013	**16-JAN-2023**	
25.070	L2041330	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-803	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-803-06	RESTORATION NO. 6 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
	63600-105	MOS	120				16-JAN-2013	**16-JAN-2023**	
25.070	L2041339	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-803	AFL							
25-64-17-350-803-07	RESTORATION NO. 7 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
	63600-105	MOS	120				16-JAN-2013	**16-JAN-2023**	
25.080	L2041332	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-803	AFL							
25-64-17-350-803-08	RESTORATION NO. 8 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
	63600-105	MOS	120				16-JAN-2013	**16-JAN-2023**	
25.080	L2041333	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-803	AFL							
25-64-17-350-803-09	RESTORATION NO. 9 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
	63600-105	MOS	120				16-JAN-2013	**16-JAN-2023**	
25.081	L2041338	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-803	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-803-10	RESTORATION NO. 10 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
	63600-105	MOS	120				16-JAN-2013	**16-JAN-2023**	
25.081	L2041331	HRS/MSC							
OVERHAUL	**REF:** AMM 25-64-17-350-803	AFL							
+ 25-64-17-350-803-11	RESTORATION NO. 11 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
	PN	MOS					04-MAY-2007		
25.082	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 25-64-17-350-803	AFL					0		
+ 25-64-17-350-803-12	RESTORATION NO. 12 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
	NOT INSTALLED	MOS					04-MAY-2007		
25.082	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 25-64-17-350-803	AFL					0		
25-64-17-900-802-01	PILOT LIFE VEST								
	63600-505	MOS		TSN:0			07-MAY-2018		
25.045	L3986881	HRS/MSC	O/C	TSN:0			3041.8		
	REF: GENERIC CMM	AFL		TSN:0			2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-900-802-02	COPILOT LIFE VEST								
	63600-505	MOS		TSN:0			20-OCT-2016		
25.046	L3319281	HRS/MSC	O/C	TSN:0			2666.6		
	REF: GENERIC CMM	AFL		TSN:0			2066		
25-64-17-900-802-03	THIRD CREW MEMBER LIFE VEST								
	63600-505	MOS		TSN:0			20-OCT-2016		
25.047	L3319282	HRS/MSC	O/C	TSN:0			2666.6		
	REF: GENERIC CMM	AFL		TSN:0			2066		
25-64-17-900-803-01	NO. 1 PASSENGER LIFE VEST								
	63600-105	MOS		TSN:0			04-NOV-2016		
25.050	L2043744	HRS/MSC	O/C	TSN:0			2668.6		
	REF: GENERIC CMM	AFL		TSN:0			2070		
25-64-17-900-803-02	NO. 2 PASSENGER LIFE VEST								
	63600-105	MOS		TSN:0			04-NOV-2016		
25.050	L2041334	HRS/MSC	O/C	TSN:0			2668.6		
	REF: GENERIC CMM	AFL		TSN:0			2070		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-900-803-03	NO. 3 PASSENGER LIFE VEST								
	63600-105	MOS		TSN:0			04-NOV-2016		
25.060	L2043722	HRS/MSC	O/C	TSN:0			2668.6		
	REF: GENERIC CMM	AFL		TSN:0			2070		
25-64-17-900-803-04	NO. 4 PASSENGER LIFE VEST								
	63600-105	MOS		TSN:0			04-NOV-2016		
25.060	L2041337	HRS/MSC	O/C	TSN:0			2668.6		
	REF: GENERIC CMM	AFL		TSN:0			2070		
25-64-17-900-803-05	NO. 5 PASSENGER LIFE VEST								
	63600-105	MOS		TSN:0			04-NOV-2016		
25.070	L2041330	HRS/MSC	O/C	TSN:0			2668.6		
	REF: GENERIC CMM	AFL		TSN:0			2070		
25-64-17-900-803-06	NO. 6 PASSENGER LIFE VEST								
	63600-105	MOS		TSN:0			04-NOV-2016		
25.070	L2041339	HRS/MSC	O/C	TSN:0			2668.6		
	REF: GENERIC CMM	AFL		TSN:0			2070		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-900-803-07	NO. 7 PASSENGER LIFE VEST								
	63600-105	MOS		TSN:0			04-NOV-2016		
25.080	L2041332	HRS/MSC	O/C	TSN:0			2668.6		
	REF: GENERIC CMM	AFL		TSN:0			2070		
25-64-17-900-803-08	NO. 8 PASSENGER LIFE VEST								
	63600-105	MOS		TSN:0			04-NOV-2016		
25.080	L2041333	HRS/MSC	O/C	TSN:0			2668.6		
	REF: GENERIC CMM	AFL		TSN:0			2070		
25-64-17-900-803-09	NO. 9 PASSENGER LIFE VEST								
	63600-105	MOS		TSN:0			04-NOV-2016		
25.081	L2041338	HRS/MSC	O/C	TSN:0			2668.6		
	REF: GENERIC CMM	AFL		TSN:0			2070		
25-64-17-900-803-10	NO. 10 PASSENGER LIFE VEST								
	63600-105	MOS		TSN:0			04-NOV-2016		
25.081	L2041331	HRS/MSC	O/C	TSN:0			2668.6		
	REF: GENERIC CMM	AFL		TSN:0			2070		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-900-803-11	NO. 11 PASSENGER LIFE VEST								
	PN	MOS		TSN:0			13-DEC-2006		
25.082	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC CMM	AFL		TSN:0			0		
25-64-17-900-803-12	NO. 12 PASSENGER LIFE VEST								
	NOT INSTALLED	MOS		TSN:0			13-DEC-2006		
25.082	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC CMM	AFL		TSN:0			0		
25-90-18-900-801-01	ESPRESSO MAKER								
	PN	MOS		TSN:0			13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
		APH		TSN:0			0		
25-90-19-900-801-01	MICROWAVE OVEN								
	400-1338-04-L	MOS					13-DEC-2006		
	06-11-40041	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250860	AFT LAV SWITCH PANEL								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
251811	PILOT SEAT ACTUATOR								
	8260	MOS		TSN:0			13-DEC-2006		
25.030	1711	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
251812	COPILOT SEAT ACTUATOR								
	8260	MOS		TSN:0			13-DEC-2006		
25.030	1718	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
256A88	REPLACE NO. 1 LIFE RAFT #1 RAFT ELT BATTERY								
	913-FAUL-790-1-601	MOS					14-APR-2016	**01-DEC-2021 M**	
	9UL-00518	HRS/MSC	DUE				2602.4		
VENDOR RECOMMENDATION	**REF:**	AFL					1981		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256K01	FIRST AID KIT								
	500020	MOS		TSR:0			08-FEB-2010		
	011107013	HRS/MSC	O/C	TSR:0			864.5		
SEI-SUPPLEMENTAL EQUIPMENT INSTALLED	**REF:**	AFL		TSR:0			619		
259011	VHF1/ELT ANTENNAS CIRCULATOR								
	PN	MOS		TSN:0			13-DEC-2006		
25.140	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 26	**FIRE PROTECTION**								
26-10-00-720-801-01	FUNCTIONAL TEST OF THE PNEUMATIC FAN FIRE DETECTORS - ENGINE 1 FAN FIRE DETECTOR								
		MOS					13-DEC-2006		
26.010		HRS/MSC	7500/E/C				0		**7500**
	REF: AMM 26-10-00-720-801	AFL					0		
26-10-00-720-801-02	FUNCTIONAL TEST OF THE PNEUMATIC FAN FIRE DETECTORS - ENGINE 2 FAN FIRE DETECTOR								
		MOS					04-MAY-2007		
26.010		HRS/MSC	7500/E/C				0		**7500**
	REF: AMM 26-10-00-720-801	AFL					0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-10-00-720-801-03	FUNCTIONAL TEST APU FIRE DETECTOR								
	36018190040009	MOS					04-MAY-2007		
26.020	102017	HRS/MSC	C/C				0		
	REF: AMM 26-10-00-720-801	AFL					0		
		APH	5000				0	**5000**	
26-10-00-720-801-04	FUNCTIONAL TEST OF THE PNEUMATIC CORE FIRE DETECTOR - ENGINE 1 CORE FIRE DETECTOR								
		MOS					04-MAY-2007		
26.140		HRS/MSC	7500/E/C				0	**7500**	
	REF: AMM 26-10-00-720-801	AFL							
26-10-00-720-801-05	FUNCTIONAL TEST OF THE PNEUMATIC CORE FIRE DETECTOR - ENGINE 2 CORE FIRE DETECTOR								
		MOS					04-MAY-2007		
26.150		HRS/MSC	7500/E/C				0	**7500**	
	REF: AMM 26-10-00-720-801	AFL							
26-10-01-900-801-01	NO. 1 ENGINE FAN FIRE DETECTOR								
	8890-09-1000/450-18	MOS							
26.160	1360	HRS/MSC	O/C						
	REF: AMM 26-10-01-900-801	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-10-01-900-801-02	NO. 2 ENGINE FAN FIRE DETECTOR								
	8890-09-1000/450-18	MOS							
26.160	1363	HRS/MSC	O/C						
	REF: AMM 26-10-01-900-801	AFL							
26-10-05-900-801-01	NO. 1 ENGINE CORE FIRE DETECTOR								
	8890-10-1200/810-7	MOS							
26.170	1333	HRS/MSC	O/C						
	REF: AMM 26-10-05-900-801	AFL							
26-10-05-900-801-02	NO. 2 ENGINE CORE FIRE DETECTOR								
	8890-10-1200/810-7	MOS							
26.170	1368	HRS/MSC	O/C						
	REF: AMM 26-10-05-900-801	AFL							
26-10-17-720-801-01 (s)	FUNCTIONAL TEST LH MAIN LANDING GEAR (MLG) COMPARTMENT FIRE DETECTOR						PKG		
	PKG 22	MOS					16-APR-2018		
		HRS/MSC	3200				3041.8		
	REF: AMM 26-10-17-720-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-10-17-720-801-01A	FUNCTIONAL TEST LH MAIN LANDING GEAR (MLG) COMPARTMENT FIRE DETECTOR (MANDATORY 5-40)								
		MOS					16-APR-2018		
		HRS/MSC	20000				3041.8	**23041.8**	
CMR	**REF:** AMM 26-10-17-720-801	AFL					2328		
26-10-17-720-801-02 (s)	FUNCTIONAL TEST RH MAIN LANDING GEAR (MLG) COMPARTMENT FIRE DETECTOR						PKG		
	PKG 22	MOS					16-APR-2018		
		HRS/MSC	3200				3041.8		
	REF: AMM 26-10-17-720-801	AFL					2328		
26-10-17-720-801-02A	FUNCTIONAL TEST RH MAIN LANDING GEAR (MLG) COMPARTMENT FIRE DETECTOR (MANDATORY 5-40)								
		MOS					16-APR-2018		
		HRS/MSC	20000				3041.8	**23041.8**	
CMR	**REF:** AMM 26-10-17-720-801	AFL					2328		
26-10-17-900-801-01	LH MAIN LANDING GEAR COMPARTMENT FIRE DETECTOR								
	HB160	MOS		TSN:0			13-DEC-2006		
26.050	UK600	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-10-17-900-801-02	RH MAIN LANDING GEAR COMPARTMENT FIRE DETECTOR								
	HB160	MOS		TSN:0			13-DEC-2006		
26.050	UK599	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
26-10-19-900-801-01	APU FIRE DETECTOR								
	36018190040009	MOS		TSN:0			13-DEC-2006		
26.020	102017	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-19-900-801	AFL		TSN:0			0		
26-10-21-900-801-01	BAGGAGE COMPARTMENT SMOKE DETECTOR								
	FR2220	MOS		TSN:0			13-DEC-2006		
26.030	FW901	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-21-900-801	AFL		TSN:0			0		
+ 26-10-29-720-801-01 (s)	FUNCTIONAL TEST OF THE OVERHEAT PROBE						PKG		
	PKG 22	MOS					20-APR-2018		
26.200		HRS/MSC	3200	+40			3041.8		
	REF: AMM 26-10-29-720-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-10-29-900-801-01	OVERHEAT PROBE								
	RP129-02	MOS		TSN:0			13-DEC-2006		
26.180	5990	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-10-29-900-801	AFL		TSN:0			0		
26-20-00-760-801-01	INSULATION TEST NO. 1 ENGINE FIRST-SHOOT PERCUSSION (L10WB) CARTRIDGE								
	862700-00	MOS					14-APR-2016		
	SN-UNKNOWN	HRS/MSC	O/C				2602.4		
	REF: AMM 26-20-00-760-801	AFL					1981		
26-20-00-760-801-02	INSULATION TEST NO. 1 ENGINE SECOND-SHOOT PERCUSSION (R10WB) CARTRIDGE								
	862700-00	MOS					14-APR-2016		
	SN-UNKNOWN	HRS/MSC	O/C				2602.4		
	REF: AMM 26-20-00-760-801	AFL					1981		
26-20-00-760-801-03	INSULATION TEST APU PERCUSSION (11WB) CARTRIDGE								
	862700-00	MOS					14-APR-2016		
	SN-UNKNOWN	HRS/MSC	O/C				2602.4		
	REF: AMM 26-20-00-760-801	AFL					1981		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-00-760-801-04	INSULATION TEST NO. 2 ENGINE SECOND-SHOOT PERCUSSION (L20WB) CARTRIDGE								
	862710-00	MOS					14-APR-2016		
	SN-UNKNOWN	HRS/MSC	O/C				2602.4		
	REF: AMM 26-20-00-760-801	AFL					1981		
26-20-00-760-801-05	INSULATION TEST NO. 2 ENGINE FIRST-SHOOT PERCUSSION (R20WB) CARTRIDGE								
	862710-00	MOS					14-APR-2016		
	SN-UNKNOWN	HRS/MSC	O/C				2602.4		
	REF: AMM 26-20-00-760-801	AFL					1981		
26-20-01-760-801-01 (s)	CHECK OF THE CORRECT OPERATION OF THE NO.1 ENGINE DISCHARGE 1 CONTROL SWITCH						PKG		
	PKG 31	MOS	72	+2m			08-JUL-2013		
		HRS/MSC					1872.8		
	REF: AMM 26-20-01-760-801	AFL	3750				1323		
26-20-01-760-801-02 (s)	CHECK OF THE CORRECT OPERATION OF THE NO.1 ENGINE DISCHARGE 2 CONTROL SWITCH						PKG		
	PKG 31	MOS	72	+2m			08-JUL-2013		
		HRS/MSC					1872.8		
	REF: AMM 26-20-01-760-801	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-01-760-801-03 (s)	CHECK OF THE CORRECT OPERATION OF THE NO.2 ENGINE DISCHARGE 1 CONTROL SWITCH						PKG		
	PKG 31	MOS	72	+2m			08-JUL-2013		
		HRS/MSC					1872.8		
	REF: AMM 26-20-01-760-801	AFL	3750				1323		
26-20-01-760-801-04 (s)	CHECK OF THE CORRECT OPERATION OF THE NO.2 ENGINE DISCHARGE 2 CONTROL SWITCH						PKG		
	PKG 31	MOS	72	+2m			08-JUL-2013		
		HRS/MSC					1872.8		
	REF: AMM 26-20-01-760-801	AFL	3750				1323		
26-20-01-760-801-05 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL APU "DISCH 1" SWITCH/LIGHT						PKG		
	PKG 31	MOS	72	+2m			08-JUL-2013		
26.100		HRS/MSC					1872.8		
	REF: AMM 26-20-01-760-801	AFL	3750				1323		
26-20-01-900-801-01	FIRE CONTROL PANEL								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-20-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-09-220-801-01	WEIGHING NO. 1 ENGINE FIRE EXTINGUISHER									
26.080	863470-01 UE00629 **REF:** AMM 26-20-09-220-801	MOS HRS/MSC AFL	18	+3%				03-APR-2017	**03-OCT-2018**	19-OCT-2018
26-20-09-220-801-02	WEIGHING NO. 2 ENGINE FIRE EXTINGUISHER									
26.090	863470-01 UE00444 **REF:** AMM 26-20-09-220-801	MOS HRS/MSC AFL	18	+3%				07-APR-2017	**07-OCT-2018**	23-OCT-2018
26-20-09-220-801-03	WEIGHING APU FIRE EXTINGUISHER									
26.100	863470-01 UE00461 **REF:** AMM 26-20-09-220-801	MOS HRS/MSC AFL	18	+3%				07-APR-2017	**07-OCT-2018**	23-OCT-2018
26-20-09-350-801-01	RESTORATION NO. 1 ENGINE FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAUGE CALIBRATION)									
26.080 **MANDATORY**	863470-01 UE00629 **REF:** AMM 26-20-09-350-801	MOS HRS/MSC AFL	120	+3%				03-APR-2017	**03-APR-2027**	21-JUL-2027

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-09-350-801-02	RESTORATION NO. 2 ENGINE FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAUGE CALIBRATION)								
	863470-01	MOS	120	+3%			07-APR-2017	**07-APR-2027**	25-JUL-2027
26.090	UE00444	HRS/MSC							
MANDATORY	**REF:** AMM 26-20-09-350-801	AFL							
26-20-09-350-801-03	RESTORATION APU FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAUGE CALIBRATION)								
	863470-01	MOS	120	+3%			07-APR-2017	**07-APR-2027**	25-JUL-2027
26.100	UE00461	HRS/MSC							
MANDATORY	**REF:** AMM 26-20-09-350-801	AFL							
26-20-09-900-801-01	NO. 1 ENGINE FIRE EXTINGUISHER								
	863470-01	MOS		TSO:0			28-APR-2017		
26.080	UE00629	HRS/MSC	O/C	TSO:0			2775.3		
	REF: AMM 26-20-09-900-801	AFL		TSO:0			2149		
26-20-09-900-801-02	NO. 2 ENGINE FIRE EXTINGUISHER								
	863470-01	MOS		TSO:0			28-APR-2017		
26.090	UE00444	HRS/MSC	O/C	TSO:0			2775.3		
	REF: AMM 26-20-09-900-801	AFL		TSO:0			2149		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-09-900-801-03	APU FIRE EXTINGUISHER								
	863470-01	MOS		TSO:0			28-APR-2017		
26.100	UE00461	HRS/MSC	O/C	TSO:0			2775.3		
	REF: AMM 26-20-09-900-801	AFL		TSO:0			2149		
26-20-12-900-801-01	NO. 1 ENGINE SHUTTLE VALVE								
	861585	MOS		TSN:0			13-DEC-2006		
26.130	4977	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-20-12-900-801	AFL		TSN:0			0		
26-20-12-900-801-02	NO. 2 ENGINE SHUTTLE VALVE								
	861585	MOS		TSN:0			13-DEC-2006		
26.130	4978	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 26-20-12-900-801	AFL		TSN:0			0		
26-20-12-960-801-01	DISCARD NO. 1 ENGINE SHUTTLE VALVE								
	861585	MOS					13-DEC-2006		
	4977	HRS/MSC	A/R				0		
LIFE LIMIT	**REF:** AMM 26-20-12-960-801	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-12-960-801-02	DISCARD NO. 2 ENGINE SHUTTLE VALVE								
	861585	MOS					13-DEC-2006		
	4978	HRS/MSC	A/R				0		
LIFE LIMIT	**REF:** AMM 26-20-12-960-801	AFL					0		
26-20-13-900-802-01	NO. 1 ENGINE FIRST-SHOOT PERCUSSION (L10WB) CARTRIDGE								
	862700-00	MOS		TSN:0			14-APR-2016		
	SN-UNKNOWN	HRS/MSC	H/T	TSN:0			2602.4		
	REF: AMM 26-20-13-900-802	AFL		TSN:0			1981		
26-20-13-900-802-02	NO. 1 ENGINE SECOND-SHOOT PERCUSSION (R10WB) CARTRIDGE								
	862700-00	MOS		TSN:0			14-APR-2016		
	SN-UNKNOWN	HRS/MSC	H/T	TSN:0			2602.4		
	REF: AMM 26-20-13-900-802	AFL		TSN:0			1981		
26-20-13-900-802-03	NO. 2 ENGINE SECOND-SHOOT PERCUSSION (L20WB) CARTRIDGE								
	862710-00	MOS		TSN:0			14-APR-2016		
	SN-UNKNOWN	HRS/MSC	H/T	TSN:0			2602.4		
	REF: AMM 26-20-13-900-802	AFL		TSN:0			1981		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-900-802-04	NO. 2 ENGINE FIRST-SHOOT PERCUSSION (R20WB) CARTRIDGE								
	862710-00	MOS		TSN:0			14-APR-2016		
	SN-UNKNOWN	HRS/MSC	H/T	TSN:0			2602.4		
	REF: AMM 26-20-13-900-802	AFL		TSN:0			1981		
26-20-13-900-802-05	APU PERCUSSION (11WB) CARTRIDGE								
	862700-00	MOS		TSN:0			14-APR-2016		
	SN-UNKNOWN	HRS/MSC	H/T	TSN:0			2602.4		
	REF: AMM 26-20-13-900-802	AFL		TSN:0			1981		
26-20-13-960-801-01	DISCARD NO. 1 ENGINE FIRST-SHOOT PERCUSSION (L10WB) CARTRIDGE (SERVICE LIFE)								
	862700-00	MOS	120				14-APR-2016	**14-APR-2026**	
26.080	SN-UNKNOWN	HRS/MSC					2602.4		
SCRAP	**REF:** AMM 26-20-13-960-801	AFL					1981		
26-20-13-960-801-01M	DISCARD NO. 1 ENGINE FIRST-SHOOT PERCUSSION (L10WB) CARTRIDGE (LIFE LIMIT)								
	862700-00	MOS	144				09-SEP-2015	**09-SEP-2027**	
26.080	SN-UNKNOWN	HRS/MSC							
LIFE LIMIT	**REF:** AMM 26-20-13-960-801	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-960-801-02	DISCARD NO. 1 ENGINE SECOND-SHOOT PERCUSSION (R10WB) CARTRIDGE (SERVICE LIFE)								
	862700-00	MOS	120				14-APR-2016	**14-APR-2026**	
26.080	SN-UNKNOWN	HRS/MSC					2602.4		
SCRAP	**REF:** AMM 26-20-13-960-801	AFL					1981		
26-20-13-960-801-02M	DISCARD NO. 1 ENGINE SECOND-SHOOT PERCUSSION (R10WB) CARTRIDGE (LIFE LIMIT)								
	862700-00	MOS	144				09-SEP-2015	**09-SEP-2027**	
26.090	SN-UNKNOWN	HRS/MSC							
LIFE LIMIT	**REF:** AMM 26-20-13-960-801	AFL							
26-20-13-960-801-03	DISCARD NO. 2 ENGINE SECOND-SHOOT PERCUSSION (L20WB) CARTRIDGE NO. 2 ENGINE (SERVICE LIFE)								
	862710-00	MOS	120				14-APR-2016	**14-APR-2026**	
26.090	SN-UNKNOWN	HRS/MSC					2602.4		
SCRAP	**REF:** AMM 26-20-13-960-801	AFL					1981		
26-20-13-960-801-03M	REPLACE NO. 2 ENGINE SECOND-SHOOT PERCUSSION (L20WB) CARTRIDGE NO. 1 ENGINE (LIFE LIMIT)								
	862710-00	MOS	144				07-JUL-2015	**07-JUL-2027**	
26.080	SN-UNKNOWN	HRS/MSC							
LIFE LIMIT	**REF:** AMM 26-20-13-960-801	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-960-801-04	DISCARD NO. 2 ENGINE FIRST-SHOOT PERCUSSION (R20WB) CARTRIDGE (SERVICE LIFE)								
	862710-00	MOS	120				14-APR-2016	**14-APR-2026**	
26.090	SN-UNKNOWN	HRS/MSC					2602.4		
SCRAP	**REF:** AMM 26-20-13-960-801	AFL					1981		
26-20-13-960-801-04M	DISCARD NO. 2 ENGINE FIRST-SHOOT PERCUSSION (R20WB) CARTRIDGE (LIFE LIMIT)								
	862710-00	MOS	144				07-JUL-2015	**07-JUL-2027**	
26.090	SN-UNKNOWN	HRS/MSC							
LIFE LIMIT	**REF:** AMM 26-20-13-960-801	AFL							
26-20-13-960-801-05	DISCARD APU PERCUSSION (11WB) CARTRIDGE APU (SERVICE LIFE)								
	862700-00	MOS	120				14-APR-2016	**14-APR-2026**	
26.100	SN-UNKNOWN	HRS/MSC					2602.4		
SCRAP	**REF:** AMM 26-20-13-960-801	AFL					1981		
26-20-13-960-801-05M	DISCARD APU PERCUSSION (11WB) CARTRIDGE APU (LIFE LIMIT)								
	862700-00	MOS	144				09-SEP-2015	**09-SEP-2027**	
26.100	SN-UNKNOWN	HRS/MSC							
LIFE LIMIT	**REF:** AMM 26-20-13-960-801	AFL							

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-15-720-801-01	WEIGHING COCKPIT HALON PORTABLE EXTINGUISHER								
	C352	MOS					01-JAN-2017		
26.120	D-00397744	HRS/MSC	O/C						
	REF: AMM 26-20-15-720-801	AFL							
26-20-15-720-801-02	WEIGHING FORWARD HALON PORTABLE EXTINGUISHER								
	C352	MOS					01-JAN-2017		
26.110	D-00397741	HRS/MSC	O/C						
	REF: AMM 26-20-15-720-801	AFL							
26-20-15-720-801-03	WEIGHING AFT HALON PORTABLE EXTINGUISHER								
	C352	MOS					01-JAN-2017		
26.120	B-77061970	HRS/MSC	O/C						
	REF: AMM 26-20-15-720-801	AFL							
26-20-15-720-801-04	WEIGHING LAV/BAGGAGE COMPARTMENT HALON PORTABLE FIRE EXTINGUISHER								
	466090	MOS	24	+3%			11-MAY-2017	**11-MAY-2019**	02-JUN-2019
26.190	X-115299	HRS/MSC					2801.8		
	REF: AMM 26-20-15-720-801	AFL					2164		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-15-790-801-01	HYDROSTATIC TEST COCKPIT HALON PORTABLE EXTINGUISHER								
	C352	MOS	144	+3%			01-JAN-2017	**01-JAN-2029**	10-MAY-2029
26.120	D-00397744	HRS/MSC							
MANDATORY	**REF:** AMM 26-20-15-790-801	AFL							
26-20-15-790-801-02	HYDROSTATIC TEST FORWARD HALON PORTABLE EXTINGUISHER								
	C352	MOS	144	+3%			01-JAN-2017	**01-JAN-2029**	10-MAY-2029
26.110	D-00397741	HRS/MSC							
MANDATORY	**REF:** AMM 26-20-15-790-801	AFL							
26-20-15-790-801-03	HYDROSTATIC TEST AFT HALON PORTABLE EXTINGUISHER								
	C352	MOS	144	+3%			01-JAN-2016	**01-JAN-2028**	10-MAY-2028
26.120	B-77061970	HRS/MSC							
MANDATORY	**REF:** AMM 26-20-15-790-801	AFL							
26-20-15-790-801-04	HYDROSTATIC TEST LAV/BAGGAGE COMPARTMENT HALON PORTABLE FIRE EXTINGUISHER								
	466090	MOS	144	+3%			01-JAN-2017	**01-JAN-2029**	10-MAY-2029
26.190	X-115299	HRS/MSC							
	REF: AMM 26-20-15-790-801	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-19-720-801-01	WEIGHING DISPOSABLE FIRE EXTINGUISHER								
	PN NOT INSTALLED **REF:** AMM 26-20-19-720-801	MOS HRS/MSC AFL	N/A						
26-90-01-900-801-01	DISPOSABLE FIRE EXTINGUISHER								
	PN NOT INSTALLED **REF:** GENERIC NO REF	MOS HRS/MSC AFL APH	O/C						
262036	LH NO.1 ENGINE/APU MONITORING UNIT								
26.060	6342-02 1335 **REF:** GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:15.25			30-APR-2007 21.5 7		
262038	RH NO.2 ENGINE MONITORING UNIT								
26.070	6342-02 1385 **REF:** GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:15.25			30-APR-2007 21.5 7		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262081	FORWARD HALON PORTABLE EXTINGUISHER								
	C352	MOS		TSN:0			11-MAY-2017		
26.110	D-00397741	HRS/MSC	O/C	TSN:0			2801.8		
	REF: GENERIC NO REF	AFL		TSN:0			2164		
262082	AFT HALON PORTABLE EXTINGUISHER								
	C352	MOS		TSN:0			11-MAY-2017		
26.120	B-77061970	HRS/MSC	O/C	TSN:0			2801.8		
	REF: GENERIC NO REF	AFL		TSN:0			2164		
262083	COCKPIT HALON PORTABLE EXTINGUISHER								
	C352	MOS		TSN:0			11-MAY-2017		
26.120	D-00397744	HRS/MSC	O/C	TSN:0			2801.8		
	REF: GENERIC NO REF	AFL		TSN:0			2164		
262084	LAV/BAGGAGE COMPARTMENT HALON PORTABLE FIRE EXTINGUISHER								
	466090	MOS		TSN:0			21-DEC-2006		
26.190	X-115299	HRS/MSC	O/C						
	REF: GENERIC NO REF	AFL							

CHAPTER 27 FLIGHT CONTROLS

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-220-801-01A	INTEGRITY CHECK AND VISUAL INSPECTION FOR CORROSION AND EXTERNAL LEAKS ON FLIGHT CONTROL HYDRAULIC COMPONENTS (MANDATORY 5-40)								
		MOS					24-JUN-2017		
27.550		HRS/MSC	4000				2832.2	**6832.2**	
CMR	**REF:** AMM 27-00-00-220-801	AFL					2192		
27-00-00-640-801-01 (s)	PRESSURE GREASING OF THE LH AILERON SERVO-ACTUATOR						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
		HRS/MSC					0		
	REF: AMM 27-00-00-640-801	AFL	7500				0		
27-00-00-640-801-02 (s)	PRESSURE GREASING OF THE RH AILERON SERVO-ACTUATOR						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
		HRS/MSC					0		
	REF: AMM 27-00-00-640-801	AFL	7500				0		
27-00-00-640-801-03 (s)	PRESSURE GREASING OF THE RUDDER SERVO-ACTUATOR BEARINGS						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
27.025		HRS/MSC					0		
	REF: AMM 27-00-00-640-801	AFL	7500				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-640-801-04 (s)	PRESSURE GREASING OF THE ELEVATOR SERVO-ACTUATOR BEARINGS						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
27.025		HRS/MSC					0		
	REF: AMM 27-00-00-640-801	AFL	7500				0		
27-00-00-640-802-01 (s)	PRESSURE GREASING/LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN THE PRESSURIZED AREA						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
27.030		HRS/MSC					0		
	REF: AMM 27-00-00-640-802	AFL	7500				0		
27-00-00-640-802-02 (s)	PRESSURE GREASING/LUBRICATION OF FLIGHT CONTROL RODS AND BELLCRANKS BEARINGS IN NON PRESSURIZED AREA						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
27.030		HRS/MSC					0		
	REF: AMM 27-00-00-640-802	AFL	7500				0		
27-00-00-640-805-01 (s)	VISUALLY INSPECT SEALED FLIGHT CONTROL BOX						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
27.045		HRS/MSC					0		
	REF: AMM 27-00-00-640-805	AFL	7500				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-640-805-02 (s)	GREASE SEALED FLIGHT CONTROL BOX BEARINGS						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
27.045		HRS/MSC					0		
	REF: AMM 27-00-00-640-805	AFL	7500				0		
27-00-00-710-801-01 (s)	OPERATIONAL TEST NO. 1 HYDRAULIC SYSTEM FLIGHT CONTROLS						PKG		
	PKG 21	MOS					17-APR-2018		
27.005		HRS/MSC	1600	+40			3041.8		
	REF: AMM 27-00-00-710-801	AFL					2328		
27-00-00-710-801-01A	OPERATIONAL TEST NO. 1 HYDRAULIC SYSTEM FLIGHT CONTROLS (MANDATORY 5-40)								
		MOS					17-APR-2018		
27.005		HRS/MSC	1650				3041.8	**4691.8**	
CMR	**REF:** AMM 27-00-00-710-801	AFL					2328		
27-00-00-710-801-02 (s)	OPERATIONAL TEST NO. 2 HYDRAULIC SYSTEM FLIGHT CONTROLS						PKG		
	PKG 21	MOS					17-APR-2018		
27.005		HRS/MSC	1600	+40			3041.8		
	REF: AMM 27-00-00-710-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-710-801-02A	OPERATIONAL TEST NO. 2 HYDRAULIC SYSTEM FLIGHT CONTROLS (MANDATORY 5-40)								
		MOS					17-APR-2018		
27.005		HRS/MSC	1650				3041.8	**4691.8**	
CMR	**REF:** AMM 27-00-00-710-801	AFL					2328		
27-00-00-710-802-01 (s)	OPERATIONAL TEST OF THE ROLL TRIM SYSTEM						PKG		
	PKG 31	MOS	72	+2m			12-JUN-2013		
27.010		HRS/MSC					1872.8		
	REF: AMM 27-00-00-710-802	AFL	3750				1323		
27-00-00-710-802-02 (s)	OPERATIONAL TEST OF THE ROLL EMERGENCY TRIM SYSTEM						PKG		
	PKG 31	MOS	72	+2m			12-JUN-2013		
27.010		HRS/MSC					1872.8		
	REF: AMM 27-00-00-710-802	AFL	3750				1323		
27-00-00-710-802-03 (s)	OPERATIONAL TEST OF THE YAW TRIM SYSTEM						PKG		
	PKG 31	MOS	72	+2m			12-JUN-2013		
27.010		HRS/MSC					1872.8		
	REF: AMM 27-00-00-710-802	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-00-00-710-803-01 (s)	OPERATIONAL TEST OF THE SERVO-ACTUATOR ACCUMULATOR MONITORING LOGIC						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			20-APR-2018		
27.455		HRS/MSC	400	+40			3041.8		
	REF: AMM 27-00-00-710-803	AFL					2328		
27-00-00-720-804-01 (s)	INSPECTION OF LH ROLL AAFU NON-DISCONNECTION						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
		HRS/MSC					0		
	REF: AMM 27-00-00-720-804	AFL	7500				0		
27-00-00-720-804-01A	INSPECTION OF LH ROLL AAFU NON-DISCONNECTION (MANDATORY 5-40)								
		MOS					13-DEC-2006		
		HRS/MSC	10000				0	**10000**	
CMR	**REF:** AMM 27-00-00-720-804	AFL					0		
27-00-00-720-804-02 (s)	FUNCTIONAL TEST OF LH ROLL AAFU NON-DISCONNECTION						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
		HRS/MSC					0		
	REF: AMM 27-00-00-720-804	AFL	7500				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-720-804-03 (s)	INSPECTION OF RH ROLL AAFU NON-DISCONNECTION						PKG		
	PKG 32	MOS	144 +2m				13-DEC-2006		
		HRS/MSC					0		
	REF: AMM 27-00-00-720-804	AFL	7500				0		
27-00-00-720-804-03A	INSPECTION OF RH ROLL AAFU NON-DISCONNECTION (MANDATORY 5-40)								
		MOS					13-DEC-2006		
		HRS/MSC	10000				0	**10000**	
CMR	**REF:** AMM 27-00-00-720-804	AFL					0		
27-00-00-720-804-04 (s)	FUNCTIONAL TEST OF RH ROLL AAFU NON-DISCONNECTION						PKG		
	PKG 32	MOS	144 +2m				13-DEC-2006		
		HRS/MSC					0		
	REF: AMM 27-00-00-720-804	AFL	7500				0		
27-00-00-720-804-05 (s)	INSPECTION YAW AUXILIARY AFU NON DISCONNECTION						PKG		
	PKG 32	MOS	144 +2m				13-DEC-2006		
27.040		HRS/MSC					0		
	REF: AMM 27-00-00-720-804	AFL	7500				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-720-804-05A	INSPECTION YAW AUXILIARY AFU NON DISCONNECTION (MANDATORY 5-40)								
		MOS					13-DEC-2006		
27.040		HRS/MSC	10000				0		**10000**
CMR	**REF:** AMM 27-00-00-720-804	AFL					0		
27-00-00-720-804-06 (s)	FUNCTIONAL TEST OF THE YAW AAFU (20CL)						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
27.015		HRS/MSC					0		
	REF: AMM 27-00-00-720-804	AFL	7500				0		
27-00-00-720-804-07 (s)	INSPECTION PITCH AUXILIARY AFU NON DISCONNECTION						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
27.040		HRS/MSC					0		
	REF: AMM 27-00-00-720-804	AFL	7500				0		
27-00-00-720-804-07A	INSPECTION PITCH AUXILIARY AFU NON-DISCONNECTION (MANDATORY 5-40)								
		MOS					13-DEC-2006		
27.040		HRS/MSC	10000				0		**10000**
CMR	**REF:** AMM 27-00-00-720-804	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-720-804-08 (s)	FUNCTIONAL TEST OF THE PITCH AAFU (20CP)						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
27.015		HRS/MSC					0		
	REF: AMM 27-00-00-720-804	AFL	7500				0		
27-00-00-790-803-01 (s)	CHECK OF THE LH AILERON SERVO-ACTUATOR INTERNAL DAMPING						PKG		
	PKG 21	MOS					30-APR-2018		
		HRS/MSC	1600	+40			3041.8		
	REF: AMM 27-00-00-790-803	AFL					2328		
27-00-00-790-803-01A	CHECK OF THE LH AILERON SERVO-ACTUATOR INTERNAL DAMPING (MANDATORY 5-40)								
		MOS					30-APR-2018		
		HRS/MSC	1800				3041.8	**4841.8**	
CMR	**REF:** AMM 27-00-00-790-803	AFL					2328		
27-00-00-790-803-02 (s)	CHECK OF THE RH AILERON SERVO-ACTUATOR INTERNAL DAMPING						PKG		
	PKG 21	MOS					30-APR-2018		
		HRS/MSC	1600	+40			3041.8		
	REF: AMM 27-00-00-790-803	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-790-803-02A	CHECK OF THE RH AILERON SERVO-ACTUATOR INTERNAL DAMPING (MANDATORY 5-40)								
		MOS					30-APR-2018		
		HRS/MSC	1800				3041.8	**4841.8**	
CMR	**REF:** AMM 27-00-00-790-803	AFL					2328		
27-00-00-790-803-03 (s)	CHECK OF THE RUDDER SERVO-ACTUATOR INTERNAL DAMPING						PKG		
	PKG 21	MOS					30-APR-2018		
27.035		HRS/MSC	1600	+40			3041.8		
	REF: AMM 27-00-00-790-803	AFL					2328		
27-00-00-790-803-03A	CHECK RUDDER SERVO ACTUATOR INTERNAL DAMPING (MANDATORY 5-40)								
		MOS					30-APR-2018		
27.035		HRS/MSC	1800				3041.8	**4841.8**	
CMR	**REF:** AMM 27-00-00-790-803	AFL					2328		
27-00-00-790-803-04 (s)	CHECK OF THE ELEVATOR SERVO-ACTUATOR INTERNAL DAMPING						PKG		
	PKG 21	MOS					30-APR-2018		
27.035		HRS/MSC	1600	+40			3041.8		
	REF: AMM 27-00-00-790-803	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-790-803-04A	CHECK ELEVATOR SERVO ACTUATOR INTERNAL DAMPING (MANDATORY 5-40)								
		MOS					30-APR-2018		
27.035		HRS/MSC	1800				3041.8	**4841.8**	
CMR	**REF:** AMM 27-00-00-790-803	AFL					2328		
27-12-01-900-801-01	LH AILERON SERVO-ACTUATOR ACTUATOR								
	103151-05	MOS		TSN:0			13-DEC-2006		
27.130	654	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-12-01-900-801	AFL		TSN:0			0		
27-12-01-900-801-02	RH AILERON SERVO-ACTUATOR ACTUATOR								
	103151-08	MOS					14-DEC-2009		
27.130	743	HRS/MSC	O/C	TSN:344.3			802.8		
	REF: AMM 27-12-01-900-801	AFL					584		
27-13-01-640-801-01	GREASING/LUBRICATION OF THE ROLL CONTROL LINKAGE COMPONENTS IN PRESSURIZED AREA								
		MOS					13-DEC-2006		
27.085		HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-13-01-640-806-01 (s)	LUBRICATION OF THE ROLL CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA OF LEFT WING						PKG		
	PKG 31	MOS	72	+2m			20-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 27-13-01-640-806	AFL	3750				1323		
27-13-01-640-806-02 (s)	LUBRICATION OF THE ROLL CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA OF RIGHT WING						PKG		
	PKG 31	MOS	72	+2m			20-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 27-13-01-640-806	AFL	3750				1323		
27-13-01-640-808-01 (s)	GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA OF LEFT WING						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
		HRS/MSC					2832.2		
	REF: AMM 27-13-01-640-808	AFL					2192		
27-13-01-640-808-02 (s)	GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA OF RIGHT WING						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
		HRS/MSC					2832.2		
	REF: AMM 27-13-01-640-808	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-13-01-900-801-01	LH ROLL CONTROL ROD								
	FE344200000	MOS		TSN:0			13-DEC-2006		
27.500	FR408	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-13-01-900-801	AFL		TSN:0			0		
27-13-01-900-801-02	RH ROLL CONTROL ROD								
	FE344200000	MOS		TSN:0			13-DEC-2006		
27.500	FR407	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-13-01-900-801	AFL		TSN:0			0		
27-14-01-350-801-01	RESTORATION ROLL TRIM ACTUATOR (FUNCTIONAL TEST)								
	021057-37	MOS	144 +3%				04-MAY-2007	**04-MAY-2019**	13-SEP-2019
27.105	9708	HRS/MSC					0		
	REF: AMM 27-14-01-350-801	AFL					0		
27-14-01-900-801-01	ROLL TRIM ACTUATOR								
	021057-37	MOS		TSN:0			13-DEC-2006		
27.105	9708	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-14-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-14-03-350-801-01	RESTORATION EMERGENCY ROLL TRIM ACTUATOR (FUNCTIONAL TEST)								
	021127-01	MOS	144	+3%			04-MAY-2007	**04-MAY-2019**	13-SEP-2019
27.110	1110	HRS/MSC					0		
	REF: AMM 27-14-03-350-801	AFL					0		
27-14-03-900-801-01	EMERGENCY ROLL TRIM ACTUATOR								
	021127-01	MOS		TSN:0			13-DEC-2006		
27.110	1110	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-14-03-900-801	AFL		TSN:0			0		
27-14-05-720-801-01 (s)	FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAYS						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
27.095		HRS/MSC					0		
	REF: AMM 27-14-05-720-801	AFL	7500				0		
27-14-05-720-801-01A	FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAYS (MANDATORY 5-40)								
		MOS					13-DEC-2006		
27.095		HRS/MSC	20000				0		**20000**
CMR	**REF:** AMM 27-14-05-720-801	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-15-01-640-801-01 (s)	PRESSURE GREASING OF THE ROLL ARTHUR VARIABLE BELLCRANK BEARINGS						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
27.090		HRS/MSC					0		
	REF: AMM 27-15-01-640-801	AFL	7500				0		
27-15-01-720-801-01 (s)	FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK						PKG		
	PKG 31	MOS	72	+2m			08-JUL-2013		
27.090		HRS/MSC					1872.8		
	REF: AMM 27-15-01-720-801	AFL	3750				1323		
27-15-01-900-801-01	ROLL ARTHUR VARIABLE BELLCRANK								
	8421-6	MOS		TSN:0			13-DEC-2006		
27.090	1094	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-15-01-900-801	AFL		TSN:0			0		
27-15-05-350-801-01	RESTORATION ROLL MAIN (AFU) ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST/SERVICING)								
	105124	MOS	144	+3%			04-MAY-2007	**04-MAY-2019**	13-SEP-2019
27.115	739	HRS/MSC					0		
	REF: AMM 27-15-05-350-801	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-15-05-900-801-01	ROLL MAIN (AFU) ARTIFICIAL FEEL UNIT								
	105124	MOS		TSN:0			13-DEC-2006		
27.115	739	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-15-05-900-801	AFL		TSN:0			0		
27-15-07-350-801-01	RESTORATION LH AILERON AUXILIARY ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST/SERVICING)								
	105070-07	MOS	144	+3%			04-MAY-2007	**04-MAY-2019**	13-SEP-2019
27.120	1817	HRS/MSC					0		
	REF: AMM 27-15-07-350-801	AFL					0		
27-15-07-350-801-02	RESTORATION RH AILERON AUXILIARY ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST/SERVICING)								
	105070-08	MOS	144	+3%			04-MAY-2007	**04-MAY-2019**	13-SEP-2019
27.120	1824	HRS/MSC					0		
	REF: AMM 27-15-07-350-801	AFL					0		
27-15-07-640-801-01 (s)	PRESSURE GREASING OF THE LH ROLL AAFU AUXILIARY AFU BEARING						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
		HRS/MSC					0		
	REF: AMM 27-15-07-640-801	AFL	7500				0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-15-07-640-801-02 (s)	PRESSURE GREASING OF THE RH ROLL AAFU AUXILIARY AFU BEARING							PKG		
	PKG 32	MOS	144	+2m				13-DEC-2006		
		HRS/MSC						0		
	REF: AMM 27-15-07-640-801	AFL	7500					0		
		APH						0		
27-22-01-900-801-01	RUDDER SERVO-ACTUATOR ACTUATOR									
	103145-01	MOS			TSN:0			13-DEC-2006		
27.170	353	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 27-22-01-900-801	AFL			TSN:0			0		
27-23-01-640-801-01	LUBRICATION OF YAW CONTROL LINKAGE HINGES OUTSIDE PRESSURIZED AREA									
		MOS						13-DEC-2006		
27.150		HRS/MSC	O/C					0		
	REF: AMM 27-23-01-640-806	AFL						0		
27-23-01-640-803-01	GREASING/LUBRICATION OF THE YAW CONTROL HINGES IN PRESSURIZED AREA									
		MOS						13-DEC-2006		
27.155		HRS/MSC	O/C					0		
	REF: GENERIC NO REF	AFL						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-23-01-640-803-02	GREASING/LUBRICATION OF THE YAW CONTROL BALL BUSHINGS IN PRESSURIZED AREA								
		MOS					13-DEC-2006		
27.155		HRS/MSC	O/C				0		
	REF: AMM 27-23-01-640-807	AFL					0		
27-23-01-640-806-01 (s)	LUBRICATION OF THE YAW CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						PKG		
	PKG 31	MOS	72	+2m			20-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 27-23-01-640-806	AFL	3750				1323		
27-23-01-640-807-01 (s)	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA						PKG		
	PKG 31	MOS	72	+2m			20-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 27-23-01-640-807	AFL	3750				1323		
27-23-01-640-808-01 (s)	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
		HRS/MSC					2832.2		
	REF: AMM 27-23-01-640-808	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-23-01-900-801-03	YAW CONTROL (81CL) ROD								
	FE343000000	MOS		TSN:0			13-DEC-2006		
27.510	FR195	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-23-01-900-801	AFL		TSN:0			0		
27-23-01-900-801-20	LH PILOT YAW PEDAL ACTUATOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-23-01-900-801	AFL		TSN:0			0		
27-23-01-900-801-21	RH PILOT YAW PEDAL ACTUATOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-23-01-900-801	AFL		TSN:0			0		
27-23-01-900-801-22	LH COPILOT YAW PEDAL ACTUATOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-23-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-23-01-900-801-23	RH COPILOT YAW PEDAL ACTUATOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-23-01-900-801	AFL		TSN:0			0		
27-24-01-350-801-01	RESTORATION YAW TRIM ACTUATOR (FUNCTIONAL TEST)								
	021057-36	MOS	144 +3%				04-MAY-2007	**04-MAY-2019**	13-SEP-2019
27.170	5680	HRS/MSC					0		
	REF: AMM 27-24-01-350-801	AFL					0		
27-24-01-900-801-01	YAW MAIN (AFU) ARTIFICIAL FEEL UNIT								
	105125-01	MOS		TSN:0			13-DEC-2006		
27.165	745	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-24-01-900-801	AFL		TSN:0			0		
27-24-01-900-801-02	YAW TRIM ACTUATOR								
	021057-36	MOS		TSN:0			13-DEC-2006		
27.170	5680	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-24-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-24-05-720-802-01 (s)	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS							PKG		
	PKG 32	MOS	144	+2m				13-DEC-2006		
27.160		HRS/MSC						0		
	REF: AMM 27-24-05-720-802	AFL	7500					0		
27-24-05-720-802-01A	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS (MANDATORY 5-40)									
		MOS						13-DEC-2006		
27.160		HRS/MSC	20000					0	**20000**	
CMR	**REF:** AMM 27-24-05-720-802	AFL						0		
27-25-05-350-801-01	RESTORATION YAW MAIN (AFU) ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST/SERVICING)									
	105125-01	MOS	144	+3%				04-MAY-2007	**04-MAY-2019**	13-SEP-2019
27.165	745	HRS/MSC						0		
	REF: AMM 27-25-05-350-801	AFL						0		
27-25-07-350-801-01	RESTORATION YAW (AAFU) AUXILIARY ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST/SERVICING)									
	105070-06	MOS	144	+3%				04-MAY-2007	**04-MAY-2019**	13-SEP-2019
27.165	1803	HRS/MSC						0		
	REF: AMM 27-25-07-350-801	AFL						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-25-07-900-801-01	YAW (AAFU) AUXILIARY ARTIFICIAL FEEL UNIT								
	105070-06	MOS		TSN:0			13-DEC-2006		
27.165	1803	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-25-07-900-801	AFL		TSN:0			0		
27-31-01-640-801-01 (s)	GREASING OF THE PILOT CONTROL COLUMN/WHEEL						PKG		
	PKG 32	MOS	144 +2m				13-DEC-2006		
		HRS/MSC					0		
	REF: AMM 27-31-01-640-801	AFL	7500				0		
		APH					0		
27-31-01-640-801-02 (s)	GREASING OF THE COPILOT CONTROL COLUMN/WHEEL						PKG		
	PKG 32	MOS	144 +2m				13-DEC-2006		
		HRS/MSC					0		
	REF: AMM 27-31-01-640-801	AFL	7500				0		
		APH					0		
27-31-01-900-801-01	PILOT CONTROL COLUMN/WHEEL								
	VLP-402-10	MOS		TSN:0			22-FEB-2008		
27.125	125	HRS/MSC	O/C	TSN:0			303.4		
	REF: AMM 27-31-01-900-801	AFL		TSN:0			206		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-31-01-900-801-02	COPILOT CONTROL COLUMN/WHEEL								
	VLC202-10	MOS		TSN:0			13-DEC-2006		
27.125	278	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-31-01-900-801	AFL		TSN:0			0		
27-32-01-900-801-01	ELEVATOR SERVO ACTUATOR								
	103144-03	MOS					02-DEC-2009		
27.215	417	HRS/MSC	O/C	TSN:512.8			801.3		
	REF: AMM 27-32-01-900-801	AFL		TSN:383			583		
27-33-01-640-801-01	GREASING/LUBRICATION OF THE PITCH CONTROL LINKAGE COMPONENTS OUTSIDE PRESSURIZED AREA								
		MOS					13-DEC-2006		
27.185		HRS/MSC	O/C				0		
	REF: AMM 27-33-01-640-806	AFL					0		
27-33-01-640-803-01	GREASING/LUBRICATION OF THE PITCH BALL-BUSHINGS IN PRESSURIZED AREA								
		MOS					13-DEC-2006		
27.180		HRS/MSC	O/C				0		
	REF: AMM 27-33-01-640-807	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-33-01-640-804-01	GREASING/LUBRICATION OF THE PITCH CONTROL LINKAGE COMPONENTS IN PRESSURIZED AREA								
		MOS					13-DEC-2006		
27.190		HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
27-33-01-640-806-01 (s)	LUBRICATION OF THE PITCH CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						PKG		
	PKG 31	MOS	72	+2m			20-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 27-33-01-640-806	AFL	3750				1323		
27-33-01-640-807-01 (s)	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA						PKG		
	PKG 31	MOS	72	+2m			20-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 27-33-01-640-807	AFL	3750				1323		
27-33-01-900-801-03	PITCH CONTROL ROD								
	FE342000000	MOS		TSN:0			13-DEC-2006		
27.490	FR201	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-33-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-35-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PITCH ARTHUR CONTROL SYSTEM							PKG		
	PKG 22	MOS						23-APR-2018		
		HRS/MSC	3200	+40				3041.8		
	REF: AMM 27-35-00-720-801	AFL						2328		
27-35-01-640-801-01 (s)	PRESSURE GREASING OF THE PITCH ARTHUR VARIABLE BELLCRANK BEARINGS							PKG		
	PKG 32	MOS	144	+2m				28-NOV-2008		
27.195		HRS/MSC						514		
	REF: AMM 27-35-01-640-801	AFL	7500					385		
27-35-01-900-801-01	PITCH ARTHUR VARIABLE BELLCRANK									
	221150M02	MOS			TSN:0			28-NOV-2008		
27.195	390	HRS/MSC	O/C		TSN:0			514		
	REF: AMM 27-35-01-900-801	AFL			TSN:0			385		
27-35-05-350-801-01	RESTORATION PITCH MAIN (AFU) ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST/SERVICING)									
	105122-08	MOS	144	+3%				26-APR-2018	**26-APR-2030**	04-SEP-2030
27.205	1114	HRS/MSC								
	REF: AMM 27-35-05-350-801	AFL								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-35-05-710-801-01 (s)	TEST OF THE ELECTRICAL HEATING OF PITCH MAIN AFU							PKG		
	PKG 21	MOS						17-APR-2018		
27.460		HRS/MSC	1600	+40				3041.8		
	REF: AMM 27-35-05-710-801	AFL						2328		
27-35-05-900-801-01	PITCH MAIN (AFU) ARTIFICIAL FEEL UNIT									
	105122-08	MOS			TSR:1			23-MAY-2018		
27.205	1114	HRS/MSC	O/C		TSR:0			3041.8		
	REF: AMM 27-35-05-900-801	AFL			TSR:0			2328		
27-35-07-350-802-01	RESTORATION PITCH (AAFU) AUXILIARY ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST/SERVICING)									
	105045-13	MOS						13-DEC-2006		
27.210	5535	HRS/MSC	O/C					0		
	REF:	AFL						0		
		APH						0		
27-35-07-640-801-01 (s)	PRESSURE GREASING OF THE PITCH (AAFU) AUXILIARY ARTIFICIAL FEEL UNIT BEARINGS							PKG		
	PKG 32	MOS	144	+2m				02-DEC-2009		
27.210		HRS/MSC						801.3		
	REF: AMM 27-35-07-640-801	AFL	7500					583		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-35-07-900-801-01	PITCH (AAFU) AUXILIARY ARTIFICIAL FEEL UNIT									
	105045-13	MOS						02-DEC-2009		
27.210	5535	HRS/MSC	O/C		TSN:512.8			801.3		
	REF: AMM 27-35-07-900-801	AFL			TSN:383			583		
27-40-00-720-801-01 (s)	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER CONTROL AND INDICATING SYSTEM							PKG		
	PKG 21	MOS						17-APR-2018		
		HRS/MSC	1600	+40				3041.8		
	REF: AMM 27-40-00-720-801	AFL						2328		
27-40-01-210-802-01	VISUAL INSPECTION HORIZONTAL STABILIZER ELECTRIC ACTUATOR									
	021121-12	MOS	72	+3%				24-JUN-2015	**24-JUN-2021**	28-AUG-2021
27.260	1131	HRS/MSC						2409.6		
	REF: AMM 27-40-01-210-802	AFL	3750	+3%				1816	**5566**	5678.5
27-40-01-350-801-01	RESTORATION HORIZONTAL STABILIZER ELECTRIC ACTUATOR (FULL DISASSEMBLY INSPECTION/CHECK AND NDT)									
	021121-12	MOS	144	+3%				04-MAY-2007	**04-MAY-2019**	13-SEP-2019
27.260	1131	HRS/MSC						801.3		
OVERHAUL	**REF:** AMM 27-40-01-350-801	AFL	7500	+3%	TSI:0			583	**7700**	7925

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40-01-350-801-01A	RESTORATION OF THE HORIZONTAL STABILIZER ELECTRIC ACTUATOR (FULL DISASSEMBLY INSPECTION/CHECK AND NDT) (MANDATORY 5-40)								
		MOS					13-DEC-2006		
		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 27-40-01-350-801	AFL	7725				0	**7725**	
		APH					0		
27-40-01-640-802-01 (s)	GREASING OF THE HORIZONTAL STABILIZER ACTUATOR HINGES AND JACK SCREW						PKG		
	PKG 2 ,31,39	MOS	16	+1m			18-APR-2018		
27.235		HRS/MSC	800	+40			3041.8		
	REF: AMM 27-40-01-640-802	AFL					2328		
27-40-01-900-801-01	HORIZONTAL STABILIZER ELECTRIC ACTUATOR								
	021121-12	MOS		TSR:0			02-DEC-2009		
27.260	1131	HRS/MSC	O/C	TSN:512.8 TSR:0			801.3		
	REF: AMM 27-40-01-900-801	AFL		TSN:383 TSR:0			583		
27-40-03-900-801-01	NORMAL MOTOR OF THE HORIZONTAL STABLIZER ACTUATOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-40-03-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40-05-900-801-01	HORIZONTAL STABILIZER POSITION REPEATER BOX BOX									
	016095-02	MOS						02-DEC-2009		
27.275	672	HRS/MSC	O/C		TSN:512.8			801.3		
	REF: AMM 27-40-05-900-801	AFL			TSN:383			583		
27-40-15-710-801-01 (s)	OPERATIONAL TEST OF THE RELAY IN THE HORIZONTAL STABILIZER EMERGENCY CONTROL BOX							PKG		
	PKG 32	MOS	144	+2m				13-DEC-2006		
27.270		HRS/MSC						0		
	REF: AMM 27-40-15-710-801	AFL	7500					0		
27-40-15-710-801-01A	OPERATIONAL TEST OF THE RELAY IN THE HORIZONTAL STABILIZER EMERGENCY CONTROL BOX (MANDATORY 5-40)									
		MOS						13-DEC-2006		
27.270		HRS/MSC	16000					0	**16000**	
CMR	**REF:** AMM 27-40-15-710-801	AFL						0		
27-40-17-720-801-01 (s)	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX							PKG		
	PKG 23	MOS						13-DEC-2006		
27.255		HRS/MSC	4800	+40				0		
	REF: AMM 27-40-17-720-801	AFL						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40-17-720-801-01A	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX (MANDATORY 5-40)								
		MOS					13-DEC-2006		
27.255		HRS/MSC	5000				0	**5000**	
CMR	**REF:** AMM 27-40-17-720-801	AFL					0		
27-50-00-640-801-01 (s)	GREASING/LUBRICATION OF FLAP MECHANISMS						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			17-APR-2018		
27.675		HRS/MSC	400	+40			3041.8		
	REF:	AFL					2328		
27-50-00-710-801-01	OPERATIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM								
		MOS					02-APR-2012		
27.305		HRS/MSC	O/C				1495.4		
	REF: AMM 27-50-00-710-801	AFL					1032		
27-50-00-720-801-02	FUNCTIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM - USING THE STAND-BY ELECTRICAL PUMP								
		MOS							
		HRS/MSC	O/C						
	REF: AMM 27-50-00-720-801	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50-00-720-802-01 (s)	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				17-APR-2018		
27.295		HRS/MSC	400	+40				3041.8		
	REF: AMM 27-50-00-720-802	AFL						2328		
27-50-00-720-802-01A	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM (MANDATORY 5-40)									
		MOS						17-APR-2018		
27.295		HRS/MSC	450					3041.8	**3491.8**	
CMR	**REF:** AMM 27-50-00-720-802	AFL						2328		
27-50-00-720-803-01 (s)	CHECK OF THE GEAR BACKLASH OF FLAP LINKAGE							PKG		
	PKG 21	MOS						16-APR-2018		
		HRS/MSC	1600	+40				3041.8		
	REF: AMM 27-50-00-720-803	AFL						2328		
27-51-09-820-801-01	ADJUSTMENT OF THE LH FLAP POSITION POTENTIOMETER									
		MOS						13-DEC-2006		
		HRS/MSC	A/R					0		
	REF: AMM 27-51-09-820-801	AFL						0		
		APH						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-09-820-801-02	ADJUSTMENT OF THE RH FLAP POSITION POTENTIOMETER								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 27-51-09-820-801	AFL					0		
		APH					0		
27-52-01-900-801-01	FLAP POWER DRIVE UNIT								
	5-4440-6	MOS		TSN:0			13-DEC-2006		
27.325	763	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-52-01-900-801	AFL		TSN:0			0		
27-52-13-200-801-01 (s)	CHECK/GREASING OF FLAP CONTROL ROD SPLINES						PKG		
	PKG 31	MOS	72	+2m			20-JUN-2013		
27.320		HRS/MSC					1872.8		
	REF: AMM 27-52-13-200-801	AFL	3750				1323		
27-53-01-220-801-01 (s)	CLEANING/CHECK OF THE LH OUTBOARD FLAP SCREW JACK						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			17-APR-2018		
27.685		HRS/MSC	400	+40			3041.8		
	REF: AMM 27-53-01-220-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-220-801-02 (s)	CLEANING/CHECK OF THE LH INBOARD FLAP LATERAL SCREW JACK						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			17-APR-2018		
27.685		HRS/MSC	400	+40			3041.8		
	REF: AMM 27-53-01-220-801	AFL					2328		
27-53-01-220-801-03 (s)	CLEANING/CHECK OF THE LH INBOARD FLAP CENTER SCREW JACK						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			17-APR-2018		
27.685		HRS/MSC	400	+40			3041.8		
	REF: AMM 27-53-01-220-801	AFL					2328		
27-53-01-220-801-04 (s)	CLEANING/CHECK OF THE RH INBOARD FLAP CENTER SCREW JACK						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			17-APR-2018		
27.685		HRS/MSC	400	+40			3041.8		
	REF: AMM 27-53-01-220-801	AFL					2328		
27-53-01-220-801-05 (s)	CLEANING/CHECK OF THE RH INBOARD FLAP LATERAL SCREW JACK						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			17-APR-2018		
27.685		HRS/MSC	400	+40			3041.8		
	REF: AMM 27-53-01-220-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-220-801-06 (s)	CLEANING/CHECK OF THE RH OUTBOARD FLAP SCREW JACK							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				17-APR-2018		
27.685		HRS/MSC	400	+40				3041.8		
	REF: AMM 27-53-01-220-801	AFL						2328		
27-53-01-350-801-01	RESTORATION LH OUTBOARD FLAP SCREW JACK ACTUATOR (OVERHAUL) (MANDATORY 5-40)									
	1-5319-3	MOS						04-MAY-2007		
27.310	735	HRS/MSC								
MANDATORY 5-40	**REF:** AMM 27-53-01-350-801	AFL	4500					0	**4500**	
27-53-01-350-801-02	RESTORATION LH INBOARD FLAP LATERAL SCREW JACK ACTUATOR (OVERHAUL) (MANDATORY 5-40)									
	5318-3	MOS						04-MAY-2007		
27.315	2612	HRS/MSC								
MANDATORY 5-40	**REF:** AMM 27-53-01-350-801	AFL	3500					0	**3500**	
27-53-01-350-801-03	RESTORATION LH INBOARD FLAP CENTER SCREW JACK ACTUATOR (OVERHAUL) (MANDATORY 5-40)									
	5318-3	MOS						04-MAY-2007		
27.470	2614	HRS/MSC								
MANDATORY 5-40	**REF:** AMM 27-53-01-350-801	AFL	3500					0	**3500**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-350-801-04	RESTORATION RH INBOARD FLAP CENTER SCREW JACK ACTUATOR (OVERHAUL) (MANDATORY 5-40)								
	5318-3	MOS					04-MAY-2007		
27.470	2613	HRS/MSC							
MANDATORY 5-40	**REF:** AMM 27-53-01-350-801	AFL	3500				0	**3500**	
27-53-01-350-801-05	RESTORATION RH INBOARD FLAP LATERAL SCREW JACK ACTUATOR (OVERHAUL) (MANDATORY 5-40)								
	5318-3	MOS					04-MAY-2007		
27.315	2615	HRS/MSC							
MANDATORY 5-40	**REF:** AMM 27-53-01-350-801	AFL	3500				0	**3500**	
27-53-01-350-801-06	RESTORATION RH OUTBOARD FLAP SCREW JACK ACTUATOR (OVERHAUL) (MANDATORY 5-40)								
	2-5319-3	MOS					04-MAY-2007		
27.310	736	HRS/MSC							
MANDATORY 5-40	**REF:** AMM 27-53-01-350-801	AFL	4500				0	**4500**	
27-53-01-640-803-01 (s)	GREASING OF LH OUTBOARD FLAP SCREW JACK						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			17-APR-2018		
		HRS/MSC	400	+40			3041.8		
	REF: AMM 27-53-01-640-803	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-640-803-02 (s)	GREASING OF LH INBOARD FLAP LATERAL SCREW JACK							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				17-APR-2018		
		HRS/MSC	400	+40				3041.8		
	REF: AMM 27-53-01-640-803	AFL						2328		
27-53-01-640-803-03 (s)	GREASING OF LH INBOARD FLAP CENTER SCREW JACK							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				17-APR-2018		
		HRS/MSC	400	+40				3041.8		
	REF: AMM 27-53-01-640-803	AFL						2328		
27-53-01-640-803-04 (s)	GREASING OF RH INBOARD FLAP CENTER SCREW JACK							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				17-APR-2018		
		HRS/MSC	400	+40				3041.8		
	REF: AMM 27-53-01-640-803	AFL						2328		
27-53-01-640-803-05 (s)	GREASING OF RH INBOARD FLAP LATERAL SCREW JACK							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				17-APR-2018		
		HRS/MSC	400	+40				3041.8		
	REF: AMM 27-53-01-640-803	AFL						2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-640-803-06 (s)	GREASING OF RH OUTBOARD FLAP SCREW JACK						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			17-APR-2018		
		HRS/MSC	400	+40			3041.8		
	REF: AMM 27-53-01-640-803	AFL					2328		
27-53-01-720-803-01	CHECK LH OUTBOARD FLAP SCREW JACK ACTUATOR SCREW/NUT PLAY (MANDATORY 5-40)								
	1-5319-3	MOS					13-DEC-2006		
27.310	735	HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 27-53-01-720-803	AFL	3000				0	**3000**	
27-53-01-720-803-02	CHECK LH INBOARD FLAP LATERAL SCREW JACK ACTUATOR SCREW/NUT PLAY (MANDATORY 5-40)								
	5318-3	MOS					13-DEC-2006		
27.315	2612	HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 27-53-01-720-803	AFL	3000				0	**3000**	
27-53-01-720-803-03	CHECK LH INBOARD FLAP CENTER SCREW JACK ACTUATOR SCREW/NUT PLAY (MANDATORY 5-40)								
	5318-3	MOS					13-DEC-2006		
27.470	2614	HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 27-53-01-720-803	AFL	3000				0	**3000**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-720-803-04	CHECK RH INBOARD FLAP CENTER SCREW JACK ACTUATOR SCREW/NUT PLAY (MANDATORY 5-40)								
	5318-3	MOS					13-DEC-2006		
27.470	2613	HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 27-53-01-720-803	AFL	3000				0	**3000**	
27-53-01-720-803-05	CHECK RH INBOARD FLAP LATERAL SCREW JACK ACTUATOR SCREW/NUT PLAY (MANDATORY 5-40)								
	5318-3	MOS					13-DEC-2006		
27.315	2615	HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 27-53-01-720-803	AFL	3000				0	**3000**	
27-53-01-720-803-06	CHECK RH OUTBOARD FLAP SCREW JACK ACTUATOR SCREW/NUT PLAY (MANDATORY 5-40)								
	2-5319-3	MOS					13-DEC-2006		
27.310	736	HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 27-53-01-720-803	AFL	3000				0	**3000**	
27-53-01-900-803-01	LH OUTBOARD FLAP SCREW JACK ACTUATOR								
	1-5319-3	MOS		TSN:0			13-DEC-2006		
27.310	735	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-53-01-900-803	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-900-803-02	LH INBOARD FLAP LATERAL SCREW JACK ACTUATOR								
	5318-3	MOS		TSN:0			13-DEC-2006		
27.315	2612	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-53-01-900-803	AFL		TSN:0			0		
27-53-01-900-803-03	LH INBOARD FLAP CENTER SCREW JACK ACTUATOR								
	5318-3	MOS		TSN:0			13-DEC-2006		
27.470	2614	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-53-01-900-803	AFL		TSN:0			0		
27-53-01-900-803-04	RH INBOARD FLAP CENTER SCREW JACK ACTUATOR								
	5318-3	MOS		TSN:0			13-DEC-2006		
27.470	2613	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-53-01-900-803	AFL		TSN:0			0		
27-53-01-900-803-05	RH INBOARD FLAP LATERAL SCREW JACK ACTUATOR								
	5318-3	MOS		TSN:0			13-DEC-2006		
27.315	2615	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-53-01-900-803	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-900-803-06	RH OUTBOARD FLAP SCREW JACK ACTUATOR								
	2-5319-3	MOS		TSN:0			13-DEC-2006		
27.310	736	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-53-01-900-803	AFL		TSN:0			0		
27-53-01-960-801-01	DISCARD LH OUTBOARD FLAP SCREW JACK ACTUATOR								
	1-5319-3	MOS					04-MAY-2007		
27.310	735	HRS/MSC							
LIFE LIMIT	**REF:** AMM 27-53-01-960-801	AFL	16000				0		**16000**
27-53-01-960-801-02	DISCARD LH INBOARD FLAP LATERAL SCREW JACK ACTUATOR								
	5318-3	MOS					04-MAY-2007		
27.315	2612	HRS/MSC							
LIFE LIMIT	**REF:** AMM 27-53-01-960-801	AFL	15000				0		**15000**
27-53-01-960-801-03	DISCARD LH INBOARD FLAP CENTER SCREW JACK ACTUATOR								
	5318-3	MOS					04-MAY-2007		
27.470	2614	HRS/MSC							
LIFE LIMIT	**REF:** AMM 27-53-01-960-801	AFL	15000				0		**15000**

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-960-801-04	DISCARD RH INBOARD FLAP CENTER SCREW JACK ACTUATOR								
	5318-3	MOS					04-MAY-2007		
27.470	2613	HRS/MSC							
LIFE LIMIT	**REF:** AMM 27-53-01-960-801	AFL	15000				0	**15000**	
27-53-01-960-801-05	DISCARD RH INBOARD FLAP LATERAL SCREW JACK ACTUATOR								
	5318-3	MOS					04-MAY-2007		
27.315	2615	HRS/MSC							
LIFE LIMIT	**REF:** AMM 27-53-01-960-801	AFL	15000				0	**15000**	
27-53-01-960-801-06	DISCARD RH OUTBOARD FLAP SCREW JACK ACTUATOR								
	2-5319-3	MOS					04-MAY-2007		
27.310	736	HRS/MSC							
LIFE LIMIT	**REF:** AMM 27-53-01-960-801	AFL	16000				0	**16000**	
27-60-00-710-801-01 (s)	OPERATIONAL TEST OF THE AIRBRAKES IN NORMAL MODE						PKG		
	PKG 21	MOS					17-APR-2018		
27.350		HRS/MSC	1600	+40			3041.8		
	REF: AMM 27-60-00-710-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-61-00-720-801-01 (s)	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT ("BSCU HARDWARE" RELAY)						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			17-APR-2018		
27.300		HRS/MSC	400	+40			3041.8		
	REF: AMM 27-61-00-720-801	AFL					2328		
27-61-00-720-801-01A	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT ("BSCU HARDWARE" RELAY) (MANDATORY 5-40)								
		MOS					17-APR-2018		
27.300		HRS/MSC	440				3041.8	**3481.8**	
CMR	**REF:** AMM 27-61-00-720-801	AFL					2328		
27-61-00-720-802-01 (s)	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT ("LH THROTTLE" AND "RH THROTTLE" RELAYS)						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			17-APR-2018		
27.475		HRS/MSC	400	+40			3041.8		
	REF: AMM 27-61-00-720-802	AFL					2328		
27-61-00-720-802-01A	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT("LH THROTTLE" AND "RH THROTTLE" RELAYS) (MANDATORY 5-40)								
		MOS					17-APR-2018		
27.475		HRS/MSC	440				3041.8	**3481.8**	
CMR	**REF:** AMM 27-61-00-720-802	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-61-00-720-803-01 (s)	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT ("BSCU SOFTWARE" RELAY) SOFTWARE RELAYS OF AUTO AIRBRAKE PCB							PKG		
	PKG 3 ,31	MOS	24	+1m				24-JUN-2017		
27.480		HRS/MSC	1200	+40				2832.2		
	REF: AMM 27-61-00-720-803	AFL						2192		
27-61-00-720-803-01A	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT ("BSCU SOFTWARE" RELAY) SOFTWARE RELAYS OF AUTO AIRBRAKE PCB (MANDATORY 5-40)									
		MOS						24-JUN-2017		
27.480		HRS/MSC	1240					2832.2	**4072.2**	
CMR	**REF:** AMM 27-61-00-720-803	AFL						2192		
27-61-00-720-804-01	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT ("WOW " AND "SEFL-HOLDING" RELAYS)									
		MOS						13-DEC-2006		
		HRS/MSC	O/C					0		
	REF: AMM 27-61-00-720-804	AFL						0		
		APH						0		
27-61-00-720-806-01 (s)	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT (MONITORING SYSTEM)							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				17-APR-2018		
27.485		HRS/MSC	400	+40				3041.8		
	REF: AMM 27-61-00-720-806	AFL						2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-61-00-720-806-01A	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT (MONITORING SYSTEM) (MANDATORY 5-40)								
		MOS					17-APR-2018		
27.485		HRS/MSC	440				3041.8	**3481.8**	
CMR	**REF:** AMM 27-61-00-720-806	AFL					2328		
27-61-01-900-801-01	LEFT OUTBOARD AIRBRAKE MICROSWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
27-61-01-900-801-02	LEFT CENTER AIRBRAKE MICROSWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
27-61-01-900-801-03	LEFT INBOARD AIRBRAKE MICROSWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-61-01-900-801-04	RIGHT INBOARD AIRBRAKE MICROSWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
27-61-01-900-801-05	RIGHT CENTER AIRBRAKE MICROSWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
27-61-01-900-801-06	RIGHT OUTBOARD AIRBRAKE MICROSWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
27-62-01-900-801-01	LH OUTBOARD AIRBRAKE ACTUATOR								
	106091-07	MOS		TSN:0			13-DEC-2006		
27.355	7633	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-62-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-62-01-900-801-02	LH MIDDLE AIRBRAKE ACTUATOR								
	106091-08	MOS		TSN:0			13-DEC-2006		
27.355	7625	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-62-01-900-801	AFL		TSN:0			0		
27-62-01-900-801-03	LH INBOARD AIRBRAKE ACTUATOR								
	106091-09	MOS		TSN:0			13-DEC-2006		
27.355	7603	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-62-01-900-801	AFL		TSN:0			0		
27-62-01-900-801-04	RH INBOARD AIRBRAKE ACTUATOR								
	106091-09	MOS		TSN:0			13-DEC-2006		
27.360	7604	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-62-01-900-801	AFL		TSN:0			0		
27-62-01-900-801-05	RH MIDDLE AIRBRAKE ACTUATOR								
	106091-08	MOS		TSN:0			13-DEC-2006		
27.360	7634	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-62-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-62-01-900-801-06	RH OUTBOARD AIRBRAKE ACTUATOR								
	106091-07	MOS		TSN:0			13-DEC-2006		
27.360	7658	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-62-01-900-801	AFL		TSN:0			0		
27-80-00-710-807-01 (s)	OPERATIONAL TEST OF SLAT EXTENSION THROUGH LH OUTBOARD SOLENOID						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			25-MAY-2018		
		HRS/MSC	400	+40			3041.8		
	REF: AMM 27-80-00-710-807	AFL					2328		
27-80-00-710-807-01A	OPERATIONAL TEST OF SLAT EXTENSION THROUGH LH OUTBOARD SOLENOID (MANDATORY 5-40)								
		MOS					25-MAY-2018		
		HRS/MSC	O/C				3041.8		
CMR	**REF:** AMM 27-80-00-710-807	AFL					2328		
27-80-00-710-808-01 (s)	OPERATIONAL TEST OF THE SLAT EXTENDED POSITION MICROSWITCHES - LH OUTBOARD SLAT EXTENDED MICROSWITCH (L210CM)						PKG		
	PKG 22	MOS					25-MAY-2018		
		HRS/MSC	3200	+40			3041.8		
	REF: AMM 27-80-00-710-808	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-00-710-808-01A	OPERATIONAL TEST OF THE SLAT EXTENDED POSITION MICROSWITCHES - LH OUTBOARD SLAT EXTENDED MICROSWITCH (L210CM) (MANDATORY 5-40)								
		MOS					25-MAY-2018		
		HRS/MSC	O/C				3041.8		
CMR	**REF:** AMM 27-80-00-710-808	AFL					2328		
27-80-00-710-808-02 (s)	OPERATIONAL TEST OF THE SLAT EXTENDED POSITION MICROSWITCHES - LH INBOARD SLAT EXTENDED MICROSWITCH (L240CM)						PKG		
	PKG 22	MOS					25-MAY-2018		
		HRS/MSC	3200				3041.8		
	REF: AMM 27-80-00-710-808	AFL					2328		
27-80-00-710-808-02A	OPERATIONAL TEST OF THE SLAT EXTENDED POSITION MICROSWITCHES - LH INBOARD SLAT EXTENDED MICROSWITCH (L240CM) (MANDATORY 5-40)								
		MOS					25-MAY-2018		
		HRS/MSC	O/C				3041.8		
CMR	**REF:** AMM 27-80-00-710-808	AFL					2328		
27-80-00-710-808-03 (s)	OPERATIONAL TEST OF THE SLAT EXTENDED POSITION MICROSWITCHES - RH INBOARD SLAT EXTENDED MICROSWITCH (R240CM)						PKG		
	PKG 22	MOS					25-MAY-2018		
		HRS/MSC	3200				3041.8		
	REF: AMM 27-80-00-710-808	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-00-710-808-03A	OPERATIONAL TEST OF THE SLAT EXTENDED POSITION MICROSWITCHES - RH INBOARD SLAT EXTENDED MICROSWITCH (R240CM) (MANDATORY 5-40)								
		MOS					25-MAY-2018		
		HRS/MSC	O/C				3041.8		
CMR	**REF:** AMM 27-80-00-710-808	AFL					2328		
27-80-00-710-808-04 (s)	OPERATIONAL TEST OF THE SLAT EXTENDED POSITION MICROSWITCHES - RH OUTBOARD SLAT EXTENDED MICROSWITCH (R210CM)						PKG		
	PKG 22	MOS					25-MAY-2018		
		HRS/MSC	3200				3041.8		
	REF: AMM 27-80-00-710-808	AFL					2328		
27-80-00-710-808-04A	OPERATIONAL TEST OF THE SLAT EXTENDED POSITION MICROSWITCHES - RH OUTBOARD SLAT EXTENDED MICROSWITCH (R210CM) (MANDATORY 5-40)								
		MOS					25-MAY-2018		
		HRS/MSC	O/C				3041.8		
CMR	**REF:** AMM 27-80-00-710-808	AFL					2328		
27-80-00-720-801-01 (s)	FUNCTIONAL TEST OF THE SLATS NORMAL MODE						PKG		
	PKG 21	MOS					17-APR-2018		
		HRS/MSC	1600	+40			3041.8		
	REF: See Workcard	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-00-720-801-01A	FUNCTIONAL TEST OF THE SLATS NORMAL MODE (MANDATORY 5-40)								
		MOS					17-APR-2018		
		HRS/MSC	1800				3041.8	**4841.8**	
CMR	**REF:** See Workcard	AFL					2328		
27-80-00-720-801-02 (s)	FUNCTIONAL TEST OF THE SLATS AUTOMATIC MODE						PKG		
	PKG 21	MOS					20-APR-2018		
		HRS/MSC	1600 +40				3041.8		
	REF: See Workcard	AFL					2328		
27-80-00-720-801-02A	FUNCTIONAL TEST OF THE SLATS AUTOMATIC MODE (MANDATORY 5-40)								
		MOS					20-APR-2018		
		HRS/MSC	1800				3041.8	**4841.8**	
CMR	**REF:** See Workcard	AFL					2328		
27-80-00-720-801-03 (s)	FUNCTIONAL TEST OF THE SLATS EMERGENCY MODE						PKG		
	PKG 21	MOS					20-APR-2018		
		HRS/MSC	1600 +40				3041.8		
	REF: See Workcard	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-00-720-801-03A	FUNCTIONAL TEST OF THE SLATS EMERGENCY MODE (MANDATORY 5-40)								
		MOS					20-APR-2018		
		HRS/MSC	1800				3041.8	**4841.8**	
CMR	**REF:** See Workcard	AFL					2328		
27-80-01-350-801-01	RESTORATION OUTBOARD SLATS MANIFOLD (INSPECTION)								
	108143-01	MOS	144	+131d			15-JUN-2015	**15-JUN-2027**	24-OCT-2027
27.420	372	HRS/MSC							
	REF:	AFL							
27-80-05-900-801-01	LH OUTBOARD SLAT OUTBOARD ACTUATOR								
	106132-08	MOS		TSN:0			13-DEC-2006		
27.430	5265	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801	AFL		TSN:0			0		
27-80-05-900-801-02	RH OUTBOARD SLAT OUTBOARD ACTUATOR								
	106132-06	MOS		TSN:0			13-DEC-2006		
27.435	5292	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-05-900-801-03	LH OUTBOARD SLAT INBOARD ACTUATOR								
	106132-06	MOS		TSN:0			13-DEC-2006		
27.430	5291	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801	AFL		TSN:0			0		
27-80-05-900-801-04	RH OUTBOARD SLAT INBOARD ACTUATOR								
	106132-08	MOS		TSN:0			22-FEB-2008		
27.435	6159	HRS/MSC	O/C	TSN:0			303.4		
	REF: AMM 27-80-05-900-801	AFL		TSN:0			206		
27-80-05-900-801-05	LH OUTBOARD SLAT EMERGENCY ACTUATOR								
	106132-07	MOS		TSN:0			13-DEC-2006		
27.440	5298	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801	AFL		TSN:0			0		
27-80-05-900-801-06	RH OUTBOARD SLAT EMERGENCY ACTUATOR								
	106132-07	MOS		TSN:0			13-DEC-2006		
27.440	5299	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-05-900-801-07	LH INBOARD SLAT ACTUATOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801	AFL		TSN:0			0		
27-80-05-900-801-08	RH INBOARD SLAT ACTUATOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801	AFL		TSN:0			0		
27-80-17-720-801-01 (s)	FUNCTIONAL TEST OF THE LH SLAT EXTENDED POSITION MICROSWITCH						PKG		
	PKG 22	MOS					23-APR-2018		
27.405		HRS/MSC	3200	+40			3041.8		
	REF: AMM 27-80-17-720-801	AFL					2328		
27-80-17-720-801-02 (s)	FUNCTIONAL TEST OF THE LH SLAT RETRACTED POSITION MICROSWITCH						PKG		
	PKG 22	MOS					23-APR-2018		
27.405		HRS/MSC	3200	+40			3041.8		
	REF: AMM 27-80-17-720-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-17-720-801-03 (s)	FUNCTIONAL TEST OF THE RH SLAT EXTENDED POSITION MICROSWITCH						PKG		
	PKG 22	MOS					23-APR-2018		
27.405		HRS/MSC	3200	+40			3041.8		
	REF: AMM 27-80-17-720-801	AFL					2328		
27-80-17-720-801-04 (s)	FUNCTIONAL TEST OF THE RH SLAT RETRACTED POSITION MICROSWITCH						PKG		
	PKG 22	MOS					23-APR-2018		
27.405		HRS/MSC	3200	+40			3041.8		
	REF: AMM 27-80-17-720-801	AFL					2328		
27-80-17-720-801-05	FUNCTIONAL TEST OF THE LH SLAT EXTENDED POSITION MICROSWITCH								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 27-80-17-720-801	AFL					0		
27-80-17-720-801-06	FUNCTIONAL TEST OF THE LH SLAT RETRACTED POSITION MICROSWITCH								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 27-80-17-720-801	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-17-720-801-07	FUNCTIONAL TEST OF THE RH SLAT EXTENDED POSITION MICROSWITCH								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 27-80-17-720-801	AFL					0		
27-80-17-720-801-08	FUNCTIONAL TEST OF THE RH SLAT RETRACTED POSITION MICROSWITCH								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 27-80-17-720-801	AFL					0		
27-80-23-720-801-01	FUNCTIONAL TEST OF THE INBOARD SLAT VALVE BOX								
		MOS	144				13-DEC-2006	**13-DEC-2018**	
		HRS/MSC					0		
	REF: AMM 27-80-23-720-801	AFL					0		
270801	TRIM CONTROL BOX								
	013015-18	MOS		TSN:0			13-DEC-2006		
27.050	2130	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-00-00-640-805	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270811	PILOT PEDAL ASSEMBLY								
	FE230-001	MOS		TSN:0			13-DEC-2006		
27.060	FR356	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
270816	COPILOT PEDAL ASSEMBLY								
	FE213-003	MOS		TSN:0			13-DEC-2006		
27.060	FR616	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
270831	PILOT PEDAL ADJUSTMENT ROD BOX								
	4505-1	MOS		TSN:0			13-DEC-2006		
27.070	1803	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
270841	COPILOT PEDAL ADJUSTMENT ROD BOX								
	4505-1	MOS		TSN:0			13-DEC-2006		
27.070	1802	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270846	SLAT/FLAP CONTROL BOX								
	7-7061	MOS		TSN:0			13-DEC-2006		
27.100	1028	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-00-00-640-805	AFL		TSN:0			0		
271191	LH AILERON AUXILIARY ARTIFICIAL FEEL UNIT								
	105070-07	MOS		TSN:0			13-DEC-2006		
27.120	1817	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
271192	RH AILERON AUXILIARY ARTIFICIAL FEEL UNIT								
	105070-08	MOS		TSN:0			13-DEC-2006		
27.120	1824	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
272811	LH PILOT YAW BAR POSITION ADJUSTMENT FLEXIBLE CONTROL								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272812	RH PILOT YAW BAR POSITION ADJUSTMENT FLEXIBLE CONTROL								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
272813	LH COPILOT YAW BAR POSITION ADJUSTMENT FLEXIBLE CONTROL								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
272814	RH COPILOT YAW BAR POSITION ADJUSTMENT FLEXIBLE CONTROL								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
273801	LH CONTROL COLUMN - STICK ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-31-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273802	RH CONTROL COLUMN - STICK ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-31-01-900-801	AFL		TSN:0			0		
273806	ELEVATOR ARTHUR CONTROL BOX								
	PN	MOS		TSN:0			13-DEC-2006		
27.220	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-00-00-640-805	AFL		TSN:0			0		
275801	LH LEFT FLAP DUAL TRANSFER GEARBOX								
	1-5593	MOS		TSN:0			13-DEC-2006		
27.330	759	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
275811	RH RIGHT FLAP DUAL TRANSFER GEARBOX								
	2-5593	MOS		TSN:0			13-DEC-2006		
27.330	750	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275821	LEFT FLAP POSITION TRANSMITTER								
	1-4414-2	MOS		TSN:0			13-DEC-2006		
27.335	1414	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
275831	RIGHT FLAP POSITION TRANSMITTER								
	2-4414-2	MOS		TSN:0			13-DEC-2006		
27.335	1151	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
275841	LH FLAP INTERMEDIATE TRANSMISSION								
	5592	MOS		TSN:0			13-DEC-2006		
27.140	1371	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
275846	RH FLAP INTERMEDIATE TRANSMISSION								
	5592	MOS		TSN:0			13-DEC-2006		
27.140	1372	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276801	AIRBRAKE/EMERGENCY SLATS MANIFOLD								
	71365-1	MOS		TSN:0			13-DEC-2006		
27.365	364	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-80-01-900-801	AFL		TSN:0			0		
276806	AIRBRAKE PRESSURE HOLDING VALVE								
	D25AB1704	MOS		TSN:0			13-DEC-2006		
27.370	621	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
276811	AIRBRAKE PRESSURE GAUGE								
	GP12-105	MOS		TSN:0			13-DEC-2006		
27.375	03-1216172	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
276816	CHARGING VALVE								
	PN	MOS		TSN:0			13-DEC-2006		
27.380	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276821	LH OUTBOARD AIRBRAKE RESTRICTOR								
	C24370-402	MOS		TSN:0			13-DEC-2006		
27.385	H3253	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
276826	LH MIDDLE AIRBRAKE RESTRICTOR								
	C24370-302	MOS		TSN:0			13-DEC-2006		
27.385	H3162	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
276831	LH INBOARD AIRBRAKE RESTRICTOR								
	C24370-202	MOS		TSN:0			13-DEC-2006		
27.385	H3096	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
276836	RH INBOARD AIRBRAKE RESTRICTOR								
	C24370-202	MOS		TSN:0			13-DEC-2006		
27.390	H3097	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276841	RH MIDDLE AIRBRAKE RESTRICTOR								
	C24370-302	MOS		TSN:0			13-DEC-2006		
27.390	H3161	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
276846	RH OUTBOARD AIRBRAKE RESTRICTOR								
	C24370-402	MOS		TSN:0			13-DEC-2006		
27.390	H3252	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
278821	INBOARD SLAT VALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
278825	INBOARD SLATS VALVE BOX								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-80-23-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
278831	LH INBOARD SLAT ACTUATOR ADJUSTABLE VALVE ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
278832	RH INBOARD SLAT ACTUATOR ADJUSTABLE RESTRICTOR VALVE ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
278841	LH SLAT EMERGENCY ACTUATOR ONE-WAY RESTRICTOR VALVE								
	FGFB756380A2	MOS		TSN:0			13-DEC-2006		
27.445	MA1524	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
278846	RH SLAT EMERGENCY ACTUATOR ONE-WAY RESTRICTOR VALVE								
	FGFB756380A2	MOS		TSN:0			13-DEC-2006		
27.445	MA1525	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
278851	LH SLAT ACTUATOR ADJUSTABLE RESTRICTOR								
	C24370-102	MOS		TSN:0			13-DEC-2006		
27.450	H3003	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
278856	RH SLAT ACTUATOR ADJUSTABLE RESTRICTOR								
	C24370-102	MOS		TSN:0			13-DEC-2006		
27.450	H3009	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
278861	OUTBOARD SLATS MANIFOLD								
	108143-01	MOS		TSR:0		08/18/2017	18-AUG-2015		
27.420	372	HRS/MSC	O/C	TSN:5505 TSR:0			2449.8		
	REF: AMM 27-80-01-900-801	AFL		TSN:3006 TSR:0			1849		
CHAPTER 28	**FUEL**								
28-00-00-280-801-01 (s)	CHECK FOR NON-CONTAMINATION OF THE FUEL						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			18-MAY-2018		
28.140		HRS/MSC	400	+40			3041.8		
	REF: AMM 28-00-00-280-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-00-290-801-01	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH FEEDER TANK								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		
28-00-00-290-801-02	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH FEEDER TANK								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		
28-00-00-290-801-03	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH CENTER-WING TANK								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		
28-00-00-290-801-04	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH CENTER-WING TANK								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-00-290-801-05	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE REAR TANK								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		
28-00-00-290-801-06	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH WING TANK								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		
28-00-00-290-801-07	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH WING TANK								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		
28-00-00-910-803-01	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - FUEL INJECTION METHOD								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 28-00-00-910-803	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-00-910-803-02	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - GRAVITY POURING METHOD								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 28-00-00-910-803	AFL					0		
28-00-00-910-803-03	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - FUEL INJECTION METHOD								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 28-00-00-910-803	AFL					0		
28-00-00-910-803-04	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - GRAVITY POURING METHOD								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 28-00-00-910-803	AFL					0		
28-00-00-910-803-05	DECONTAMINATION OF THE FUEL SYSTEMS - INSPECTION OF FEEDER TANKS								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 28-00-00-910-803	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-00-910-803-06	DECONTAMINATION OF THE FUEL SYSTEMS - CLEANING / REPLACEMENT OF FILTERS								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 28-00-00-910-803	AFL					0		
28-00-00-910-803-07	DECONTAMINATION OF THE FUEL SYSTEMS - CLEANING OF FUEL TANKS								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 28-00-00-910-803	AFL					0		
28-00-00-910-804-01	ACCOMPLISH MEASURES TO BE TAKEN AFTER MAINTENANCE OPERATIONS IN THE FUEL TANKS								
		MOS					13-DEC-2006		
28.630		HRS/MSC	A/R				0		
	REF: AMM 28-00-00-910-804	AFL					0		
		APH					0		
28-10-00-280-801-01 (s)	SPECIAL DETAILED INSPECTION OF THE FUEL TANK FLAPPER VALVES						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
28.020		HRS/MSC					0		
	REF: AMM 28-10-00-280-801	AFL	7500				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-00-100-801-01 (s)	CLEANING OF THE LH CROSSFEED UNIT FILTER							PKG		
	PKG 2 ,31,39	MOS	16	+1m				25-APR-2018		
28.671		HRS/MSC	800	+40				3041.8		
	REF: AMM 28-21-00-100-801	AFL						2328		
28-21-00-100-801-02 (s)	CLEANING OF THE RH CROSSFEED UNIT FILTER							PKG		
	PKG 2 ,31,39	MOS	16	+1m				25-APR-2018		
28.671		HRS/MSC	800	+40				3041.8		
	REF: AMM 28-21-00-100-801	AFL						2328		
28-21-00-100-801-03 (s)	CLEANING OF THE RH REAR TRANSFER VALVE FILTER							PKG		
	PKG 2 ,31,39	MOS	16	+1m				25-APR-2018		
28.671		HRS/MSC	800	+40				3041.8		
	REF: AMM 28-21-00-100-801	AFL						2328		
28-21-00-100-801-04 (s)	CLEANING OF THE LH REAR TRANSFER VALVE FILTER							PKG		
	PKG 2 ,31,39	MOS	16	+1m				25-APR-2018		
28.671		HRS/MSC	800	+40				3041.8		
	REF: AMM 28-21-00-100-801	AFL						2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-00-100-801-05 (s)	CLEANING OF THE FRONT TRANSFER VALVE FILTER							PKG		
	PKG 2 ,31,39	MOS	16	+1m				25-APR-2018		
28.671		HRS/MSC	800	+40				3041.8		
	REF: AMM 28-21-00-100-801	AFL						2328		
28-21-01-900-801-01	LH STAND-BY BOOSTER PUMP									
	P99C31-601	MOS			TSN:0			13-DEC-2006		
28.250	C50771	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-21-01-900-801	AFL			TSN:0			0		
28-21-01-900-801-02	RH STAND-BY BOOSTER PUMP									
	P99C31-601	MOS			TSN:0			13-DEC-2006		
28.250	C50772	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-21-01-900-801	AFL			TSN:0			0		
28-21-01-900-801-03	LH NORMAL BOOSTER PUMP									
	P99C31-601	MOS			TSN:0			13-DEC-2006		
28.540	C50769	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-21-01-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU)	NEXT DUE A/C	MAX LIMIT
28-21-01-900-801-04	RH NORMAL BOOSTER PUMP										
	P99C31-601	MOS			TSN:0			13-DEC-2006			
28.540	C50770	HRS/MSC	O/C		TSN:0			0			
	REF: AMM 28-21-01-900-801	AFL			TSN:0			0			
28-21-13-710-801-01 (s)	OPERATIONAL TEST OF THE NO. 1 ENGINE FUEL SHUT-OFF VALVE							PKG			
	PKG 31	MOS	72	+2m				13-JUN-2013			
76.030		HRS/MSC						1872.8			
	REF: AMM 28-21-13-710-801	AFL	3750					1323			
28-21-13-710-801-02 (s)	OPERATIONAL TEST OF THE NO. 2 ENGINE FUEL SHUT-OFF VALVE							PKG			
	PKG 31	MOS	72	+2m				13-JUN-2013			
76.030		HRS/MSC						1872.8			
	REF: AMM 28-21-13-710-801	AFL	3750					1323			
28-21-13-720-801-01	FUNCTIONAL TEST NO. 1 ENGINE FUEL SHUT-OFF VALVE MANIFOLD THERMAL EXPANSION										
	B97-31-652	MOS						13-DEC-2006			
28.270	C38663	HRS/MSC	10000	+3%				0	**10000**		10300
	REF: AMM 28-21-13-720-801	AFL						0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-13-720-801-02	FUNCTIONAL TEST NO. 2 ENGINE FUEL SHUT-OFF VALVE MANIFOLD THERMAL EXPANSION									
	B97-31-652	MOS						13-DEC-2006		
28.270	C38662	HRS/MSC	10000	+3%				0	**10000**	10300
	REF: AMM 28-21-13-720-801	AFL						0		
28-21-13-900-802-01	LH ENGINE FUEL SHUT-OFF VALVE ACTUATOR									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-21-13-900-802	AFL			TSN:0			0		
28-21-13-900-802-02	RH ENGINE FUEL SHUT-OFF VALVE ACTUATOR									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-21-13-900-802	AFL			TSN:0			0		
28-21-13-900-803-01	NO. 1 ENGINE FUEL SHUT-OFF VALVE									
	B97-31-652	MOS			TSN:0			13-DEC-2006		
76.030	C38663	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-21-13-900-803	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-13-900-803-02	NO. 2 ENGINE FUEL SHUT-OFF VALVE								
	B97-31-652	MOS		TSN:0			13-DEC-2006		
76.030	C38662	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-21-13-900-803	AFL		TSN:0			0		
28-21-17-790-801-01	SEALING TEST OF THE APU FUEL SHUTOFF VALVE								
		MOS					13-DEC-2006		
49.010		HRS/MSC	C/C				0		
	REF: AMM 28-21-17-790-801	AFL					0		
28-21-17-900-801-01	APU FUEL SHUT-OFF VALVE								
	B97-31-659	MOS		TSR:0			28-NOV-2008		
28.490	C26433	HRS/MSC	O/C	TSN:492 TSR:0			514		
	REF: AMM 28-21-17-900-801	AFL		TSR:0			385		
28-21-19-790-801-01	LEAK CHECK OF THE FRONT TRANSFER VALVE CANISTER						PKG		
	PKG 39	MOS					03-APR-2012		
28.671		HRS/MSC	N/A				1495.4		
	REF: AMM 28-21-19-790-801	AFL					1032		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-19-790-801-02	LEAK CHECK OF THE LH REAR TRANSFER VALVE CANISTER							PKG		
	PKG 39	MOS						03-APR-2012		
28.671		HRS/MSC	N/A					1495.4		
	REF: AMM 28-21-19-790-801	AFL						1032		
28-21-19-790-801-03	LEAK CHECK OF THE RH REAR TRANSFER VALVE CANISTER							PKG		
	PKG 39	MOS						03-APR-2012		
28.671		HRS/MSC	N/A					1495.4		
	REF: AMM 28-21-19-790-801	AFL						1032		
28-21-25-710-801-01 (s)	OPERATIONAL TEST OF THE CROSSFEED UNITS							PKG		
	PKG 2 ,31	MOS	16	+1m				17-APR-2018		
28.240		HRS/MSC	800	+40				3041.8		
	REF: AMM 28-21-25-710-801	AFL						2328		
28-21-25-900-801-01	LH CROSSFEED UNIT									
	L88A31-672	MOS			TSN:0			13-DEC-2006		
28.270	C50453	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-21-25-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-25-900-801-02	RH CROSSFEED UNIT								
	L88A31-666-2	MOS		TSN:0			13-DEC-2006		
28.270	C46713	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-21-25-900-801	AFL		TSN:0			0		
28-21-27-900-801-01	LH CROSSFEED UNIT ACTUATOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-21-27-900-801	AFL		TSN:0			0		
28-21-27-900-801-02	RH CROSSFEED UNIT ACTUATOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-21-27-900-801	AFL		TSN:0			0		
28-22-01-900-801-01	TANK INTERCONNECTION VALVE								
	L87B63-653	MOS		TSN:0			13-DEC-2006		
28.220	C26678	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-22-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-30-00-680-802-01	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE LH TANK GROUP								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 28-30-00-680-802	AFL					0		
28-30-00-680-802-02	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE RH TANK GROUP								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 28-30-00-680-802	AFL					0		
28-30-00-680-802-03	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - FUEL SAMPLING								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 28-30-00-680-802	AFL					0		
28-30-00-680-802-04	PERFORM FUEL TANK SUMP DRAINING								
		MOS	2	+5d			25-APR-2018	**25-JUN-2018**	30-JUN-2018
		HRS/MSC					3041.8		
	REF:	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-30-00-680-802-05	PERFORM LEAK CHECK OF THE FUEL TANK DRY BAY									
		MOS	2	+5d				25-APR-2018	**25-JUN-2018**	30-JUN-2018
		HRS/MSC						3041.8		
	REF: AMM 28-30-00-680-802	AFL						2328		
28-30-11-960-802-01	DISCARD OF THE FUEL DRAIN CAPS									
		MOS						13-DEC-2006		
		HRS/MSC	O/C					0		
	REF:	AFL						0		
28-41-00-720-801-01 (s)	FUNCTIONAL TEST OF THE LH FUEL QUANTITY INDICATOR							PKG		
	PKG 22	MOS						17-APR-2018		
		HRS/MSC	3200	+40				3041.8		
	REF: AMM 28-41-00-720-801	AFL						2328		
28-41-00-720-801-02 (s)	FUNCTIONAL TEST OF THE RH FUEL QUANTITY INDICATOR							PKG		
	PKG 22	MOS						17-APR-2018		
		HRS/MSC	3200	+40				3041.8		
	REF: AMM 28-41-00-720-801	AFL						2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-01-900-801-01	FUEL QUANTITY MANAGEMENT (FQMC) COMPUTER								
	738325-1-8	MOS		TSR:0			13-SEP-2010		
28.360	00246	HRS/MSC	O/C	TSN:796 TSR:0			1040.9		
	REF: AMM 28-41-01-900-801	AFL		TSR:0			737		
28-41-05-900-801-01	LH FEEDER TANK GAUGE								
	764936-1-0	MOS		TSN:0			13-DEC-2006		
28.310	481	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-05-900-801	AFL		TSN:0			0		
28-41-05-900-801-02	RH FEEDER TANK GAUGE								
	764936-1-0	MOS		TSN:0			13-DEC-2006		
28.310	480	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-05-900-801	AFL		TSN:0			0		
28-41-05-900-801-03	LH CENTERWING TANK GAUGE								
	764935-3-0	MOS		TSN:0			13-DEC-2006		
28.320	512	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-05-900-801-04	RH CENTERWING TANK GAUGE								
	764935-3-0	MOS		TSN:0			13-DEC-2006		
28.320	511	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-05-900-801	AFL		TSN:0			0		
28-41-05-900-801-05	REAR TANK FRONT GAUGE								
	762401-1-0	MOS		TSN:0			13-DEC-2006		
28.550	244	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-05-900-801	AFL		TSN:0			0		
28-41-05-900-801-06	FRONT TANK REAR GAUGE								
	762-081-2-0	MOS		TSN:0			13-DEC-2006		
28.560	0243	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-05-900-801	AFL		TSN:0			0		
28-41-05-900-801-07	REAR TANK REAR GAUGE								
	762083-1-0	MOS		TSN:0			13-DEC-2006		
28.550	280	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-05-900-801-08	FRONT TANK FRONT GAUGE								
	762-400-1-0	MOS		TSN:0			13-DEC-2006		
28.560	0219	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-05-900-801	AFL		TSN:0			0		
28-41-05-900-801-09	REAR TANK HIGH LEVEL SENSOR								
	722810-1-0	MOS		TSN:0			13-DEC-2006		
28.570	222	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-05-900-801	AFL		TSN:0			0		
28-41-09-900-801-01	LH INBOARD FUEL QUANTITY GAUGE								
	764934-1-0	MOS		TSN:0			13-DEC-2006		
28.300	0489	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-09-900-801	AFL		TSN:0			0		
28-41-09-900-801-02	RH INBOARD FUEL QUANTITY GAUGE								
	764934-1-0	MOS		TSN:0			13-DEC-2006		
28.330	0490	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-41-09-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-09-900-801-03	LH MIDDLE FUEL QUANTITY GAUGE								
	764933-1-0	MOS		TSN:0		04/28/2018	28-APR-2016		
28.300	1636	HRS/MSC	O/C	TSN:0			2617.9		
	REF: AMM 28-41-09-900-801	AFL		TSN:0			2002		
28-41-09-900-801-04	RH MIDDLE FUEL QUANTITY GAUGE								
	764933-1-0	MOS		TSN:14			12-SEP-2016		
28.330	1725	HRS/MSC	O/C	TSN:0			2656.1		
	REF: AMM 28-41-09-900-801	AFL		TSN:0			2052		
28-41-09-900-801-05	LH OUTBOARD FUEL QUANTITY GAUGE								
	764932-1-0	MOS		TSN:0			01-DEC-2015		
28.300	1659	HRS/MSC	O/C	TSN:0			2534.6		
	REF: AMM 28-41-09-900-801	AFL		TSN:0			1921		
28-41-09-900-801-06	RH OUTBOARD FUEL QUANTITY GAUGE								
	764932-1-0	MOS					16-NOV-2015		
28.330	0494	HRS/MSC	O/C	TSN:2534.6			2534.6		
	REF: AMM 28-41-09-900-801	AFL		TSN:1921			1921		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-43-01-720-801-01 (s)	FUNCTIONAL TEST OF THE FUEL TEMPERATURE PROBE SENSOR							PKG		
	PKG 31	MOS	72	+2m				13-JUN-2013		
28.620		HRS/MSC						1872.8		
	REF: AMM 28-43-01-720-801	AFL	3750					1323		
28-50-01-900-801-01	(RCP) REFUELING CONTROL PANEL									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-50-01-900-801	AFL			TSN:0			0		
28-70-05-790-801-01	SEALING TEST PRESSURE REDUCING VALVE FUNCTION									
	B14DE2080	MOS						02-MAY-2009		
28.170	753	HRS/MSC	7500	+3%				617.1	**8117.1**	8342.1
	REF: AMM 28-70-05-790-801	AFL						460		
28-70-05-900-801-01	PRESSURE REDUCING VALVE									
	B14DE2080	MOS			TSO:0			02-MAY-2009		
28.170	753	HRS/MSC	O/C		TSN:1167 TSO:0			617.1		
	REF: AMM 28-70-05-900-801	AFL			TSN:624 TSO:0			460		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-70-09-350-801-01	RESTORATION LH VALVE BOX (FILTER CLEANING AND CALIBRATION CHECK)									
	B04BA1005	MOS						13-DEC-2006		
28.180	1878	HRS/MSC	5000	+3%				0	**5000**	5150
	REF: AMM 28-70-09-350-801	AFL						0		
28-70-09-350-801-02	RESTORATION RH VALVE BOX (FILTER CLEANING AND CALIBRATION CHECK)									
	B04BA1005	MOS						13-DEC-2006		
28.180	1879	HRS/MSC	5000	+3%				0	**5000**	5150
	REF: AMM 28-70-09-350-801	AFL						0		
28-70-09-900-801-01	LH VALVE BOX									
	B04BA1005	MOS			TSN:0			13-DEC-2006		
	1878	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-70-09-900-801	AFL			TSN:0			0		
28-70-09-900-801-02	RH VALVE BOX									
	B04BA1005	MOS			TSN:0			13-DEC-2006		
	1879	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-70-09-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-70-13-350-801-01	RESTORATION LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (AIR FLOW AND PRESSURE DROP TEST/LEAK TEST)								
	B06GA1051	MOS					(EBT)		
	2614	HRS/MSC	O/C						
	REF: AMM 28-70-13-350-801	AFL							
28-70-13-350-801-02	RESTORATION RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (AIR FLOW AND PRESSURE DROP TEST/LEAK TEST)								
	B06GA1051	MOS					(EBT)		
	2588	HRS/MSC	O/C						
	REF: AMM 28-70-13-350-801	AFL							
28-70-13-720-802-01	FUNCTIONAL TEST LH WING TANK NEGATIVE PRESSURE RELIEF VALVE								
	B06GA1051	MOS					13-DEC-2006		
28.150	2614	HRS/MSC	5000	+3%			0	**5000**	5150
	REF: AMM 28-70-13-720-802	AFL					0		
28-70-13-720-802-02	FUNCTIONAL TEST RH WING TANK NEGATIVE PRESSURE RELIEF VALVE								
	B06GA1051	MOS					13-DEC-2006		
28.150	2588	HRS/MSC	5000	+3%			0	**5000**	5150
	REF: AMM 28-70-13-720-802	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-70-13-900-801-01	LH WING TANK NEGATIVE PRESSURE RELIEF VALVE									
	B06GA1051	MOS			TSN:0			13-DEC-2006		
28.150	2614	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-70-13-900-801	AFL			TSN:0			0		
28-70-13-900-801-02	RH WING TANK NEGATIVE PRESSURE RELIEF VALVE									
	B06GA1051	MOS			TSN:0			13-DEC-2006		
28.150	2588	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-70-13-900-801	AFL			TSN:0			0		
28-70-17-130-801-01 (s)	CLEANING OF FUEL TANK PRESSURIZATION AIR FILTERS							PKG		
	PKG 21	MOS						16-APR-2018		
28.120		HRS/MSC	1600	+40				3041.8		
	REF: AMM 28-70-17-130-801	AFL						2328		
28-70-17-700-801-01 (s)	CHECK OF THE LH FUEL NON RETURN VALVE FOR JAMMING							PKG		
	PKG 31	MOS	72	+2m				20-JUN-2013		
		HRS/MSC						1872.8		
	REF: AMM 28-70-17-700-801	AFL	3750					1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-70-17-700-801-02 (s)	CHECK OF THE RH FUEL NON RETURN VALVE FOR JAMMING							PKG		
	PKG 31	MOS	72	+2m				20-JUN-2013		
		HRS/MSC						1872.8		
	REF: AMM 28-70-17-700-801	AFL	3750					1323		
28-70-21-900-801-01	LH VENT VALVE									
	B97N38-653	MOS			TSN:0			13-DEC-2006		
28.070	C48898	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-70-21-900-801	AFL			TSN:0			0		
28-70-21-900-801-02	RH VENT VALVE									
	B97N38-653	MOS			TSN:0			13-DEC-2006		
28.070	C48908	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-70-21-900-801	AFL			TSN:0			0		
28-70-21-900-801-03	REAR VENT VALVE									
	B97N38-653	MOS			TSN:0			13-DEC-2006		
28.450	C48905	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 28-70-21-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281801	FRONT TANK								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281802	REAR TANK								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281806	LEFT WING ELECTRICAL REFUELING VALVE								
	L94Z31-201	MOS		TSN:0			13-DEC-2006		
28.040	C49538	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-50-09-900-801	AFL		TSN:0			0		
281807	CENTER TANK LEFT HAND ELECTRICAL REFUELING VALVE								
	L94Z31-201	MOS		TSN:0			13-DEC-2006		
28.400	C49539	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-50-09-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281810	REFUELING FILLER CONNECTOR								
	K97-51-202	MOS		TSN:0			13-DEC-2006		
28.030	C450868	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281811	RIGHT WING ELECTRICAL REFUELING VALVE								
	L94Z31-201	MOS		TSN:0			13-DEC-2006		
28.040	C49537	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-50-09-900-801	AFL		TSN:0			0		
281812	CENTER TANK RIGHT HAND ELECTRICAL REFUELING VALVE								
	L94Z31-201	MOS		TSN:0			13-DEC-2006		
28.400	C49536	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-50-09-900-801	AFL		TSN:0			0		
281816	LEFT WING FUELING NON-RETURN VALVE								
	L96Z31-201	MOS		TSN:0			13-DEC-2006		
28.050	C45514	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281817	CENTER TANK LEFT HAND FUELING NON-RETURN VALVE								
	L96Z31-201	MOS		TSN:0			13-DEC-2006		
28.410	C36841	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281821	RIGHT WING FUELING NON-RETURN VALVE								
	L96Z31-201	MOS		TSN:0			13-DEC-2006		
28.050	C45513	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281822	CENTER TANK RIGHT HAND FUELING NON-RETURN VALVE								
	L96Z31-201	MOS		TSN:0			13-DEC-2006		
28.410	C40226	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281824	NON RETURN VALVE								
	L85-25-002	MOS		TSN:0			13-DEC-2006		
28.420	B91859	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281826	FUELING PANEL								
	798977-1-1	MOS		TSN:0			13-DEC-2006		
28.060	221	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281832	TANK REFUELING UNIT								
	K99-31-013	MOS		TSN:0			13-DEC-2006		
28.430	B90996	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281834	REAR TANK FUEL REAR DRAIN VALVE								
	142D12-1	MOS					18-JUN-2013		
28.440	F68012	HRS/MSC	O/C				1872.8		
	REF: GENERIC NO REF	AFL					1323		
281835	REAR TANK FUEL FRONT DRAIN VALVE								
	142D12-1	MOS					18-JUN-2013		
28.600	F84143	HRS/MSC	O/C				1872.8		
	REF: GENERIC NO REF	AFL					1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281846	FRONT TANK JET PUMP								
	C17AR0011	MOS		TSN:0			13-DEC-2006		
28.460	2244	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281847	REAR TANK FRONT JET PUMP								
	C17AR0011	MOS		TSN:0			13-DEC-2006		
28.470	2245	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281848	REAR TANK REAR JET PUMP								
	C17AR0011	MOS		TSN:0			13-DEC-2006		
28.480	2246	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281851	LEFT WING OUTBOARD JET-PUMP								
	C17AR0011	MOS		TSN:0			13-DEC-2006		
28.080	2247	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281856	RIGHT WING OUTBOARD JET-PUMP								
	C17AR0011	MOS		TSN:0			13-DEC-2006		
28.080	2248	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281861	LEFT WING TANK CENTRAL JET-PUMP								
	C17AQ0011	MOS		TSN:0			13-DEC-2006		
28.090	6042	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281866	RIGHT WING TANK CENTRAL JET-PUMP								
	C17AQ0011	MOS		TSN:0			13-DEC-2006		
28.090	6035	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281871	LEFT WING INBOARD JET-PUMP								
	C17AQ0011	MOS		TSN:0			13-DEC-2006		
28.100	6034	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281876	RIGHT WING INBOARD JET-PUMP								
	C17AQ0011	MOS		TSN:0			13-DEC-2006		
28.110	6030	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281881	LEFT WING CENTER JET-PUMP								
	C17AQ0011	MOS		TSN:0			13-DEC-2006		
28.100	6031	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
281886	RIGHT WING CENTER JET-PUMP								
	C17AQ0011	MOS		TSN:0			13-DEC-2006		
28.110	6032	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
282801	SUCTION DEFUELING VALVE								
	L88A31-680	MOS		TSN:0			13-DEC-2006		
28.190	C50805	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282806	LH FUEL NON-RETURN VALVE								
	L96Z19-003	MOS		TSN:0			13-DEC-2006		
28.200	C50394	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
282811	RH FUEL NON-RETURN VALVE								
	L96Z19-003	MOS		TSN:0			13-DEC-2006		
28.200	C50381	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
282816	FUEL PRESSURIZATION AIR FILTER								
	018500AA000NF0A	MOS		TSN:0			13-DEC-2006		
28.210	M200870030	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
282821	REAR TANK LEFT VALVE FILTER								
	L92B13-604	MOS		TSN:0			13-DEC-2006		
28.500	C41916	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282822	REAR TANK LEFT FILTERING VALVE HOUSING								
	C93R13-603	MOS		TSN:0			13-DEC-2006		
28.510	C30512	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
282831	REAR TANK RIGHT VALVE FILTER								
	L92B13-604	MOS		TSN:0			13-DEC-2006		
28.500	C41917	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
282832	REAR TANK RIGHT FILTERING VALVE HOUSING								
	C93R13-603	MOS		TSN:0			13-DEC-2006		
28.510	C30510	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
282841	FRONT TANK VALVE FILTER								
	L92B13-604	MOS		TSN:0			13-DEC-2006		
28.520	C41918	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282842	FRONT TANK FILTERING VALVE HOUSING								
	C93R13-603	MOS		TSN:0			13-DEC-2006		
28.530	C30511	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
283041	SIDE TANK GROUP INTERCONNECTION VALVE CONTROL PISTON								
	PN	MOS		TSN:0			13-DEC-2006		
28.260	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
283801	LH FUEL STAND-BY BOOSTER PUMP CANISTER								
	C93R31-601	MOS		TSN:0			13-DEC-2006		
28.280	C46862	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-21-04-900-801	AFL		TSN:0			0		
283811	RH FUEL STAND-BY BOOSTER PUMP CANISTER								
	C93R31-601	MOS		TSN:0			13-DEC-2006		
28.280	C46869	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-21-04-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
283821	LH FUEL BOOSTER PUMP CANISTER								
	C93R31-601	MOS		TSN:0			13-DEC-2006		
28.580	C46861	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-21-04-900-801	AFL		TSN:0			0		
283826	RH FUEL BOOSTER PUMP CANISTER								
	C93R31-601	MOS		TSN:0			13-DEC-2006		
28.580	C46870	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-21-04-900-801	AFL		TSN:0			0		
283850	SUCTION DEFUELING VALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
284801	FUEL TEMPERATURE PROBE								
	798840-1-0	MOS		TSN:0			13-DEC-2006		
28.590	00913	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284820	FUEL LOW LEVEL DETECTION BOX								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
285801	FUEL PRESSURE GAUGE								
	MPMC50701-01	MOS		TSN:0			13-DEC-2006		
28.340	875	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
287021	LEFT WING FUEL DRAIN VALVE								
	142D12-1	MOS		TSN:0			23-SEP-2016		
28.370	E25441	HRS/MSC	O/C	TSN:0			2664.6		
	REF: GENERIC NO REF	AFL		TSN:0			2062		
287022	RIGHT WING FUEL DRAIN VALVE								
	142D12-1	MOS					18-JUN-2013		
28.370	F68021	HRS/MSC	O/C				1872.8		
	REF: GENERIC NO REF	AFL					1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
287023	LEFT CENTER WING AFT DRAIN VALVE								
	142G12-32	MOS					18-JUN-2013		
28.380	H06179	HRS/MSC	O/C				1872.8		
	REF: GENERIC NO REF	AFL					1323		
287024	RIGHT CENTER WING AFT DRAIN VALVE								
	142G12-32	MOS					18-JUN-2013		
28.380	F94203	HRS/MSC	O/C				1872.8		
	REF: GENERIC NO REF	AFL					1323		
287025	CENTER WING FORWARD DRAIN VALVE								
	142G12-32	MOS					18-JUN-2013		
28.390	F94202	HRS/MSC	O/C				1872.8		
	REF: GENERIC NO REF	AFL					1323		
287026	CENTER WING MIDDLE DRAIN VALVE								
	142G12-32	MOS					18-JUN-2013		
28.390	H06181	HRS/MSC	O/C				1872.8		
	REF: GENERIC NO REF	AFL					1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
287027	FORWARD TANK FUEL FRONT DRAIN VALVE								
	142G12-32	MOS					18-JUN-2013		
28.610	F85592	HRS/MSC	O/C				1872.8		
	REF: GENERIC NO REF	AFL					1323		
287028	FORWARD TANK FUEL REAR DRAIN VALVE								
	142G12-32	MOS					18-JUN-2013		
28.610	H06178	HRS/MSC	O/C				1872.8		
	REF: GENERIC NO REF	AFL					1323		
CHAPTER 29	**HYDRAULIC POWER**								
29-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE MAIN HYDRAULIC SYSTEM 1						PKG		
	PKG 31	MOS	72 +2m				09-JUL-2013		
29.030		HRS/MSC					1872.8		
	REF: AMM 29-10-00-720-801	AFL	3750				1323		
29-10-00-720-801-02 (s)	FUNCTIONAL TEST OF THE MAIN HYDRAULIC SYSTEM 2						PKG		
	PKG 31	MOS	72 +2m				09-JUL-2013		
29.030		HRS/MSC					1872.8		
	REF: AMM 29-10-00-720-801	AFL	3750				1323		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-11-01-350-801-01	RESTORATION NO. 1 ENGINE HYDRAULIC NO. 1 SYSTEM PUMP (OVERHAUL)								
	3031749-001	MOS					11-JUN-2015		
29.050	MX603223	HRS/MSC	4000	+3%			2406.8	**6406.8**	6526.8
OVERHAUL	**REF:** AMM 29-11-01-350-801	AFL					1811		
29-11-01-350-801-02	RESTORATION NO. 2 ENGINE HYDRAULIC NO. 1 SYSTEM PUMP (OVERHAUL)								
	3031749-001	MOS					11-JUN-2015		
29.050	MX664861	HRS/MSC	4000	+3%			2406.8	**6406.8**	6526.8
OVERHAUL	**REF:** AMM 29-11-01-350-801	AFL					1811		
29-11-01-350-801-03	RESTORATION NO. 2 ENGINE HYDRAULIC NO. 2 SYSTEM PUMP (OVERHAUL)								
	3031749-001	MOS					13-DEC-2006		
29.060	MX697613	HRS/MSC	4000	+3%			0	**4000**	4120
OVERHAUL	**REF:** AMM 29-11-01-350-801	AFL					0		
29-11-01-900-801-01	NO. 1 ENGINE HYDRAULIC NO. 1 SYSTEM PUMP								
	3031749-001	MOS		TSN:52 TSO:0		06/11/2017	11-JUN-2015		
29.050	MX603223	HRS/MSC	O/C	TSO:0			2406.8		
	REF: AMM 29-11-01-900-801	AFL		TSO:0			1811		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-11-01-900-801-02	NO. 2 ENGINE HYDRAULIC NO. 1 SYSTEM PUMP								
	3031749-001	MOS		TSN:147 TSO:0		06/11/2017	11-JUN-2015		
29.050	MX664861	HRS/MSC	O/C	TSO:0			2406.8		
	REF: AMM 29-11-01-900-801	AFL		TSO:0			1811		
29-11-01-900-801-03	NO. 2 ENGINE HYDRAULIC NO. 2 SYSTEM PUMP								
	3031749-001	MOS		TSN:0			13-DEC-2006		
29.060	MX697613	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-11-01-900-801	AFL		TSN:0			0		
29-11-21-900-801-01	NO. 1 HYDRAULIC PUMP PRESSURE RELIEF VALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-11-21-900-801	AFL		TSN:0			0		
29-11-21-900-801-02	NO. 2 HYDRAULIC PUMP PRESSURE RELIEF VALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-11-21-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-11-21-900-801-03	NO. 3 HYDRAULIC PUMP PRESSURE RELIEF VALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-11-21-900-801	AFL		TSN:0			0		
29-11-25-900-801-01	NO. 1 ENGINE NO. 1 SYSTEM PUMP PRESSURE SWITCH								
	15H0088PH	MOS		TSN:0			13-DEC-2006		
29.180	668	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-11-25-900-801	AFL		TSN:0			0		
29-11-25-900-801-02	NO. 2 ENGINE NO. 2 SYSTEM PUMP PRESSURE SWITCH								
	15H0088PH	MOS		TSN:0			13-DEC-2006		
29.190	667	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-11-25-900-801	AFL		TSN:0			0		
29-11-25-900-801-03	NO. 2 ENGINE NO.1 SYSTEM PUMP PRESSURE SWITCH								
	15H0088PH	MOS		TSN:0			13-DEC-2006		
29.180	669	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-11-25-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-11-25-960-801-01	DISCARD NO. 1 ENGINE NO. 1 SYSTEM PUMP PRESSURE SWITCH								
	15H0088PH	MOS					13-DEC-2006		
29.180	668	HRS/MSC	N/A				0		
	REF: AMM 29-11-25-960-801	AFL					0		
29-11-25-960-801-02	DISCARD NO. 2 ENGINE NO.1 SYSTEM PUMP PRESSURE SWITCH								
	15H0088PH	MOS					13-DEC-2006		
29.180	669	HRS/MSC	N/A				0		
	REF: AMM 29-11-25-960-801	AFL					0		
29-11-25-960-801-03	DISCARD NO. 2 ENGINE NO. 2 SYSTEM PUMP PRESSURE SWITCH								
	15H0088PH	MOS					13-DEC-2006		
29.190	667	HRS/MSC	N/A				0		
	REF: AMM 29-11-25-960-801	AFL					0		
29-12-05-710-801-01 (s)	OPERATIONAL TEST OF THE LH ENGINE HYDRAULIC SYSTEM 1 SHUT-OFF VALVE						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			16-APR-2018		
		HRS/MSC	400	+40			3041.8		
	REF: AMM 29-12-05-710-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-12-05-710-801-01A	OPERATIONAL TEST OF THE LH ENGINE HYDRAULIC SYSTEM 1 SHUT-OFF VALVE (MANDATORY 5-40)								
		MOS					16-APR-2018		
		HRS/MSC	450				3041.8	**3491.8**	
CMR	**REF:** AMM 29-12-05-710-801	AFL					2328		
29-12-05-710-801-02 (s)	OPERATIONAL TEST OF THE RH ENGINE HYDRAULIC SYSTEM 1 SHUT-OFF VALVE						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			16-APR-2018		
		HRS/MSC	400	+40			3041.8		
	REF: AMM 29-12-05-710-801	AFL					2328		
29-12-05-710-801-02A	OPERATIONAL TEST OF THE RH ENGINE HYDRAULIC SYSTEM 1 SHUT-OFF VALVE (MANDATORY 5-40)								
		MOS					16-APR-2018		
		HRS/MSC	450				3041.8	**3491.8**	
CMR	**REF:** AMM 29-12-05-710-801	AFL					2328		
29-12-05-710-801-03 (s)	OPERATIONAL TEST OF THE RH ENGINE HYDRAULIC SYSTEM 2 SHUT-OFF VALVE						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			16-APR-2018		
		HRS/MSC	400	+40			3041.8		
	REF: AMM 29-12-05-710-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-12-05-710-801-03A	OPERATIONAL TEST OF THE RH ENGINE HYDRAULIC SYSTEM 2 SHUT-OFF VALVE (MANDATORY 5-40)								
		MOS					16-APR-2018		
		HRS/MSC	450				3041.8	**3491.8**	
CMR	**REF:** AMM 29-12-05-710-801	AFL					2328		
29-13-09-960-801-01 (s)	REPLACEMENT OF THE HYDRAULIC FILTER- ENGINE 1 HYDRAULIC SYSTEM 1 DELIVERY FILTER (P11)						PKG		
	PKG 31	MOS	72				13-DEC-2006		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		
		APH					0		
29-13-09-960-801-02 (s)	REPLACEMENT OF THE HYDRAULIC FILTER- ENGINE 2 HYDRAULIC SYSTEM 1 DELIVERY FILTER (P12)						PKG		
	PKG 31	MOS	72				13-DEC-2006		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		
		APH					0		
29-13-09-960-801-03 (s)	REPLACEMENT OF THE HYDRAULIC FILTER- ENGINE 1 HYDRAULIC SYSTEM 1 RETURN FILTER (CD11)						PKG		
	PKG 31	MOS	72				13-DEC-2006		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-13-09-960-801-04 (s)	REPLACEMENT OF THE HYDRAULIC FILTER- ENGINE 2 HYDRAULIC SYSTEM 1 RETURN FILTER (CD12)						PKG		
	PKG 31	MOS	72				13-DEC-2006		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		
29-13-09-960-801-05 (s)	REPLACEMENT OF THE HYDRAULIC FILTER- HYDRAULIC SYSTEM 1 GENERAL RETURN FILTER (RET)						PKG		
	PKG 31	MOS	72				13-DEC-2006		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		
29-13-09-960-801-06 (s)	REPLACEMENT OF THE HYDRAULIC FILTER- ENGINE 2 HYDRAULIC SYSTEM 2 DELIVERY FILTER (P2)						PKG		
	PKG 31	MOS	72				13-DEC-2006		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		
29-13-09-960-801-07 (s)	REPLACEMENT OF THE HYDRAULIC FILTER- ENGINE 2 HYDRAULIC SYSTEM 2 RETURN FILTER (CD2)						PKG		
	PKG 31	MOS	72				13-DEC-2006		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-13-09-960-801-08 (s)	REPLACEMENT OF THE HYDRAULIC FILTER- HYDRAULIC SYSTEM 2 GENERAL RETURN FILTER (RET)						PKG		
	PKG 31	MOS	72				13-DEC-2006		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		
29-13-09-960-801-09 (s)	REPLACEMENT OF THE HYDRAULIC FILTER- STAND-BY PUMP DELIVERY FILTER (ST-BY)						PKG		
	PKG 31	MOS	72				13-DEC-2006		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		
29-14-01-680-801-01 (s)	DRAINING OF THE SYSTEM 1 HYDRAULIC RESERVOIRS						PKG		
	PKG 31	MOS	72	+2m			18-JUN-2013		
29.080		HRS/MSC					1872.8		
	REF: AMM 29-14-01-680-801	AFL	3750				1323		
29-14-01-680-801-02 (s)	DRAINING OF THE SYSTEM 2 HYDRAULIC RESERVOIRS						PKG		
	PKG 31	MOS	72	+2m			18-JUN-2013		
29.080		HRS/MSC					1872.8		
	REF: AMM 29-14-01-680-801	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-14-01-900-801-01	NO. 1 SYSTEM HYDRAULIC RESERVOIR								
	C19KP0015	MOS		TSN:0			13-DEC-2006		
29.070	550	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-14-01-900-801	AFL		TSN:0			0		
29-14-01-900-801-02	NO. 2 SYSTEM HYDRAULIC RESERVOIR								
	C19JP0016	MOS		TSN:0			13-DEC-2006		
29.070	552	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-14-01-900-801	AFL		TSN:0			0		
29-14-11-780-801-01 (s)	CHECK NO. 1 OF THE HYDRAULIC SYSTEM 1 ACCUMULATOR CAPACITY						PKG		
	PKG 2 ,31,39	MOS	16	+1m			18-APR-2018		
29.250		HRS/MSC	800	+40			3041.8		
	REF: AMM 29-14-11-780-801	AFL					2328		
29-14-11-900-801-01	NO. 1 SYSTEM HYDRAULIC ACCUMULATOR								
	47723-1000VA	MOS		TSN:0			13-DEC-2006		
29.040	214	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-14-11-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-14-11-900-801-02	NO. 2 SYSTEM HYDRAULIC ACCUMULATOR									
	47723-1000VA	MOS			TSN:0			13-DEC-2006		
29.040	142	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 29-14-11-900-801	AFL			TSN:0			0		
29-15-01-130-801-01 (s)	CLEANING OF THE PRESSURIZATION AIR FILTER OF THE HYDRAULIC RESERVOIR							PKG		
	PKG 21	MOS						16-APR-2018		
29.010		HRS/MSC	1600	+40				3041.8		
	REF: AMM 29-15-01-130-801	AFL						2328		
29-20-01-900-801-01	STAND-BY ELECTRICAL PUMP									
	42032	MOS			TSN:0			13-DEC-2006		
29.130	BC634	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 29-20-01-900-801	AFL			TSN:0			0		
29-20-03-220-801-01	CHECK STAND-BY ELECTRICAL PUMP BRUSHES									
	42032	MOS						13-DEC-2006		
29.130	BC634	HRS/MSC	5000	+3%				0	**5000**	5150
	REF: AMM 29-20-03-220-801	AFL						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-20-03-720-801-01	FUNCTIONAL TEST STAND-BY ELECTRICAL PUMP MOTOR									
	42032	MOS						13-DEC-2006		
29.130	BC634	HRS/MSC	5000	+3%				0	**5000**	5150
	REF: AMM 29-20-03-720-801	AFL						0		
29-20-07-900-801-01	NO. 1 SYSTEM STANDBY PUMP PRESSURE SWITCH									
	15H0091PH	MOS			TSN:0			13-DEC-2006		
29.150	215	HRS/MSC	O/C		TSN:0			0		
	REF: See Workcard	AFL			TSN:0			0		
29-20-07-900-801-02	NO. 2 SYSTEM STANDBY PUMP PRESSURE SWITCH									
	15H0091PH	MOS			TSN:0			21-MAY-2015		
29.150	2542	HRS/MSC	O/C		TSN:0			2395.7		
	REF: See Workcard	AFL			TSN:0			1800		
29-20-07-960-801-01	DISCARD NO. 1 SYSTEM STANDBY PUMP PRESSURE SWITCH									
	15H0091PH	MOS						13-DEC-2006		
29.150	215	HRS/MSC	N/A					0		
	REF: AMM 29-20-07-960-801	AFL						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-20-07-960-801-02	DISCARD NO. 2 SYSTEM STANDBY PUMP PRESSURE SWITCH								
	15H0091PH	MOS							
29.150	2542	HRS/MSC	N/A						
	REF: AMM 29-20-07-960-801	AFL							
291801	HYDRAULIC SYSTEM PRESSURE REDUCER								
	2407J010410	MOS		TSN:0			13-DEC-2006		
29.090	516	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
291811	HYDRAULIC SYSTEM SOLENOID SHUT-OFF VALVE								
	71275-1	MOS		TSN:0			13-DEC-2006		
29.100	361A	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
291841	NO. 1 HYDRAULIC SYSTEM MANIFOLD								
	AEB937-811	MOS		TSN:0			13-DEC-2006		
29.120	315	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291851	NO. 2 HYDRAULIC SYSTEM MANIFOLD								
	AEB938-81	MOS		TSN:0			13-DEC-2006		
29.120	503	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
291856	HYDRAULIC TANK AIR FILTER								
	018502AA000NF0A	MOS		TSN:0			13-DEC-2006		
29.125	386	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
291861	NO. 1 HYDRAULIC SYSTEM RESERVOIR GAUGE								
	768-345-2	MOS		TSN:0			13-DEC-2006		
29.220	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
291862	NO. 1 ENGINE NO. 1 HYDRAULIC SYSTEM SHUT-OFF VALVE								
	D09BB1001	MOS		TSN:0			13-DEC-2006		
29.230	1088	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291863	NO. 2 ENGINE NO. 1 HYDRAULIC SYSTEM SHUT-OFF VALVE								
	D09BB1001	MOS		TSN:0			13-DEC-2006		
29.230	1087	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
291871	NO. 2 HYDRAULIC SYSTEM RESERVOIR GAUGE								
	768345-2	MOS		TSR:0			18-NOV-2008		
29.220	1021	HRS/MSC	O/C	TSR:0			512.8		
	REF: GENERIC NO REF	AFL		TSR:0			383		
291872	NO. 2 ENGINE NO. 2 HYDRAULIC SYSTEM SHUT-OFF VALVE								
	D09BB1001	MOS		TSN:0			13-DEC-2006		
29.230	1083	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
292821	ELECTRIC PUMP SELECTOR								
	B94A13-205	MOS		TSN:0			13-DEC-2006		
29.160	C45566	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
293801	NO. 1 HYDRAULIC SYSTEMS TRANSMITTER								
	64279-530-2	MOS					17-SEP-2015		
29.170	5247	HRS/MSC	O/C	TSN:2486.2			2486.2		
	REF: GENERIC NO REF	AFL		TSN:1874			1874		
293811	NO. 2 HYDRAULIC SYSTEMS TRANSMITTER								
	64279-530-2	MOS					17-SEP-2015		
29.170	5256	HRS/MSC	O/C	TSN:2486.2			2486.2		
	REF: GENERIC NO REF	AFL		TSN:1874			1874		
293851	NO. 1 SYSTEM RESERVOIR SWITCH								
	8A1206-1	MOS		TSN:0			13-DEC-2006		
29.200	1421	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
293861	NO. 2 SYSTEM RESERVOIR SWITCH								
	8A1206-1	MOS		TSN:0			13-DEC-2006		
29.200	1444	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

CHAPTER 30 ICE AND RAIN PROTECTION

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-11-09-720-801-01	FUNCTIONAL TEST LH OUTBOARD SLAT TELESCOPIC DUCT								
	5035-600	MOS					23-APR-2018		
30.020	872	HRS/MSC	1240				3041.8	**4281.8**	
	REF: AMM 30-11-09-720-801	AFL	1000				2328	**3328**	
30-11-09-720-801-02	FUNCTIONAL TEST RH OUTBOARD SLAT TELESCOPIC DUCT								
	5035-700	MOS					23-APR-2018		
30.020	872	HRS/MSC	1240				3041.8	**4281.8**	
	REF: AMM 30-11-09-720-801	AFL	1000				2328	**3328**	
30-11-09-720-801-04	FUNCTIONAL TEST RH INBOARD SLAT TELESCOPIC DUCT								
	PN	MOS					13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 30-11-09-720-801	AFL					0		
30-11-09-900-801-01	LH OUTBOARD SLAT TELESCOPIC DUCT								
	5035-600	MOS					23-JUN-2015		
30.020	872	HRS/MSC	O/C				2409.6		
	REF: AMM 30-11-09-900-801	AFL					1816		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-11-09-900-801-02	RH OUTBOARD SLAT TELESCOPIC DUCT								
	5035-700	MOS					23-JUN-2015		
30.020	872	HRS/MSC	O/C				2409.6		
	REF: AMM 30-11-09-900-801	AFL					1816		
30-11-09-900-801-03	LH INBOARD SLAT TELESCOPIC DUCT								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 30-11-09-900-801	AFL		TSN:0			0		
30-11-09-900-801-04	RH INBOARD SLAT TELESCOPIC DUCT								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 30-11-09-900-801	AFL		TSN:0			0		
+ 30-11-11-280-801-01 (s)	SPECIAL DETAILED INSPECTION LH OUTBOARD SLAT PICCOLO TUBE OF THE PICCOLO TUBES - LH OUTBOARD SLAT PICCOLO TUBE						PKG		
	PN PKG 1 ,2 ,31	MOS					24-JUN-2017		
	SN-UNKNOWN	HRS/MSC	O/C				2832.2		
	REF: AMM 30-11-11-280-801	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-11-11-280-801-02 (s)	SPECIAL DETAILED INSPECTION RH OUTBOARD SLAT PICCOLO TUBE OF THE PICCOLO TUBES - RH OUTBOARD SLAT PICCOLO TUBE						PKG		
	PN PKG 1 ,2 ,31	MOS					24-JUN-2017		
	SN-UNKNOWN	HRS/MSC	O/C				2832.2		
	REF: AMM 30-11-11-280-801	AFL					2192		
30-11-11-900-801-01	LH OUTBOARD SLAT PICCOLO TUBE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 30-11-11-960-801	AFL		TSN:0			0		
30-11-11-900-801-04	RH OUTBOARD SLAT PICCOLO TUBE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 30-11-11-960-801	AFL		TSN:0			0		
30-11-17-200-801-01 (s)	INSPECTION OF THE WING ANTI-ICING SYSTEM COUPLINGS						PKG		
	PKG 31	MOS	72	+2m			17-JUN-2013		
30.010		HRS/MSC					1872.8		
	REF: AMM 30-11-17-200-801	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-12-01-900-801-01	WING ANTI-ICING VALVE								
	BYLB52188-6	MOS		TSR:0			08-JAN-2010		
30.150	457	HRS/MSC	O/C	TSR:0			814.6		
	REF: AMM 30-12-01-900-801	AFL		TSR:0			591		
30-12-05-900-801-01	WING ANTI-ICING PRESSURE SENSOR								
	ZRA233-01	MOS		TSN:2			24-JUL-2007		
36.120	1778	HRS/MSC	O/C	TSN:133.4			133.4		
	REF: AMM 30-12-05-900-801	AFL		TSN:79			79		
30-12-10-900-801-01	RH FORWARD WING ANTI-ICING TEMPERATURE SENSOR								
	RP493-00	MOS		TSN:0			19-MAR-2009		
36.140	DAAB00226	HRS/MSC	O/C	TSN:0			593.3		
	REF: AMM 30-12-10-900-801	AFL		TSN:0			438		
30-12-13-900-801-01	LH WING ANTI-ICING PRESSURE SWITCH								
	8G1199-5	MOS		TSN:0			13-DEC-2006		
30.030	2583	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-12-13-900-801-02	RH WING ANTI-ICING PRESSURE SWITCH								
	8G1199-5	MOS		TSN:0			13-DEC-2006		
30.030	2584	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
30-20-00-710-801-01 (s)	OPERATIONAL TEST OF THE NO.1 ENGINE AIR INTAKE ANTI-ICING SYSTEM						PKG		
	PKG 21	MOS					19-APR-2018		
30.040		HRS/MSC	1600	+40			3041.8		
	REF: AMM 30-20-00-710-801	AFL					2328		
30-20-00-710-801-02 (s)	OPERATIONAL TEST OF THE NO.2 ENGINE AIR INTAKE ANTI-ICING SYSTEM						PKG		
	PKG 21	MOS					19-APR-2018		
30.040		HRS/MSC	1600	+40			3041.8		
	REF: AMM 30-20-00-710-801	AFL					2328		
30-20-01-700-801-01	FUNCTIONAL/SEALING TEST LH ENGINE AIR INTAKE ANTI-ICING VALVE								
	06ND30203-9	MOS					02-DEC-2013		
30.050	0555B	HRS/MSC	O/C				1987.7		
	REF: AMM 30-20-01-700-801	AFL					1428		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-20-01-700-801-02	FUNCTIONAL/SEALING TEST RH ENGINE AIR INTAKE ANTI-ICING VALVE								
	06ND30203-9	MOS					02-DEC-2013		
30.050	0801B	HRS/MSC	O/C				1987.7		
	REF: AMM 30-20-01-700-801	AFL					1428		
30-20-01-900-801-01	LH ENGINE AIR INTAKE ANTI-ICING VALVE								
	06ND30203-9	MOS		TSO:0			02-DEC-2013		
30.050	0555B	HRS/MSC	O/C	TSO:0			1987.7		
	REF: AMM 30-20-01-900-801	AFL		TSO:0			1428		
30-20-01-900-801-02	RH ENGINE AIR INTAKE ANTI-ICING VALVE								
	06ND30203-9	MOS		TSO:0			02-DEC-2013		
30.050	0801B	HRS/MSC	O/C	TSO:0			1987.7		
	REF: AMM 30-20-01-900-801	AFL		TSO:0			1428		
30-20-09-900-801-01	NO. 1 ENGINE ANTI-ICE LOW PRESSURE INDICATING SWITCH								
	06ND30204-1	MOS		TSN:0			20-AUG-2008		
30.060	147	HRS/MSC	O/C	TSN:0			429.8		
	REF: AMM 30-20-09-900-801	AFL		TSN:0			319		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-20-09-900-801-02	NO. 2 ENGINE ANTI-ICE LOW PRESSURE INDICATING SWITCH								
	06ND30204-1	MOS		TSN:0			20-AUG-2008		
30.060	159	HRS/MSC	O/C	TSN:0			429.8		
	REF: AMM 30-20-09-900-801	AFL		TSN:0			319		
30-20-09-900-801-03	NO. 1 ENGINE ANTI-ICE OVER PRESSURE INDICATING SWITCH								
	06ND30204-3	MOS		TSN:0			24-SEP-2010		
30.070	318	HRS/MSC	O/C	TSN:0			1064.6		
	REF: AMM 30-20-09-900-801	AFL		TSN:0			753		
30-20-09-900-801-04	NO. 2 ENGINE ANTI-ICE OVER PRESSURE INDICATING SWITCH								
	06ND30204-3	MOS		TSN:0			18-MAR-2017		
30.070	950	HRS/MSC	O/C	TSN:0			2729.7		
	REF: AMM 30-20-09-900-801	AFL		TSN:0			2109		
30-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE AIR DATA PROBE ANTI-ICING SYSTEM						PKG		
	PKG 21	MOS					20-APR-2018		
30.080		HRS/MSC	1600	+40			3041.8		
	REF: AMM 30-30-00-710-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-41-00-710-801-01 (s)	OPERATIONAL TEST OF THE WINDSHIELD DE-ICING SYSTEM							PKG		
	PKG 23	MOS						13-DEC-2006		
30.130		HRS/MSC	4800	+40				0		
	REF: AMM 30-41-00-710-801	AFL						0		
30-41-01-900-801-01	LH WINDSHIELD RESISTOR BOX									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 30-41-01-900-801	AFL			TSN:0			0		
30-41-01-900-801-02	RH WINDSHIELD RESISTOR BOX									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 30-41-01-900-801	AFL			TSN:0			0		
30-43-05-900-801-01	LH WINDSHIELD WIPER MOTOR									
	4267568	MOS			TSN:0			13-DEC-2006		
30.090	26229	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 30-43-05-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-43-05-900-801-02	RH WINDSHIELD WIPER MOTOR									
	4267575	MOS			TSN:0			13-DEC-2006		
30.090	26228	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 30-43-05-900-801	AFL			TSN:0			0		
30-43-09-220-801-01	CHECK LH WINDSHIELD WIPER MOTOR BRUSHES									
	4267568	MOS						13-DEC-2006		
30.090	26229	HRS/MSC	15000	+3%				0	**15000**	15450
	REF: AMM 30-43-09-220-801	AFL						0		
30-43-09-220-801-02	CHECK RH WINDSHIELD WIPER MOTOR BRUSHES									
	4267575	MOS						13-DEC-2006		
30.090	26228	HRS/MSC	15000	+3%				0	**15000**	15450
	REF: AMM 30-43-09-220-801	AFL						0		
+ 30-90-00-710-801-01	OPERATIONAL TEST OF THE BRAKE HEATING SYSTEM									
		MOS						13-DEC-2006		
30.140		HRS/MSC	O/C					0		
	REF: AMM 30-90-00-710-801	AFL						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-90-01-900-801-01	LH BRAKE HEATING VALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 30-90-01-900-801	AFL		TSN:0			0		
30-90-01-900-801-02	RH BRAKE HEATING VALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 30-90-01-900-801	AFL		TSN:0			0		
304801	PILOT WINDSHIELD HEATING REGULATOR								
	AV30559060030-1	MOS		TSN:0			13-DEC-2006		
30.100	1500	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
304811	COPILOT WINDSHIELD HEATING REGULATOR								
	AV30559060030-1	MOS		TSN:0			13-DEC-2006		
30.100	1499	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304821	REAR WINDOW HEATING REGULATOR								
	AV30564060030	MOS		TSN:92			25-AUG-2014		
30.110	1462	HRS/MSC	O/C	TSN:2185.4			2185.4		
	REF: GENERIC NO REF	AFL		TSN:1607			1607		
304831	LATERAL WINDOW HEATING REGULATOR								
	AV30564060030	MOS		TSN:92			25-AUG-2014		
30.110	1461	HRS/MSC	O/C	TSN:2185.4			2185.4		
	REF: GENERIC NO REF	AFL		TSN:1607			1607		
304841	PILOT WINDSHIELD WIPER ARTICULATED ARM								
	PN	MOS		TSN:0			13-DEC-2006		
30.160	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
304846	COPILOT WINDSHIELD WIPER ARTICULATED ARM								
	PN	MOS		TSN:0			13-DEC-2006		
30.160	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-10-13-900-801-02	(140LC) OVERHEAD RHEOSTAT								
	419-49-47K2K2F	MOS		TSN:0			21-MAY-2015		
	859020	HRS/MSC	O/C	TSN:0			2395.7		
	REF: AMM 33-10-13-900-801	AFL		TSN:0			1800		
CHAPTER 31	**INDICATING/RECORDING SYSTEMS**								
31-11-01-900-801-01	OVERHEAD PANEL								
	PN	MOS		TSN:0			13-DEC-2006		
31.415	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-11-01-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		
31-11-17-900-801-01	LH OVERHEAD PANEL POWER SUPPLY PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-11-17-900-801	AFL		TSN:0			0		
31-11-17-900-801-02	RH OVERHEAD PANEL POWER SUPPLY PCB								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-11-17-900-801	AFL		TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-21-05-900-801-01	PILOT CLOCK								
	PN	MOS		TSN:0			13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
		APH		TSN:0			0		
31-21-05-900-801-02	COPILOT CLOCK								
	PN	MOS		TSN:0			13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
		APH		TSN:0			0		
31-21-05-960-801-01	REPLACEMENT PILOT CLOCK BATTERY								
	PN	MOS					13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C				0		
	REF: AMM 31-21-05-960-801	AFL					0		
		APH					0		
31-21-05-960-801-02	REPLACEMENT COPILOT CLOCK BATTERY								
	PN	MOS					13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C				0		
	REF: AMM 31-21-05-960-801	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-00-710-802-01 (s)	OPERATIONAL TEST OF THE FLIGHT DATA (FDR) RECORDER						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			16-APR-2018		
31.110		HRS/MSC					3041.8		
	REF: AMM 31-31-00-710-802	AFL					2328		
31-31-00-720-801-01	FUNCTIONAL TEST OF THE FLIGHT DATA (FDR) RECORDER 88 PARAMETERS DFDR								
		MOS					13-DEC-2006		
31.110		HRS/MSC	A/R				0		
	REF: AMM 31-31-00-720-801	AFL					0		
31-31-00-970-801-01	DOWNLOAD OF THE FLIGHT DATA (FDR) RECORDER								
		MOS					04-JAN-2010		
31.110		HRS/MSC	A/R				802.8		
	REF: AMM 31-31-00-970-801	AFL					584		
31-31-09-710-801-01	OPERATIONAL TEST COCKPIT VOICE RECORDER (CVR) ACCELERATION CONTACT								
	400-10B	MOS	240	+3%			02-MAY-2009	**02-MAY-2029**	08-DEC-2029
23.120	6089	HRS/MSC					617.1		
	REF: AMM 31-31-09-710-801	AFL					460		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-09-710-801-02	OPERATIONAL TEST FLIGHT DATA RECORDER (FDR) ACCELERATION CONTACT									
	400-10B	MOS	240	+3%				02-MAY-2009	**02-MAY-2029**	08-DEC-2029
31.085	6088	HRS/MSC						617.1		
	REF: AMM 31-31-09-710-801	AFL						460		
31-31-09-900-801-01	COCKPIT VOICE RECORDER (CVR) ACCELERATION CONTACT									
	400-10B	MOS			TSN:0			02-MAY-2009		
23.120	6089	HRS/MSC	O/C		TSN:0			617.1		
	REF: AMM 31-31-09-900-801	AFL			TSN:0			460		
31-31-09-900-801-02	FLIGHT DATA RECORDER (FDR) ACCELERATION CONTACT									
	400-10B	MOS			TSN:0			02-MAY-2009		
31.085	6088	HRS/MSC	O/C		TSN:0			617.1		
	REF: AMM 31-31-09-900-801	AFL			TSN:0			460		
31-31-31-900-801-01	FLIGHT DATA (FDR) RECORDER									
	980-4710-003	MOS						30-APR-2007		
31.110	ARFDR00862	HRS/MSC	O/C					21.5		
	REF: AMM 31-31-31-900-801	AFL						7		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-33-900-801-01	LH ROLL CONTROL SURFACE POSITION SENSOR								
	3K2204A	MOS		TSN:0			28-APR-2017		
31.130	A0649	HRS/MSC	O/C	TSN:0			2729.7		
	REF: AMM 31-31-33-900-801	AFL		TSN:0			2109		
31-31-33-900-801-02	RH ROLL CONTROL SURFACE POSITION SENSOR								
	3K2204A	MOS		TSN:0			28-APR-2017		
31.130	A0659	HRS/MSC	O/C	TSN:0			2729.7		
	REF: AMM 31-31-33-900-801	AFL		TSN:0			2109		
31-31-33-900-801-03	ELEVATOR POSITION SENSOR								
	3K2205A	MOS		TSN:0			28-APR-2017		
31.140	A0309	HRS/MSC	O/C	TSN:0			2729.7		
	REF: AMM 31-31-33-900-801	AFL		TSN:0			2109		
31-31-33-900-801-04	FLIGHT DATA RECORDER (FDR) YAW CONTROL SURFACE POSITION SENSOR SENSOR								
	3K2203A	MOS		TSN:0			28-APR-2017		
31.150	A0332	HRS/MSC	O/C	TSN:0			2729.7		
	REF: AMM 31-31-33-900-801	AFL		TSN:0			2109		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-35-700-801-01 (s)	CHECK OF THE FLIGHT CONTROL INPUT FORCE SENSORS						PKG		
	PKG 14 ,31	MOS	32 +1m				23-APR-2018		
22.060		HRS/MSC					3041.8		
	REF: AMM 31-31-35-700-801	AFL					2328		
31-31-37-900-801-01	FDR FLIGHT PITCH CONTROL POSITION POTENTIOMETER								
	100-2000-M00	MOS		TSN:0			13-DEC-2006		
31.080	1965	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-31-37-900-801	AFL		TSN:0			0		
31-31-37-900-801-02	FDR FLIGHT YAW CONTROL POSITION POTENTIOMETER								
	100-2000-M00	MOS		TSN:0			13-DEC-2006		
31.090	1967	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-31-37-900-801	AFL		TSN:0			0		
31-31-37-900-801-03	FDR FLIGHT ROLL CONTROL POSITION POTENTIOMETER								
	100-2000-M00	MOS		TSN:0			13-DEC-2006		
31.100	1966	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-31-37-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-50-710-801-01 (s)	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER						PKG		
	PKG 12 ,14 ,31	MOS	16 +1m				16-APR-2018		
23.140		HRS/MSC					3041.8		
	REF: AMM 31-31-50-710-801	AFL					2328		
31-31-50-970-801-01	DOWNLOAD OF THE COCKPIT VOICE RECORDER								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 31-31-50-970-801	AFL					0		
31-31-51-900-801-01	(CVR) COCKPIT VOICE RECORDER								
	980-6044-002	MOS		TSN:0			29-JUN-2015		
23.140	010-02353	HRS/MSC	O/C	TSN:0			2409.6		
	REF: AMM 31-31-51-900-801	AFL		TSN:0			1816		
31-31-53-710-801-01	OPERATIONAL TEST OF THE RECORDER INDEPENDENT (RIPS) POWER SUPPLY								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-53-900-801-01	RECORDER INDEPENDENT (RIPS) POWER SUPPLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-31-53-900-801	AFL		TSN:0			0		
31-31-55-900-801-01	COCKPIT VOICE RECORDER (CVR) MICROPHONE								
	980-6113-010	MOS		TSN:0			13-DEC-2006		
23.160	4276	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-31-55-900-801	AFL		TSN:0			0		
31-32-00-970-801-01	DOWNLOAD QUICK ACCESS (QAR) RECORDER								
	PN	MOS					13-DEC-2006		
31.410	NOT INSTALLED	HRS/MSC	O/C				0		
	REF: AMM 31-32-00-970-801	AFL					0		
		APH					0		
31-32-01-900-801-01	QUICK ACCESS (QAR) RECORDER								
	PN	MOS		TSN:0			13-DEC-2006		
31.410	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-32-01-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-32-05-960-801-01	REPLACE QUICK ACCESS (QAR) RECORDER BATTERY								
	PN	MOS					13-DEC-2006		
31.410	NOT INSTALLED	HRS/MSC	N/A				0		
	REF: See Workcard	AFL					0		
		APH					0		
31-41-05-900-801-01	NO. 1 MAU POWER SUPPLY NO.1 MODULE								
	7024440-1901	MOS		TSN:0			13-DEC-2006		
31.240	06055359	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-41-05-900-801	AFL		TSN:0			0		
31-41-05-900-801-02	NO. 1 MAU POWER SUPPLY NO.3 MODULE								
	7024440-1901	MOS		TSN:0			13-DEC-2006		
31.250	06055502	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-41-05-900-801	AFL		TSN:0			0		
31-41-05-900-801-03	NO. 2 MAU POWER SUPPLY NO.1 MODULE								
	7024440-1901	MOS		TSN:0			13-DEC-2006		
31.240	06065288	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-41-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-41-05-900-801-04	NO. 2 MAU POWER SUPPLY NO.3 MODULE								
	7024440-1901	MOS		TSN:0			13-DEC-2006		
31.250	06055503	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-41-05-900-801	AFL		TSN:0			0		
31-41-05-900-802-01	NO. 1 POWER SUPPLY AIR MANAGEMENT BLANK MODULE 2 (PS-AMBM 2)(910FX) MODULE								
	7029308-1901	MOS		TSN:0			13-DEC-2006		
31.260	06060365	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-41-05-900-802	AFL		TSN:0			0		
31-41-05-900-802-02	NO. 2 POWER SUPPLY AIR MANAGEMENT BLANK MODULE 2 (PS-AMBM 2)(911FX) MODULE								
	7029308-1901	MOS		TSN:0			13-DEC-2006		
31.260	06050354	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-41-05-900-802	AFL		TSN:0			0		
31-41-09-900-801-01	NO. 5 PROCESSOR MODULE								
	7034056-1901	MOS		TSN:0			26-JUN-2015		
31.290	15032593	HRS/MSC	O/C	TSN:0			2409.6		
	REF: AMM 31-41-09-900-801	AFL		TSN:0			1816		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-41-09-900-801-02	NO. 6 PROCESSOR MODULE								
	PN	MOS					26-JUN-2015		
31.290	NOT INSTALLED	HRS/MSC	O/C				2409.6		
	REF: AMM 31-41-09-900-801	AFL					1816		
31-41-17-900-801-01	NO. 1 (AFBM) AIR FLOW BLOCKAGE MODULE								
	7027208-1903	MOS		TSN:0			26-JUN-2015		
31.050	1504T415	HRS/MSC	O/C	TSN:0			2409.6		
	REF: AMM 31-41-17-900-801	AFL		TSN:0			1816		
31-41-17-900-801-02	NO. 2 (AFBM) AIR FLOW BLOCKAGE MODULE								
	7027208-1903	MOS		TSN:0			26-JUN-2015		
31.050	1504T431	HRS/MSC	O/C	TSN:0			2409.6		
	REF: AMM 31-41-17-900-801	AFL		TSN:0			1816		
31-41-17-900-801-03	NO. 3 (AFBM) AIR FLOW BLOCKAGE MODULE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-41-17-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-41-17-900-801-04	NO. 4 (AFBM) AIR FLOW BLOCKAGE MODULE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-41-17-900-801	AFL		TSN:0			0		
31-41-17-900-801-05	NO. 5 (AFBM) AIR FLOW BLOCKAGE MODULE								
	7027208-1903	MOS		TSN:0			26-JUN-2015		
	1504T416	HRS/MSC	O/C	TSN:0			2409.6		
	REF: AMM 31-41-17-900-801	AFL		TSN:0			1816		
31-41-17-900-801-06	NO. 6 (AFBM) AIR FLOW BLOCKAGE MODULE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-41-17-900-801	AFL		TSN:0			0		
31-41-17-900-801-07	NO. 7 (AFBM) AIR FLOW BLOCKAGE MODULE								
	7027208-1903	MOS					26-JUN-2015		
	10067042	HRS/MSC	O/C	TSN:2409.6			2409.6		
	REF: AMM 31-41-17-900-801	AFL		TSN:1816			1816		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-41-17-900-801-08	NO. 8 (AFBM) AIR FLOW BLOCKAGE MODULE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-41-17-900-801	AFL		TSN:0			0		
31-41-17-900-801-09	NO. 9 (AFBM) AIR FLOW BLOCKAGE MODULE								
	PN	MOS					26-JUN-2015		
	NOT INSTALLED	HRS/MSC	O/C				2409.6		
	REF: AMM 31-41-17-900-801	AFL					1816		
31-42-01-900-801-01	NO. 1 NIC / PROCESSOR MODULE								
	7038231-1901	MOS		TSN:0			16-JUN-2015		
31.220	1503B873	HRS/MSC	O/C	TSN:0			2409.6		
	REF: AMM 31-42-01-900-801	AFL		TSN:0			1816		
31-42-01-900-801-02	NO. 2 NIC / PROCESSOR MODULE								
	7038231-1902	MOS		TSN:0			16-JUN-2015		
31.220	1503B974	HRS/MSC	O/C	TSN:0			2409.6		
	REF: AMM 31-42-01-900-801	AFL		TSN:0			1816		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-42-01-900-801-03	NO. 3 NIC / PROCESSOR MODULE								
	7038231-1901	MOS		TSN:0			16-JUN-2015		
31.230	1503C147	HRS/MSC	O/C	TSN:0			2409.6		
	REF: AMM 31-42-01-900-801	AFL		TSN:0			1816		
31-42-01-900-801-04	NO. 4 NIC / PROCESSOR MODULE								
	7038231-1902	MOS		TSN:0			16-JUN-2015		
31.230	1503C033	HRS/MSC	O/C	TSN:0			2409.6		
	REF: AMM 31-42-01-900-801	AFL		TSN:0			1816		
31-42-05-900-801-01	CONTROL I/O MODULE 2								
	7026534-1902	MOS		TSN:0			13-DEC-2006		
31.200	06051848	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
31-42-09-900-801-01	CONTROL I/O VIDEO MODULE 1								
	7026531-1902	MOS		TSN:0			13-DEC-2006		
31.210	06060956	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-42-09-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-42-11-900-801-01	NO. 1 CUSTOM I/O (CSIO) MODULE								
	7028425-1901	MOS		TSN:0			13-DEC-2006		
31.180	06060374	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-42-11-900-801	AFL		TSN:0			0		
31-42-11-900-801-02	NO. 2 CUSTOM I/O (CSIO) MODULE								
	7028425-1901	MOS		TSN:0			13-DEC-2006		
31.180	06060403	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-42-11-900-801	AFL		TSN:0			0		
31-42-13-900-801-01	NO. 1 GENERIC I/O (GIO) MODULE								
	7025365-1901	MOS		TSN:0			13-DEC-2006		
31.170	06062342	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-42-13-900-801	AFL		TSN:0			0		
31-42-13-900-801-02	NO. 2 GENERIC I/O (GIO) MODULE								
	7025365-1901	MOS		TSN:0			13-DEC-2006		
31.170	06062332	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-42-13-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-42-17-900-801-01	LH ASCB BUS COUPLER								
	7027566-901	MOS		TSN:0			13-DEC-2006		
31.310	06052114	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-42-17-900-801	AFL		TSN:0			0		
31-42-17-900-801-02	RH ASCB BUS COUPLER								
	7027566-901	MOS		TSN:0			13-DEC-2006		
31.310	06052113	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-42-17-900-801	AFL		TSN:0			0		
31-42-21-900-801-01	NO. 1 DATABASE MODULE								
	PN	MOS					26-JUN-2015		
31.280	NOT INSTALLED	HRS/MSC	O/C				2409.6		
	REF: AMM 31-42-21-900-801	AFL					1816		
31-42-21-900-801-02	NO. 2 DATABASE MODULE								
	PN	MOS					26-JUN-2015		
31.280	NOT INSTALLED	HRS/MSC	O/C				2409.6		
	REF: AMM 31-42-21-900-801	AFL					1816		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-42-25-900-801-01	NO. 1 NIC/PROC 1 APM CONFIGURATION MODULE								
	7519272-901	MOS		TSN:0			13-DEC-2006		
34.210	06054550	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-42-25-900-801	AFL		TSN:0			0		
31-42-25-900-801-02	NO. 2 NIC/PROC 3 APM CONFIGURATION MODULE								
	7519272-901	MOS		TSN:0			13-DEC-2006		
34.210	06054551	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-42-25-900-801	AFL		TSN:0			0		
31-43-01-900-801-01	NO. 1 (MRC) MODULAR RADIO CABINET								
	7517959-904	MOS		TSN:0			13-DEC-2006		
34.100	06051871	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-43-01-900-801	AFL		TSN:0			0		
31-43-01-900-801-02	NO. 2 (MRC) MODULAR RADIO CABINET								
	7517959-904	MOS		TSN:0			13-DEC-2006		
34.100	06051935	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-43-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-43-05-900-801-01	NO. 1 NETWORK INTERFACE (NIM) MODULE								
	7517964-910	MOS					25-FEB-2017		
31.300	06011746	HRS/MSC	O/C				2712.3		
	REF: AMM 31-43-05-900-801	AFL					2098		
31-43-05-900-801-02	NO. 2 NETWORK INTERFACE (NIM) MODULE								
	7517964-910	MOS		TSR:0			25-AUG-2009		
31.300	05111564 MOD AT	HRS/MSC	O/C	TSR:0			715.2		
	REF: AMM 31-43-05-900-801	AFL		TSR:0			522		
31-55-00-720-801-01	FUNCTIONAL TEST OF THE LANDING SAFETIES								
		MOS					18-APR-2018		
31.040		HRS/MSC	O/C				3041.8		
	REF: See Workcard	AFL					2328		
31-57-01-710-801-01	OPERATIONAL TEST OF THE LOW-HEIGHT CONSOLE TABLE MICROSWITCH AND ALERT SYSTEM								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 31-57-01-710-801	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-60-00-710-801-20 (s)	OPERATIONAL TEST OF THE CENTRAL DISPLAY SYSTEM (CDS) - TEST OF THE CURSOR CONTROL DEVICE AND REVERSION COMMANDS							PKG		
	PKG 21	MOS						16-APR-2018		
		HRS/MSC	1600	+40				3041.8		
	REF: AMM 31-60-00-710-801	AFL						2328		
31-60-00-710-801-20A	OPERATIONAL TEST OF THE CENTRAL DISPLAY SYSTEM (CDS) - TEST OF THE CURSOR CONTROL DEVICE AND REVERSION COMMANDS (MANDATORY 5-40)									
		MOS						16-APR-2018		
		HRS/MSC	1640					3041.8	**4681.8**	
MANDATORY 5-40	**REF:** AMM 31-60-00-710-801	AFL						2328		
31-60-05-900-801-01	LH CHECKLIST CONTROLLER									
	7030900-907	MOS			TSN:0			13-DEC-2006		
31.400	06040482	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 31-60-05-900-801	AFL			TSN:0			0		
31-60-05-900-801-02	RH CHECKLIST CONTROLLER									
	7030900-905	MOS			TSN:0			13-DEC-2006		
31.400	06050495	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 31-60-05-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-60-06-900-801-01	LH CURSOR CONTROL (CCD) DEVICE								
	7028640-901	MOS		TSN:0			13-DEC-2006		
31.190	06050518	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-60-06-900-801	AFL		TSN:0			0		
31-60-06-900-801-02	RH CURSOR CONTROL (CCD) DEVICE								
	7028640-901	MOS		TSN:0			13-DEC-2006		
31.190	06050517	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-60-06-900-801	AFL		TSN:0			0		
31-60-09-900-801-01	LH MULTIFUNCTION (MKB) KEYBOARD								
	7028560-921	MOS		TSO:0			29-JUN-2015		
31.350	08060967	HRS/MSC	O/C	TSO:0			2409.6		
	REF: AMM 31-60-09-900-801	AFL		TSO:0			1816		
31-60-09-900-801-02	RH MULTIFUNCTION (MKB) KEYBOARD								
	7028560-921	MOS		TSO:0			29-JUN-2015		
31.350	11072904	HRS/MSC	O/C	TSO:0			2409.6		
	REF: AMM 31-60-09-900-801	AFL		TSO:0			1816		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-60-13-900-801-01	LH PRIMARY FLIGHT (PFD) DISPLAY UNIT								
	7028140-901	MOS		TSN:0			13-DEC-2006		
31.330	06091906 L	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-60-13-900-801	AFL		TSN:0			0		
31-60-13-900-801-02	RH PRIMARY FLIGHT (PFD) DISPLAY UNIT								
	7028140-901	MOS		TSN:0			13-DEC-2006		
31.330	06091962 L	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-60-13-900-801	AFL		TSN:0			0		
31-60-13-900-801-03	UPPER MULTIFUNCTION (MFD) DISPLAY UNIT								
	7028140-901	MOS		TSN:0			13-DEC-2006		
31.340	06091963 L	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-60-13-900-801	AFL		TSN:0			0		
31-60-13-900-801-04	LOWER MULTIFUNCTION (MFD) DISPLAY UNIT								
	7028140-901	MOS		TSR:0			21-DEC-2010		
31.340	06101984 MOD N	HRS/MSC	O/C	TSR:0			1124.8		
	REF: AMM 31-60-13-900-801	AFL		TSR:0			792		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-60-17-900-801-01	NO. 1 ADVANCED GRAPHICS (AGM) MODULE								
	7036410-1903	MOS		TSO:0			23-JUN-2015		
31.360	10116827	HRS/MSC	O/C	TSO:0			2409.6		
	REF: AMM 31-60-17-900-801	AFL		TSO:0			1816		
31-60-17-900-801-02	NO. 3 ADVANCED GRAPHICS (AGM) MODULE								
	7036410-1903	MOS		TSO:0			23-JUN-2015		
31.360	12018742	HRS/MSC	O/C	TSO:0			2409.6		
	REF: AMM 31-60-17-900-801	AFL		TSO:0			1816		
31-60-17-900-801-03	NO. 2 ADVANCED GRAPHICS (AGM) MODULE								
	7036410-1903	MOS		TSO:0			23-JUN-2015		
31.370	11027354	HRS/MSC	O/C	TSO:0			2409.6		
	REF: AMM 31-60-17-900-801	AFL		TSO:0			1816		
31-60-17-900-801-04	NO. 4 ADVANCED GRAPHICS (AGM) MODULE								
	7036410-1903	MOS		TSO:0			23-JUN-2015		
31.370	11077995	HRS/MSC	O/C	TSO:0			2409.6		
	REF: AMM 31-60-17-900-801	AFL		TSO:0			1816		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-60-21-900-801-01	DISPLAY UNIT REVERSION CONTROLLER								
	7029270-903	MOS		TSN:0			13-DEC-2006		
34.120	06060290	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-60-21-900-801	AFL		TSN:0			0		
313A21	FDR ACCELEROMETER SENSOR								
	223-00107-196	MOS		TSN:0			13-DEC-2006		
31.390	8942	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 31-31-38-900-801	AFL		TSN:0			0		
314091	NO. 1 MODULAR AVIONICS UNIT								
	7029782-1920	MOS		TSN:0			13-DEC-2006		
31.270	06051314	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
314092	NO. 2 MODULAR AVIONICS UNIT								
	7029782-1920	MOS		TSN:0			13-DEC-2006		
31.270	06051313	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

CHAPTER 32 LANDING GEAR

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-00-00-700-801-01	CHECK OF THE NOSE LANDING GEAR (NLG) UPLOCK BOX									
		MOS						13-DEC-2006		
32.190		HRS/MSC	O/C					0		
	REF: AMM 32-00-00-700-801	AFL						0		
32-00-00-700-801-02	CHECK OF THE LH MAIN LANDING GEAR (MLG) UPLOCK BOX									
		MOS						30-MAR-2011		
32.220		HRS/MSC	O/C					1238.5		
	REF: AMM 32-00-00-700-801	AFL						863		
32-00-00-700-801-03	CHECK OF THE RH MAIN LANDING GEAR (MLG) UPLOCK BOX									
		MOS						12-APR-2011		
32.220		HRS/MSC	O/C					1238.5		
	REF: AMM 32-00-00-700-801	AFL						863		
32-10-00-640-801-01 (s)	LUBRICATION OF THE LH MLG AND MLG DOOR							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				17-APR-2018		
		HRS/MSC	400	+40				3041.8		
	REF: AMM 32-10-00-640-801	AFL						2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10-00-640-801-02 (s)	LUBRICATION OF THE RH MLG AND MLG DOOR							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				17-APR-2018		
		HRS/MSC	400	+40				3041.8		
	REF: AMM 32-10-00-640-801	AFL						2328		
+ 32-11-00-220-801-01	DETAILED INSPECTION LH MAIN LANDING GEAR (MLG) LEG									
	D23733000-1	MOS	72	+8m				08-JUL-2013	**08-JUL-2019**	08-MAR-2020
32.040	B116	HRS/MSC						1872.8		
	REF: AMM 32-11-00-220-801	AFL						1323		
+ 32-11-00-220-801-02	DETAILED INSPECTION RH MAIN LANDING GEAR (MLG) LEG									
	D23734000-1	MOS	72	+8m				08-JUL-2013	**08-JUL-2019**	08-MAR-2020
32.040	B116	HRS/MSC						1872.8		
	REF: AMM 32-11-00-220-801	AFL						1323		
32-11-00-350-801-01	RESTORATION LH MAIN LANDING GEAR (MLG) LEG (OVERHAUL)									
	D23733000-1	MOS	144	+3%				04-MAY-2007	**04-MAY-2019**	13-SEP-2019
	B116	HRS/MSC								
OVERHAUL	**REF:** AMM 32-11-00-350-801	AFL	6000					0	**6000**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-00-350-801-02	RESTORATION RH MAIN LANDING GEAR (MLG) LEG (OVERHAUL)									
	D23734000-1	MOS	144	+3%				04-MAY-2007	**04-MAY-2019**	13-SEP-2019
	B116	HRS/MSC								
OVERHAUL	**REF:** AMM 32-11-00-350-801	AFL	6000					0	**6000**	
32-11-00-700-802-01	CHECK AND ADJUSTMENT LH MAIN LANDING GEAR (MLG) LEG AXIAL PLAY TORQUE LINKS									
	D23733000-1	MOS	72	+3%				19-JUN-2013	**19-JUN-2019**	23-AUG-2019
	B116	HRS/MSC						1872.8		
	REF: AMM 32-11-00-700-802	AFL	3000	+3%				1323	**4323**	4413
32-11-00-700-802-02	CHECK AND ADJUSTMENT RH MAIN LANDING GEAR (MLG) LEG AXIAL PLAY TORQUE LINKS									
	D23734000-1	MOS	72	+3%				19-JUN-2013	**19-JUN-2019**	23-AUG-2019
	B116	HRS/MSC						1872.8		
	REF: AMM 32-11-00-700-802	AFL	3000	+3%				1323	**4323**	4413
32-11-00-900-801-01	LH MAIN LANDING GEAR (MLG) LEG									
	D23733000-1	MOS			TSN:79			08-JUL-2013		
32.020	B116	HRS/MSC	H/T		TSN:1872.8			1872.8		
	REF: AMM 32-11-00-900-801	AFL			TSN:1323			1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-00-900-801-02	RH MAIN LANDING GEAR (MLG) LEG								
	D23734000-1	MOS		TSN:79			08-JUL-2013		
32.030	B116	HRS/MSC	H/T	TSN:1872.8			1872.8		
	REF: AMM 32-11-00-900-801	AFL		TSN:1323			1323		
32-11-00-960-801-01	REPLACE LH MAIN LANDING GEAR (MLG) LEG (DISCARD OF LIFE LIMITED PARTS)								
	D23733000-1	MOS					13-DEC-2006		
	B116	HRS/MSC					0		
LIFE LIMIT	**REF:** AMM 32-11-00-960-801	AFL	20000				0		**20000**
+ 32-11-00-960-801-01A	REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITED PARTS) - LH MLG LEG (5GA) (MANDATORY 5-40)								
	D23733000-1	MOS					13-DEC-2006		
	B116	HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 32-11-00-960-801	AFL	20000				0		**20000**
32-11-00-960-801-02	REPLACE RH MAIN LANDING GEAR (MLG) LEG (DISCARD OF LIFE LIMITED PARTS)								
	D23734000-1	MOS					13-DEC-2006		
	B116	HRS/MSC					0		
LIFE LIMIT	**REF:** AMM 32-11-00-960-801	AFL	20000				0		**20000**

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-11-00-960-801-02A	REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITED PARTS) - RH MLG LEG (10GA) (MANDATORY 5-40)								
	D23734000-1	MOS					13-DEC-2006		
	B116	HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 32-11-00-960-801	AFL	20000				0	**20000**	
+ 32-11-05-780-801-01 (s)	CHECK OF THE LH MAIN LANDING GEAR (MLG) SHOCK ABSORBER CHARGING PRESSURE						PKG		
	PKG 21	MOS					24-APR-2018		
32.020		HRS/MSC	1600	+40			3041.8		
	REF: AMM 32-11-05-780-801	AFL					2328		
+ 32-11-05-780-801-02 (s)	CHECK OF THE RH MAIN LANDING GEAR (MLG) SHOCK ABSORBER CHARGING PRESSURE						PKG		
	PKG 21	MOS					24-APR-2018		
32.030		HRS/MSC	1600	+40			3041.8		
	REF: AMM 32-11-05-780-801	AFL					2328		
32-11-05-900-801-01	LH MAIN LANDING GEAR (MLG) SHOCK ABSORBER								
	PN	MOS		TSN:0			13-DEC-2006		
32.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-11-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-05-900-801-02	RH MAIN LANDING GEAR (MLG) SHOCK ABSORBER								
	PN	MOS		TSN:0			13-DEC-2006		
32.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-11-05-900-801	AFL		TSN:0			0		
32-11-21-900-801-01	LH MAIN LANDING GEAR (MLG) BRACE STRUT ACTUATOR								
	D23735000	MOS		TSN:0			13-DEC-2006		
32.060	HN0021	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-11-21-900-801	AFL		TSN:0			0		
32-11-21-900-801-02	RH MAIN LANDING GEAR (MLG) BRACE STRUT ACTUATOR								
	D23736000	MOS		TSN:0			13-DEC-2006		
32.060	HN0026	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-11-21-900-801	AFL		TSN:0			0		
32-12-17-900-801-01	LH MAIN LANDING GEAR (MLG) UPLOCK BOX								
	C24244007-3	MOS		TSR:0			30-MAR-2011		
32.220	H1058	HRS/MSC	O/C	TSR:0			1238.5		
	REF: AMM 32-12-17-900-801	AFL		TSR:0			863		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-12-17-900-801-02	RH MAIN LANDING GEAR (MLG) UPLOCK BOX								
	C24245007-3	MOS		TSR:0			20-APR-2011		
32.220	H1049	HRS/MSC	O/C	TSN:10323.42 TSR:0			1238.5		
	REF: AMM 32-12-17-900-801	AFL		TSN:6731 TSR:0			863		
32-12-25-900-801-01	LH (MLG) MAIN LANDING GEAR MAIN DOOR ACTUATOR								
	VN1031-2	MOS		TSN:0			13-DEC-2006		
32.050	1520	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-12-25-900-801	AFL		TSN:0			0		
32-12-25-900-801-02	RH (MLG) MAIN LANDING GEAR MAIN DOOR ACTUATOR								
	VN1031-2	MOS		TSN:0			13-DEC-2006		
32.050	1521	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-12-25-900-801	AFL		TSN:0			0		
32-12-29-900-801-01	LH MAIN LANDING GEAR (MLG) DOOR LATCH UPLOCK BOX								
	C24257002-2	MOS		TSN:0			13-DEC-2006		
32.250	H2229	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-12-29-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-12-29-900-801-02	RH MAIN LANDING GEAR (MLG) DOOR LATCH UPLOCK BOX									
	C24257002-2	MOS			TSN:0			13-DEC-2006		
32.250	H2230	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 32-12-29-900-801	AFL			TSN:0			0		
32-20-00-640-801-01 (s)	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				17-APR-2018		
32.070		HRS/MSC	400	+40				3041.8		
	REF: AMM 32-20-00-640-801	AFL						2328		
32-21-00-220-801-01	DETAILED INSPECTION NOSE LANDING GEAR (NLG) LEG									
	D23732000-1	MOS	72	+8m				08-JUL-2013	**08-JUL-2019**	08-MAR-2020
	B115	HRS/MSC						1872.8		
	REF: AMM 32-21-00-220-801	AFL						1323		
32-21-00-350-801-01	RESTORATION NOSE LANDING GEAR (NLG) LEG (OVERHAUL)									
	D23732000-1	MOS	144	+3%				04-MAY-2007	**04-MAY-2019**	13-SEP-2019
	B115	HRS/MSC								
OVERHAUL	**REF:** AMM 32-21-00-350-801	AFL	6000					0	**6000**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-00-900-801-01	NOSE LANDING GEAR (NLG) LEG								
	D23732000-1	MOS		TSN:0			13-DEC-2006		
32.080	B115	HRS/MSC	H/T	TSN:0			0		
	REF: AMM 32-21-00-900-801	AFL		TSN:0			0		
32-21-00-960-801-01	REPLACEMENT NOSE LANDING GEAR (NLG) LEG (DISCARD OF LIFE LIMITED PARTS)								
	D23732000-1	MOS					13-DEC-2006		
	B115	HRS/MSC					0		
LIFE LIMIT	**REF:** AMM 32-21-00-960-801	AFL	20000				0	**20000**	
+ 32-21-00-960-801-01A	REPLACEMENT OF THE NLG LEG (DISCARD OF LIFE LIMITED PARTS) - NLG LEG (5GB) (MANDATORY 5-40)								
	D23732000-1	MOS					13-DEC-2006		
	B115	HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 32-21-00-960-801	AFL	20000				0	**20000**	
32-21-01-780-801-01 (s)	CHECK OF THE CHARGING PRESSURE OF THE NLG SHOCK ABSORBER						PKG		
	PKG 21	MOS					24-APR-2018		
32.110		HRS/MSC	1600 +40				3041.8		
	REF: AMM 32-21-01-780-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-01-780-802-01	CHECK OF THE CHARGING PRESSURE OF THE NLG SHOCK ABSORBER BY APPLYING A ROTATIONAL TORQUE								
		MOS					13-DEC-2006		
32.780		HRS/MSC	O/C				0		
	REF: AMM 32-21-01-780-802	AFL					0		
32-21-01-900-801-01	NOSE LANDING GEAR (NLG) SHOCK ABSORBER								
	PN	MOS		TSN:0			13-DEC-2006		
32.080	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-21-01-900-801	AFL		TSN:0			0		
32-22-01-350-801-01	RESTORATION NOSE LANDING GEAR (NLG) DRAG BRACE (OVERHAUL)								
	D23754000	MOS	144	+3%			04-MAY-2007	**04-MAY-2019**	13-SEP-2019
32.100	HN008	HRS/MSC					0		
OVERHAUL	**REF:** AMM 32-22-01-350-801	AFL	6000				0	**6000**	
32-22-01-900-801-01	NOSE LANDING GEAR (NLG) DRAG BRACE								
	D23754000	MOS		TSN:0			13-DEC-2006		
32.100	HN008	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-22-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-22-13-900-801-01	NOSE LANDING GEAR (NLG) LEG ACTUATOR								
	D22795001	MOS		TSN:0			13-DEC-2006		
32.120	MM324	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-22-13-900-801	AFL		TSN:0			0		
32-22-17-900-801-01	NOSE LANDING GEAR (NLG) UPLOCK BOX								
	C24245006-3	MOS		TSN:0			13-DEC-2006		
32.190	H1603	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-22-17-900-801	AFL		TSN:0			0		
32-30-00-720-801-01 (s)	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS NORMAL OPERATION						PKG		
	PKG 21	MOS					24-APR-2018		
32.140		HRS/MSC	1600	+40			3041.8		
	REF: AMM 32-30-00-720-801	AFL					2328		
32-30-00-720-801-02 (s)	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS HYDRAULIC EMERGENCY OPERATION						PKG		
	PKG 21	MOS					24-APR-2018		
32.140		HRS/MSC	1600	+40			3041.8		
	REF: AMM 32-30-00-720-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-30-00-720-801-03 (s)	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS MECHANICAL EMERGENCY OPERATION							PKG		
	PKG 21	MOS						24-APR-2018		
32.140		HRS/MSC	1600	+40				3041.8		
	REF: AMM 32-30-00-720-801	AFL						2328		
32-30-13-900-801-01	L/G NORMAL/EMERGENCY SELECTOR VALVE									
	B94B09-202-1	MOS			TSN:0			13-DEC-2006		
32.230	C49079	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 32-30-13-900-801	AFL			TSN:0			0		
32-31-00-700-801-01 (s)	CHECK OF THE LANDING GEAR RETRACTION INHIBITION ON THE GROUND							PKG		
	PKG 21	MOS						24-APR-2018		
32.170		HRS/MSC	1600	+40				3041.8		
	REF: AMM 32-31-00-700-801	AFL						2328		
32-31-01-900-801-01	LANDING GEAR CONTROL LEVER									
	12-337-39	MOS			TSN:0			13-DEC-2006		
32.210	411	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 32-31-01-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-32-00-640-801-01 (s)	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE NOSE LANDING GEAR CONTROL						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
32.160		HRS/MSC					3041.8		
	REF: AMM 32-32-00-640-801	AFL					2328		
32-32-00-640-801-02 (s)	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE NLG CONTROL ACTUATION FORCE						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
		HRS/MSC					3041.8		
	REF: AMM 32-32-00-640-801	AFL					2328		
32-32-00-640-801-03 (s)	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE MLG CONTROLS						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
		HRS/MSC					3041.8		
	REF: AMM 32-32-00-640-801	AFL					2328		
32-32-00-640-801-04 (s)	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE MLG CONTROL ACTUATION FORCE						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
		HRS/MSC					3041.8		
	REF: AMM 32-32-00-640-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-32-00-700-801-01	CHECK AFTER LANDING GEAR EMERGENCY EXTENSION								
		MOS					13-DEC-2006		
32.820		HRS/MSC	A/R				0		
	REF: AMM 32-32-00-700-801	AFL					0		
		APH					0		
32-32-17-640-801-01 (s)	SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - LUBRICATION OF THE L/G HYDRAULIC EMERGENCY EXTENSION CONTROL						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			18-APR-2018		
32.150		HRS/MSC					3041.8		
	REF: AMM 32-32-17-640-801	AFL					2328		
32-32-17-640-801-02 (s)	SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - CHECK OF CONTROL ACTUATION LOADS						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			18-APR-2018		
		HRS/MSC					3041.8		
	REF: AMM 32-32-17-640-801	AFL					2328		
32-32-17-900-801-01	LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE								
	4808707	MOS		TSN:0			13-DEC-2006		
32.180	15092	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-32-17-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-40-00-780-801-01 (s)	CHECK SYSTEM NO.1 OF BRAKING PRESSURES							PKG		
	PKG 22	MOS						24-APR-2018		
32.380		HRS/MSC	3200	+40				3041.8		
	REF: AMM 32-40-00-780-801	AFL						2328		
32-40-00-780-801-02 (s)	CHECK SYSTEM NO.2 OF BRAKING PRESSURES							PKG		
	PKG 22	MOS						24-APR-2018		
32.380		HRS/MSC	3200	+40				3041.8		
	REF: AMM 32-40-00-780-801	AFL						2328		
32-40-00-780-801-03 (s)	CHECK OF PARKING BRAKING PRESSURES							PKG		
	PKG 22	MOS						24-APR-2018		
32.380		HRS/MSC	3200	+40				3041.8		
	REF: AMM 32-40-00-780-801	AFL						2328		
32-40-00-870-801-01	BLEEDING OF THE BRAKE HYDRAULIC SYSTEM									
		MOS						13-DEC-2006		
		HRS/MSC	O/C					0		
	REF: AMM 32-40-00-870-801	AFL						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-00-220-801-01 (s)	DETAILED INSPECTION OF THE BRAKE LINKAGE CONTROL						PKG		
	PKG 18 ,31,205	MOS	24 +1m				24-JUN-2017		
32.420		HRS/MSC					2832.2		
	REF: AMM 32-41-00-220-801	AFL					2192		
32-41-00-710-803-01	OPERATIONAL TEST OF THE AUTO-BRAKE SYSTEM								
		MOS					13-DEC-2006		
32.920		HRS/MSC	N/A				0		
	REF: AMM 32-41-00-710-803	AFL					0		
		APH					0		
32-41-00-710-803-01A	OPERATIONAL TEST OF THE AUTO-BRAKE SYSTEM (MANDATORY 5-40)								
		MOS					13-DEC-2006		
32.920		HRS/MSC	N/A				0		
	REF: AMM 32-41-00-710-803	AFL					0		
		APH					0		
32-41-00-720-803-01	FUNCTIONAL TEST OF THE AUTO-BRAKE SYSTEM TEST OF POSITIVE COIL OF PCB						PKG		
	PKG 39	MOS					13-DEC-2006		
32.905		HRS/MSC	N/A				0		
	REF: AMM 32-41-00-720-803	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-00-720-803-01A	FUNCTIONAL TEST OF THE AUTO-BRAKE SYSTEM TEST OF POSITIVE COIL OF PCB (MANDATORY 5-40)								
		MOS					13-DEC-2006		
32.905		HRS/MSC	N/A				0		
	REF: AMM 32-41-00-720-803	AFL					0		
		APH					0		
32-41-00-720-803-02	FUNCTIONAL TEST OF THE AUTO-BRAKE SYSTEM TEST OF NEGATIVE COIL OF PCB						PKG		
	PKG 39	MOS					13-DEC-2006		
32.910		HRS/MSC	N/A				0		
	REF: AMM 32-41-00-720-803	AFL					0		
		APH					0		
32-41-00-720-803-02A	FUNCTIONAL TEST OF THE AUTO-BRAKE SYSTEM TEST OF NEGATIVE COIL OF PCB (MANDATORY 5-40)								
		MOS					13-DEC-2006		
32.910		HRS/MSC	N/A				0		
	REF: AMM 32-41-00-720-803	AFL					0		
		APH					0		
32-41-00-720-803-03	FUNCTIONAL TEST OF THE AUTO-BRAKE SYSTEM TEST OF INDICATING SYSTEM								
		MOS					13-DEC-2006		
32.915		HRS/MSC	N/A				0		
	REF: AMM 32-41-00-720-803	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-00-720-803-03A	FUNCTIONAL TEST OF THE AUTO-BRAKE SYSTEM TEST OF INDICATING SYSTEM (MANDATORY 5-40)								
		MOS					13-DEC-2006		
32.915		HRS/MSC	N/A				0		
	REF: AMM 32-41-00-720-803	AFL					0		
		APH					0		
32-41-02-710-801-01	OPERATIONAL TEST NO. 1 BRAKING AND STEERING CONTROL (BSCU 1) UNIT								
	E213521020302	MOS					13-DEC-2006		
	400	HRS/MSC	O/C				0		
	REF: AMM 32-41-02-710-801	AFL					0		
32-41-02-710-801-02	OPERATIONAL TEST NO. 2 BRAKING AND STEERING CONTROL (BSCU 2) UNIT								
	E213521020302	MOS					13-DEC-2006		
	401	HRS/MSC	O/C				0		
	REF: AMM 32-41-02-710-801	AFL					0		
32-41-02-900-801-01	NO. 1 BRAKING AND STEERING CONTROL (BSCU 1) UNIT								
	E213521020302	MOS					07-MAY-2012		
32.530	400	HRS/MSC	O/C	TSN:1513			1513		
	REF: AMM 32-41-02-900-801	AFL		TSN:1052			1052		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-02-900-801-02	NO. 2 BRAKING AND STEERING CONTROL (BSCU 2) UNIT								
	E213521020302	MOS					07-MAY-2012		
32.530	401	HRS/MSC	O/C	TSN:1513			1513		
	REF: AMM 32-41-02-900-801	AFL		TSN:1052			1052		
32-41-05-900-801-01	LH BRAKE PEDAL POSITION TRANSMITTER								
	C20344000-1	MOS		TSN:0			13-DEC-2006		
32.360	00737	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-05-900-801	AFL		TSN:0			0		
32-41-05-900-801-02	RH BRAKE PEDAL POSITION TRANSMITTER								
	C20344000-1	MOS		TSN:0			13-DEC-2006		
32.360	00738	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-05-900-801	AFL		TSN:0			0		
32-41-07-610-801-01 (s)	SERVICING OF THE PEDAL INTERCONNECTION FLEXIBLE CONTROLS						PKG		
	PKG 31	MOS	72	+2m			19-JUN-2013		
32.430		HRS/MSC					1872.8		
	REF: AMM 32-41-07-610-801	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-07-900-801-01	LH INTERCONNECTION FLEXIBLE CONTROL								
	4807034	MOS		TSN:0			13-DEC-2006		
32.730	15876	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-07-900-801	AFL		TSN:0			0		
32-41-07-900-801-02	RH INTERCONNECTION FLEXIBLE CONTROL								
	4807034	MOS		TSN:0			13-DEC-2006		
32.730	15877	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-07-900-801	AFL		TSN:0			0		
32-41-09-720-801-01 (s)	FUNCTIONAL TEST OF THE LH HYDRAULIC FUSE						PKG		
	PKG 22	MOS					24-APR-2018		
		HRS/MSC	3200	+40			3041.8		
	REF: AMM 32-41-09-720-801	AFL					2328		
32-41-09-720-801-02 (s)	FUNCTIONAL TEST OF THE RH HYDRAULIC FUSE						PKG		
	PKG 22	MOS					24-APR-2018		
		HRS/MSC	3200	+40			3041.8		
	REF: AMM 32-41-09-720-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-17-900-801-01	NO. 1 SYSTEM BRAKE SHUT-OFF VALVE								
	65670-2	MOS		TSN:0			13-DEC-2006		
32.540	2897A	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-17-900-801	AFL		TSN:0			0		
32-41-17-900-801-02	NO. 2 SYSTEM BRAKE SHUT-OFF VALVE								
	65670-2	MOS		TSN:0			13-DEC-2006		
32.540	2895A	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-17-900-801	AFL		TSN:0			0		
32-41-33-900-801-01	LH INBOARD BRAKE TEMPERATURE SENSOR								
	C20547000	MOS		TSN:0			26-JAN-2016		
32.760	02095	HRS/MSC	O/C	TSN:0			2568.9		
	REF: AMM 32-41-33-900-801	AFL		TSN:0			1959		
32-41-33-900-801-02	RH INBOARD BRAKE TEMPERATURE SENSOR								
	C20547000	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-33-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-33-900-801-03	LH OUTBOARD BRAKE TEMPERATURE SENSOR								
	C20547000	MOS					04-FEB-2015		
	SN-UNKNOWN	HRS/MSC	O/C				2300.1		
	REF: AMM 32-41-33-900-801	AFL					1708		
32-41-33-900-801-04	RH OUTBOARD BRAKE TEMPERATURE SENSOR								
	C20547000	MOS		TSN:0			13-DEC-2006		
32.760	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-33-900-801	AFL		TSN:0			0		
32-41-37-960-801-01 (s)	REPLACE LH SYSTEM 1 BRAKE FILTER						PKG		
	ADB295-4 PKG 21	MOS					24-APR-2018		
32.390	2569	HRS/MSC	1600 +40				3041.8		
	REF: AMM 32-41-37-960-801	AFL					2328		
32-41-37-960-801-02 (s)	REPLACE RH SYSTEM 2 BRAKE FILTER						PKG		
	ADB295-4 PKG 21	MOS					24-APR-2018		
32.390	2565	HRS/MSC	1600 +40				3041.8		
	REF: AMM 32-41-37-960-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-37-960-801-03 (s)	REPLACE PARKING BRAKE (450GC) FILTER							PKG		
	PN PKG 21	MOS						24-APR-2018		
	SN-UNKNOWN	HRS/MSC	1600	+40				3041.8		
	REF: AMM 32-41-37-960-801	AFL						2328		
32-41-37-960-801-04 (s)	REPLACE PARKING BRAKE (460GC) FILTER							PKG		
	PN PKG 21	MOS						24-APR-2018		
	SN-UNKNOWN	HRS/MSC	1600	+40				3041.8		
	REF: AMM 32-41-37-960-801	AFL						2328		
32-41-49-900-801-01	LH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL TACHOMETER GENERATOR									
	C20345000	MOS			TSN:0			13-DEC-2006		
32.400	1482	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 32-41-49-900-801	AFL			TSN:0			0		
32-41-49-900-801-02	LH INBOARD MAIN LANDING GEAR (MLG) WHEEL TACHOMETER GENERATOR									
	C20345000	MOS			TSN:0			13-DEC-2006		
32.400	1483	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 32-41-49-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-49-900-801-03	RH INBOARD MAIN LANDING GEAR (MLG) WHEEL TACHOMETER GENERATOR								
	PN	MOS		TSN:0			13-DEC-2006		
32.410	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-49-900-801	AFL		TSN:0			0		
32-41-49-900-801-04	RH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL TACHOMETER GENERATOR								
	PN	MOS		TSN:0			13-DEC-2006		
32.410	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-49-900-801	AFL		TSN:0			0		
32-41-57-900-801-01	LH SYSTEM 1 BRAKE SERVOVALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
32-41-57-900-801-02	RH SYSTEM 1 BRAKE SERVOVALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-57-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-57-900-801-03	LH SYSTEM 2 BRAKE SERVOVALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-57-900-801	AFL		TSN:0			0		
32-41-57-900-801-04	RH SYSTEM 2 BRAKE SERVOVALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-57-900-801	AFL		TSN:0			0		
32-41-59-710-801-01	OPERATIONAL TEST OF THE AUTO-BRAKE PCB INDICATING SYSTEM								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 32-41-59-710-801	AFL					0		
		APH					0		
32-41-59-710-801-01A	OPERATIONAL TEST OF THE AUTO-BRAKE PCB INDICATING SYSTEM (MANDATORY 5-40)								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 32-41-59-710-801	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-59-710-801-02	OPERATIONAL TEST OF THE AUTO-BRAKE PCB MONITORING FUNCTION -BRAKE PCB MONITORING FUNCTION								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 32-41-59-710-801	AFL					0		
		APH					0		
32-41-59-710-801-02A	OPERATIONAL TEST OF THE AUTO-BRAKE PCB MONITORING FUNCTION (MANDATORY 5-40)								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 32-41-59-710-801	AFL					0		
		APH					0		
32-41-59-900-801-01	LH AUTO-BRAKE (PCB) PRINTED CIRCUIT BOARD								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-59-900-801	AFL		TSN:0			0		
32-41-59-900-801-02	RH AUTO-BRAKE (PCB) PRINTED CIRCUIT BOARD								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-59-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-42-00-610-801-01 (s)	SERVICING OF THE PARK BRAKE CONTROL							PKG		
	PKG 12 ,14 ,31	MOS	16	+1m				17-APR-2018		
32.450		HRS/MSC						3041.8		
	REF: AMM 32-42-00-610-801	AFL						2328		
32-42-01-900-801-01	PARK BRAKE SELECTOR VALVE									
	70012-21	MOS			TSN:0			13-DEC-2006		
32.480	712	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 32-42-01-900-801	AFL			TSN:0			0		
32-42-05-720-801-01 (s)	FUNCTIONAL TEST OF THE PARK BRAKE ACCUMULATOR CAPACITY							PKG		
	PKG 3 ,31	MOS	24	+1m				24-JUN-2017		
32.370		HRS/MSC	1200	+40				2832.2		
	REF: AMM 32-42-05-720-801	AFL						2192		
32-42-05-720-801-01A	FUNCTIONAL TEST OF THE PARK BRAKE ACCUMULATOR CAPACITY (MANDATORY 05-40)									
		MOS						24-JUN-2017		
32.370		HRS/MSC	1240					2832.2	**4072.2**	
CMR	**REF:** AMM 32-42-05-720-801	AFL						2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-42-05-720-801-02 (s)	FUNCTIONAL TEST OF THE PARK BRAKE ACCUMULATOR CAPACITY						PKG		
	PKG 14 ,31	MOS	32				17-APR-2018		
		HRS/MSC					3041.8		
	REF: AMM 32-42-05-720-801	AFL					2328		
32-42-05-780-801-01	CHECK OF THE PARK BRAKE SYSTEM ACCUMULATOR PRESSURE - PARK BRAKE ACCUMULATOR (110GC)								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 32-42-05-780-801	AFL					0		
32-42-05-900-801-01	PARK BRAKE ACCUMULATOR								
	47723-1200	MOS		TSN:0			13-DEC-2006		
32.510	263	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-42-05-900-801	AFL		TSN:0			0		
32-42-05-900-802-01	PARK BRAKE SYSTEM ACCUMULATOR SWITCH								
	ZMA387-00	MOS		TSN:0			13-DEC-2006		
32.600	00773	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-42-05-900-802	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-42-09-960-801-01	DISCARD PARK BRAKE HANDLE								
	6-4506	MOS					13-DEC-2006		
32.700	612	HRS/MSC					0		
LIFE LIMIT	**REF:** AMM 32-42-09-960-801	AFL	10000				0	**10000**	
		APH					0		
32-42-13-900-801-01	PARK BRAKE FLEXIBLE CONTROL								
	4808737	MOS		TSN:0			13-DEC-2006		
32.440	15100	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-42-13-900-801	AFL		TSN:0			0		
32-44-00-220-801-01	DETAILED INSPECTION OF THE MLG AND NLG WHEEL TIRES								
		MOS	2	+5d			24-APR-2018	**24-JUN-2018**	29-JUN-2018
		HRS/MSC					3041.8		
	REF: AMM 32-44-00-220-801	AFL					2328		
32-44-00-250-801-01	SPECIAL DETAILED INSPECTION LH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL SUBASSEMBLIES								
	C20545100	MOS					03-MAR-2018		
32.300	02256/00045	HRS/MSC					3007.5		
	REF: AMM 32-44-00-250-801	AFL	300	+100			2303	**2603**	2703

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-00-250-801-02	SPECIAL DETAILED INSPECTION LH INBOARD MAIN LANDING GEAR (MLG) WHEEL SUBASSEMBLIES									
	C20545100	MOS						03-MAR-2018		
32.310	00444/00411	HRS/MSC						3007.5		
	REF: AMM 32-44-00-250-801	AFL	300	+100				2303	**2603**	2703
32-44-00-250-801-03	SPECIAL DETAILED INSPECTION RH INBOARD MAIN LANDING GEAR (MLG) WHEEL SUBASSEMBLIES									
	C20545100	MOS						13-OCT-2017		
32.320	00307	HRS/MSC						2933.3		
	REF: AMM 32-44-00-250-801	AFL	1500	+3%				2258	**3758**	3803
32-44-00-250-801-04	SPECIAL DETAILED INSPECTION RH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL SUBASSEMBLIES									
	C20545100	MOS						13-OCT-2017		
32.330	0234	HRS/MSC						2933.3		
	REF: AMM 32-44-00-250-801	AFL	1500	+3%				2258	**3758**	3803
32-44-00-250-801-05	SPECIAL DETAILED INSPECTION LH NOSE LANDING GEAR (NLG) WHEEL SUBASSEMBLIES									
	C20546000	MOS						01-APR-2016		
32.340	00338	HRS/MSC						2602.4		
	REF: AMM 32-44-00-250-801	AFL	3000	+3%	TSI:0			1981	**3888**	3978

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-00-250-801-06	SPECIAL DETAILED INSPECTION RH NOSE LANDING GEAR (NLG) WHEEL SUBASSEMBLIES									
	C20546000	MOS						01-APR-2016		
32.350	00347	HRS/MSC						2602.4		
	REF: AMM 32-44-00-250-801	AFL	3000	+3%	TSI:0			1981	**3888**	3978
32-44-00-780-801-01	PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES									
		MOS	2	+5d		-15		25-APR-2018	**10-JUN-2018**	15-JUN-2018
		HRS/MSC						3041.8		
	REF: AMM 32-44-00-780-801	AFL						2328		
32-44-01-900-801-01	LH NOSE LANDING GEAR (NLG) WHEEL									
	C20546000	MOS			TSR:0			01-APR-2016		
32.340	00338	HRS/MSC	O/C		TSR:0			2602.4		
	REF: AMM 32-44-01-900-801	AFL			TSN:1093 TSR:0			1981		
32-44-01-900-801-02	RH NOSE LANDING GEAR (NLG) WHEEL									
	C20546000	MOS			TSR:0			01-APR-2016		
32.350	00347	HRS/MSC	O/C		TSR:0			2602.4		
	REF: AMM 32-44-01-900-801	AFL			TSN:1093 TSR:0			1981		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-05-900-801-01	LH NOSE LANDING GEAR (NLG) TIRE								
	M15201-01	MOS		TSN:19			01-NOV-2017		
32.340	6099C112	HRS/MSC	O/C	TSN:0			2933.3		
	REF: AMM 32-44-05-900-801	AFL		TSN:0			2258		
32-44-05-900-801-02	RH NOSE LANDING GEAR (NLG) TIRE								
	M15201-01	MOS		TSN:19			01-NOV-2017		
32.350	6203C257	HRS/MSC	O/C	TSN:0			2933.3		
	REF: AMM 32-44-05-900-801	AFL		TSN:0			2258		
32-44-09-350-801-01	RESTORATION LH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL (OVERHAUL)								
	C20545100	MOS					03-MAR-2018		
	02256/00045	HRS/MSC	O/C				3007.5		
	REF:	AFL					2303		
32-44-09-350-801-02	RESTORATION LH INBOARD MAIN LANDING GEAR (MLG) WHEEL (OVERHAUL)								
	C20545100	MOS					03-MAR-2018		
	00444/00411	HRS/MSC	O/C				3007.5		
	REF:	AFL					2303		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-09-350-801-03	RESTORATION RH INBOARD MAIN LANDING GEAR (MLG) WHEEL (OVERHAUL)								
	C20545100	MOS					13-OCT-2017		
	00307	HRS/MSC	O/C				2933.3		
	REF:	AFL					2258		
32-44-09-350-801-04	RESTORATION RH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL (OVERHAUL)								
	C20545100	MOS					13-OCT-2017		
	0234	HRS/MSC	O/C				2933.3		
	REF:	AFL					2258		
32-44-09-900-801-01	LH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL								
	C20545100	MOS		TSO:16			03-MAR-2018		
32.300	02256/00045	HRS/MSC	O/C	TSO:0			3007.5		
	REF: AMM 32-44-09-900-801	AFL		TSO:0			2303		
32-44-09-900-801-02	LH INBOARD MAIN LANDING GEAR (MLG) WHEEL								
	C20545100	MOS		TSO:14			03-MAR-2018		
32.310	00444/00411	HRS/MSC	O/C	TSO:0			3007.5		
	REF: AMM 32-44-09-900-801	AFL		TSO:0			2303		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-09-900-801-03	RH INBOARD MAIN LANDING GEAR (MLG) WHEEL								
	C20545100	MOS		TSO:9			13-OCT-2017		
32.320	00307	HRS/MSC	O/C	TSO:256.4			2933.3		
	REF: AMM 32-44-09-900-801	AFL		TSO:182			2258		
32-44-09-900-801-04	RH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL								
	C20545100	MOS		TSO:0			13-OCT-2017		
32.330	0234	HRS/MSC	O/C	TSO:0			2933.3		
	REF: AMM 32-44-09-900-801	AFL		TSO:0			2258		
32-44-13-900-801-01	LH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL TIRE								
	M15101-01	MOS		TSN:23			03-MAR-2018		
32.300	5312J112	HRS/MSC	O/C	TSN:0			3007.5		
	REF: AMM 32-44-13-900-801	AFL		TSN:0			2303		
32-44-13-900-801-02	LH INBOARD MAIN LANDING GEAR (MLG) WHEEL TIRE								
	M15101-01	MOS		TSN:18			03-MAR-2018		
32.310	6102J107	HRS/MSC	O/C	TSN:0			3007.5		
	REF: AMM 32-44-13-900-801	AFL		TSN:0			2303		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-13-900-801-03	RH INBOARD MAIN LANDING GEAR (MLG) WHEEL TIRE								
	M15101-1	MOS		TSN:2			13-OCT-2017		
32.320	7113J101	HRS/MSC	O/C	TSN:0			2933.3		
	REF: AMM 32-44-13-900-801	AFL		TSN:0			2258		
32-44-13-900-801-04	RH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL TIRE								
	M15101-01	MOS		TSN:2			13-OCT-2017		
32.330	7122J105	HRS/MSC	O/C	TSN:0			2933.3		
	REF: AMM 32-44-13-900-801	AFL		TSN:0			2258		
32-44-17-350-801-01	RESTORATION LH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE (OVERHAUL)								
	C20544000	MOS					04-FEB-2015		
32.460	00112	HRS/MSC	A/R				2300.1		
OVERHAUL	**REF:** AMM 32-44-17-350-801	AFL					1708		
32-44-17-350-801-02	RESTORATION LH INBOARD MAIN LANDING GEAR (MLG) BRAKE (OVERHAUL)								
	C20544000	MOS					11-JAN-2016		
32.460	00236	HRS/MSC	A/R				2553		
OVERHAUL	**REF:** AMM 32-44-17-350-801	AFL					1942		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-17-350-801-03	RESTORATION RH INBOARD MAIN LANDING GEAR (MLG) BRAKE (OVERHAUL)								
	C20544000	MOS					13-DEC-2006		
32.470	00529	HRS/MSC	A/R				0		
OVERHAUL	**REF:** AMM 32-44-17-350-801	AFL					0		
32-44-17-350-801-04	RESTORATION RH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE (OVERHAUL)								
	C20544000	MOS					13-DEC-2006		
32.470	00530	HRS/MSC	A/R				0		
OVERHAUL	**REF:** AMM 32-44-17-350-801	AFL					0		
32-44-17-900-801-01	LH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE								
	C20544000	MOS		TSO:0			04-FEB-2015		
32.460	00112	HRS/MSC	O/C	TSN:1279 TSO:0			2300.1		
	REF: AMM 32-44-17-900-801	AFL		TSN:1100 TSO:0			1708		
32-44-17-900-801-02	LH INBOARD MAIN LANDING GEAR (MLG) BRAKE								
	C20544000	MOS		TSO:0			11-JAN-2016		
32.460	00236	HRS/MSC	O/C	TSO:0			2553		
	REF: AMM 32-44-17-900-801	AFL		TSO:0			1942		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-17-900-801-03	RH INBOARD MAIN LANDING GEAR (MLG) BRAKE								
	C20544000	MOS		TSN:0			13-DEC-2006		
32.470	00529	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-44-17-900-801	AFL		TSN:0			0		
32-44-17-900-801-04	RH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE								
	C20544000	MOS		TSN:0			13-DEC-2006		
32.470	00530	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-44-17-900-801	AFL		TSN:0			0		
32-44-18-960-801-01	REPLACEMENT LH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE SEAL								
	C20544000	MOS					04-FEB-2015		
32.460	00112	HRS/MSC	A/R				2300.1		
	REF: AMM 32-44-18-960-801	AFL					1708		
32-44-18-960-801-02	REPLACEMENT LH INBOARD MAIN LANDING GEAR (MLG) BRAKE SEAL								
	C20544000	MOS					11-JAN-2016		
32.460	00236	HRS/MSC	A/R				2553		
	REF: AMM 32-44-18-960-801	AFL					1942		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-18-960-801-03	REPLACEMENT RH INBOARD MAIN LANDING GEAR (MLG) BRAKE SEAL								
	C20544000	MOS					13-DEC-2006		
32.470	00529	HRS/MSC	A/R				0		
	REF: AMM 32-44-18-960-801	AFL					0		
32-44-18-960-801-04	REPLACEMENT RH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE SEAL								
	C20544000	MOS					13-DEC-2006		
32.470	00530	HRS/MSC	A/R				0		
	REF: AMM 32-44-18-960-801	AFL					0		
32-44-21-900-801-01	UPPER BRAKE SWIVEL COUPLING								
	A100-24660	MOS		TSN:0			13-DEC-2006		
32.500	H1148	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-44-21-900-801	AFL		TSN:0			0		
32-44-21-900-801-02	LOWER BRAKE SWIVEL COUPLING								
	A101-24660	MOS		TSN:0			13-DEC-2006		
32.500	H1145	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-44-21-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-50-00-710-801-01 (s)	OPERATIONAL TEST OF THE STEERING CONTROL SYSTEM							PKG		
	PKG 31	MOS	72	+2m				08-JUL-2013		
32.670		HRS/MSC						1872.8		
	REF: AMM 32-50-00-710-801	AFL	3750					1323		
32-50-25-900-801-01	STEERING CONTROL HANDWHEEL UNIT									
	287837-1	MOS			TSN:0			13-DEC-2006		
32.680	H1571	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 32-50-25-900-801	AFL			TSN:0			0		
32-61-45-900-801-01	LH GEAR DOOR ACTUATOR PROXIMITY SWITCH									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 32-61-45-900-801	AFL			TSN:0			0		
32-61-45-900-801-02	RH GEAR DOOR ACTUATOR PROXIMITY SWITCH									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 32-61-45-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-49-900-801-01	LH BRACE ACTUATOR MONITORING PROXIMITY SWITCH								
	D22884000-1	MOS		TSN:0			13-DEC-2006		
32.055	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
32-61-49-900-801-02	LH BRACE ACTUATOR CONTROL PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-61-49-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		
32-61-49-900-801-03	RH BRACE ACTUATOR MONITORING PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-61-49-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		
32-61-49-900-801-04	RH BRACE ACTUATOR CONTROL PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-61-49-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-49-900-801-05	LH MAIN LANDING GEAR (MLG) UPLOCK BOX PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-61-49-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		
32-61-49-900-801-06	RH MAIN LANDING GEAR (MLG) UPLOCK BOX PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-61-49-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		
32-61-49-900-801-07	LH MAIN LANDING GEAR (MLG) DOOR LATCH CONTROL PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-61-49-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		
32-61-49-900-801-08	LH MAIN LANDING GEAR (MLG) DOOR LATCH MONITORING PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-61-49-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-49-900-801-09	RH MAIN LANDING GEAR (MLG) DOOR LATCH CONTROL PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-61-49-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		
32-61-49-900-801-10	RH MAIN LANDING GEAR (MLG) DOOR LATCH MONITORING PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-61-49-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		
32-61-49-900-801-11	LH MAIN LANDING GEAR (MLG) LEG INBOARD PROXIMITY SWITCH								
	D22884000-1	MOS		TSN:0			13-DEC-2006		
32.055	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-61-49-900-801	AFL		TSN:0			0		
32-61-49-900-801-12	LH MAIN LANDING GEAR (MLG) OUTBOARD PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
		APH		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-49-900-801-13	RH MAIN LANDING GEAR (MLG) LEG INBOARD PROXIMITY SWITCH								
	D22884000-1	MOS		TSN:0			13-DEC-2006		
32.065	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-61-49-900-801	AFL		TSN:0			0		
32-61-49-900-801-14	RH MAIN LANDING GEAR (MLG) LEG OUTBOARD PROXIMITY SWITCH								
	D22884000-1	MOS		TSN:0			13-DEC-2006		
32.065	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
32-61-49-900-801-15	NOSE LANDING GEAR (NLG) DRAG BRACE MONITORING PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
		APH		TSN:0			0		
32-61-49-900-801-16	NOSE LANDING GEAR (NLG) DRAG BRACE CONTROL PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-61-49-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-49-900-801-17	NOSE LANDING GEAR (NLG) UPLOCK BOX CONTROL MONITORING SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
		APH		TSN:0			0		
32-61-49-900-801-18	NOSE LANDING GEAR (NLG) UPLOCK BOX MONITORING PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
		APH		TSN:0			0		
32-61-49-900-801-19	LH NOSE LANDING GEAR LEG PROXIMITY SWITCH								
	D22858000-1	MOS		TSN:0			13-DEC-2006		
32.520	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
32-61-49-900-801-20	RH NOSE LANDING GEAR LEG PROXIMITY SWITCH								
	D22859000-2	MOS		TSN:0			13-DEC-2006		
32.520	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-49-900-801-21	NOSE LANDING GEAR (NLG) LH MAIN DOOR PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
		APH		TSN:0			0		
32-61-49-900-801-22	NOSE LANDING GEAR (NLG) RH MAIN DOOR PROXIMITY SWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
		APH		TSN:0			0		
322806	NOSE LANDING GEAR SWIVEL COUPLING								
	C24266-1	MOS		TSN:0			13-DEC-2006		
32.130	H1409	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
323806	LH MAIN LANDING GEAR EXTENSION RESTRICTOR VALVE								
	A24508-5160	MOS		TSN:0			13-DEC-2006		
32.200	H3060	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323811	RH MAIN LANDING GEAR EXTENSION RESTRICTOR VALVE								
	A24508-5160	MOS		TSN:0			13-DEC-2006		
32.200	H3059	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
323836	LANDING GEAR/DOOR HYDRAULIC SUPPLY UNIT								
	BHC1031-2	MOS		TSN:349 TSR:0		06/11/2017	11-JUN-2015		
32.240	24	HRS/MSC	O/C	TSO:12771 TSR:0			2406.8		
	REF: GENERIC NO REF	AFL		TSO:6359 TSR:0			1811		
323851	NOSE LANDING GEAR (NLG) EXTENSION RESTRICTOR VALVE								
	A24508-5180	MOS		TSN:0			13-DEC-2006		
32.260	H2889	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
323856	NOSE LANDING GEAR (NLG) RETRACTION RESTRICTOR VALVE								
	A24508-5070	MOS		TSN:0			13-DEC-2006		
32.260	H2863	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323861	MAIN LANDING GEAR (MLG) HYDRAULIC PROTECTION SYSTEM CHECK VALVE								
	C24816000	MOS		TSN:0			13-DEC-2006		
32.270	FM1141	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
323866	LANDING GEAR EMERGENCY HYDRAULIC EXTENSION HANDLE								
	4509-2	MOS		TSN:0			13-DEC-2006		
32.280	4529	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
323871	LH MAIN LANDING GEAR/DOOR FREE FALL FLEX CONTROL								
	4808714	MOS		TSN:0			13-DEC-2006		
32.290	15090	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
323876	RH MAIN LANDING GEAR/DOOR FREE FALL FLEX CONTROL								
	4808536	MOS		TSN:0			13-DEC-2006		
32.290	15122	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324157	LH SYSTEM NO.1 BRAKE SERVOVALVE MANIFOLD								
	C20103510-1	MOS		TSR:0			21-AUG-2008		
32.550	00951	HRS/MSC	O/C	TSN:3412 TSR:0			429.8		
	REF: AMM 32-41-57-900-801	AFL		TSN:1811 TSR:0			319		
324158	RH SYSTEM NO.1 BRAKE SERVOVALVE MANIFOLD								
	C20103510-1	MOS		TSR:0			24-JUN-2017		
32.550	151	HRS/MSC	O/C	TSR:0			2833.6		
	REF: AMM 32-41-57-900-801	AFL		TSR:0			2193		
324159	LH SYSTEM NO.2 BRAKE SERVOVALVE MANIFOLD								
	C20103510-1	MOS					24-JUN-2017		
32.560	151	HRS/MSC	O/C				2832.2		
	REF: AMM 32-41-57-900-801	AFL					2192		
324160	RH SYSTEM NO.2 BRAKE SERVOVALVE MANIFOLD								
	C20103510-1	MOS		TSR:0			03-JUN-2010		
32.560	00970	HRS/MSC	O/C	TSN:1567 TSR:0			943.2		
	REF: AMM 32-41-57-900-801	AFL		TSR:0			671		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324801	LH HYDRAULIC FUSE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324802	RH HYDRAULIC FUSE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324807	PARKING BRAKE DISTRIBUTOR CHECK VALVE								
	C24815000	MOS		TSN:0			13-DEC-2006		
32.480	FM1028	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324809	LH BRAKE SYSTEM SHUTTLE VALVE								
	CN100	MOS		TSN:0			13-DEC-2006		
32.490	1634	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324812	RH BRAKE SYSTEM SHUTTLE VALVE								
	CN100	MOS		TSN:0			13-DEC-2006		
32.490	1635	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324815	PARK BRAKE SYSTEM THERMAL VALVE								
	V3500-61	MOS		TSN:0			13-DEC-2006		
32.490	374	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324851	LH SYSTEM 1 BRAKE FILTER								
	ADB295-4	MOS		TSN:0			13-DEC-2006		
32.570	2569	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324852	RH SYSTEM 2 BRAKE FILTER								
	ADB295-4	MOS		TSN:0			13-DEC-2006		
32.570	2565	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324853	PARKING BRAKE (450GC) FILTER								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324854	PARKING BRAKE (460GC) FILTER								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324856	NO. 1 SYSTEM HYDRAULIC NON RETURN VALVE								
	A24515	MOS		TSN:0			13-DEC-2006		
32.720	FM3785	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324860	LH SYSTEM NO.1 BRAKE CHECK VALVE								
	A24516	MOS		TSN:0			13-DEC-2006		
32.610	FM5967	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324861	RH BRAKE ACCUMULATOR PRESSURE GAUGE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324863	RH SYSTEM NO.1 BRAKE CHECK VALVE								
	A24516	MOS		TSN:0			13-DEC-2006		
32.610	FM5966	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324866	LH SYSTEM NO.2 BRAKE CHECK VALVE								
	A24516	MOS		TSN:0			13-DEC-2006		
32.620	FM5969	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324869	RH SYSTEM NO.2 BRAKE CHECK VALVE								
	A24516	MOS		TSN:0			13-DEC-2006		
32.620	FM5968	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32486A	LH SYSTEM NO.1 BRAKE PRESSURE SWITCH								
	ZMA387-00	MOS		TSN:104			04-AUG-2015		
32.580	00789	HRS/MSC	O/C	TSN:2439.3			2439.3		
	REF: GENERIC NO REF	AFL		TSN:1841			1841		
32486B	RH SYSTEM NO.1 BRAKE PRESSURE SWITCH								
	ZMA387-00	MOS		TSN:0			13-DEC-2006		
32.580	00787	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
32486C	LH SYSTEM NO.2 BRAKE PRESSURE SWITCH								
	7G1042	MOS		TSN:104			04-AUG-2015		
32.590	1237	HRS/MSC	O/C	TSN:2439.3			2439.3		
	REF: GENERIC NO REF	AFL		TSN:1841			1841		
32486D	RH SYSTEM NO.2 BRAKE PRESSURE SWITCH								
	7G1042	MOS		TSN:0			07-AUG-2015		
32.590	2161	HRS/MSC	O/C	TSN:0			2439.3		
	REF: GENERIC NO REF	AFL		TSN:0			1841		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324871	LH BRAKE ACCUMULATOR PRESSURE GAUGE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324872	LH SYSTEM NO.1 BRAKE RESTRICTOR								
	C24758080	MOS		TSN:0			13-DEC-2006		
32.630	H1918	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324875	RH SYSTEM NO.1 BRAKE RESTRICTOR								
	C24758080	MOS		TSN:0			13-DEC-2006		
32.630	H1919	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324878	LH SYSTEM NO.2 BRAKE RESTRICTOR								
	C24758080	MOS		TSN:0			13-DEC-2006		
32.640	H1917	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324881	RH SYSTEM NO.2 BRAKE RESTRICTOR								
	C24758080	MOS		TSN:0			13-DEC-2006		
32.640	H1920	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
324894	NO. 1 BRAKE TEST PRESSURE SWITCH								
	ZMA387-00	MOS		TSN:104			04-AUG-2015		
32.740	00772	HRS/MSC	O/C	TSN:2439.3			2439.3		
	REF: GENERIC NO REF	AFL		TSN:1841			1841		
324895	NO. 2 BRAKE TEST PRESSURE SWITCH								
	1203P0224	MOS		TSN:0			27-SEP-2010		
32.740	0026	HRS/MSC	O/C	TSN:0			1064.6		
	REF: GENERIC NO REF	AFL		TSN:0			753		
324896	PARK BRAKE HANDLE								
	6-4506	MOS		TSN:0			13-DEC-2006		
32.700	612	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324898	PARK BRAKE SENSOR								
	84738712	MOS		TSN:0			13-DEC-2006		
32.770	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
325801	NOSE GEAR STEERING SOLENOID VALVE								
	65670-2	MOS		TSN:0			13-DEC-2006		
32.680	2871A	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
325803	NOSE GEAR STEERING CHECK VALVE								
	A24515	MOS		TSN:0			13-DEC-2006		
32.680	FM3809	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 33	**LIGHTS**								
33-10-13-900-801-01	(90LC) SHIELD RHEOSTAT								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-10-13-900-801	AFL		TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-10-13-900-801-03	(135LC) PANEL RHEOSTAT								
	0280-2006-0010	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-10-13-900-801	AFL		TSN:0			0		
33-10-13-900-801-04	(136LC) DIM/BRIGHT ROTATORY SWITCH								
	0280-2006-0010	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-10-13-900-801	AFL		TSN:0			0		
33-10-17-900-801-01	LH CIRCUIT BREAKER SPOTLIGHTS PANEL								
	PN	MOS		TSN:0			13-DEC-2006		
33.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-10-17-900-801	AFL		TSN:0			0		
33-10-17-900-801-02	RH CIRCUIT BREAKER SPOTLIGHTS PANEL								
	PN	MOS		TSN:0			13-DEC-2006		
33.030	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-10-17-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-40-01-900-801-01	LH WING NAVIGATION LIGHT								
	03-9001-0003	MOS		TSN:10			22-JAN-2018		
33.350	30121003	HRS/MSC	O/C	TSN:0			2970.6		
	REF: AMM 33-40-01-900-801	AFL		TSN:0			2282		
33-40-01-900-801-02	RH WING NAVIGATION LIGHT								
	03-9001-0004	MOS		TSN:0			28-APR-2010		
33.350	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			900.3		
	REF: AMM 33-40-01-900-801	AFL		TSN:0			636		
33-40-09-900-802-01	UPPER ANTI-COLLISION RED LIGHT								
	01-0790044-09	MOS		TSN:0			13-DEC-2006		
33.100	05515	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-09-900-802	AFL		TSN:0			0		
33-40-33-900-801-01	LH UPPER LOGO LIGHT (L310LX)								
	PN	MOS		TSN:0			13-DEC-2006		
33.330	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-33-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-40-33-900-801-02	RH UPPER LOGO LIGHT (R310LX)								
	PN	MOS		TSN:0			13-DEC-2006		
33.330	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-33-900-801	AFL		TSN:0			0		
33-40-33-900-801-03	LH LOWER LOGO LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-33-900-801	AFL		TSN:0			0		
33-40-33-900-801-03	LH LOWER LOGO LOGHT (L320LX)								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-33-900-801	AFL		TSN:0			0		
33-40-33-900-801-04	RH LOWER LOGO LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-33-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-40-33-900-801-04	RH LOWER LOGO LIGHT (R320LX)								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-33-900-801	AFL		TSN:0			0		
33-40-37-900-801-01	LH LANDING LIGHT								
	4240531	MOS		TSN:0			13-DEC-2006		
33.130	75533	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-37-900-801	AFL		TSN:0			0		
33-40-37-900-801-02	RH LANDING LIGHT								
	4240531	MOS		TSN:0			13-DEC-2006		
33.130	75532	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-37-900-801	AFL		TSN:0			0		
33-40-41-900-801-01	TAXI LIGHT								
	4060622	MOS		TSN:0			13-DEC-2006		
33.150	87678	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-41-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-00-720-801-01	FUNCTIONAL TEST NO. 1 EMERGENCY LIGHTING (EPS 1) POWER SUPPLY								
	D734-02-001	MOS	17	+3%			18-MAY-2018	**18-OCT-2019**	02-NOV-2019
33.200	4715/06-2014	HRS/MSC					3041.8		
	REF: AMM 33-50-00-720-801	AFL					2328		
33-50-00-720-801-02	FUNCTIONAL TEST NO. 2 EMERGENCY LIGHTING (EPS 2) POWER SUPPLY								
	D734-02-001	MOS	17	+3%			18-MAY-2018	**18-OCT-2019**	02-NOV-2019
33.200	4716/06-2014	HRS/MSC					3041.8		
	REF: AMM 33-50-00-720-801	AFL					2328		
33-50-00-720-801-03	FUNCTIONAL TEST NO. 3 EMERGENCY LIGHTING (EPS 3) POWER SUPPLY								
	D734-02-001	MOS	17	+3%			18-MAY-2018	**18-OCT-2019**	02-NOV-2019
33.210	4826/10-2014	HRS/MSC					3041.8		
	REF: AMM 33-50-00-720-801	AFL					2328		
33-50-05-350-803-01	RESTORATION (OVERHAUL) PILOT FLASHLIGHT (AIR LITE 2R LED ONLY)								
	PN	MOS					13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 33-50-05-350-803	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-05-350-803-02	RESTORATION (OVERHAUL) COPILOT FLASHLIGHT (AIR LITE 2R LED ONLY)								
	PN	MOS					13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 33-50-05-350-803	AFL					0		
33-50-05-900-801-01	PILOT FLASHLIGHT								
	PN	MOS							
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: See Workcard	AFL							
33-50-05-900-801-02	COPILOT FLASHLIGHT								
	PN	MOS							
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: See Workcard	AFL							
33-50-05-960-801-01	DISCARD OF THE RECHARGEABLE FLASHLIGHT BATTERY - LH FLASHLIGHT BATTERY (9610ME)								
	PN	MOS							
	SN-UNKNOWN	HRS/MSC	N/A						
	REF: AMM 33-50-05-960-801	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-05-960-801-02	DISCARD OF THE RECHARGEABLE FLASHLIGHT BATTERY - RH FLASHLIGHT BATTERY (9620ME)								
	PN	MOS							
	SN-UNKNOWN	HRS/MSC	N/A						
	REF: AMM 33-50-05-960-801	AFL							
33-50-33-610-801-01	SERVICING NO. 1 EMERGENCY LIGHTING (EPS 1) POWER SUPPLY								
	D734-02-001	MOS					10-JUN-2015		
33.200	4715/06-2014	HRS/MSC	O/C				2406.8		
	REF: AMM 33-50-33-610-801	AFL					1811		
33-50-33-610-801-02	SERVICING NO. 2 EMERGENCY LIGHTING (EPS 2) POWER SUPPLY								
	D734-02-001	MOS					10-JUN-2015		
33.200	4716/06-2014	HRS/MSC	O/C				2406.8		
	REF: AMM 33-50-33-610-801	AFL					1811		
33-50-33-610-801-03	SERVICING NO. 3 EMERGENCY LIGHTING (EPS 3) POWER SUPPLY								
	D734-02-001	MOS					10-JUN-2015		
33.210	4826/10-2014	HRS/MSC	O/C				2406.8		
	REF: AMM 33-50-33-610-801	AFL					1811		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-33-900-801-01	NO. 1 EMERGENCY LIGHTING (EPS 1) POWER SUPPLY								
	D734-02-001	MOS		TSN:24 TSR:0			24-JUN-2017		
33.200	4715/06-2014	HRS/MSC	O/C	TSN:425.4 TSR:0			2832.2		
	REF: AMM 33-50-33-900-801	AFL		TSN:381 TSR:0			2192		
33-50-33-900-801-02	NO. 2 EMERGENCY LIGHTING (EPS 2) POWER SUPPLY								
	D734-02-001	MOS		TSN:24 TSR:0			24-JUN-2017		
33.200	4716/06-2014	HRS/MSC	O/C	TSN:425.4 TSR:0			2832.2		
	REF: AMM 33-50-33-900-801	AFL		TSN:381 TSR:0			2192		
33-50-33-900-801-03	NO. 3 EMERGENCY LIGHTING (EPS 3) POWER SUPPLY								
	D734-02-001	MOS		TSN:24 TSR:0			24-JUN-2017		
33.210	4826/10-2014	HRS/MSC	O/C	TSN:425.4 TSR:0			2832.2		
	REF: AMM 33-50-33-900-801	AFL		TSN:381 TSR:0			2192		
33-50-37-900-801-01	NO. 1 EMERGENCY POWER SUPPLY BATTERY PACK								
	D734-02-001	MOS					24-JUN-2017		
	4715	HRS/MSC	O/C				2832.2		
	REF: AMM 33-50-37-900-801	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-37-900-801-02	NO. 2 EMERGENCY POWER SUPPLY BATTERY PACK								
	D734-02-001	MOS					24-JUN-2017		
	4716	HRS/MSC	O/C				2832.2		
	REF: AMM 33-50-37-900-801	AFL					2192		
33-50-37-900-801-03	NO. 3 EMERGENCY POWER SUPPLY BATTERY PACK								
	D734-02-001	MOS					24-JUN-2017		
	4826	HRS/MSC	O/C				2832.2		
	REF: AMM 33-50-37-900-801	AFL					2192		
33-50-37-960-802-01	DISCARD NO. 1 EMERGENCY POWER SUPPLY BATTERY PACK								
	D734-02-001	MOS	25				13-JUN-2017	**13-JUL-2019**	
33.200	4715	HRS/MSC							
LIFE LIMIT	**REF:** AMM 33-50-37-960-802	AFL							
33-50-37-960-802-02	DISCARD NO. 2 EMERGENCY POWER SUPPLY BATTERY PACK								
	D734-02-001	MOS	25				13-JUN-2017	**13-JUL-2019**	
33.200	4716	HRS/MSC							
LIFE LIMIT	**REF:** AMM 33-50-37-960-802	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-37-960-802-03	DISCARD NO. 3 EMERGENCY POWER SUPPLY BATTERY PACK								
	D734-02-001	MOS	25				13-JUN-2017	**13-JUL-2019**	
33.210	4826	HRS/MSC							
LIFE LIMIT	**REF:** AMM 33-50-37-960-802	AFL							
331001	PILOT UPPER SHIELD LIGHT								
	C0567F100	MOS		TSN:0			13-DEC-2006		
33.040	176	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-10-09-960-801	AFL		TSN:0			0		
331002	COPILOT UPPER SHIELD LIGHT								
	C0566F100	MOS		TSN:0			13-DEC-2006		
33.040	171	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-10-09-960-801	AFL		TSN:0			0		
331801	PILOT READING LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.010	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331806	COPILOT READING LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.010	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
331811	PILOT READING LIGHT DIMMER BOX								
	24-01	MOS		TSN:0			13-DEC-2006		
33.020	050030	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
331816	COPILOT READING LIGHT DIMMER BOX								
	24-01	MOS		TSN:0			13-DEC-2006		
33.020	050029	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
331841	SHIELD LIGHTING POWER SUPPLY								
	PN	MOS		TSN:0			13-DEC-2006		
33.050	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331846	INSTRUMENT LIGHTING POWER SUPPLY								
	PN	MOS		TSN:0			13-DEC-2006		
33.050	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
331856	INSTRUMENT LIGHTING TRANSFORMER								
	96PS002	MOS		TSN:0			13-DEC-2006		
33.060	1213	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
331871	PULSELITE CONTROL UNIT								
	PE892	MOS		TSN:0			13-DEC-2006		
33.270	622	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
333801	AFT SERVICING COMPARTMENT CEILING LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
333811	BAGGAGE COMPARTMENT CEILING LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.250	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
333821	FORWARD SERVICING COMPARTMENT CEILING LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.300	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
333841	BAGGAGE COMPARTMENT DOOR FLOODLIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.080	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
333846	FUELING PANEL FLOODLIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.310	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
333861	NOSE CONE INSPECTION LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.320	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
334002	BELLY ANTI-COLLISION LIGHT								
	39-59-2	MOS		TSN:0			13-DEC-2006		
33.290	932	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-09-960-803	AFL		TSN:0			0		
334003	REAR NAVIGATION AND ANTI-COLLISION WHITE LIGHT								
	39-54-21	MOS		TSN:0			13-DEC-2006		
33.260	1487	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-07-900-801	AFL		TSN:0			0		
334004	LH WING ANTI-COLLISION WHITE LIGHT								
	03-9503-5003	MOS		TSN:0			28-APR-2010		
33.160	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			900.3		
	REF: See Workcard	AFL		TSN:0			636		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334005	RH WING ANTI-COLLISION WHITE LIGHT								
	03-9503-5003	MOS		TSN:0			28-APR-2010		
33.160	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			900.3		
	REF: See Workcard	AFL		TSN:0			636		
334806	LH NAVIGATION LIGHT FAIRING								
	07-7100-0001	MOS		TSN:0			28-APR-2010		
33.110	004015/2	HRS/MSC	O/C	TSN:0			900.3		
	REF: GENERIC NO REF	AFL		TSN:0			636		
334811	RH NAVIGATION LIGHT FAIRING								
	07-7100-0000	MOS		TSN:0			05-OCT-2010		
33.110	004014/10	HRS/MSC	O/C	TSN:0			1072.6		
	REF: GENERIC NO REF	AFL		TSN:0			759		
334821	REAR NAVIGATION/ANTICOLLISION LIGHT POWER SUPPLY								
	39-42-4	MOS					01-DEC-2015		
33.120	528	HRS/MSC	O/C	TSN:900.3			2534.6		
	REF: GENERIC NO REF	AFL					1921		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334841	LH LANDING LIGHT LENS ASSEMBLY								
	SPSF900-10-5-0	MOS		TSN:0			13-DEC-2006		
33.140	3049	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
334846	RH LANDING LIGHT LENS ASSEMBLY								
	SPSF900-9-5-0	MOS		TSN:0			13-DEC-2006		
33.140	3160	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
334866	LEFT WING ANTICOLLISION LIGHT POWER SUPPLY BOX								
	PN	MOS		TSN:0			13-DEC-2006		
33.170	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-65-960-801	AFL		TSN:0			0		
334871	RIGHT WING ANTICOLLISION LIGHT POWER SUPPLY BOX								
	PN	MOS		TSN:0			13-DEC-2006		
33.170	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 33-40-65-960-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334876	LH WING DETECTION LIGHT								
	4371567	MOS		TSN:0			13-DEC-2006		
33.180	519	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
334881	RH WING DETECTION LIGHT								
	4371574	MOS		TSN:0			13-DEC-2006		
33.180	456	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
334891	BELLY STROBE POWER SUPPLY								
	39-44-31	MOS		TSN:0			13-DEC-2006		
33.280	1510	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
334896	LH LOWER FIN LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.340	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334897	LH UPPER FIN LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.340	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
334A10	OPERATIONAL CHECK OF THE WINGLET POSITION AND ANTI-COLLISION LIGHTS								
		MOS	2				21-MAY-2018	**21-JUL-2018**	
		HRS/MSC	200				3041.8	**3241.8**	
	REF:	AFL					2328		
335831	PILOT DOME LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.220	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
335841	COPILOT DOME LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.220	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
335851	EVACUATION LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.230	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
335861	OUTSIDE EMERGENCY EXIT LIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.230	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
335871	FRAME 4/5 PASSENGER DOOR SPOTLIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.240	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
335881	FRAME 6/7 PASSENGER DOOR SPOTLIGHT								
	PN	MOS		TSN:0			13-DEC-2006		
33.240	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

CHAPTER 34 NAVIGATION

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-10-00-720-801-01	FUNCTIONAL TEST NO. 1 AIR DATA MODULE									
	HG1153CA01	MOS	24	+3%				17-APR-2018	**17-APR-2020**	08-MAY-2020
34.050	06071624	HRS/MSC						3041.8		
RVSM	**REF:** AMM 34-10-00-720-801	AFL						2328		
34-10-00-720-801-02	FUNCTIONAL TEST NO. 2 AIR DATA MODULE									
	HG1153CA01	MOS	24	+3%				17-APR-2018	**17-APR-2020**	08-MAY-2020
34.050	06071643	HRS/MSC						3041.8		
RVSM	**REF:** AMM 34-10-00-720-801	AFL						2328		
+ 34-10-00-720-881-01	TEST NO. 1 AIR DATA MODULE (FAR 91.411)									
	HG1153CA01	MOS	24			-29		17-APR-2018	**19-MAR-2020**	
34.050	06071624	HRS/MSC								
MANDATORY	**REF:** FAR 91.411	AFL								
+ 34-10-00-720-881-02	TEST NO. 2 AIR DATA MODULE (FAR 91.411)									
	HG1153CA01	MOS	24			-29		17-APR-2018	**19-MAR-2020**	
34.050	06071643	HRS/MSC								
MANDATORY	**REF:** FAR 91.411	AFL								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-10-01-900-801-01	REMOVAL / INSTALLATION OF THE OUTSIDE AIR TEMPERATURE PROBE - OUTSIDE AIR TEMPERATURE PROBE (120FE)								
	102AU1CK	MOS		TSN:0			13-DEC-2006		
34.090	A63317	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
34-10-11-720-801-01 (s)	CHECK THE ELECTRICAL ZERO SETTING OF THE LH ANGLE OF ATTACK SENSOR						PKG		
	PKG 31	MOS	72	+2m			13-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 34-10-11-720-801	AFL	3750				1323		
34-10-11-720-801-02 (s)	CHECK THE ELECTRICAL ZERO SETTING OF THE RH ANGLE OF ATTACK SENSOR						PKG		
	PKG 31	MOS	72	+2m			13-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 34-10-11-720-801	AFL	3750				1323		
34-10-11-900-801-01	LH ANGLE-OF-ATTACK (AOA) SENSOR								
	861CAU2	MOS		TSN:0			13-DEC-2006		
27.425	1492A	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-10-11-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-10-11-900-801-02	RH ANGLE-OF-ATTACK (AOA) SENSOR								
	861CAU2	MOS		TSN:0			13-DEC-2006		
27.425	1608A	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-10-11-900-801	AFL		TSN:0			0		
34-11-00-790-801-01	LEAK TEST OF THE PILOT STATIC PRESSURE SYSTEM								
		MOS					25-MAY-2018		
		HRS/MSC	O/C				3041.8		
	REF: AMM 34-11-00-790-801	AFL					2328		
34-11-00-790-801-02	LEAK TEST OF THE PILOT TOTAL PRESSURE SYSTEM								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 34-11-00-790-801	AFL					0		
34-11-00-790-801-03	LEAK TEST OF THE COPILOT STATIC PRESSURE SYSTEM								
		MOS					25-MAY-2018		
		HRS/MSC	O/C				3041.8		
	REF: AMM 34-11-00-790-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-00-790-801-04	LEAK TEST OF THE COPILOT TOTAL PRESSURE SYSTEM								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 34-11-00-790-801	AFL					0		
34-11-00-790-801-05	LEAK TEST OF THE STAND-BY STATIC PRESSURE SYSTEM								
		MOS					25-MAY-2018		
		HRS/MSC	O/C				3041.8		
	REF: AMM 34-11-00-790-801	AFL					2328		
34-11-00-790-801-06	LEAK TEST OF THE STAND-BY TOTAL PRESSURE SYSTEM								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 34-11-00-790-801	AFL					0		
34-11-00-790-881-01	LEAK TEST OF NORMAL AIR PRESSURE SYSTEM (FAR 91.411)								
		MOS	24		-30		17-APR-2018	**18-MAR-2020**	
34.110		HRS/MSC							
CALIBRATE	**REF:**	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-00-790-881-02	LEAK TEST OF STAND-BY AIR PRESSURE SYSTEM (FAR 91.411)								
		MOS	24		-30		17-APR-2018	**18-MAR-2020**	
34.110		HRS/MSC							
CALIBRATE	**REF:**	AFL							
34-11-01-200-801-01 (s)	CHECK OF THE LH TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING						PKG		
	PKG 11 ,12 ,14 ,31	MOS	8	+1m			17-APR-2018		
34.060		HRS/MSC					3041.8		
	REF: AMM 34-11-01-200-801	AFL					2328		
+ 34-11-01-200-801-02 (s)	CHECK OF THE RH TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING						PKG		
	PKG 11 ,12 ,14 ,31	MOS	8				17-APR-2018		
34.060		HRS/MSC					3041.8		
	REF:	AFL					2328		
+ 34-11-01-200-801-03 (s)	CHECK OF THE STAND-BY TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING						PKG		
	PKG 11 ,12 ,14 ,31	MOS	8				17-APR-2018		
34.060		HRS/MSC					3041.8		
	REF:	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-01-900-801-01	LH TOTAL PRESSURE PROBE								
	50520	MOS		TSN:0			13-DEC-2006		
	3856	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-11-01-900-801	AFL		TSN:0			0		
34-11-01-900-801-02	RH TOTAL PRESSURE PROBE								
	50520	MOS		TSN:0			13-DEC-2006		
	3857	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-11-01-900-801	AFL		TSN:0			0		
34-11-01-900-801-03	STAND-BY TOTAL PRESSURE PROBE								
	50520	MOS		TSN:0			13-DEC-2006		
34.070	3858	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-11-01-900-801	AFL		TSN:0			0		
34-11-05-900-801-01	LH STATIC PRESSURE PROBE								
	C16778AA	MOS		TSN:0			13-DEC-2006		
34.080	102	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-05-900-801-02	RH STATIC PRESSURE PROBE								
	C16778AA	MOS		TSN:0			13-DEC-2006		
34.080	108	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
34-11-05-900-802-01	PILOT STAND-BY STATIC PRESSURE PROBE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-11-05-900-802	AFL		TSN:0			0		
34-11-05-900-802-02	COPILOT STAND-BY STATIC PRESSURE PROBE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-11-05-900-802	AFL		TSN:0			0		
34-14-01-900-802-01	NO. 1 AIR DATA MODULE								
	HG1153CA01	MOS		TSN:0			13-DEC-2006		
34.050	06071624	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-14-01-900-802	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-14-01-900-802-02	NO. 2 AIR DATA MODULE								
	HG1153CA01	MOS		TSN:0			13-DEC-2006		
34.050	06071643	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-14-01-900-802	AFL		TSN:0			0		
34-21-00-700-801-01 (s)	CHECK OF THE GENERAL-PURPOSE BUSES TO THE INERTIAL REFERENCE SYSTEM (IRS) - IRU NO. 1						PKG		
	PKG 23	MOS					13-DEC-2006		
34.590		HRS/MSC	4800	+40			0		
	REF: AMM 34-21-00-700-801	AFL					0		
34-21-00-700-801-01A	CHECK OF THE GENERAL-PURPOSE BUSES TO THE INERTIAL REFERENCE SYSTEM (IRS) - IRU NO. 1 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
34.580		HRS/MSC	5000				0	**5000**	
CMR	**REF:** AMM 34-21-00-700-801	AFL					0		
34-21-00-700-801-02 (s)	CHECK OF THE GENERAL-PURPOSE BUSES TO THE INERTIAL REFERENCE SYSTEM (IRS) - IRU NO. 2						PKG		
	PKG 23	MOS					13-DEC-2006		
		HRS/MSC	4800	+40			0		
	REF: AMM 34-21-00-700-801	AFL					0		
		APH							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-21-00-700-801-02A	CHECK OF THE GENERAL-PURPOSE BUSES TO THE INERTIAL REFERENCE SYSTEM (IRS) - IRU NO. 2 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
		HRS/MSC	5000				0		**5000**
CMR	**REF:** AMM 34-21-00-700-801	AFL					0		
		APH							
34-21-00-700-801-03 (s)	CHECK OF THE GENERAL-PURPOSE BUSES TO THE INERTIAL REFERENCE SYSTEM (IRS) - IRU NO. 3						PKG		
	PKG 23	MOS					13-DEC-2006		
		HRS/MSC	4800	+40			0		
	REF: AMM 34-21-00-700-801	AFL					0		
		APH							
34-21-00-700-801-03A	CHECK OF THE GENERAL-PURPOSE BUSES TO THE INERTIAL REFERENCE SYSTEM (IRS) - IRU NO. 3 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
		HRS/MSC	5000				0		**5000**
CMR	**REF:** AMM 34-21-00-700-801	AFL					0		
		APH							
34-21-01-900-801-01	NO. 1 INERTIAL REFERENCE (IRU 1) UNIT								
	HG2100AB02	MOS		TSN:0			13-DEC-2006		
34.410	56010782	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-21-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-21-01-900-801-02	NO. 2 INERTIAL REFERENCE (IRU 2) UNIT								
	HG2100AB02	MOS		TSN:103			02-JUL-2015		
34.410	56010794	HRS/MSC	O/C	TSN:2409.6			2409.6		
	REF: AMM 34-21-01-900-801	AFL		TSN:1816			1816		
34-21-01-900-801-03	NO. 3 INERTIAL REFERENCE (IRU 3) UNIT								
	HG2100AB02	MOS		TSR:14			02-JUL-2015		
34.415	56022036	HRS/MSC	O/C	TSR:324.6			2409.6		
	REF: AMM 34-21-01-900-801	AFL		TSR:304			1816		
34-21-09-900-801-01	NO. 1 IRS MODULE								
	7519272-901	MOS		TSN:0			13-DEC-2006		
34.230	06054538	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-21-09-900-801	AFL		TSN:0			0		
34-21-09-900-801-02	NO. 2 IRS MODULE								
	7519272-901	MOS		TSN:0			13-DEC-2006		
34.230	06054542	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-21-09-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-21-09-900-801-03	NO. 3 IRS MODULE								
	7519272-901	MOS		TSN:0			13-DEC-2006		
34.230	06054552	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-21-09-900-801	AFL		TSN:0			0		
34-23-00-720-801-01	FUNCTIONAL TEST SECONDARY FLIGHT DISPLAY AIR DATA (ADU) UNIT								
	27100-01-01	MOS	24	+3%			17-APR-2018	**17-APR-2020**	08-MAY-2020
	M016755	HRS/MSC					3041.8		
	REF: AMM 34-23-00-720-801	AFL					2328		
34-23-00-720-801-02	FUNCTIONAL TEST OF THE SECONDARY FLIGHT DISPLAY (SFD) AND AIR DATA UNIT (ADU) - SFD (320NH)								
	39216-00-02	MOS	24	+3%			25-MAY-2018	**25-MAY-2020**	16-JUN-2020
	M018701	HRS/MSC					3041.8		
	REF: AMM 34-23-00-720-801	AFL					2328		
34-23-00-720-881-01	TEST SECONDARY FLIGHT DISPLAY AIR DATA (ADU) UNIT (FAR 91.411)								
	27100-01-01	MOS	24		-30		17-APR-2018	**18-MAR-2020**	
34.510	M016755	HRS/MSC							
MANDATORY	**REF:** FAR 91.411	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-23-01-900-801-01	SECONDARY FLIGHT (SFD) DISPLAY								
	39216-00-02	MOS		TSN:0			13-DEC-2006		
34.490	M018701	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-23-01-900-801	AFL		TSN:0			0		
34-23-05-900-801-01	SECONDARY FLIGHT DISPLAY AIR DATA (ADU) UNIT								
	27100-01-01	MOS		TSR:6			02-APR-2014		
34.510	M016755	HRS/MSC	O/C	TSR:0			2076.6		
	REF: AMM 34-23-05-900-801	AFL		TSR:0			1501		
34-25-00-820-801-01	COMPENSATION OF STANDBY COMPASS								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 34-25-00-820-801	AFL					0		
34-31-00-710-801-01	OPERATIONAL TEST OF THE HEAD-UP GUIDANCE SYSTEM (HGS)								
		MOS					11-JUN-2013		
34.470		HRS/MSC	O/C				1872.8		
	REF: AMM 34-31-00-710-801	AFL					1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-31-00-900-801-01	HUD MOUNTING TRAY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
34-31-01-900-801-01	HEAD-UP GUIDANCE SUSTEM (HGS) OVERHEAD UNIT								
	1500-1550-003	MOS					13-DEC-2006		
	22320	HRS/MSC	O/C				0		
	REF: AMM 34-31-01-900-801	AFL					0		
		APH					0		
34-31-01-900-802-01	OVERHEAD PROJECTOR UNIT								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
34-31-05-900-801-01	HEAD-UP GUIDANCE (HGS) COMBINER								
	1500-2950-002	MOS					22-FEB-2008		
	22468	HRS/MSC	O/C				303.4		
	REF: AMM 34-31-05-900-801	AFL					206		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-31-05-900-802-01	OVERHEAD COMBINER UNIT								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
34-31-09-900-801-01	HEAD-UP GUIDANCE SYSTEM (HGS) COMPUTER								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-31-09-900-801	AFL		TSN:0			0		
34-31-09-900-802-01	HUD COMPUTER UNIT								
	1500-2380-003	MOS					22-FEB-2008		
	22372	HRS/MSC	O/C				303.4		
	REF:	AFL					206		
34-31-11-900-801-01	HUD COMPUTER TRAY								
	S4765F03	MOS					13-DEC-2006		
	48	HRS/MSC	O/C				0		
	REF:	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-31-13-900-802-01	HUD COMPUTER FAN ASSEMBLY								
	011384	MOS					13-DEC-2006		
	106394081	HRS/MSC	O/C				0		
	REF:	AFL					0		
		APH					0		
34-31-17-900-801-01	HUD CONTROL PANEL PANEL								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
+ 34-32-01-100-801-01 (s)	CLEANING OF THE INFRARED SENSOR UNIT (ISU) LENS						PKG		
	PKG 2 ,31	MOS					17-APR-2018		
34.605		HRS/MSC	O/C				3041.8		
	REF: AMM 34-32-01-100-801	AFL					2328		
+ 34-32-01-780-801-01 (s)	PRESSURE CHECK OF THE INFRARED SENSOR UNIT (ISU)						PKG		
	PKG 2 ,31,202	MOS	16	+1m			17-APR-2018		
34.600		HRS/MSC	800	+40			3041.8		
	REF: AMM 34-32-01-780-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-32-01-900-801-01	INFRARED SENSOR UNIT (ISU)								
	1500-2960-002	MOS					15-JUL-2013		
	07360901	HRS/MSC	O/C				1872.8		
	REF: AMM 34-32-01-900-801	AFL					1323		
34-32-02-900-801-01	INFRARED SENSOR UNIT (ISU) FAN								
	031175	MOS		TSN:0			22-FEB-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			303.4		
	REF: AMM 34-32-02-900-801	AFL		TSN:0			206		
34-32-03-900-801-01	NO. 1 EFVS VIDEO FILTER								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
34-32-03-900-801-02	NO. 2 EFVS VIDEO FILTER								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-32-05-100-801-01	CLEANING OF THE INFRARED WINDOW (IRW)								
		MOS					24-JUN-2017		
34.610		HRS/MSC	O/C				2832.2		
	REF: AMM 34-32-05-100-801	AFL					2192		
34-32-05-900-801-01	INFRARED (IRW) WINDOW								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-32-05-900-801	AFL		TSN:0			0		
34-32-06-900-801-01	INFRARED WINDOW (IRW) INVERTER								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-32-06-900-801	AFL		TSN:0			0		
34-32-09-900-801-01	AIRCRAFT IDENTIFICATION (AIT) TAG								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-32-09-960-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-32-09-960-801-01	REPLACE AIRCRAFT IDENTIFICATION (AIT) TAG								
	PN	MOS					13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 34-32-09-960-801	AFL					0		
34-41-01-900-801-01	WEATHER RADAR RECEIVER / TRANSMITTER / ANTENNA ASSEMBLY								
	7021450-801	MOS		TSR:0			28-JUL-2014		
34.290	1112C065	HRS/MSC	O/C	TSR:0			2157.2		
	REF: AMM 34-41-01-900-801	AFL		TSR:0			1582		
34-42-01-820-801-01	CALIBRATION NO. 1 RADIO ALTIMETER RECEIVER/TRANSMITTER								
	7001840-932	MOS					13-DEC-2006		
34.920	0604C745	HRS/MSC	O/C				0		
	REF: AMM 34-42-01-820-801	AFL					0		
		APH					0		
34-42-01-820-801-02	CALIBRATION NO. 2 RADIO ALTIMETER RECEIVER/TRANSMITTER								
	PN	MOS					13-DEC-2006		
34.305	NOT INSTALLED	HRS/MSC	O/C				0		
	REF: AMM 34-42-01-820-801	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-42-01-900-801-01	NO. 1 RADIO ALTIMETER RECEIVER/TRANSMITTER								
	7001840-932	MOS		TSN:0			13-DEC-2006		
34.295	0604C745	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-42-01-900-801	AFL		TSN:0			0		
34-42-01-900-801-02	NO. 2 RADIO ALTIMETER RECEIVER/TRANSMITTER								
	PN	MOS		TSN:0			13-DEC-2006		
34.305	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-42-01-900-801	AFL		TSN:0			0		
		APH		TSN:0			0		
34-42-09-900-801-01	NO. 1 RADIO-ALTIMETER TRANSMITTER ANTENNA								
	S67-2002-13	MOS		TSN:0			07-APR-2009		
34.270	545-3813	HRS/MSC	O/C	TSN:0			604.2		
	REF: AMM 34-42-09-900-801	AFL		TSN:0			449		
34-42-09-900-801-02	NO. 1 RADIO-ALTIMETER RECEIVER ANTENNA								
	S67-2002-13	MOS		TSN:0			07-APR-2009		
34.270	545-3818	HRS/MSC	O/C	TSN:0			604.2		
	REF: AMM 34-42-09-900-801	AFL		TSN:0			449		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-42-09-900-801-03	NO. 2 RADIO-ALTIMETER TRANSMITTER ANTENNA								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-42-09-900-801	AFL		TSN:0			0		
34-42-09-900-801-04	NO. 2 RADIO-ALTIMETER RECEIVER ANTENNA								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-42-09-900-801	AFL		TSN:0			0		
34-44-01-900-801-01	TCAS TRANSCEIVER								
	7517900-55020	MOS					15-JUL-2013		
34.540	20008302	HRS/MSC	O/C				1872.8		
	REF: AMM 34-44-01-900-801	AFL					1323		
34-44-05-900-801-01	LOWER TCAS ANTENNA								
	7514081-913	MOS		TSN:0		08/18/2017	18-AUG-2015		
34.550	ANE46623	HRS/MSC	O/C	TSN:0			2449.8		
	REF: AMM 34-44-05-900-801	AFL		TSN:0			1849		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-44-05-900-801-02	UPPER TCAS ANTENNA								
	7514081-913	MOS		TSN:0			13-DEC-2006		
34.550	ANE24723	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-44-05-900-801	AFL		TSN:0			0		
34-45-01-900-801-01	EGPWS MODULE								
	7028419-1904	MOS					30-APR-2007		
31.320	06061156	HRS/MSC	O/C	TSN:15.25			21.5		
	REF: AMM 34-45-01-900-801	AFL					7		
34-51-00-710-801-01	OPERATIONAL TEST OF THE VOR NAVIGATION SYSTEM								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 34-51-00-710-801	AFL					0		
34-51-01-900-802-01	NO. 1 VOR / ILS DATA LINK MODULE								
	7026202-802	MOS		TSN:28 TSR:0			18-SEP-2009		
34.240	06051780 MOD E	HRS/MSC	O/C	TSN:715.2 TSR:0					
	REF: AMM 34-51-01-900-802	AFL		TSN:522 TSR:0					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-51-01-900-802-02	NO. 2 VOR / ILS DATA LINK MODULE								
	7026202-802	MOS		TSR:0			24-JUN-2010		
34.240	07042556 MOD G	HRS/MSC	O/C	TSR:0			956.5		
	REF: AMM 34-51-01-900-802	AFL		TSR:0			683		
34-51-05-900-801-01	LH VOR/LOC ANTENNA								
	19-78	MOS		TSN:0			13-DEC-2006		
34.330	9240	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-51-05-900-801	AFL		TSN:0			0		
34-51-05-900-801-02	RH VOR/LOC ANTENNA								
	19-78	MOS		TSN:0			13-DEC-2006		
34.330	9579	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-51-05-900-801	AFL		TSN:0			0		
34-51-17-900-801-01	REMOVAL / INSTALLATION OF THE MARKER ANTENNA - MARKER ANTENNA (260NR)								
	S35-1000-1	MOS		TSN:0			13-DEC-2006		
34.370	101-6061	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-51-61-900-801-01	NO. 1 GPS MODULE								
	245-604067-100	MOS		TSO:2			27-AUG-2015		
34.560	08022885	HRS/MSC	O/C	TSO:45.3			2454.9		
	REF: AMM 34-51-61-900-801	AFL		TSO:41			1857		
34-51-61-900-801-02	NO. 2 GPS MODULE								
	245-604067-100	MOS				09/17/2016	17-SEP-2015		
34.560	11014997	HRS/MSC	O/C				2486.2		
	REF: AMM 34-51-61-900-801	AFL					1874		
34-51-65-900-801-01	NO. 1 GPS ANTENNA								
	S67-1575-137	MOS		TSN:0			29-JUN-2015		
34.570	773-2798	HRS/MSC	O/C	TSN:0			2409.6		
	REF: AMM 34-51-65-900-801	AFL		TSN:0			1816		
34-51-65-900-801-02	NO. 2 GPS ANTENNA								
	S67-1575-137	MOS		TSN:0			29-JUN-2015		
34.570	773-2799	HRS/MSC	O/C	TSN:0			2409.6		
	REF: AMM 34-51-65-900-801	AFL		TSN:0			1816		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-52-01-900-801-01	NO. 1 DME MODULE								
	7510184-855	MOS		TSN:10			11-MAR-2008		
34.390	0605A727	HRS/MSC	O/C	TSN:320			320		
	REF: AMM 34-52-01-900-801	AFL		TSN:220			220		
34-52-01-900-801-02	NO. 2 DME MODULE								
	7510184-855	MOS		TSN:0			14-MAR-2008		
34.390	0708C890	HRS/MSC	O/C	TSN:0			320		
	REF: AMM 34-52-01-900-801	AFL		TSN:0			220		
34-52-05-900-801-01	NO. 1 DME ANTENNA								
	DMNI50-2-2	MOS		TSN:0			13-DEC-2006		
34.400	107707	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-52-05-900-801	AFL		TSN:0			0		
34-52-05-900-801-02	NO. 2 DME ANTENNA								
	DMNI50-2-2	MOS		TSN:0			13-DEC-2006		
34.400	107708	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-52-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-53-01-900-801-01	NO. 1 ADF (ADF 1) MODULE								
	7510114-855	MOS		TSR:0		08/12/2015	12-AUG-2014		
	0604A649	HRS/MSC	O/C	TSN:2137.2 TSR:0			2180.3		
	REF: AMM 34-53-01-900-801	AFL		TSN:1567 TSR:0			1599		
34-53-01-900-801-02	NO. 2 ADF (ADF 2) MODULE								
	7510114-855	MOS		TSR:54			09-JUL-2014		
	04056565	HRS/MSC	O/C	TSR:1277.2			2137.2		
	REF: AMM 34-53-01-900-801	AFL		TSR:954			1567		
34-53-05-900-801-01	NO. 1 ADF ANTENNA								
	7510300-901	MOS		TSN:37			25-JAN-2010		
34.360	0605A490	HRS/MSC	O/C	TSN:860			860		
	REF: AMM 34-53-05-900-801	AFL		TSN:613			613		
34-53-05-900-801-02	NO. 2 ADF ANTENNA								
	7510300-901	MOS		TSN:0			25-JAN-2010		
34.360	0909G283	HRS/MSC	O/C	TSN:0			860		
	REF: AMM 34-53-05-900-801	AFL		TSN:0			613		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-54-00-720-802-01	FUNCTIONAL TEST NO. 1 ATC TRANSPONDER MODULE									
	7517402-970	MOS	24	+3%				17-APR-2018	**17-APR-2020**	08-MAY-2020
34.300	05099652	HRS/MSC						3041.8		
RVSM	**REF:** See Workcard	AFL						2328		
34-54-00-720-802-02	FUNCTIONAL TEST NO. 2 ATC TRANSPONDER MODULE									
	7517402-970	MOS	24	+3%				17-APR-2018	**17-APR-2020**	08-MAY-2020
34.300	0811E931	HRS/MSC						3041.8		
RVSM	**REF:** See Workcard	AFL						2328		
+ 34-54-00-720-881-01	TEST NO. 1 ATC TRANSPONDER MODULE (FAR 91.413)									
	7517402-970	MOS	24			-29		17-APR-2018	**19-MAR-2020**	
34.300	05099652	HRS/MSC								
MANDATORY	**REF:** GENERIC CUSTOM	AFL								
+ 34-54-00-720-881-02	TEST NO. 2 ATC TRANSPONDER MODULE (FAR 91.413)									
	7517402-970	MOS	24			-29		17-APR-2018	**19-MAR-2020**	
34.300	0811E931	HRS/MSC								
MANDATORY	**REF:** GENERIC CUSTOM	AFL								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-54-01-900-801-01	NO. 1 ATC TRANSPONDER MODULE								
	7517402-970	MOS		TSO:34			17-APR-2018		
34.300	05099652	HRS/MSC	O/C	TSO:632.2			3041.8		
	REF: AMM 34-54-01-900-801	AFL		TSO:512			2328		
34-54-01-900-801-02	NO. 2 ATC TRANSPONDER MODULE								
	7517402-970	MOS		TSO:34			17-APR-2018		
34.300	0811E931	HRS/MSC	O/C	TSO:632.2			3041.8		
	REF: AMM 34-54-01-900-801	AFL		TSO:512			2328		
34-54-05-900-801-01	NO.1 UPPER ATC ANTENNA								
	DMNI50-2-2	MOS		TSN:0			13-DEC-2006		
34.310	107703	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-54-05-900-801	AFL		TSN:0			0		
34-54-05-900-801-02	NO.2 UPPER ATC ANTENNA								
	DMNI50-2-2	MOS		TSN:0			13-DEC-2006		
34.310	107704	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-54-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-54-05-900-801-03	NO.1 LOWER ATC ANTENNA								
	DMNI50-2-2	MOS		TSN:0			13-DEC-2006		
34.320	107705	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-54-05-900-801	AFL		TSN:0			0		
34-54-05-900-801-04	NO.2 LOWER ATC ANTENNA								
	DMNI50-2-2	MOS		TSN:0			13-DEC-2006		
34.320	107706	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-54-05-900-801	AFL		TSN:0			0		
34-58-01-900-801-01	XM WEATHER RECEIVER								
	990-5732-001	MOS		TSN:0			13-DEC-2006		
	06120034680	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-58-01-900-801	AFL		TSN:0			0		
34-58-05-900-801-01	XM WEATHER ANTENNA								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-58-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-90-10-900-801-01	CONTROL DISPLAY (CDU) (731NG) UNIT								
	PN	MOS		TSN:0			13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
		APH		TSN:0			0		
34-90-10-900-801-02	CONTROL DISPLAY (CDU) (732NG) UNIT								
	PN	MOS		TSN:0			13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
342801	STAND-BY COMPASS								
	KCA0105W	MOS		TSN:0			13-DEC-2006		
34.180	AW934	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
343811	NO. 1 RADIO-ALTIMETER CONVERTER								
	PN	MOS		TSN:0			13-DEC-2006		
34.130	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345033	VOR/LOC DIVIDER / COUPLER								
	7-98B	MOS		TSN:0			13-DEC-2006		
34.250	7306	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-51-09-900-801	AFL		TSN:0			0		
345836	GLIDE SLOPE ANTENNA								
	DMN25-2	MOS		TSN:0			13-DEC-2006		
34.380	5508-2	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
349806	NO. 1 INERTIAL REFERENCE SYSTEM MODE SELECTOR UNIT								
	PN	MOS		TSN:0			13-DEC-2006		
34.430	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
349816	NO. 2 INERTIAL REFERENCE SYSTEM MODE SELECTOR UNIT								
	PN	MOS		TSN:0			13-DEC-2006		
34.430	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
349826	NO. 3 INERTIAL REFERENCE SYSTEM MODE SELECTOR UNIT								
	PN	MOS		TSN:0			13-DEC-2006		
34.430	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 35	**OXYGEN**								
34-00-00-900-803-04	PILOT OXYGEN MASK BOX								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
34-00-00-900-803-05	COPILOT OXYGEN MASK BOX								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
35-10-05-350-801-01	RESTORATION PILOT OXYGEN MASK (OVERHAUL)								
	MC10-12-152	MOS	72	+3%			12-DEC-2017	**12-DEC-2023**	16-FEB-2024
35.020	94502	HRS/MSC							
OVERHAUL	**REF:** AMM 35-10-05-350-801	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-10-05-350-801-02	RESTORATION COPILOT OXYGEN MASK (OVERHAUL)								
	MC10-12-152	MOS	72	+3%			07-MAR-2018	**07-MAR-2024**	11-MAY-2024
35.020	SE19423	HRS/MSC							
OVERHAUL	**REF:** AMM 35-10-05-350-801	AFL							
+ 35-10-05-350-801-03	RESTORATION THIRD CREW MEMBER OXYGEN MASK (OVERHAUL)								
	PN	MOS					13-DEC-2006		
35.170	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 35-10-05-350-801	AFL					0		
35-10-05-710-801-01	OPERATIONAL TEST PILOT OXYGEN MASK								
		MOS	12	+3%			19-APR-2018	**19-APR-2019**	29-APR-2019
35.020		HRS/MSC					3041.8		
	REF: AMM 35-10-05-710-801	AFL					2328		
35-10-05-710-801-02	OPERATIONAL TEST COPILOT OXYGEN MASK								
		MOS	12	+3%			19-APR-2018	**19-APR-2019**	29-APR-2019
35.020		HRS/MSC					3041.8		
	REF: AMM 35-10-05-710-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-10-05-710-801-03	OPERATIONAL TEST THIRD CREW MEMBER OXYGEN MASK								
		MOS					04-MAY-2007		
35.170		HRS/MSC	N/A				0		
	REF: AMM 35-10-05-710-801	AFL					0		
35-10-05-900-801-01	PILOT OXYGEN MASK								
	MC10-12-152	MOS		TSN:202 TSO:4			19-APR-2018		
35.020	94502	HRS/MSC	O/C	TSO:0			3041.8		
	REF: AMM 35-10-05-900-801	AFL		TSO:0			2328		
35-10-05-900-801-02	COPILOT OXYGEN MASK								
	MC10-12-152	MOS		TSN:120 TSO:1			19-APR-2018		
35.020	SE19423	HRS/MSC	O/C	TSO:0			3041.8		
	REF: AMM 35-10-05-900-801	AFL		TSO:0			2328		
35-10-05-900-801-03	THIRD CREW MEMBER OXYGEN MASK								
	PN	MOS		TSN:0			13-DEC-2006		
35.170	SN-UNKNOWN	HRS/MSC	H/T	TSN:0			0		
	REF: AMM 35-10-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER OXYGEN MASKS AND SMOKE MASKS						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			19-APR-2018		
35.190		HRS/MSC					3041.8		
	REF: AMM 35-20-00-210-801	AFL					2328		
35-20-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM						PKG		
	PKG 21	MOS					20-APR-2018		
35.040		HRS/MSC	1600	+40			3041.8		
	REF: AMM 35-20-00-720-801	AFL					2328		
35-20-00-720-801-01A	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM (MANDATORY 5-40)								
		MOS					20-APR-2018		
35.040		HRS/MSC	1640				3041.8	**4681.8**	
CMR	**REF:** AMM 35-20-00-720-801	AFL					2328		
35-20-01-900-801-01	PASSENGER OXYGEN CONTROLLER								
	448833-4	MOS					22-FEB-2008		
35.050	306	HRS/MSC	O/C				303.4		
	REF: AMM 35-20-01-900-801	AFL					206		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20-09-900-801-01	NO. 1 PASSENGER OXYGEN MASK								
	PN	MOS		TSN:0			13-DEC-2006		
35.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 35-20-09-900-801	AFL		TSN:0			0		
35-20-09-900-801-02	NO. 2 PASSENGER OXYGEN MASK								
	289-601-228	MOS		TSN:0			02-DEC-2016		
35.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			2676.9		
	REF: AMM 35-20-09-900-801	AFL		TSN:0			2076		
35-20-09-900-801-03	NO. 3 PASSENGER OXYGEN MASK								
	PN	MOS		TSN:0			13-DEC-2006		
35.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 35-20-09-900-801	AFL		TSN:0			0		
35-20-09-900-801-04	NO. 4 PASSENGER OXYGEN MASK								
	PN	MOS		TSN:0			13-DEC-2006		
35.080	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 35-20-09-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20-09-900-801-05	NO. 5 PASSENGER OXYGEN MASK								
	PN	MOS		TSN:0			13-DEC-2006		
35.080	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 35-20-09-900-801	AFL		TSN:0			0		
35-20-09-900-801-06	NO. 6 PASSENGER OXYGEN MASK								
	PN	MOS		TSN:0			13-DEC-2006		
35.080	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 35-20-09-900-801	AFL		TSN:0			0		
35-20-09-900-801-07	NO. 7 PASSENGER OXYGEN MASK								
	PN	MOS		TSN:0			13-DEC-2006		
35.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 35-20-09-900-801	AFL		TSN:0			0		
35-20-09-900-801-08	NO. 8 PASSENGER OXYGEN MASK								
	PN	MOS		TSN:0			13-DEC-2006		
35.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 35-20-09-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20-09-900-801-09	NO. 9 PASSENGER OXYGEN MASK								
	289-601-228	MOS		TSN:0			02-DEC-2016		
35.090	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			2676.9		
	REF: AMM 35-20-09-900-801	AFL		TSN:0			2076		
35-20-09-900-801-10	NO. 10 PASSENGER OXYGEN MASK								
	PN	MOS		TSN:0			13-DEC-2006		
35.100	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 35-20-09-900-801	AFL		TSN:0			0		
35-20-09-900-801-11	NO. 11 PASSENGER OXYGEN MASK								
	PN	MOS		TSN:0			13-DEC-2006		
35.100	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 35-20-09-900-801	AFL		TSN:0			0		
35-21-05-210-801-01 (s)	INSPECTION OF THE RILSAN TUBE ASSEMBLY						PKG		
	PKG 21	MOS					18-APR-2018		
		HRS/MSC	1600	+40			3041.8		
	REF: AMM 35-21-05-210-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-30-01-960-801-01	DISCARD SMOKE HOOD								
	802300-14	MOS	120				28-APR-2017	**28-APR-2027**	
35.110	E16100264	HRS/MSC					2775.3		
LIFE LIMIT	**REF:** AMM 35-30-01-960-801	AFL					2149		
35-30-05-210-801-01	GENERAL VISUAL INSPECTION NO. 1 PORTABLE OXYGEN BOTTLE AND MASKS								
	894-20330	MOS	12	+3%			19-APR-2018	**19-APR-2019**	29-APR-2019
35.140	P07021122	HRS/MSC					3041.8		
	REF: AMM 35-30-05-210-801	AFL					2328		
35-30-05-350-801-01	RESTORATION NO. 1 PORTABLE OXYGEN BOTTLE (OVERHAUL) AND MASKS								
	894-20330	MOS	60	+3%			28-APR-2017	**28-APR-2022**	21-JUN-2022
35.140	P07021122	HRS/MSC					2775.3		
OVERHAUL	**REF:** AMM 35-30-05-350-801	AFL					2149		
35-30-09-100-801-01	CLEANING OF THE NO. 1 PORTABLE OXYGEN MASKS								
		MOS	12	+3%			19-APR-2018	**19-APR-2019**	29-APR-2019
35.140		HRS/MSC					3041.8		
	REF: AMM 35-30-09-100-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-30-09-350-801-01	RESTORATION SMOKE MASK (OVERHAUL)								
	PN	MOS					13-DEC-2006		
35.180	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 35-30-09-350-801	AFL					0		
35-40-01-790-801-01	HYDROSTATIC CHECK OXYGEN CYLINDER								
	176219-115	MOS	60				28-JUL-2014	**28-JUL-2019**	
35.010	627770712	HRS/MSC							
	REF: AMM 35-40-01-790-801	AFL							
35-40-01-900-801-01	OXYGEN CYLINDER								
	176219-115	MOS		TSN:5			17-DEC-2014		
35.010	627770712	HRS/MSC	O/C	TSN:2286					
	REF: AMM 35-40-01-900-801	AFL		TSN:1687					
35-40-01-960-801-01	DISCARD OXYGEN CYLINDER								
	176219-115	MOS	180				31-JUL-2014	**31-JUL-2029**	
35.010	627770712	HRS/MSC							
LIFE LIMIT	**REF:** AMM 35-40-01-960-801	AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-40-05-720-801-01	FUNCTIONAL TEST OXYGEN CYLINDER PRESSURE REDUCTION VALVE								
	PN	MOS	60				28-JUL-2014	**28-JUL-2019**	
35.010	SN-UNKNOWN	HRS/MSC							
	REF: AMM 35-40-05-720-801	AFL							
350801	OXYGEN CYLINDER MANOMETER								
	PN	MOS		TSN:0			13-DEC-2006		
35.150	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
350806	OXYGEN CYLINDER PRESSURE REDUCTION VALVE								
	PN	MOS		TSN:0			13-DEC-2006		
35.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
350811	ALTITUDE OXYGEN SWITCH								
	12595	MOS		TSN:0			13-DEC-2006		
35.160	0959	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351810	SMOKE MASK								
	PN	MOS		TSN:0			13-DEC-2006		
35.180	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
352840	FIRST AID OXYGEN MASK BOX								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
353012	CLEAN NO. 2 PORTABLE OXYGEN BOTTLE MASK								
		MOS					21-JUL-2010		
35.140		HRS/MSC	N/A				965.5		
	REF: GENERIC NO REF	AFL					691		
353022	GENERAL VISUAL INSPECTION NO. 2 PORTABLE OXYGEN BOTTLE OF THE PORTABLE OXYGEN BOTTLE AND MASKS								
	PN	MOS					13-DEC-2006		
35.140	NOT INSTALLED	HRS/MSC	N/A				0		
	REF: AMM 35-30-05-210-801	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
353102	OVERHAUL NO. 2 PORTABLE OXYGEN BOTTLE								
	PN	MOS							
35.140	NOT INSTALLED	HRS/MSC	N/A						
	REF: AMM 35-30-05-350-801	AFL							
353801	SMOKE HOOD								
	802300-14	MOS		TSN:0			28-APR-2017		
35.110	E16100264	HRS/MSC	O/C	TSN:0			2775.3		
	REF: AMM 35-30-01-960-801	AFL		TSN:0			2149		
353851	NO. 1 PORTABLE OXYGEN BOTTLE								
	894-20330	MOS		TSO:0			28-APR-2017		
35.140	P07021122	HRS/MSC	O/C	TSO:0			2775.3		
	REF: GENERIC NO REF	AFL		TSO:0			2149		
353856	NO. 2 PORTABLE OXYGEN BOTTLE								
	PN	MOS		TSN:0			13-DEC-2006		
35.140	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

CHAPTER 36 PNEUMATIC

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-00-01-710-802-01 (s)	OPERATIONAL TEST OF ARINC LINK BETWEEN BASC AND MAU						PKG		
	PKG 24	MOS					13-DEC-2006		
		HRS/MSC	6400				0		
	REF: AMM 36-00-01-710-802	AFL					0		
36-00-01-710-802-01A	OPERATIONAL TEST OF ARINC LINK BETWEEN BASC AND MAU (MANDATORY 5-40)								
		MOS					13-DEC-2006		
		HRS/MSC	9000				0	**9000**	
CMR	**REF:** AMM 36-00-01-710-802	AFL					0		
36-00-01-900-801-01	BLEED AIR SUPPLY (BASC) COMPUTER								
	92189A030800	MOS		TSR:0			04-JAN-2010		
36.090	00102	HRS/MSC	O/C	TSR:0			802.8		
	REF: AMM 36-00-01-900-801	AFL		TSR:0			584		
36-10-02-900-801-01	LH ENGINE HP BLEED AIR VALVE								
	6041A020002	MOS		TSN:0			13-DEC-2006		
36.060	348	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 36-10-02-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-10-02-900-801-02	RH ENGINE HP BLEED AIR VALVE								
	6041A020002	MOS		TSN:0			13-DEC-2006		
36.060	349	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 36-10-02-900-801	AFL		TSN:0			0		
36-10-05-200-801-01 (s)	INSPECTION OF THE NO. 1 ENGINE BLEED AIR CHECK VALVE						PKG		
	PKG 21	MOS					19-APR-2018		
36.070		HRS/MSC	1600	+40			3041.8		
	REF: AMM 36-10-05-200-801	AFL					2328		
36-10-05-200-801-02 (s)	INSPECTION OF THE NO. 2 ENGINE BLEED AIR CHECK VALVE						PKG		
	PKG 21	MOS					19-APR-2018		
36.070		HRS/MSC	1600	+40			3041.8		
	REF: AMM 36-10-05-200-801	AFL					2328		
36-10-11-900-801-01	NO. 1 PRESSURE REDUCING (PRV1) VALVE								
	RYLB53181-2	MOS		TSR:0		07/15/2017	15-JUL-2015		
21.030	0435	HRS/MSC	O/C	TSR:0			2414.5		
	REF: AMM 36-10-11-900-801	AFL		TSR:0			1825		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-10-11-900-801-02	NO. 2 PRESSURE REDUCING (PRV2) VALVE								
	RYLB53181-2	MOS					09-JUL-2015		
21.030	0283	HRS/MSC	O/C	TSR:1688.4			2412.5		
	REF: AMM 36-10-11-900-801	AFL		TSR:1292			1821		
36-10-21-900-801-01	FEEDER ISOLATION VALVE								
	BYLB51994	MOS		TSR:0			09-AUG-2013		
36.050	400	HRS/MSC	O/C	TSR:0			1900.7		
	REF: AMM 36-10-21-900-801	AFL		TSR:0			1346		
+ 36-10-25-200-801-01 (s)	INSPECTION OF THE NO. 1 ENGINE HP BLEED AIR CIRCUIT CHECK VALVE FOR JAMMING						PKG		
	PKG 31	MOS	72	+2m			20-JUN-2013		
36.030		HRS/MSC					1872.8		
	REF: AMM 36-10-25-200-801	AFL	3750				1323		
+ 36-10-25-200-801-02 (s)	INSPECTION OF THE NO. 2 ENGINE HP BLEED AIR CIRCUIT CHECK VALVE FOR JAMMING						PKG		
	PKG 31	MOS	72	+2m			20-JUN-2013		
36.030		HRS/MSC					1872.8		
	REF: AMM 36-10-25-200-801	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 36-10-25-200-801-03 (s)	INSPECTION OF THE APU HP BLEED AIR CIRCUIT CHECK VALVE FOR JAMMING							PKG		
	PKG 31	MOS	72	+2m				20-JUN-2013		
36.040		HRS/MSC						1872.8		
	REF: AMM 36-10-25-200-801	AFL	3750					1323		
36-21-05-900-802-01	LH FORWARD CONDITIONING PAX TEMPERATURE SENSOR									
	RP493-00	MOS			TSN:0			19-MAR-2009		
36.130	DAAB00232	HRS/MSC	O/C		TSN:0			593.3		
	REF: AMM 36-21-05-900-802	AFL			TSN:0			438		
36-21-05-900-803-01	CONDITIONING CREW TEMPERATURE SENSOR									
	RP493-00	MOS			TSN:0			19-MAR-2009		
36.150	DAAB00222	HRS/MSC	O/C		TSN:0			593.3		
	REF: AMM 36-21-05-900-803	AFL			TSN:0			438		
36-21-07-900-801-01	CONDITIONING PAX PRESSURE SENSOR									
	ZRA233-01	MOS			TSN:2			24-JUL-2007		
36.110	1779	HRS/MSC	O/C		TSN:133.4			133.4		
	REF: AMM 36-21-07-900-801	AFL			TSN:79			79		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-21-13-900-802-01	NO. 1 ENGINE HP/LP TEMPERATURE SENSOR								
	RP482-00	MOS		TSN:0			02-AUG-2007		
36.100	00310	HRS/MSC	O/C	TSN:0			134.2		
	REF: AMM 36-21-13-900-802	AFL		TSN:0			80		
36-21-13-900-803-01	NO. 2 ENGINE HP/LP TEMPERATURE SENSOR								
	RP482-00	MOS		TSN:0			02-AUG-2007		
36.100	00301	HRS/MSC	O/C	TSN:0			134.2		
	REF: AMM 36-21-13-900-803	AFL		TSN:0			80		
36-21-21-710-801-01 (s)	OPERATIONAL TEST OF THE LH PYLON OVERHEAT PROBE						PKG		
	PKG 21	MOS					18-APR-2018		
36.020		HRS/MSC	1600 +40				3041.8		
	REF: AMM 36-21-21-710-801	AFL					2328		
36-21-21-710-801-01A	OPERATIONAL TEST OF THE LH PYLON OVERHEAT PROBE (MANDATORY 5-40)								
		MOS					18-APR-2018		
36.020		HRS/MSC	1800				3041.8	**4841.8**	
CMR	**REF:** AMM 36-21-21-710-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-21-21-710-801-02 (s)	OPERATIONAL TEST OF THE RH PYLON OVERHEAT PROBE							PKG		
	PKG 21	MOS						18-APR-2018		
36.020		HRS/MSC	1600	+40				3041.8		
	REF: AMM 36-21-21-710-801	AFL						2328		
36-21-21-710-801-02A	OPERATIONAL TEST OF THE RH PYLON OVERHEAT PROBE (MANDATORY 05-40)									
		MOS						18-APR-2018		
36.020		HRS/MSC	1800					3041.8	**4841.8**	
CMR	**REF:** AMM 36-21-21-710-801	AFL						2328		
361061	NO. 1 ENGINE HP BLEED AIR CIRCUIT CHECK VALVE									
	CYLB51161-2	MOS			TSN:0			13-DEC-2006		
36.030	3269	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	AFL			TSN:0			0		
361062	NO. 2 ENGINE HP BLEED AIR CIRCUIT CHECK VALVE									
	CYLB51161-2	MOS			TSN:0			13-DEC-2006		
36.030	3267	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361063	APU HP BLEED AIR CIRCUIT CHECK VALVE								
	CYLB51161-2	MOS		TSN:0			13-DEC-2006		
36.040	3275	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
361064	NO. 1 ENGINE BLEED AIR CHECK VALVE								
	CYLB51161-2	MOS		TSN:0			13-DEC-2006		
36.070	3270	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
361065	NO. 2 ENGINE BLEED AIR CHECK VALVE								
	CYLB51161-2	MOS		TSN:0			13-DEC-2006		
36.070	3268	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
361801	PNEUMATIC - GROUND POWER RECEPTACLE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-42-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361891	LH PYLON OVERHEAT PROBE								
	H125	MOS		TSN:0			13-DEC-2006		
36.160	RQ361	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
361892	RH PYLON OVERHEAT PROBE								
	H125	MOS		TSN:0			13-DEC-2006		
36.160	RQ360	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 38	**WATER/WASTE**								
38-00-00-610-801-01 (s)	SERVICING OF THE WATER SYSTEM						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
38.030		HRS/MSC					3041.8		
	REF: AMM 38-00-00-610-801	AFL					2328		
38-00-00-900-801-01	FULL LIGHT INHIBITION MICROSWITCH								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 38-00-00-900-801	AFL		TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-10-00-210-801-01 (s)	DETAILED INSPECTION OF WATER SYSTEM COMPONENTS							PKG		
	PKG 31	MOS	72	+2m				08-JUL-2013		
		HRS/MSC						1872.8		
	REF: AMM 38-10-00-210-801	AFL	3750					1323		
38-10-00-670-801-01 (s)	STERILIZATION OF THE POTABLE WATER SYSTEM							PKG		
	PKG 11 ,12 ,14 ,31	MOS	8	+1m				17-APR-2018		
38.010		HRS/MSC						3041.8		
	REF: AMM 38-10-00-670-801	AFL						2328		
38-13-09-900-801-01	REAR WATER HEATER									
	8921082G6	MOS			TSN:0			16-DEC-2016		
38.050	N1616124	HRS/MSC	O/C		TSN:0			2676.9		
	REF: AMM 38-13-09-900-801	AFL			TSN:0			2076		
38-13-09-900-802-01	FORWARD WATER HEATER									
	7700244-503	MOS						13-DEC-2006		
	06-04-38812	HRS/MSC	O/C					0		
	REF: AMM 38-13-09-900-802	AFL						0		
		APH						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-13-55-710-801-01	OPERATIONAL TEST OF THE LAVATORY WATER SOLENOID / PAD								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 38-13-55-710-801	AFL					0		
38-15-01-710-801-01	OPERATIONAL TEST OF THE UV STERILIZER								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 38-15-01-710-801	AFL					0		
		APH					0		
38-15-09-900-801-01	ULTRA-VIOLET (UV) LAMP								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 38-15-09-900-801	AFL		TSN:0			0		
38-15-09-960-801-01	REPLACEMENT ULTRA-VIOLET (UV) LAMP								
	PN	MOS					13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 38-15-09-960-801	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-15-17-100-801-01	CLEANING OF THE UV STERILIZER QUARTZ SLEEVE						PKG		
	PKG 39	MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 38-15-17-100-801	AFL					0		
		APH					0		
38-30-01-900-801-01	FRONT WATER HEATED DRAIN MASTS DRAIN MAST								
	MAT-302706-A	MOS		TSN:0			13-SEP-2010		
38.060	532	HRS/MSC	O/C	TSN:0			1040.9		
	REF: AMM 38-30-01-900-801	AFL		TSN:0			737		
38-30-01-900-801-02	REAR WATER DRAIN STUB								
	MAT-200506	MOS		TSN:0			13-DEC-2006		
38.020	S1CV/03	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 38-30-01-900-801	AFL		TSN:0			0		
38-30-09-900-801-01	GALLEY DRAIN VALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 38-30-09-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-30-09-900-801-02	AFT LAVATORY DRAIN VALVE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 38-30-09-900-801	AFL		TSN:0			0		
38-31-13-160-801-01	CLEANING OF THE STRAINER								
		MOS							
		HRS/MSC	-						
	REF: AMM 38-31-13-160-801	AFL							
38-31-13-960-801-01	REPLACEMENT OF THE GALLEY WATER FILTER								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 38-31-13-960-801	AFL					0		
38-34-17-210-801-01	GENERAL VISUAL INSPECTION OF THE FORWARD TOILET DRAIN CONTROL								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 38-34-17-210-801	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-34-21-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE AFT TOILET DRAIN CONTROL							PKG		
	PKG 14 ,31	MOS	32	+1m				16-APR-2018		
		HRS/MSC						3041.8		
	REF: AMM 38-34-21-210-801	AFL						2328		
38-40-17-900-801-01	HIGH PRESSURE REGULATOR AIR FILTER ASSEMBLY									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 38-40-17-900-801	AFL			TSN:0			0		
38-40-21-900-801-01	LOW-PRESSURE REGULATOR FILTER									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 38-40-21-900-801	AFL			TSN:0			0		
381810	WATER STORAGE SYSTEM VALVE									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
381821	WATER SYSTEM LEVEL GAUGE								
	M8540-21	MOS		TSN:0			20-MAY-2010		
38.040	NSN	HRS/MSC	O/C	TSN:0			933.6		
	REF: GENERIC NO REF	AFL		TSN:0			661		
381851	WATER SYSTEM ACCUMULATOR								
	7700181-501	MOS		TSN:0			13-DEC-2006		
38.070	14637-1-06	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
381861	MAIN FILTER (WATER) ASSEMBLY								
	AD-9410-672	MOS		TSN:0			02-JUL-2015		
38.080	2642	HRS/MSC	O/C	TSN:0			2409.6		
	REF: GENERIC NO REF	AFL		TSN:0			1816		
381871	COMPOSITE WATER TANK								
	7700237-503	MOS		TSN:0			13-DEC-2006		
38.090	690	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
381876	REAR TOILET DISTRIBUTION VALVE								
	PN	MOS							
38.110	SN-UNKNOWN	HRS/MSC	O/C						
	REF: GENERIC NO REF	AFL							
382011	TOILET								
	15900-018	MOS		TSN:0			13-DEC-2006		
38.100	116	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
383801	HEATED DRAIN LINE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 45	**CENTRAL MAINT SYSTEM**								
45-00-00-070-801-01	ACCOMPLISH ERASE OF THE AIRCRAFT FAULT CODES								
		MOS					13-DEC-2006		
45.050		HRS/MSC	A/R				0		
	REF: AMM 45-00-00-070-801	AFL					0		
		APH					0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
45-00-00-970-801-01	DOWNLOAD OF THE ENGINE COMPUTERS								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 45-00-00-970-801	AFL					0		
45-10-00-910-802-01	ACCOMPLISH USE OF THE CENTRAL MAINTENANCE COMPUTER (CMC)								
		MOS					13-DEC-2006		
45.040		HRS/MSC	A/R				0		
	REF: AMM 45-10-00-910-802	AFL					0		
		APH					0		
45-10-00-970-801-01	DOWNLOAD OF THE FAULT HISTORY DATABASE (FHDB)								
		DAYS					07-AUG-2017		
		HRS/MSC	O/C				2882.6		
	REF: AMM 45-10-00-970-801	AFL					2216		
45-10-01-900-801-01	CENTRAL MAINTENANCE COMPUTER (CMC) MODULE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 45-10-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
45-90-00-810-801-01	DATA LOADING TROUBLESHOOTING								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 45-90-00-810-801	AFL					0		
45-90-00-860-801-01B	UPDATE INDS ELECTRONIC TERMINAL CHARTS (BLUE DISC)								
		MOS					25-MAY-2018	**06-JUN-2018 M**	
		HRS/MSC	A/R				3041.8		
	REF: AMM 45-90-00-860-801	AFL					2328		
45-90-00-860-801-01G	UPDATE INDS EGPWM DATA (GREEN DISC)								
		MOS					24-JUN-2017		
		HRS/MSC	A/R				2832.2		
	REF: AMM 45-90-00-860-801	AFL					2192		
45-90-00-860-801-01R	UPDATE INDS EPIC AIRSPACE & COMM & NAVIGATION DATA (RED DISC)								
		MOS					25-MAY-2018	**20-JUN-2018 M**	
		HRS/MSC	A/R				3041.8		
	REF: AMM 45-90-00-860-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
45-90-00-860-803-01	DATABASE LOADING								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 45-90-00-860-803	AFL					0		
45-90-00-860-804-01	SOFTWARE LOADING								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 45-90-00-860-804	AFL					0		
45-90-00-910-801-01	ACCOMPLISH USE OF DATA LOADING SYSTEM (DLS) AND PRIMUS EPIC MAINTENANCE UTILITIES TOOLS								
		MOS					13-DEC-2006		
45.030		HRS/MSC	O/C				0		
	REF: AMM 45-90-00-910-801	AFL					0		
45-90-00-910-802-01	USE OF PRIMUS EPIC MAINTENANCE UTILITIES TOOLS								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 45-90-00-910-802	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
45-90-01-900-801-01	DATA MANAGEMENT (DMU) UNIT								
	7031051-902	MOS		TSR:0			12-OCT-2011		
34.200	07101402	HRS/MSC	O/C	TSR:0			1371.5		
	REF: AMM 45-90-01-900-801	AFL		TSR:0			945		
453811	MAINTENANCE COMPUTER								
	7034055-1901	MOS		TSN:0			16-JUN-2015		
45.020	14124292	HRS/MSC	O/C	TSN:0			2409.6		
	REF: GENERIC NO REF	AFL		TSN:0			1816		
CHAPTER 46	**INFORMATION SYSTEMS**								
46-20-02-720-801-01	FUNCTIONAL TEST PILOT ELECTRONIC DISPLAY (EDU) UNIT BATTERY								
	PN	MOS					13-DEC-2006		
	NOT INSTALLED	HRS/MSC	N/A				0		
	REF:	AFL					0		
		APH					0		
46-20-02-720-801-02	FUNCTIONAL TEST COPILOT ELECTRONIC DISPLAY (EDU) UNIT BATTERY								
	PN	MOS					13-DEC-2006		
	NOT INSTALLED	HRS/MSC	N/A				0		
	REF:	AFL					0		
		APH					0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
46-20-02-900-801-01	PILOT ELECTRONIC DISPLAY(EDU) UNIT								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
46-20-02-900-801-02	COPILOT ELECTRONIC DISPLAY(EDU) UNIT								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
46-90-02-900-801-01	PILOT ELECTRONIC DISPLAY (EDU) UNIT								
	PN	MOS		TSN:0			13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
		APH		TSN:0			0		
46-90-02-900-801-02	COPILOT ELECTRONIC DISPLAY (EDU) UNIT								
	PN	MOS		TSN:0			13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
		APH		TSN:0			0		

CHAPTER 49 AIRBORNE AUXILIARY POWER

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
49-50-01-900-802-01	APU AIR INLET DOOR ACTUATOR								
	221400M04	MOS		TSR:0			03-JUN-2010		
49.190	142-A	HRS/MSC	O/C	TSR:0			943.2		
	REF: AMM 49-50-01-900-802	AFL		TSR:0			671		
491812	APU TRUSS ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
499801	COMPUTER BATTERY								
	PN	MOS		TSN:0			13-DEC-2006		
49.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
49APU1	APU								
	3800548-2	MOS		TSN:0			31-AUG-2006		
49.APU1	P-469	HRS/MSC	E/C	TSN:0			0		
	REF: AMM 49-10-01-900-802	AFL		TSN:0			0		

APU Model : GTCP36-150(F2M) Serial # P-469 Part # 3800548-2

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

APU#: S/N P-469
1042 HRS, 2865 APUS

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 49-10-05-220-801-01	APU - DETAILED INSPECTION COMPRESSOR ROTOR									
	3822281-1	MOS						05-MAY-2006		
	050350109845	HRS/MSC	4500	+3%				0	**4500**	4635
	REF:	APUS						0		
49-10-05-960-801-01	APU - DISCARD COMPRESSOR ROTOR									
	3822281-1	MOS						05-MAY-2006		
	050350109845	HRS/MSC	100000					0	**100000**	
	REF:	APUS						0		
49-10-09-960-801-01	APU - DISCARD TURBINE ROTOR									
	3615880-1	MOS						05-MAY-2006		
	060134501648	HRS/MSC	10000					0	**10000**	
	REF:	APUS						0		
+ 49-20-00-220-801-01	APU - DETAILED INSPECTION OF THE APU HOT SECTION									
		MOS						05-MAY-2006		
		HRS/MSC	4500	+3%				0	**4500**	4635
	REF: MM 49-20-00	APUS						0		

?-Insufficient Information **+-Task exists in Inspection Manual** **(s)-Suppressed Requirement** **(EBT)-Estimated Base Time** ***-Estimated Due (New Requirement)** **(EFF)-Effective C/W**
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

APU#: S/N P-469
1042 HRS, 2865 APUS

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
49-31-07-960-801-01	APU - REPLACEMENT OF THE APU FUEL FILTER									
		MOS						21-MAY-2018		
		HRS/MSC	1000	+3%		-42		1042	**2000**	2030
	REF: See Workcard	APUS						2865		
+ 49-31-09-200-801-01	APU - CHECK OF THE FLOW RATE OF THE APU FUEL NOZZLE									
		MOS						05-MAY-2006		
		HRS/MSC	4500	+3%				0	**4500**	4635
	REF: MM 49-20-00	APUS						0		
49-41-04-220-801-01	APU - DETAILED INSPECTION 9 O'CLOCK IGNITOR PLUG									
	PN	MOS						13-JUN-2011		
	SN-UNKNOWN	HRS/MSC	750	+3%				378	**1128**	1150.5
	REF: MM 49-40-33	APUS						1125		
49-41-04-220-801-02	APU - DETAILED INSPECTION 5 O'CLOCK IGNITOR PLUG (IF INSTALLED)									
	PN	MOS						13-JUN-2011		
	SN-UNKNOWN	HRS/MSC	750	+3%				378	**1128**	1150.5
	REF: MM 49-40-33	APUS						1125		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

APU#: S/N P-469
1042 HRS, 2865 APUS

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
49-41-04-900-801-01	APU - 9 O'CLOCK IGNITOR PLUG								
	PN	MOS		TSN:0			13-JUN-2011		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			378		
	REF:	APUS		TSN:0			1125		
49-41-04-900-801-02	APU - 5 O'CLOCK IGNITOR PLUG								
	PN	MOS		TSN:0			13-JUN-2011		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			378		
	REF:	APUS		TSN:0			1125		
49-41-04-960-801-01	APU - REPLACE 9 O'CLOCK IGNITOR PLUG								
	PN	MOS			-39		13-JUN-2011		
	SN-UNKNOWN	HRS/MSC	O/C				378		
	REF: MM 49-40-33	APUS					1125		
49-41-04-960-801-02	APU - REPLACE 5 O'CLOCK IGNITOR PLUG								
	PN	MOS			-39		13-JUN-2011		
	SN-UNKNOWN	HRS/MSC	O/C				378		
	REF: MM 49-40-33	APUS					1125		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

APU#: S/N P-469
1042 HRS, 2865 APUS

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
49-91-00-610-802-01	APU - REPLACEMENT OF THE APU OIL									
		MOS				-6		28-SEP-2015		
		HRS/MSC	O/C					657		
	REF: MM 49-20-00	APUS						2163		
+ 49-91-01-220-801-01	APU - INSPECTION OF THE APU MAGNETIC DRAIN PLUG									
		MOS	17	+3%				09-MAY-2017	**09-OCT-2018**	24-OCT-2018
		HRS/MSC	750	+3%				834	**1584**	1606.5
	REF: MM 49-90-46	APUS						2318		
49-91-04-960-801-01	APU - REPLACEMENT OF THE APU OIL FILTER ELEMENT									
		MOS	17	+3%				09-MAY-2017	**09-OCT-2018**	24-OCT-2018
		HRS/MSC	750	+3%				834	**1584**	1606.5
	REF: MM 49-90-47	APUS						2318		
491010	APU - TURBINE ROTOR									
	3615880-1	MOS			TSN:0			05-MAY-2006		
	060134501648	HRS/MSC	O/C		TSN:0			0		
	REF:	APUS			TSN:0			0		

?-Insufficient Information **+-Task exists in Inspection Manual** **(s)-Suppressed Requirement** **(EBT)-Estimated Base Time** ***-Estimated Due (New Requirement)** **(EFF)-Effective C/W**
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
491020	APU - COMPRESSOR ROTOR								
	3822281-1	MOS		TSN:0			05-MAY-2006		
	050350109845	HRS/MSC	O/C	TSN:0			0		
	REF:	APUS		TSN:0			0		
491122	APU - FUEL SHUTOFF VALVE								
	692545-18	MOS							
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: MM 49-30-54	APUS							
493010	APU - FUEL CONTROL								
	3882730-8	MOS		TSN:0			05-MAY-2006		
	30551	HRS/MSC	O/C	TSN:0			0		
	REF: MM 49-30-52	APUS		TSN:0			0		
493030	APU - ORIFICE FITTING								
	PN	MOS		TSN:0			05-MAY-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: MM 49-30-56	APUS		TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

APU#: S/N P-469
1042 HRS, 2865 APUS

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493060	APU - CONTROLLER								
	2118844-1	MOS		TSN:0			05-MAY-2006		
	46A0387	HRS/MSC	O/C	TSN:0			0		
	REF: MM 49-60-46	APUS		TSN:0			0		
493070	APU - LOAD CONTROL VALVE								
	109812-14	MOS		TSO:0			24-JUN-2017		
	3142	HRS/MSC	O/C	TSO:0			862		
	REF: MM 49-50-33	APUS		TSO:0			2318		
494010	APU - IGNITION UNIT								
	3876280-4	MOS		TSN:0			05-MAY-2006		
	060218066430	HRS/MSC	O/C	TSN:0			0		
	REF: MM 49-40-32	APUS		TSN:0			0		
497010	APU - MOTIONAL PICK UP TRANSDUCER								
	PN	MOS		TSN:0			05-MAY-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: MM 49-60-43	APUS		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
497020	APU - IMMERSION THERMOCOUPLE								
	3876003-3	MOS		TSN:0			07-MAY-2016		
	1615027700245	HRS/MSC	O/C	TSN:0			692		
	REF: MM 49-60-45	APUS		TSN:0			2275		
497030	APU - HOURMETER								
	PN	MOS		TSN:0			05-MAY-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: MM 49-70-41	APUS		TSN:0			0		
499010	APU - OIL ROTARY PUMP								
	PN	MOS		TSN:0			05-MAY-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: MM 49-90-51	APUS		TSN:0			0		
499050	APU - OIL PRESSURE REGULATOR VALVE								
	PN	MOS		TSN:0			05-MAY-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: MM 49-90-52	APUS		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
499060	APU - HIGH OIL TEMPERATURE SENSOR								
	PN	MOS		TSN:0			05-MAY-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: MM 49-60-46	APUS		TSN:0			0		
499070	APU - LOW OIL PRESSURE SWITCH								
	PN	MOS		TSN:0			05-MAY-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: MM 49-60-43	APUS		TSN:0			0		
499080	APU - OIL LEVEL DETECTOR								
	722446	MOS		TSR:0			08-MAR-2010		
	952	HRS/MSC	O/C	TSR:0			289		
	REF:	APUS		TSR:0			818		
CHAPTER 52	**DOORS**								
52-00-00-200-801-01 (s)	INSPECTION/CHECK OF THE PASSENGER DOORS SEALS						PKG		
	PKG 31	MOS	72	+2m			17-JUN-2013		
53.120		HRS/MSC					1872.8		
	REF: AMM 52-00-00-200-801	AFL	3750				1323		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-00-00-200-801-02 (s)	INSPECTION/CHECK OF THE BAGGAGE COMPARTMENT DOORS SEALS						PKG		
	PKG 31	MOS	72	+2m			17-JUN-2013		
53.120		HRS/MSC					1872.8		
	REF: AMM 52-00-00-200-801	AFL	3750				1323		
52-00-00-200-801-03 (s)	INSPECTION/CHECK OF THE FORWARD SERVICING COMPARTMENT DOORS SEALS						PKG		
	PKG 31	MOS	72	+2m			17-JUN-2013		
53.120		HRS/MSC					1872.8		
	REF: AMM 52-00-00-200-801	AFL	3750				1323		
52-00-00-200-801-04 (s)	INSPECTION/CHECK OF THE AFT SERVICING COMPARTMENT DOORS SEALS						PKG		
	PKG 31	MOS	72	+2m			17-JUN-2013		
53.120		HRS/MSC					1872.8		
	REF: AMM 52-00-00-200-801	AFL	3750				1323		
52-00-00-640-801-01 (s)	LUBRICATION OF SERVICE DOORS						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			18-APR-2018		
52.010		HRS/MSC	400	+40			3041.8		
	REF: AMM 52-00-00-640-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10-00-610-801-01 (s)	SERVICING OF THE PASSENGER DOOR							PKG		
	PKG 14 ,31	MOS	32	+1m				23-APR-2018		
52.020		HRS/MSC						3041.8		
	REF: AMM 52-10-00-610-801	AFL						2328		
52-10-00-610-802-01 (s)	SERVICING OF THE PASSENGER DOOR SAFETY CATCH							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				16-APR-2018		
		HRS/MSC	400	+40				3041.8		
	REF: AMM 52-10-00-610-802	AFL						2328		
52-10-00-640-801-01 (s)	LUBRICATION PASSENGER OF THE ROLLERS OF THE PASSENGER DOOR LOWER MECHANISM							PKG		
	PKG 32	MOS	144	+2m				13-DEC-2006		
52.140		HRS/MSC						0		
	REF: AMM 52-10-00-640-801	AFL	7500					0		
52-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PASSENGER DOOR							PKG		
	PKG 31	MOS	72	+2m				10-JUL-2013		
52.020		HRS/MSC						1872.8		
	REF: AMM 52-10-00-720-801	AFL	3750					1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10-01-900-801-01	PASSENGER DOOR								
	FGFB295A8	MOS		TSN:0			13-DEC-2006		
52.020	53HP161	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-10-01-900-801	AFL		TSN:0			0		
52-10-03-900-801-01	PASSENGER DOOR PNEUMATIC ACTUATOR								
	222900-1M03	MOS		TSN:0			28-APR-2017		
52.030	2582	HRS/MSC	O/C	TSN:0			2775.3		
	REF: AMM 52-10-03-900-801	AFL		TSN:0			2149		
52-10-03-960-801-01	DISCARD PASSENGER DOOR PNEUMATIC ACTUATOR								
	222900-1M03	MOS	60				28-APR-2017	**28-APR-2022**	
52.030	2582	HRS/MSC					2775.3		
LIFE LIMIT	**REF:** AMM 52-10-03-960-801	AFL					2149		
52-10-09-900-801-01	PASSENGER DOOR GEARED MOTOR								
	222200-1M01	MOS		TSN:0			13-DEC-2006		
52.030	371	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-10-09-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20-00-610-801-01 (s)	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
		HRS/MSC					3041.8		
	REF: AMM 52-20-00-610-801	AFL					2328		
+ 52-20-00-610-801-01A	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN (MANDATORY 5-40)								
		MOS	24				17-APR-2018	**17-APR-2020**	
52.040		HRS/MSC					3041.8		
MANDATORY 5-40	**REF:** AMM 52-20-00-610-801	AFL					2328		
52-20-00-610-801-02 (s)	SERVICING OF THE EMERGENCY EXIT DOOR						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
52.040		HRS/MSC					3041.8		
	REF: AMM 52-20-00-610-801	AFL					2328		
52-20-00-710-801-01 (s)	OPERATIONAL TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM OUTSIDE						PKG		
	PKG 21	MOS					17-APR-2018		
52.040		HRS/MSC	1600	+40			3041.8		
	REF: AMM 52-20-00-710-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20-01-900-801-01	EMERGENCY EXIT DOOR								
	F2MA296001	MOS		TSN:0			13-DEC-2006		
52.040	HAI270	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-20-01-900-801	AFL		TSN:0			0		
52-30-00-610-801-01 (s)	SERVICING OF THE BAGGAGE COMPARTMENT DOOR						PKG		
	PKG 14 ,31	MOS	32	+1m			18-APR-2018		
52.050		HRS/MSC					3041.8		
	REF: AMM 52-30-00-610-801	AFL					2328		
52-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT DOOR MECHANISMS						PKG		
	PKG 31	MOS	72	+2m			21-JUN-2013		
52.060		HRS/MSC					1872.8		
	REF: AMM 52-30-00-710-801	AFL	3750				1323		
52-30-01-900-801-01	BAGGAGE COMPARTMENT MAIN DOOR								
	F2MA249001801	MOS		TSN:0			13-DEC-2006		
52.050	TB113SL344	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-30-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30-01-900-801-02	LOWER (AUXILIARY) BAGGAGE COMPARTMENT DOOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-30-01-900-801	AFL		TSN:0			0		
52-40-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE ACCESS PANELS AND DOORS						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
52.090		HRS/MSC					2832.2		
	REF: AMM 52-40-00-210-801	AFL					2192		
52-41-07-610-801-01 (s)	SERVICING OF THE NLG WELL CEILING DOOR						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
52.100		HRS/MSC					2832.2		
	REF: AMM 52-41-07-610-801	AFL					2192		
52-50-00-710-801-01 (s)	INSPECTION/TEST OF THE BLOWOUT DOORS / PANELS						PKG		
	PKG 31	MOS	72	+2m			13-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 52-50-00-710-801	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-54-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF CABIN DOORS, DIVIDERS AND BULKHEADS						PKG		
	PKG 31	MOS	72	+2m			10-JUL-2013		
		HRS/MSC					1872.8		
	REF: AMM 52-54-00-210-801	AFL	3750				1323		
52-54-05-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR						PKG		
	PKG 2 ,31	MOS	16	+1m			16-APR-2018		
		HRS/MSC	800	+40			3041.8		
	REF: AMM 52-54-05-210-801	AFL					2328		
52-54-05-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR - INSPECTION OF MOUNTING LOCATIONS, LAMINATE AND MECHANISM						PKG		
	PKG 31	MOS	72	+2m			08-JUL-2013		
		HRS/MSC					1872.8		
	REF: AMM 52-54-05-210-801	AFL	3750				1323		
52-60-01-610-801-01 (s)	SERVICING OF THE FORWARD SERVICING COMPARTMENT DOOR						PKG		
	PKG 14 ,31	MOS	32	+1m			17-APR-2018		
52.070		HRS/MSC					3041.8		
	REF: AMM 52-60-01-610-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-60-09-610-801-01 (s)	SERVICING OF THE AFT SERVICING COMPARTMENT DOOR						PKG		
	PKG 14 ,31	MOS	32	+1m			17-APR-2018		
52.080		HRS/MSC					3041.8		
	REF: AMM 52-60-09-610-801	AFL					2328		
52-70-00-710-802-01 (s)	OPERATIONAL TEST OF THE PASSENGER DOOR INDICATING SYSTEM						PKG		
	PKG 14 ,31,204	MOS	32	+1m			17-APR-2018		
52.120		HRS/MSC					3041.8		
	REF: AMM 52-70-00-710-802	AFL					2328		
52-70-00-710-802-02 (s)	OPERATIONAL TEST OF THE EMERGENCY EXIT DOOR INDICATING SYSTEM						PKG		
	PKG 14 ,31,204	MOS	32	+1m			17-APR-2018		
52.120		HRS/MSC					3041.8		
	REF: AMM 52-70-00-710-802	AFL					2328		
52-70-00-710-802-03 (s)	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT DOOR INDICATING SYSTEM						PKG		
	PKG 14 ,31,204	MOS	32	+1m			17-APR-2018		
52.120		HRS/MSC					3041.8		
	REF: AMM 52-70-00-710-802	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-70-00-710-802-04 (s)	OPERATIONAL TEST OF THE FORWARD SERVICING COMPARTMENT DOOR INDICATING SYSTEM						PKG		
	PKG 14 ,31,204	MOS	32	+1m			17-APR-2018		
52.120		HRS/MSC					3041.8		
	REF: AMM 52-70-00-710-802	AFL					2328		
52-70-00-710-802-05 (s)	OPERATIONAL TEST OF THE AFT SERVICING COMPARTMENT DOOR INDICATING SYSTEM						PKG		
	PKG 14 ,31,204	MOS	32	+1m			17-APR-2018		
52.120		HRS/MSC					3041.8		
	REF: AMM 52-70-00-710-802	AFL					2328		
52-70-00-710-802-06	OPERATIONAL TEST OF THE FORWARD LAVATORY SERVICE DOOR INDICATING SYSTEM						PKG		
	PKG 204	MOS					02-DEC-2009		
52.120		HRS/MSC	N/A				802.8		
	REF: AMM 52-70-00-710-802	AFL					584		
52-80-05-900-801-01	LH MLG LATERAL DOOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-80-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-80-05-900-801-02	RH MLG LATERAL DOOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-80-05-900-801	AFL		TSN:0			0		
523801	FORWARD SERVICING COMPARTMENT DOOR								
	F2MA259003415	MOS		TSN:0			13-DEC-2006		
52.070	TA0366L/N0367	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-30-01-900-801	AFL		TSN:0			0		
523806	AFT SERVICING COMPARTMENT DOOR								
	F2MA259011	MOS		TSN:0			13-DEC-2006		
52.080	TB112L/N346	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-30-01-900-801	AFL		TSN:0			0		
528801	LH FRONT NOSE LANDING GEAR DOOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
528802	RH FRONT NOSE LANDING GEAR DOOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
528810	NLG AUXILIARY SHIELD DOOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
528815	LH WING LANDING GEAR DOOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-80-05-900-801	AFL		TSN:0			0		
528820	NLG MAIN SHIELD DOOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
528825	RH WING LANDING GEAR DOOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-80-05-900-801	AFL		TSN:0			0		
CHAPTER 53	**FUSELAGE**								
+ 53-00-00-200-803-01	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 26								
		MOS					13-DEC-2006		
53.150		HRS/MSC					0		
	REF: AMM 53-00-00-200-803	AFL	11250				0	**11250**	
+ 53-00-00-200-803-01A	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 26 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
53.150		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-00-00-200-803	AFL	11250				0	**11250**	
53-00-00-200-803-02	DETAILED INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 26								
		MOS					13-DEC-2006		
53.490		HRS/MSC					0		
	REF: AMM 53-00-00-200-803	AFL	11250				0	**11250**	
		APH					0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00-00-200-803-02A	DETAILED INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 26 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
53.490		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-00-00-200-803	AFL	11250				0	**11250**	
		APH					0		
53-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
53.010		HRS/MSC					2832.2		
	REF: AMM 53-00-00-210-801	AFL					2192		
53-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR (CPCP)								
		MOS	25				24-JUN-2017	**24-JUL-2019**	
53.010		HRS/MSC					2832.2		
CPCP	**REF:** AMM 53-00-00-210-801	AFL					2192		
53-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR						PKG		
	PKG 31	MOS	72	+2m			17-JUN-2013		
53.010		HRS/MSC					1872.8		
	REF: AMM 53-00-00-220-801	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00-00-220-801-01C	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR (CPCP)								
		MOS	74				17-JUN-2013	**17-AUG-2019**	
		HRS/MSC					1872.8		
CPCP	**REF:** AMM 53-00-00-220-801	AFL					1323		
53-10-00-200-808-01 (s)	INSPECTION OF THE NLG BAY						PKG		
	PKG 11 ,12 ,14 ,31	MOS	8	+1m			17-APR-2018		
53.110		HRS/MSC					3041.8		
	REF: AMM 53-10-00-200-808	AFL					2328		
53-10-00-200-808-01C	INSPECTION OF THE NLG BAY (CPCP)								
		MOS	9				17-APR-2018	**17-JAN-2019**	
53.110		HRS/MSC					3041.8		
CPCP	**REF:** AMM 53-10-00-200-808	AFL					2328		
+ 53-10-00-200-810-01	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4								
		MOS					13-DEC-2006		
53.140		HRS/MSC					0		
	REF: AMM 53-10-00-200-810	AFL	7500				0		**7500**

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-00-200-810-01A	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
53.140		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-10-00-200-810	AFL	7500				0	**7500**	
53-10-00-200-810-02	DETAILED INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4								
		MOS					13-DEC-2006		
53.485		HRS/MSC					0		
	REF: AMM 53-10-00-200-810	AFL	11250				0	**11250**	
		APH					0		
53-10-00-200-810-02A	DETAILED INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
53.485		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-10-00-200-810	AFL	11250				0	**11250**	
		APH					0		
53-10-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
53.0301		HRS/MSC					2832.2		
	REF: AMM 53-10-00-210-802	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-00-220-801-01 (s)	DETAILED INSPECTION OF THE STATIC PRESSURE PROBES AND OF THE FUSELAGE SKIN IN PROBE AREAS						PKG		
	PKG 18 ,31,205	MOS	24	+1m			18-APR-2018		
53.410		HRS/MSC					3041.8		
RVSM	**REF:** AMM 53-10-00-220-801	AFL					2328		
53-10-00-220-802-01 (s)	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT						PKG		
	PKG 31	MOS	72	+2m			08-JUL-2013		
53.0302		HRS/MSC					1872.8		
	REF: AMM 53-10-00-220-802	AFL	3750				1323		
53-10-00-220-802-01C	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)								
		MOS	74				08-JUL-2013	**08-SEP-2019**	
53.0302		HRS/MSC					1872.8		
CPCP	**REF:** AMM 53-10-00-220-802	AFL					1323		
53-10-01-250-801-01 (s)	EDDY CURRENT INSPECTION OF THE FRAME 0 STIFFENER TIP						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
53.190		HRS/MSC					0		
	REF: AMM 53-10-01-250-801	AFL	7500				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-03-220-801-03 (s)	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS						PKG		
	PKG 32	MOS	144	+2m			04-MAY-2007		
		HRS/MSC					0		
	REF: AMM 53-10-03-220-801	AFL	7500				0		
53-10-03-220-801-03C	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS (CPCP)								
		MOS	148				04-MAY-2007	**04-SEP-2019**	
		HRS/MSC					0		
CPCP	**REF:** AMM 53-10-03-220-801	AFL					0		
53-10-03-250-801-01 (s)	SPECIAL DETAILED INSPECTION OF THE UPPER PASSENGER DOOR FRAME EDGING						PKG		
	PKG 33	MOS	216	+2m			13-DEC-2006		
53.180		HRS/MSC					0		
	REF: AMM 53-10-03-250-801	AFL	11250				0		
+ 53-10-03-250-801-01A	SPECIAL DETAILED INSPECTION OF THE UPPER PASSENGER DOOR FRAME EDGING (MANDATORY 5-40)								
		MOS					13-DEC-2006		
53.180		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-10-03-250-801	AFL	11250				0	**11250**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-11-250-801-01 (s)	SPECIAL DETAILED INSPECTION OF THE SPLICE AT FRAME 11							PKG		
	PKG 33	MOS	216	+2m				13-DEC-2006		
53.370		HRS/MSC						0		
	REF: AMM 53-10-11-250-801	AFL	11250					0		
53-10-11-250-801-01A	SPECIAL DETAILED INSPECTION OF THE SPLICE AT FRAME 11 (MANDATORY 05-40)									
		MOS						13-DEC-2006		
53.370		HRS/MSC						0		
MANDATORY 5-40	**REF:** AMM 53-10-11-250-801	AFL	11250					0	**11250**	
53-10-39-220-801-01 (s)	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES							PKG		
	PKG 31	MOS	72	+2m				19-JUN-2013		
53.200		HRS/MSC						1872.8		
	REF: AMM 53-10-39-220-801	AFL	3750					1323		
53-10-39-220-801-01C	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)									
		MOS	74					19-JUN-2013	**19-AUG-2019**	
53.200		HRS/MSC						1872.8		
CPCP	**REF:** AMM 53-10-39-220-801	AFL						1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-39-220-802-01 (s)	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
53.230		HRS/MSC					0		
	REF: AMM 53-10-39-220-802	AFL	7500				0		
+ 53-10-39-220-802-01A	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (MANDATORY5-40)								
		MOS					13-DEC-2006		
53.230		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-10-39-220-802	AFL	11250				0	**11250**	
53-10-39-220-802-01C	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)								
		MOS	148				04-MAY-2007	**04-SEP-2019**	
53.230		HRS/MSC					0		
CPCP	**REF:** AMM 53-10-39-220-802	AFL					0		
53-11-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
53.0201		HRS/MSC					2832.2		
	REF: AMM 53-11-00-210-801	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-11-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA (CPCP)								
		MOS	25				24-JUN-2017	**24-JUL-2019**	
53.0201		HRS/MSC					2832.2		
CPCP	**REF:** AMM 53-11-00-210-801	AFL					2192		
53-11-00-220-801-01 (s)	DETAILED INSPECTION OF THE NOSE CONE AREA						PKG		
	PKG 31	MOS	72	+2m			11-JUL-2013		
53.0202		HRS/MSC					1872.8		
	REF:	AFL	3750				1323		
53-11-00-220-801-01C	DETAILED INSPECTION OF THE NOSE CONE AREA (CPCP)								
		MOS	74				11-JUL-2013	**11-SEP-2019**	
53.0202		HRS/MSC					1872.8		
CPCP	**REF:**	AFL					1323		
53-11-00-760-801-01 (s)	CHECK OF THE NOSE CONE ELECTRICAL BONDING						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
53.420		HRS/MSC					3041.8		
	REF: AMM 53-11-00-760-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-11-01-900-801-01	NOSE CONE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
53-11-21-960-801-01 (s)	REPLACEMENT OF THE NOSE CONE SEAL						PKG		
	PKG 31	MOS	72	+2m			13-DEC-2006		
53.450		HRS/MSC					0		
	REF: AMM 53-11-21-960-801	AFL	3750				0		
53-30-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER CABIN						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
53.0401		HRS/MSC					2832.2		
	REF: AMM 53-30-00-210-802	AFL					2192		
+ 53-30-00-220-801-01 (s)	DETAILED INSPECTION OF THE PASSENGER CABIN UNDER THE FLOOR						PKG		
	PKG 31	MOS	72	+2m			08-JUL-2013		
53.0402		HRS/MSC					1872.8		
	REF: AMM 53-30-00-220-801	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-00-220-801-01C	DETAILED INSPECTION OF THE PASSENGER CABIN UNDER THE FLOOR (CPCP)								
		MOS	74				08-JUL-2013	**08-SEP-2019**	
53.0402		HRS/MSC					1872.8		
CPCP	**REF:** AMM 53-30-00-220-801	AFL					1323		
+ 53-30-00-220-801-02 (s)	DETAILED INSPECTION OF THE PASSENGER CABIN ABOVE THE FLOOR						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
53.0402		HRS/MSC					0		
	REF: AMM 53-30-00-220-801	AFL	7500				0		
+ 53-30-00-250-801-01 (s)	EDDY CURRENT INSPECTION OF THE PASSENGER CABIN SKIN PANEL AROUND EMERGENCY EXIT DOOR ROUNDED ANGLES						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
53.170		HRS/MSC					0		
	REF: AMM 53-30-00-250-801	AFL	7500				0		
+ 53-30-00-250-801-01A	EDDY CURRENT INSPECTION OF THE PASSENGER CABIN SKIN PANEL AROUND EMERGENCY EXIT DOOR ROUNDED ANGLES (MANDATORY 5-40)								
		MOS					13-DEC-2006		
53.170		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-30-00-250-801	AFL	7500				0		**7500**

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-00-250-802-01 (s)	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
53.160		HRS/MSC					0		
	REF: AMM 53-30-00-250-802	AFL	7500				0		
+ 53-30-00-250-802-01A	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS (MANDATORY 5-40)								
		MOS					13-DEC-2006		
53.160		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-30-00-250-802	AFL	7500				0	**7500**	
+ 53-30-21-250-801-01 (s)	EDDY CURRENT INSPECTION AT FRAME 21						PKG		
	PKG 33	MOS	216	+2m			13-DEC-2006		
53.240		HRS/MSC					0		
	REF: AMM 53-30-21-250-801	AFL	11250				0		
+ 53-30-26-220-801-01 (s)	DETAILED INSPECTION STIFFENER 9 AT FRAME 26						PKG		
	PKG 33	MOS	216	+2m			13-DEC-2006		
53.280		HRS/MSC					0		
	REF: AMM 53-30-26-220-801	AFL	11250				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-26-220-801-01A	DETAILED INSPECTION STIFFENER 9 AT FRAME 26 (MANDATORY 05-40)								
		MOS					13-DEC-2006		
53.280		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-30-26-220-801	AFL	11250				0	**11250**	
+ 53-30-26-220-801-02 (s)	DETAILED INSPECTION STIFFENER 17 WEB FRAME AT FRAME 26						PKG		
	PKG 33	MOS	216	+2m			13-DEC-2006		
53.290		HRS/MSC					0		
	REF: AMM 53-30-26-220-801	AFL	11250				0		
+ 53-30-26-220-801-02A	DETAILED INSPECTION STIFFENER 17 FRAME WEB AT FRAME 26 (MANDATORY 05-40)								
		MOS					13-DEC-2006		
53.290		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-30-26-220-801	AFL	11250				0	**11250**	
+ 53-30-26-250-801-01 (s)	EDDY CURRENT INSPECTION VERTICAL BEAMS AT FRAME 26						PKG		
	PKG 31	MOS	72	+2m			26-JUN-2013		
53.250		HRS/MSC					1872.8		
	REF: AMM 53-30-26-250-801	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-26-250-801-01A	EDDY CURRENT INSPECTION VERTICAL BEAMS AT FRAME 26 (MANDATORY 5-40)								
		MOS					26-JUN-2013		
53.250		HRS/MSC					1872.8		
MANDATORY 5-40	**REF:** AMM 53-30-26-250-801	AFL	3750				1323	**5073**	
+ 53-30-26-250-801-02 (s)	EDDY CURRENT INSPECTION STIFFENER 17 AT FRAME 26						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
53.260		HRS/MSC					0		
	REF: AMM 53-30-26-250-801	AFL	7500				0		
+ 53-30-26-250-801-02A	EDDY CURRENT INSPECTION STIFFENER 17 AT FRAME 26 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
53.260		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-30-26-250-801	AFL	7500				0	**7500**	
+ 53-30-26-250-801-03 (s)	EDDY CURRENT INSPECTION KEEL BEAM FLANGE CONNECTION AT FRAME 26						PKG		
	PKG 33	MOS	216	+2m			13-DEC-2006		
53.270		HRS/MSC					0		
	REF: AMM 53-30-26-250-801	AFL	11250				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-26-250-801-03A	EDDY CURRENT INSPECTION KEEL BEAM FLANGE CONNECTION AT FRAME 26 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
53.270		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-30-26-250-801	AFL	11250				0	**11250**	
53-40-00-200-804-01 (s)	INSPECTION OF THE LH MLG BAYS						PKG		
	PKG 11 ,12 ,14 ,31	MOS	8	+1m			17-APR-2018		
53.100		HRS/MSC					3041.8		
	REF: AMM 53-40-00-200-804	AFL					2328		
53-40-00-200-804-01C	INSPECTION OF THE LH MLG BAYS (CPCP)								
		MOS	9				17-APR-2018	**17-JAN-2019**	
53.100		HRS/MSC					3041.8		
CPCP	**REF:** AMM 53-40-00-200-804	AFL					2328		
53-40-00-200-804-02 (s)	INSPECTION OF THE RH MLG BAYS						PKG		
	PKG 11 ,12 ,14 ,31	MOS	8	+1m			17-APR-2018		
53.100		HRS/MSC					3041.8		
	REF: AMM 53-40-00-200-804	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-40-00-200-804-02C	INSPECTION OF THE RH MLG BAYS (CPCP)								
		MOS	9				17-APR-2018	**17-JAN-2019**	
53.100		HRS/MSC					3041.8		
CPCP	**REF:** AMM 53-40-00-200-804	AFL					2328		
53-40-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
53.0601		HRS/MSC					2832.2		
	REF: AMM 53-40-00-210-802	AFL					2192		
53-40-00-210-802-01C	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)								
		MOS	25				24-JUN-2017	**24-JUL-2019**	
53.0601		HRS/MSC					2832.2		
CPCP	**REF:** AMM 53-40-00-210-802	AFL					2192		
53-40-00-220-801-01 (s)	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS						PKG		
	PKG 31	MOS	72	+2m			09-JUL-2013		
53.0602		HRS/MSC					1872.8		
	REF: AMM 53-40-00-220-801	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-40-00-220-801-01C	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)								
		MOS	74				09-JUL-2013	**09-SEP-2019**	
53.0602		HRS/MSC					1872.8		
CPCP	**REF:** AMM 53-40-00-220-801	AFL					1323		
53-40-00-220-802-01 (s)	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS						PKG		
	PKG 31	MOS	72	+2m			13-DEC-2016		
53.050		HRS/MSC					2676.9		
	REF: See Workcard	AFL	3750				2076		
53-40-00-220-802-01C	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)								
		MOS	74				13-DEC-2016	**13-FEB-2023**	
53.050		HRS/MSC					2676.9		
CPCP	**REF:** See Workcard	AFL					2076		
+ 53-41-00-220-801-01 (s)	DETAILED INSPECTION OF THE LH UPPER WING ROOT BOLT RECESSES						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
57.110		HRS/MSC					2832.2		
	REF: AMM 53-41-00-220-801	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-00-220-801-01C	DETAILED INSPECTION OF THE LH UPPER WING ROOT BOLT RECESSES (CPCP)								
		MOS	25				24-JUN-2017	**24-JUL-2019**	
57.110		HRS/MSC					2832.2		
CPCP	**REF:** AMM 53-41-00-220-801	AFL					2192		
+ 53-41-00-220-801-02 (s)	DETAILED INSPECTION OF THE RH UPPER WING ROOT BOLT RECESSES						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
57.110		HRS/MSC					2832.2		
	REF: AMM 53-41-00-220-801	AFL					2192		
53-41-00-220-801-02C	DETAILED INSPECTION OF THE RH UPPER WING ROOT BOLT RECESSES (CPCP)								
		MOS	25				24-JUN-2017	**24-JUL-2019**	
57.110		HRS/MSC					2832.2		
CPCP	**REF:** AMM 53-41-00-220-801	AFL					2192		
+ 53-41-00-220-802-01 (s)	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - LH WING						PKG		
	PKG 31	MOS	72	+2m			19-JUN-2013		
53.130		HRS/MSC					1872.8		
	REF: AMM 53-41-00-220-802	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-41-00-220-802-01A	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - LH WING (MANDATORY 5-40)								
		MOS					19-JUN-2013		
53.130		HRS/MSC					1872.8		
MANDATORY 5-40	**REF:** AMM 53-41-00-220-802	AFL	3750				1323	**5073**	
53-41-00-220-802-02 (s)	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - RH WING						PKG		
	PKG 31	MOS	72	+2m			19-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 53-41-00-220-802	AFL	3750				1323		
53-41-00-220-802-02A	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - RH WING (MANDATORY 5-40)								
		MOS					19-JUN-2013		
		HRS/MSC					1872.8		
MANDATORY 5-40	**REF:** AMM 53-41-00-220-802	AFL	3750				1323	**5073**	
53-41-00-620-802-01 (s)	RENEWAL OF THE TEMPORARY PROTECTION OF THE LH UPPER WING ROOT BOLT RECESSES						PKG		
	PKG 31	MOS	72	+2m			19-JUN-2013		
57.120		HRS/MSC					1872.8		
	REF: AMM 53-41-00-620-802	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-00-620-802-01C	RENEWAL OF THE TEMPORARY PROTECTION OF THE LH UPPER WING ROOT BOLT RECESSES (CPCP)								
		MOS	74				19-JUN-2013	**19-AUG-2019**	
57.120		HRS/MSC					1872.8		
CPCP	**REF:** AMM 53-41-00-620-802	AFL					1323		
53-41-00-620-802-02 (s)	RENEWAL OF THE TEMPORARY PROTECTION OF THE RH UPPER WING ROOT BOLT RECESSES						PKG		
	PKG 31	MOS	72	+2m			19-JUN-2013		
57.130		HRS/MSC					1872.8		
	REF: AMM 53-41-00-620-802	AFL	3750				1323		
53-41-00-620-802-02C	RENEWAL OF THE TEMPORARY PROTECTION OF THE RH UPPER WING ROOT BOLT RECESSES (CPCP)								
		MOS	74				19-JUN-2013	**19-AUG-2019**	
57.130		HRS/MSC					1872.8		
CPCP	**REF:** AMM 53-41-00-620-802	AFL					1323		
53-41-00-620-802-04 (s)	RENEWAL OF THE TEMPORARY PROTECTION OF THE RH WING ROOT BOLT LOWER RECESSES						PKG		
	PKG 31	MOS	72	+2m			19-JUN-2013		
57.130		HRS/MSC					1872.8		
	REF:	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-00-620-802-04C	RENEWAL OF THE TEMPORARY PROTECTION OF THE RH WING ROOT BOLT LOWER RECESSES (CPCP)								
		MOS	74				19-JUN-2013	**19-AUG-2019**	
57.130		HRS/MSC					1872.8		
CPCP	**REF:**	AFL					1323		
53-41-01-640-801-01 (s)	LUBRICATION OF THE LEFT WING TO FUSELAGE CONNECTING LINK ROD						PKG		
	PKG 31	MOS	72	+2m			18-JUN-2013		
57.020		HRS/MSC					1872.8		
	REF: AMM 53-41-01-640-801	AFL	3750				1323		
53-41-01-640-801-02 (s)	LUBRICATION OF THE RIGHT WING TO FUSELAGE CONNECTING LINK ROD						PKG		
	PKG 31	MOS	72	+2m			18-JUN-2013		
57.020		HRS/MSC					1872.8		
	REF: AMM 53-41-01-640-801	AFL	3750				1323		
53-50-00-210-804-01 (s)	GENERAL VISUAL INSPECTION OF THE AFT SERVICING COMPARTMENT						PKG		
	PKG 11 ,12 ,14 ,31	MOS	8	+1m			17-APR-2018		
53.0901		HRS/MSC					3041.8		
	REF: AMM 53-50-00-210-804	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-50-00-210-804-01C	GENERAL VISUAL INSPECTION OF THE AFT SERVICING COMPARTMENT (CPCP)								
		MOS	9				17-APR-2018	**17-JAN-2019**	
53.0901		HRS/MSC					3041.8		
CPCP	**REF:** AMM 53-50-00-210-804	AFL					2328		
53-50-00-210-805-01 (s)	GENERAL VISUAL INSPECTION OF THE FORWARD SERVICING COMPARTMENT						PKG		
	PKG 11 ,12 ,14 ,31	MOS	8	+1m			17-APR-2018		
53.0801		HRS/MSC					3041.8		
	REF: AMM 53-50-00-210-805	AFL					2328		
53-50-00-210-806-01 (s)	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
53.0701		HRS/MSC					2832.2		
	REF: AMM 53-50-00-210-806	AFL					2192		
53-50-00-210-806-01C	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)								
		MOS	25				24-JUN-2017	**24-JUL-2019**	
53.0701		HRS/MSC					2832.2		
CPCP	**REF:** AMM 53-50-00-210-806	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-50-00-210-807-01 (s)	GENERAL VISUAL INSPECTION OF THE APU AREA						PKG		
	PKG 12 ,14 ,31,203	MOS	16	+1m			17-APR-2018		
53.440		HRS/MSC					3041.8		
	REF: AMM 53-50-00-210-807	AFL					2328		
53-50-00-220-803-01 (s)	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT						PKG		
	PKG 31	MOS	72	+2m			19-JUN-2013		
53.0702		HRS/MSC					1872.8		
	REF: AMM 53-50-00-220-803	AFL	3750				1323		
53-50-00-220-803-01C	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)								
		MOS	74				19-JUN-2013	**19-AUG-2019**	
53.0702		HRS/MSC					1872.8		
CPCP	**REF:** AMM 53-50-00-220-803	AFL					1323		
53-50-00-220-804-01 (s)	DETAILED INSPECTION OF THE FORWARD SERVICING COMPARTMENT						PKG		
	PKG 31	MOS	72	+2m			14-JUN-2013		
53.0802		HRS/MSC					1872.8		
	REF: AMM 53-50-00-220-804	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-50-04-280-801-01	SPECIAL DETAILED INSPECTION OF THE APU SUPPORT ENDS								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF:	AFL					0		
53-50-07-900-801-01	VERTICAL STABLIZER CORE ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 53-50-07-900-801	AFL		TSN:0			0		
53-50-23-250-801-01 (s)	SPECIAL DETAILED INSPECTION OF FRAME 23 (LH LOWER PART)						PKG		
	PKG 33	MOS	216 +2m				13-DEC-2006		
53.380		HRS/MSC					0		
	REF:	AFL	11250				0		
53-50-23-250-801-01A	SPECIAL DETAILED INSPECTION OF FRAME 23 (LH LOWER PART) (MANDATORY 5-40)								
		MOS					13-DEC-2006		
53.380		HRS/MSC					0		
MANDATORY 5-40	**REF:** GENERIC NO REF	AFL	11250				0	**11250**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-50-23-250-801-02 (s)	SPECIAL DETAILED INSPECTION OF FRAME 23 (LH LOWER PART) - NON DESTRUCTIVE CHECK OF FRAME FLANGE						PKG		
	PKG 33	MOS	216				13-DEC-2006		
		HRS/MSC					0		
	REF:	AFL	11250				0		
53-50-23-250-801-02A	SPECIAL DETAILED INSPECTION OF FRAME 23 (LH LOWER PART) - NON DESTRUCTIVE CHECK OF FRAME FLANGE (MANDATORY 5-40)								
		MOS					13-DEC-2006		
		HRS/MSC					0		
MANDATORY 5-40	**REF:**	AFL	11250				0	**11250**	
+ 53-50-23-250-802-01 (s)	EDDY CURRENT INSPECTION OF THE BAGGAGE COMPARTMENT SKIN PANELS AROUND DOOR LOWER ROUNDED ANGLE AT FRAME 23						PKG		
	PKG 33	MOS	216	+2m			13-DEC-2006		
53.210		HRS/MSC					0		
	REF: AMM 53-50-23-250-802	AFL	11250				0		
+ 53-50-23-250-802-01A	EDDY CURRENT INSPECTION OF THE BAGGAGE COMPARTMENT SKIN PANELS AROUND DOOR LOWER ROUNDED ANGLE AT FRAME 23 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
53.210		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-50-23-250-802	AFL	11250				0	**11250**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-50-29-220-801-01 (s)	DETAILED INSPECTION OF SPLICE AT FRAME 29						PKG		
	PKG 33	MOS	216	+2m			13-DEC-2006		
53.400		HRS/MSC					0		
	REF: GENERIC NO REF	AFL	11250				0		
53-50-29-220-801-01A	DETAILED INSPECTION OF SPLICE AT FRAME 29 (MANDATORY 05-40)								
		MOS					13-DEC-2006		
53.400		HRS/MSC					0		
MANDATORY 5-40	**REF:** GENERIC NO REF	AFL	11250				0	**11250**	
53-50-30-250-801-01 (s)	EDDY CURRENT INSPECTION AT FRAME 30						PKG		
	PKG 33	MOS	216	+2m			13-DEC-2006		
53.460		HRS/MSC					0		
	REF: AMM 53-50-30-250-801	AFL	11250				0		
		APH					0		
53-50-30-250-801-01A	EDDY CURRENT INSPECTION AT FRAME 30 (MANDATORY 05-40)								
		MOS					13-DEC-2006		
53.460		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 53-50-30-250-801	AFL	11250				0	**11250**	
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-50-33-250-801-01 (s)	EDDY CURRENT INSPECTION AT FRAME 33							PKG		
	PKG 33	MOS	216	+2m				13-DEC-2006		
53.480		HRS/MSC						0		
	REF: AMM 53-50-33-250-801	AFL	11250					0		
		APH						0		
53-50-33-250-801-01A	EDDY CURRENT INSPECTION AT FRAME 33 (MANDATORY 05-40)									
		MOS						13-DEC-2006		
53.480		HRS/MSC						0		
MANDATORY 5-40	**REF:** AMM 53-50-33-250-801	AFL	11250					0	**11250**	
		APH						0		
+ 53-50-43-250-801-01 (s)	EDDY CURRENT INSPECTION OF THE LOWER FIN FRONT SPAR FLANGES							PKG		
	PKG 33	MOS	216	+2m				13-DEC-2006		
53.320		HRS/MSC						0		
	REF: AMM 53-50-43-250-801	AFL	11250					0		
+ 53-50-43-250-801-01A	EDDY CURRENT INSPECTION OF THE LOWER FIN FRONT SPAR FLANGES (MANDATORY 05-40)									
		MOS						13-DEC-2006		
53.320		HRS/MSC						0		
MANDATORY 5-40	**REF:** AMM 53-50-43-250-801	AFL	11250					0	**11250**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-50-45-250-801-01 (s)	EDDY CURRENT INSPECTION OF THE FIN STUB REAR SPAR						PKG		
	PKG 33	MOS					13-DEC-2006		
53.330		HRS/MSC					0		
	REF: AMM 53-50-45-250-801	AFL	11250				0		
+ 53-50-47-220-801-01 (s)	DETAILED INSPECTION OF LOWER FIN DOOR FRAME SKIN						PKG		
	PKG 33	MOS	216	+2m			13-DEC-2006		
53.340		HRS/MSC					0		
	REF: AMM 53-50-47-220-801	AFL	11250				0		
53-60-00-760-801-01 (s)	CHECK OF THE FUSELAGE VENTRAL FAIRING ELECTRICAL BONDING						PKG		
	PKG 14 ,31	MOS	32	+1m			18-APR-2018		
53.430		HRS/MSC					3041.8		
	REF: AMM 53-60-00-760-801	AFL					2328		
53-80-00-200-801-01 (s)	CHECK OF THE FUSELAGE CONDENSATION AND STREAM WATER DRAINS						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			18-APR-2018		
51.010		HRS/MSC					3041.8		
	REF: AMM 53-80-00-200-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-80-01-710-801-01	OPERATIONAL TEST OF THE WATER DETECTION SYSTEM - WATER LEAK DETECTION PCB (43MT)								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 53-80-01-710-801	AFL					0		
53-80-01-710-801-02	OPERATIONAL TEST OF THE WATER DETECTION SYSTEM - WATER DETECTION SENSOR (534MT)								
		MOS					13-DEC-2006		
		HRS/MSC	N/A				0		
	REF: AMM 53-80-01-710-801	AFL					0		
53-80-09-710-801-01 (s)	OPERATIONAL TEST OF THE LH STRUCTURE AUTOMATIC DRAIN CIRCLE DRAINS						PKG		
	PKG 31	MOS	72	+2m			12-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 53-80-09-710-801	AFL	3750				1323		
53-80-09-710-801-02 (s)	OPERATIONAL TEST OF THE RH STRUCTURE AUTOMATIC DRAIN CIRCLE DRAINS						PKG		
	PKG 31	MOS	72	+2m			12-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 53-80-09-710-801	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-80-09-710-801-03 (s)	OPERATIONAL TEST OF THE FUEL AUTOMATIC DRAIN CIRCLE DRAIN							PKG		
	PKG 31	MOS	72	+2m				12-JUN-2013		
		HRS/MSC						1872.8		
	REF: AMM 53-80-09-710-801	AFL	3750					1323		
530801	FUSELAGE									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	AFL			TSN:0			0		
531801	SECTION T1									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	AFL			TSN:0			0		
531811	NOSE CONE RACK ASSEMBLY									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
532801	SECTION T2								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
533801	SECTION T3								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
534801	SECTION T4								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
535801	SECTION T5								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
535821	STUB FIN TRAILING EDGE ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536401	APU FIREWALL ASSEMBLY								
	F2MA258501419	MOS		TSN:0			19-JUL-2013		
	363	HRS/MSC	O/C	TSN:0			1872.8		
	REF: GENERIC NO REF	AFL		TSN:0			1323		
536801	LH FORWARD LOWER FAIRING (F9 TO F15) LATERAL FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536802	RH FORWARD LOWER FAIRING (F9 TO F15) LATERAL FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
536803	LH TOP LATERAL (F14 TO F15) SKIN FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536804	RH TOP LATERAL (F14 TO F15) SKIN FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536805	LH BOTTOM LATERAL (F14 TO F15) SKIN FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536806	RH BOTTOM LATERAL (F14 TO F15) SKIN FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
536807	BOTTOM (F9 TO F15) SKIN FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536808	BOTTOM (F15 TO F19) SKIN FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536809	LH LOWER (F14 TO F15) LATERAL SKIN FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536810	RH LOWER (F14 TO F15) LATERAL SKIN FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
536811	LH (F21 TO F26) LOWER PANEL REAR MIDDLE ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536812	CENTRAL LOWER (F19 TO F21) PANEL ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536813	LH TOP LATERAL (F15 TO F19) SKIN FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536814	RH TOP LATERAL (F15 TO F19) SKIN FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
536815	LH FORWARD UPPER (F19 TO F23) PANEL ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536816	RH TOP CENTRAL UPPER (F21 TO F26) SKIN FILLET ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
536820	CENTRAL SECTION								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
537801	TAIL CONE ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
537802	LH TOP FAIRING (F26 TO F30) PANEL ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
537803	RH TOP FAIRING (F26 TO F30) PANEL ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
537810	LH CENTRAL LOWER (F26 TO F30) FAILRING PANEL ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 54	**NACELLES/PYLONS**								
54-00-00-210-810-01 (s)	GENERAL VISUAL INSPECTION OF THE NO.1 ENGINE NACELLES AND PYLONS						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			20-APR-2018		
54.010		HRS/MSC	400	+40			3041.8		
	REF: AMM 54-00-00-210-810	AFL					2328		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-00-00-210-810-02 (s)	GENERAL VISUAL INSPECTION OF THE NO.2 ENGINE NACELLES AND PYLONS						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			20-APR-2018		
54.010		HRS/MSC	400	+40			3041.8		
	REF: AMM 54-00-00-210-810	AFL					2328		
54-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE NO.1 ENGINE NACELLES AND PYLONS						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
54.020		HRS/MSC					0		
	REF: AMM 54-00-00-220-801	AFL	7500				0		
54-00-00-220-801-02 (s)	DETAILED INSPECTION OF THE NO.2 ENGINE NACELLES AND PYLONS						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
54.020		HRS/MSC					0		
	REF: AMM 54-00-00-220-801	AFL	7500				0		
54-11-00-610-801-01 (s)	SERVICING NO. 1 ENGINE COWLING						PKG		
	PKG 2 ,31	MOS	16	+1m			20-APR-2018		
54.050		HRS/MSC	800	+40			3041.8		
	REF: AMM 54-11-00-610-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-11-00-610-801-02 (s)	SERVICING NO. 2 ENGINE COWLING							PKG		
	PKG 2 ,31	MOS	16	+1m				20-APR-2018		
54.050		HRS/MSC	800	+40				3041.8		
	REF: AMM 54-11-00-610-801	AFL						2328		
54-11-00-760-801-01 (s)	CHECK OF THE NO.1 ENGINE COWLING ELECTRICAL BONDING							PKG		
	PKG 12 ,14 ,31	MOS	16	+1m				17-APR-2018		
		HRS/MSC						3041.8		
	REF: AMM 54-11-00-760-801	AFL						2328		
54-11-00-760-801-02 (s)	CHECK OF THE NO.2 ENGINE COWLING ELECTRICAL BONDING							PKG		
	PKG 12 ,14 ,31	MOS	16	+1m				17-APR-2018		
		HRS/MSC						3041.8		
	REF: AMM 54-11-00-760-801	AFL						2328		
54-11-01-100-801-01 (s)	CLEANING OF THE NO. 1 ENGINE UPPER COWLINGS							PKG		
	PKG 2 ,31	MOS	16	+1m				20-APR-2018		
54.070		HRS/MSC	800	+40				3041.8		
	REF: AMM 54-11-01-100-801	AFL						2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-11-01-100-801-02 (s)	CLEANING OF THE NO. 2 ENGINE UPPER COWLINGS							PKG		
	PKG 2 ,31	MOS	16	+1m				20-APR-2018		
54.080		HRS/MSC	800	+40				3041.8		
	REF: AMM 54-11-01-100-801	AFL						2328		
54-11-01-900-801-01	NO. 1 ENGINE UPPER COWLINGS									
	06ND71102-5	MOS			TSN:0			13-DEC-2006		
54.040	AX0113-313	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 54-11-01-900-801	AFL			TSN:0			0		
54-11-01-900-801-02	NO. 2 ENGINE UPPER COWLINGS									
	06ND71102-6	MOS			TSN:0			13-DEC-2006		
54.040	AX0113-314	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 54-11-01-900-801	AFL			TSN:0			0		
54-11-05-100-801-01 (s)	CLEANING OF THE NO. 1 ENGINE LOWER COWLINGS							PKG		
	PKG 2 ,31	MOS	16	+1m				20-APR-2018		
54.070		HRS/MSC	800	+40				3041.8		
	REF: AMM 54-11-05-100-801	AFL						2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-11-05-100-801-02 (s)	CLEANING OF THE NO. 2 ENGINE LOWER COWLINGS							PKG		
	PKG 2 ,31	MOS	16	+1m				20-APR-2018		
54.080		HRS/MSC	800	+40				3041.8		
	REF: AMM 54-11-05-100-801	AFL						2328		
54-11-05-900-801-01	NO. 1 ENGINE LOWER COWLINGS									
	06ND71101-5	MOS			TSN:0			13-DEC-2006		
54.130	AX0127-311	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 54-11-05-900-801	AFL			TSN:0			0		
54-11-05-900-801-02	NO. 2 ENGINE LOWER COWLINGS									
	06ND71101-7	MOS			TSN:0			13-DEC-2006		
54.130	AX0121-312	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 54-11-05-900-801	AFL			TSN:0			0		
54-12-01-900-801-01	NO. 1 ENGINE FAN DUCT									
	06ND78600-5	MOS			TSN:0			13-DEC-2006		
54.120	AX600-204	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 54-12-01-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-12-01-900-801-02	NO. 2 ENGINE FAN DUCT								
	06ND78600-7	MOS		TSN:0			13-DEC-2006		
54.120	AX600-205	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 54-12-01-900-801	AFL		TSN:0			0		
54-41-01-900-801-01	NO. 1 ENGINE AIR INTAKE								
	06ND71600-1	MOS		TSN:0			13-DEC-2006		
54.140	600-1-0207	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 54-41-01-900-801	AFL		TSN:0			0		
54-41-01-900-801-02	NO. 2 ENGINE AIR INTAKE								
	06ND71600-1	MOS		TSN:0			13-DEC-2006		
54.140	600-1-0216	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 54-41-01-900-801	AFL		TSN:0			0		
54-50-00-210-802-01	GENERAL VISUAL INSPECTION OF THE NO.1 ENGINE AFTER PYLON OVERHEAT DETECTION								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 54-50-00-210-802	AFL					0		
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-50-00-210-802-02	GENERAL VISUAL INSPECTION OF THE NO.2 ENGINE AFTER PYLON OVERHEAT DETECTION								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 54-50-00-210-802	AFL					0		
		APH					0		
54-50-00-220-801-01 (s)	DETAILED VISUAL INSPECTION OF RIBS 29 AND 29-A						PKG		
	PKG 33	MOS	216	+2d			13-DEC-2006		
54.060		HRS/MSC					0		
	REF: AMM 54-50-00-220-801	AFL	11250				0		
54-50-00-220-801-01A	DETAILED VISUAL INSPECTION OF RIBS 29 AND 29-A (MANDATORY 5-40)								
		MOS					13-DEC-2006		
54.060		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 54-50-00-220-801	AFL	11250				0	**11250**	
540051	NO. 1 ENGINE FRONT MOUNT ATTACHMENT								
	06ND71204-1	MOS		TSN:0			13-DEC-2006		
54.030	FMI26975A-7	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
540052	NO. 2 ENGINE FRONT MOUNT ATTACHMENT								
	06ND71204-1	MOS		TSN:0			13-DEC-2006		
54.030	FMI26975A-2	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
540053	NO. 1 ENGINE AFT MOUNT VIBRATION ISOLATOR								
	06ND71401-3	MOS		TSN:0			13-DEC-2006		
54.090	LK0245	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
540054	NO. 2 ENGINE AFT MOUNT VIBRATION ISOLATOR								
	06ND71401-3	MOS		TSN:0			13-DEC-2006		
54.100	LK0309	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
545801	LH PYLON ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
545802	RH PYLON ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 55	**STABILIZERS**								
55-00-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
55.0101		HRS/MSC					2832.2		
	REF: AMM 55-00-00-210-802	AFL					2192		
55-00-00-210-802-01C	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS (CPCP)								
		MOS	25				24-JUN-2017	**24-JUL-2019**	
		HRS/MSC					2832.2		
CPCP	**REF:** AMM 55-00-00-210-802	AFL					2192		
+ 55-00-00-220-802-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS						PKG		
	PKG 31	MOS	72	+2m			14-JUN-2013		
55.0102		HRS/MSC					1872.8		
	REF: AMM 55-00-00-220-802	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-00-00-220-802-01C	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS (CPCP)								
		MOS	74				14-JUN-2013	**14-AUG-2019**	
55.0102		HRS/MSC					1872.8		
CPCP	**REF:** AMM 55-00-00-220-802	AFL					1323		
55-00-00-760-801-01 (s)	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - RUDDER						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
55.090		HRS/MSC					2832.2		
	REF: AMM 55-00-00-760-801	AFL					2192		
55-00-00-760-801-02 (s)	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - LH ELEVATOR						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
55.090		HRS/MSC					2832.2		
	REF: AMM 55-00-00-760-801	AFL					2192		
55-00-00-760-801-03 (s)	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - RH ELEVATOR						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
55.090		HRS/MSC					2832.2		
	REF: AMM 55-00-00-760-801	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-00-270-801-01	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS								
		MOS	288				13-DEC-2006	**13-DEC-2030**	
55.020		HRS/MSC					0		
	REF: AMM 55-10-00-270-801	AFL	11250				0	**11250**	
+ 55-10-00-270-801-01A	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS (MANDATORY 5-40)								
		MOS					13-DEC-2006		
55.020		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 55-10-00-270-801	AFL	11250				0	**11250**	
55-10-00-640-802-01 (s)	GREASING OF THE HORIZONTAL STABILIZER FRONT TORQUE LINK AND ACTUATOR UPPER HINGE						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
27.245		HRS/MSC					2832.2		
	REF: AMM 55-10-00-640-802	AFL					2192		
55-10-01-900-801-01	HORIZONTAL STABLIZER ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 55-10-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-03-640-801-01 (s)	LUBRICATION OF THE SPRING-LOADED FAIRING MECHANISM							PKG		
	PKG 18 ,31,205	MOS	24	+1m				24-JUN-2017		
55.050		HRS/MSC						2832.2		
	REF: AMM 55-10-03-640-801	AFL						2192		
55-10-03-900-801-01	LH SPRING LOADED									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 55-10-03-900-801	AFL			TSN:0			0		
55-10-03-900-801-02	RH SPRING LOADED									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 55-10-03-900-801	AFL			TSN:0			0		
55-10-31-220-801-01 (s)	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS							PKG		
	PKG 31	MOS	72	+2m				25-JUN-2013		
55.080		HRS/MSC						1872.8		
	REF: AMM 55-10-31-220-801	AFL	3750					1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-31-220-801-01A	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS (MANDATORY 5-40)								
		MOS					25-JUN-2013		
55.080		HRS/MSC					1872.8		
MANDATORY 5-40	**REF:** AMM 55-10-31-220-801	AFL	3750				1323	**5073**	
55-10-33-640-801-01 (s)	LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			18-APR-2018		
27.230		HRS/MSC	400	+40			3041.8		
	REF: AMM 55-10-33-640-801	AFL					2328		
+ 55-10-39-220-801-01	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS ON LOWER FIN SIDE								
		MOS					13-DEC-2006		
55.030		HRS/MSC					0		
	REF: AMM 55-10-39-220-801	AFL	11250				0	**11250**	
+ 55-10-39-220-801-01A	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS ON LOWER FIN SIDE (MANDATORY 5-40)								
		MOS					13-DEC-2006		
55.030		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 55-10-39-220-801	AFL	11250				0	**11250**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10-39-220-801-02	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS ON HORIZONTAL STABILIZER SIDE								
		MOS					13-DEC-2006		
55.030		HRS/MSC					0		
	REF: AMM 55-10-39-220-801	AFL	11250				0	**11250**	
+ 55-10-39-220-801-02A	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS ON HORIZONTAL STABILIZER SIDE (MANDATORY 5-40)								
		MOS					13-DEC-2006		
55.030		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 55-10-39-220-801	AFL	11250				0	**11250**	
55-20-01-900-801-01	LH ELEVATOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 55-20-01-900-801	AFL		TSN:0			0		
55-20-01-900-801-02	RH ELEVATOR								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 55-20-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20-03-640-801-01 (s)	LUBRICATION OF THE ELEVATOR BEARINGS						PKG		
	PKG 32	MOS	144	+2m			13-DEC-2006		
55.060		HRS/MSC					0		
	REF: AMM 55-20-03-640-801	AFL	7500				0		
55-20-03-640-802-01 (s)	LUBRICATION OF THE ELEVATOR CONTROL SURFACE HINGES						PKG		
	PKG 1 ,2 ,31	MOS	8	+1m			18-APR-2018		
27.175		HRS/MSC	400	+40			3041.8		
	REF: AMM 55-20-03-640-802	AFL					2328		
55-20-05-640-801-01 (s)	LUBRICATION OF THE ELEVATOR CONTROL BEARINGS AND U-JOINTS						PKG		
	PKG 2 ,31,39	MOS	16	+1m			18-APR-2018		
27.240		HRS/MSC	800	+40			3041.8		
	REF: AMM 55-20-05-640-801	AFL					2328		
+ 55-30-00-270-801-01	ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS								
		MOS	288				13-DEC-2006	**13-DEC-2030**	
55.040		HRS/MSC					0		
	REF: AMM 55-30-00-270-801	AFL	11250				0		**11250**

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-30-00-270-801-01A	ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS (MANDATORY 5-40)								
		MOS					13-DEC-2006		
55.040		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 55-30-00-270-801	AFL	11250				0	**11250**	
55-30-01-900-801-01	VERTICAL STABLIZER ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 55-30-01-900-801	AFL		TSN:0			0		
55-30-07-900-801-01	FIN TIP FAIRING ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 55-30-07-900-801	AFL		TSN:0			0		
55-40-01-900-801-01	RUDDER ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 55-40-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40-05-640-801-01 (s)	LUBRICATION OF THE RUDDER BEARINGS							PKG		
	PKG 32	MOS	144	+2m				13-DEC-2006		
55.070		HRS/MSC						0		
	REF: AMM 55-40-05-640-801	AFL	7500					0		
55-40-05-640-802-01 (s)	LUBRICATION OF THE RUDDER CONTROL SURFACE HINGES							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				18-APR-2018		
27.145		HRS/MSC	400	+40				3041.8		
	REF: AMM 55-40-05-640-802	AFL						2328		
551810	HORIZONTAL STABLIZER LH TIP FAIRING									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	AFL			TSN:0			0		
551820	HORIZONTAL STABLIZER RH TIP FAIRING									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
551830	HORIZONTAL STABLIZER LH LEADING EDGE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
551840	HORIZONTAL STABLIZER RH LEADING EDGE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
553801	VERTICAL STABILIZER CORE ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
553810	VERTICAL STABLIZER LOWER LEADING EDGE ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
553820	VERTICAL STABLIZER UPPER LEADING EDGE ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 56	**WINDOWS**								
56-10-01-900-801-01	FRONT WINDSHIELD								
	SPSF2M1-3-2	MOS		TSN:0			13-DEC-2006		
56.030	501	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-10-01-900-801	AFL		TSN:0			0		
56-10-01-900-801-02	PILOT WINDSHIELD								
	SPSF2M2-2-2	MOS		TSN:0			13-DEC-2006		
56.030	843	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-10-01-900-801	AFL		TSN:0			0		
56-10-01-900-801-03	COPILOT WINDSHIELD								
	SPSF2M3-2-2	MOS		TSN:0			13-DEC-2006		
56.030	838	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-10-01-900-801	AFL		TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-07-900-801-02	RH LATERAL WINDOW								
	SPSF900-5-8-2	MOS		TSN:0			13-DEC-2006		
56.020	1513	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-10-07-900-801	AFL		TSN:0			0		
56-10-09-640-801-01 (s)	LUBRICATION OF THE LH OPENING WINDOW						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			18-APR-2018		
56.010		HRS/MSC					3041.8		
	REF: AMM 56-10-09-640-801	AFL					2328		
56-10-09-900-801-01	LH OPENING WINDOW								
	SPSF900-4-6-2	MOS		TSN:0			10-MAY-2011		
56.010	2608	HRS/MSC	O/C	TSN:0			1239.4		
	REF: AMM 56-10-09-900-801	AFL		TSN:0			864		
56-10-11-900-801-01	LH REAR WINDOW								
	SPSF900-6-8-2	MOS		TSN:0			13-DEC-2006		
56.040	3191	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-10-11-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-11-900-801-02	RH REAR WINDOW								
	SPSF900-7-8-2	MOS		TSN:0			13-DEC-2006		
56.040	3204	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-10-11-900-801	AFL		TSN:0			0		
56-20-05-900-801-01	NO. 1 LEFT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.050	12927	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
56-20-05-900-801-02	NO. 2 LEFT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.050	10269	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-20-05-900-801	AFL		TSN:0			0		
56-20-05-900-801-03	NO. 3 LEFT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.050	13008	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-20-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-04	NO. 4 LEFT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.060	13241	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-20-05-900-801	AFL		TSN:0			0		
56-20-05-900-801-05	NO. 5 LEFT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.060	13041	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-20-05-900-801	AFL		TSN:0			0		
56-20-05-900-801-06	NO. 6 LEFT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.060	14951	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-20-05-900-801	AFL		TSN:0			0		
56-20-05-900-801-07	NO. 7 LEFT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.070	13036	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-20-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-08	NO. 8 LEFT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.070	13140	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-20-05-900-801	AFL		TSN:0			0		
56-20-05-900-801-09	NO. 9 LEFT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.070	13044	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-20-05-900-801	AFL		TSN:0			0		
56-20-05-900-801-10	NO. 10 LEFT PASSENGER CABIN WINDOW								
	PN	MOS		TSN:0			13-DEC-2006		
56.080	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-20-05-900-801	AFL		TSN:0			0		
56-20-05-900-801-11	NO. 1 RIGHT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.090	13109	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-20-05-900-801	AFL		TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-12	NO. 2 RIGHT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.090	14961	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-20-05-900-801	AFL		TSN:0			0		
56-20-05-900-801-13	NO. 3 RIGHT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.090	14956	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-20-05-900-801	AFL		TSN:0			0		
56-20-05-900-801-14	NO. 4 RIGHT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.100	14963	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
56-20-05-900-801-15	NO. 5 RIGHT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.100	14955	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-16	NO. 6 RIGHT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.100	14962	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
56-20-05-900-801-17	NO. 7 RIGHT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.110	13130	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
56-20-05-900-801-18	NO. 8 RIGHT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.110	14960	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
56-20-05-900-801-19	NO. 9 RIGHT PASSENGER CABIN WINDOW								
	SPSF2M8-3-0	MOS		TSN:0			13-DEC-2006		
56.110	13132	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-20	NO. 10 RIGHT PASSENGER CABIN WINDOW								
	PN	MOS		TSN:0			13-DEC-2006		
56.120	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
561801	COCKPIT WINDOW GLASS PANEL ASSEMBLY								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 25-26-01-900-801	AFL		TSN:0			0		
CHAPTER 57	**WINGS**								
27-80-00-640-801-01 (s)	GREASING/LUBRICATION OF THE SLAT MECHANISMS						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
27.395		HRS/MSC					3041.8		
	REF:	AFL					2328		
57-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE LH WING						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
		HRS/MSC					2832.2		
	REF: AMM 57-00-00-210-801	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE LH WING (CPCP)								
		MOS	25				24-JUN-2017	**24-JUL-2019**	
		HRS/MSC					2832.2		
CPCP	**REF:** AMM 57-00-00-210-801	AFL					2192		
57-00-00-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE RH WING						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
		HRS/MSC					2832.2		
	REF: AMM 57-00-00-210-801	AFL					2192		
57-00-00-210-801-02C	GENERAL VISUAL INSPECTION OF THE RH WING (CPCP)								
		MOS	25				24-JUN-2017	**24-JUL-2019**	
		HRS/MSC					2832.2		
CPCP	**REF:** AMM 57-00-00-210-801	AFL					2192		
57-00-00-220-802-01 (s)	DETAILED INSPECTION OF THE LH WING						PKG		
	PKG 31	MOS	72	+2m			17-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 57-00-00-220-802	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00-00-220-802-01C	DETAILED INSPECTION OF THE LH WING (CPCP)								
		MOS	74				17-JUN-2013	**17-AUG-2019**	
		HRS/MSC					1872.8		
CPCP	**REF:** AMM 57-00-00-220-802	AFL					1323		
57-00-00-220-802-02 (s)	DETAILED INSPECTION OF THE RH WING						PKG		
	PKG 31	MOS	72	+2m			17-JUN-2013		
		HRS/MSC					1872.8		
	REF: AMM 57-00-00-220-802	AFL	3750				1323		
57-00-00-220-802-02C	DETAILED INSPECTION OF THE RH WING (CPCP)								
		MOS	74				17-JUN-2013	**17-AUG-2019**	
		HRS/MSC					1872.8		
CPCP	**REF:** AMM 57-00-00-220-802	AFL					1323		
57-00-00-760-801-01 (s)	CHECK OF THE LH SIDE WING MOVABLE SURFACE ELECTRICAL BONDING						PKG		
	PKG 18 ,31,205	MOS	24	+1m			24-JUN-2017		
57.140		HRS/MSC					2832.2		
	REF: AMM 57-00-00-760-801	AFL					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00-01-900-801-01	LH WING								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-00-01-900-801	AFL		TSN:0			0		
57-00-01-900-801-02	RH WING								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-00-01-900-801	AFL		TSN:0			0		
+ 57-10-00-290-801-01 (s)	BORESCOPE INSPECTION OF THE WING TANKS						PKG		
	PKG 31	MOS	72	+2m			13-DEC-2016		
57.030		HRS/MSC					2676.9		
	REF: AMM 57-10-00-290-801	AFL	3750				2076		
57-10-00-290-801-01C	BORESCOPE INSPECTION OF THE WING TANKS (CPCP)								
		MOS	74				13-DEC-2016	**13-FEB-2023**	
57.030		HRS/MSC					2676.9		
CPCP	**REF:** AMM 57-10-00-290-801	AFL					2076		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-01-210-801-01	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS								
		MOS					13-DEC-2006		
57.185		HRS/MSC					0		
	REF: AMM 57-10-01-210-801	AFL	11250				0	**11250**	
		APH					0		
57-10-01-210-801-01A	VISUAL INSPECTION OF THE WING LOWER PANELS (MANDATORY 5-40)								
		MOS					13-DEC-2006		
57.185		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 57-10-01-210-801	AFL	11250				0	**11250**	
		APH					0		
57-10-09-900-801-01	LH WINGLET								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-10-09-900-801	AFL		TSN:0			0		
57-10-09-900-801-02	RH WINGLET								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-10-09-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-09-960-805-01	REPLACEMENT OF THE WINGLET TIP CAP								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		
57-10-14-220-801-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9								
		MOS					13-DEC-2006		
57.190		HRS/MSC					0		
	REF: AMM 57-10-14-220-801	AFL	11250				0	**11250**	
		APH					0		
57-10-14-220-801-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
57.190		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 57-10-14-220-801	AFL	11250				0	**11250**	
		APH					0		
57-10-14-220-802-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9								
		MOS					13-DEC-2006		
57.195		HRS/MSC					0		
	REF: AMM 57-10-14-220-802	AFL	11250				0	**11250**	
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-14-220-802-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
57.195		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 57-10-14-220-802	AFL	11250				0	**11250**	
		APH					0		
57-10-15-220-801-01	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3								
		MOS					13-DEC-2006		
57.205		HRS/MSC					0		
	REF: AMM 57-10-15-220-801	AFL	11250				0	**11250**	
		APH					0		
57-10-15-220-801-01A	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
57.205		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 57-10-15-220-801	AFL	11250				0	**11250**	
		APH					0		
57-10-15-220-802-01	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17								
		MOS					13-DEC-2006		
57.200		HRS/MSC					0		
	REF: AMM 57-10-15-220-802	AFL	11250				0	**11250**	
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-15-220-802-01A	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 (MANDATORY 5-40)								
		MOS					13-DEC-2006		
57.200		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 57-10-15-220-802	AFL	11250				0	**11250**	
		APH					0		
+ 57-10-15-250-801-01	EDDY-CURRENT INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE								
		MOS					13-DEC-2006		
57.050		HRS/MSC					0		
	REF: AMM 57-10-15-250-801	AFL	11250				0	**11250**	
+ 57-10-15-250-801-01A	EDDY-CURRENT INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE (MANDATORY 5-40)								
		MOS					13-DEC-2006		
57.050		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 57-10-15-250-801	AFL	11250				0	**11250**	
57-41-03-900-801-01	FIXED LEADING EDGE - LH WING								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-41-03-900-801-02	FIXED LEADING EDGE - RH WING								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
+ 57-41-03-960-801-01	DISCARD OF THE FIXED LEADING EDGES - WING ROOT FIXED LEADING EDGE (512A) (LH WING)								
	PN	MOS					13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF:	AFL					0		
+ 57-41-03-960-801-02	DISCARD OF THE FIXED LEADING EDGES - WING ROOT FIXED LEADING EDGE (612A) (RH WING)								
	PN	MOS					13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF:	AFL					0		
57-45-01-900-801-01	LH INBOARD SLAT								
	PN	MOS		TSN:0			13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-45-01-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-45-01-900-801-02	RH INBOARD SLAT								
	PN	MOS		TSN:0			13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-45-01-900-801	AFL		TSN:0			0		
57-45-01-960-801-01	REPLACE LH INBOARD SLAT								
	PN	MOS					13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C				0		
	REF: AMM 57-45-01-960-801	AFL					0		
57-45-01-960-801-02	REPLACE RH INBOARD SLAT								
	PN	MOS					13-DEC-2006		
	NOT INSTALLED	HRS/MSC	O/C				0		
	REF: AMM 57-45-01-960-801	AFL					0		
57-45-13-280-801-01	CONDUCTIVITY CHECK OF THE SLATS								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-45-13-900-801-01	LH OUTBOARD SLAT								
	F20-0070-7	MOS		TSN:42 TSR:0			28-APR-2010		
	497/1022RA	HRS/MSC	O/C	TSN:900.3 TSR:0			900.3		
	REF: See Workcard	AFL		TSN:636 TSR:0			636		
57-45-13-900-801-02	RH OUTBOARD SLAT								
	F20-0070-8	MOS		TSR:0			28-APR-2010		
	369-869RA	HRS/MSC	O/C	TSR:0			900.3		
	REF: See Workcard	AFL		TSR:0			636		
57-45-13-960-801-01	REPLACE LH OUTBOARD SLAT								
	F20-0070-7	MOS					13-DEC-2006		
	497/1022RA	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
57-45-13-960-801-02	REPLACE RH OUTBOARD SLAT								
	F20-0070-8	MOS					13-DEC-2006		
	369-869RA	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-45-25-250-801-01 (s)	EDDY CURRENT INSPECTION OF SLAT TRACKS 5 AND 10						PKG		
	PKG 33	MOS	216 +2m				13-DEC-2006		
57.180		HRS/MSC					0		
	REF: AMM 57-45-25-250-801	AFL	11250				0		
		APH					0		
57-51-01-960-801-01	REPLACEMENT OF THE WING FIXED TRAILING EDGE SEALS - LH SEALING STRIPS								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		
57-51-01-960-801-02	REPLACEMENT OF THE WING FIXED TRAILING EDGE SEALS - RH SEALING STRIPS								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF:	AFL					0		
57-55-00-700-801-01 (s)	CHECK OF THE FLAP LATERAL CLEARANCE						PKG		
	PKG 31	MOS	72 +2m				17-JUN-2013		
57.150		HRS/MSC					1872.8		
	REF: AMM 57-55-00-700-801	AFL	3750				1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-55-01-900-801-01	LH INBOARD FLAP								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-55-01-900-801	AFL		TSN:0			0		
57-55-01-900-801-02	RH INBOARD FLAP								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
57-55-05-900-801-01	LH EXTERNAL FLAP								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-55-05-900-801	AFL		TSN:0			0		
57-55-05-900-801-02	RH EXTERNAL FLAP								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-55-05-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-55-07-220-801-01 (s)	DETAILED INSPECTION OF THE PROTECTION ON LH INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS						PKG		
	PKG 31	MOS	72	+2m			20-JUN-2013		
57.060		HRS/MSC					1872.8		
	REF: AMM 57-55-07-220-801	AFL	3750				1323		
57-55-07-220-801-02 (s)	DETAILED INSPECTION OF THE PROTECTION ON RH INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS						PKG		
	PKG 31	MOS	72	+2m			20-JUN-2013		
57.060		HRS/MSC					1872.8		
	REF: AMM 57-55-07-220-801	AFL	3750				1323		
57-55-11-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE FOREFLAP BRACKETS						PKG		
	PKG 31	MOS	72	+2m			17-JUN-2013		
57.070		HRS/MSC					1872.8		
	REF: AMM 57-55-11-210-801	AFL	3750				1323		
57-55-13-640-801-01 (s)	GREASING/LUBRICATION OF LH WING FLAP ROLLERS AND TRACKS						PKG		
	PKG 2 ,31,39	MOS	16	+1m			18-APR-2018		
		HRS/MSC	800	+40			3041.8		
	REF: AMM 57-55-13-640-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-55-13-640-801-02 (s)	GREASING/LUBRICATION OF RH WING FLAP ROLLERS AND TRACKS							PKG		
	PKG 2 ,31,39	MOS	16	+1m				18-APR-2018		
		HRS/MSC	800	+40				3041.8		
	REF: AMM 57-55-13-640-801	AFL						2328		
57-55-21-250-801-01 (s)	EDDY-CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5							PKG		
	PKG 31	MOS	72	+2m				26-JUN-2013		
57.080		HRS/MSC						1872.8		
	REF: AMM 57-55-21-250-801	AFL	3750					1323		
57-60-01-900-801-01	LH AILERON									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 57-60-01-900-801	AFL			TSN:0			0		
57-60-01-900-801-02	RH AILERON									
	PN	MOS			TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 57-60-01-900-801	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-60-05-640-801-01 (s)	PRESSURE LUBRICATION OF THE LH AILERON BEARINGS							PKG		
	PKG 31	MOS	72	+2m				20-JUN-2013		
57.090		HRS/MSC						1872.8		
	REF: AMM 57-60-05-640-801	AFL	3750					1323		
57-60-05-640-801-02 (s)	PRESSURE LUBRICATION OF THE RH AILERON BEARINGS							PKG		
	PKG 31	MOS	72	+2m				20-JUN-2013		
57.090		HRS/MSC						1872.8		
	REF: AMM 57-60-05-640-801	AFL	3750					1323		
57-60-05-640-802-01 (s)	LUBRICATION OF THE LH AILERON CONTROL SURFACE HINGES							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				17-APR-2018		
		HRS/MSC	400	+40				3041.8		
	REF: AMM 57-60-05-640-802	AFL						2328		
57-60-05-640-802-02 (s)	LUBRICATION OF THE RH AILERON CONTROL SURFACE HINGES							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				17-APR-2018		
		HRS/MSC	400	+40				3041.8		
	REF: AMM 57-60-05-640-802	AFL						2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-70-01-900-801-01	LH OUTBOARD AIRBRAKE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-70-01-900-801	AFL		TSN:0			0		
57-70-01-900-801-02	LH MIDDLE AIRBRAKE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-70-01-900-801	AFL		TSN:0			0		
57-70-01-900-801-03	LH INBOARD AIRBRAKE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-70-01-900-801	AFL		TSN:0			0		
57-70-01-900-801-04	RH INBOARD AIRBRAKE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-70-01-900-801-05	RH MIDDLE AIRBRAKE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-70-01-900-801	AFL		TSN:0			0		
57-70-01-900-801-06	RH OUTBOARD AIRBRAKE								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-70-01-900-801	AFL		TSN:0			0		
57-70-03-640-801-01 (s)	LUBRICATION OF THE AIRBRAKE HINGES						PKG		
	PKG 12 ,14 ,31,203	MOS	16	+1m			17-APR-2018		
27.340		HRS/MSC					3041.8		
	REF: AMM 57-70-03-640-801	AFL					2328		

CHAPTER 70 STANDARD PRACTICES - ENGINES

ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047

700010 (s)	NO. 1 ENGINE - CHECK OF TUBING FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS, EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION AND EVIDENCE OF FUEL OR OIL LEAKS, INCLUDING NO. 4 BRG. TUBES						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 70-00-00	ENC					1800		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
700015 (s)	NO. 1 ENGINE - CHECK WIRING FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS AND FOR EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION.						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 70-00-00	ENC					1800		
700020 (s)	NO. 1 ENGINE - CHECK WIRING HARNESS CONNECTORS FOR SECURITY						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 73-20-03	ENC					1800		
700025 (s)	NO. 1 ENGINE - CHECK ACCESSORIES FOR SECURITY OF INSTALLATION. CHECK FOR FUEL AND OIL LEAKS EXTERNALLY AND AT DRAINS.						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 70-00-00	ENC					1800		
ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047									
700010 (s)	NO. 2 ENGINE - CHECK OF TUBING FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS, EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION AND EVIDENCE OF FUEL OR OIL LEAKS, INCLUDING NO. 4 BRG. TUBES						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 70-00-00	ENC					1800		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
700015 (s)	NO. 2 ENGINE - CHECK WIRING FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS AND FOR EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION.						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 70-00-00	ENC					1800		
700020 (s)	NO. 2 ENGINE - CHECK WIRING HARNESS CONNECTORS FOR SECURITY						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 73-20-03	ENC					1800		
700025 (s)	NO. 2 ENGINE - CHECK ACCESSORIES FOR SECURITY OF INSTALLATION. CHECK FOR FUEL AND OIL LEAKS EXTERNALLY AND AT DRAINS.						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 70-00-00	ENC					1800		
CHAPTER 71	**POWER PLANT**								
71-00-00-100-801-01	ACCOMPLISH NO.1 ENGINE CLEANING								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 71-00-00-100-801	AFL					0		
		APH					0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00-00-100-801-02	ACCOMPLISH NO.2 ENGINE CLEANING								
		MOS					13-DEC-2006		
		HRS/MSC	A/R				0		
	REF: AMM 71-00-00-100-801	AFL					0		
		APH					0		
71-00-00-760-801-01 (s)	CHECK OF THE NO.1 ENGINE CASING ELECTRICAL BONDING						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
		HRS/MSC					3041.8		
	REF: AMM 71-00-00-760-801	AFL					2328		
71-00-00-760-801-02 (s)	CHECK OF THE NO.2 ENGINE CASING ELECTRICAL BONDING						PKG		
	PKG 12 ,14 ,31	MOS	16	+1m			17-APR-2018		
		HRS/MSC					3041.8		
	REF: AMM 71-00-00-760-801	AFL					2328		
71-00-00-910-802-01	ACCOMPLISH NO. 1 ENGINE RUN-UP INSPECTION								
		MOS					13-DEC-2006		
71.080		HRS/MSC	O/C				0		
	REF: AMM 71-00-00-910-802	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00-00-910-802-02	ACCOMPLISH NO. 2 ENGINE RUN-UP INSPECTION								
		MOS					13-DEC-2006		
71.080		HRS/MSC	O/C				0		
	REF: AMM 71-00-00-910-802	AFL					0		
71-00-00-910-803-01	ACCOMPLISH END OF INSPECTION NO.1 ENGINE RUN UP								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 71-00-00-910-803	AFL					0		
		APH					0		
71-00-00-910-803-02	ACCOMPLISH END OF INSPECTION NO.2 ENGINE RUN UP								
		MOS					13-DEC-2006		
		HRS/MSC	O/C				0		
	REF: AMM 71-00-00-910-803	AFL					0		
		APH					0		
+ 71-20-02-210-801-01	GENERAL VISUAL INSPECTION NO. 1 ENGINE FRONT MOUNT ATTACHMENT AND THEIR FASTENING BOLTS								
		MOS					24-JUN-2017		
54.030		HRS/MSC					2832.2		
	REF: AMM 71-20-02-210-801	AFL	3750				2192	**5942**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-20-02-210-801-02	GENERAL VISUAL INSPECTION NO. 2 ENGINE FRONT MOUNT ATTACHMENT AND THEIR FASTENING BOLTS								
		MOS					24-JUN-2017		
54.030		HRS/MSC					2832.2		
	REF: AMM 71-20-02-210-801	AFL	3750				2192	**5942**	
71-20-02-250-801-01 (s)	SPECIAL DETAILED INSPECTION OF THE NO.1 ENGINE FRONT MOUNTS (YOKE ASSEMBLY)						PKG		
	PKG 32	MOS					13-DEC-2006		
54.110		HRS/MSC					0		
	REF: AMM 71-20-02-250-801	AFL	7500				0		
71-20-02-250-801-01A	SPECIAL DETAILED INSPECTION OF THE NO.1 ENGINE FRONT MOUNTS (YOKE ASSEMBLY) (MANDATORY 5-40)								
		MOS					13-DEC-2006		
54.110		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 71-20-02-250-801	AFL	7500				0	**7500**	
71-20-02-250-801-02 (s)	SPECIAL DETAILED INSPECTION OF THE NO.2 ENGINE FRONT MOUNTS (YOKE ASSEMBLY)						PKG		
	PKG 32	MOS					13-DEC-2006		
54.110		HRS/MSC					0		
	REF: AMM 71-20-02-250-801	AFL	7500				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-02-250-801-02A	SPECIAL DETAILED INSPECTION OF THE NO.2 ENGINE FRONT MOUNTS (YOKE ASSEMBLY) (MANDATORY 5-40)								
		MOS					13-DEC-2006		
54.110		HRS/MSC					0		
MANDATORY 5-40	**REF:** AMM 71-20-02-250-801	AFL	7500				0	**7500**	
71-20-02-900-801-01	NO.1 ENGINE FORWARD MOUNT UPPER VIBRATION ISOLATOR								
	06ND71401-1	MOS		TSN:0			13-DEC-2006		
54.090	LK0489	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 71-20-02-900-801	AFL		TSN:0			0		
71-20-02-900-801-02	NO.2 ENGINE FORWARD MOUNT UPPER VIBRATION ISOLATOR								
	06ND71401-1	MOS							
54.100	LK0180	HRS/MSC	O/C						
	REF: AMM 71-20-02-900-801	AFL							
71-20-02-900-801-03	NO.1 ENGINE FORWARD MOUNT LOWER VIBRATION ISOLATOR								
	06ND71401-1	MOS		TSN:0			17-MAY-2018		
54.090	LK1970	HRS/MSC	O/C	TSN:0			3041.8		
	REF: AMM 71-20-02-900-801	AFL		TSN:0			2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-02-900-801-04	NO.2 ENGINE FORWARD MOUNT LOWER VIBRATION ISOLATOR								
	06ND71401-1	MOS		TSN:0			27-OCT-2017		
54.100	LK1948	HRS/MSC	O/C	TSN:0			2933.3		
	REF: AMM 71-20-02-900-801	AFL		TSN:0			2258		
71-20-05-350-801-01	RESTORATION NO.1 ENGINE FORWARD MOUNT UPPER VIBRATION ISOLATOR (OVERHAUL)								
	06ND71401-1	MOS					13-DEC-2006		
54.090	LK0489	HRS/MSC					0		
OVERHAUL	**REF:** AMM 71-20-05-350-801	AFL	11250				0	**11250**	
71-20-05-350-801-02	RESTORATION NO.1 ENGINE FORWARD MOUNT LOWER VIBRATION ISOLATOR (OVERHAUL)								
	06ND71401-1	MOS					17-MAY-2018		
54.090	LK1970	HRS/MSC					3041.8		
OVERHAUL	**REF:** AMM 71-20-05-350-801	AFL	11250				2328	**13578**	
+ 71-20-05-350-801-02A	RESTORATION NO.1 ENGINE FORWARD MOUNT LOWER VIBRATION ISOLATOR (OVERHAUL) (MANDATORY 5-40)								
	06ND71401-1	MOS					17-MAY-2018		
	LK1970	HRS/MSC					3041.8		
MANDATORY 5-40	**REF:**	AFL	11250				2328	**13578**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-05-350-801-03	RESTORATION NO.2 ENGINE FORWARD MOUNT UPPER VIBRATION ISOLATOR (OVERHAUL)								
	06ND71401-1	MOS					13-DEC-2006		
54.100	LK0180	HRS/MSC					0		
OVERHAUL	**REF:** AMM 71-20-05-350-801	AFL	11250				0	**11250**	
+ 71-20-05-350-801-03A	RESTORATION NO.2 ENGINE FORWARD MOUNT UPPER VIBRATION ISOLATOR (OVERHAUL) (MANDATORY 5-40)								
	06ND71401-1	MOS					13-DEC-2006		
	LK0180	HRS/MSC					0		
MANDATORY 5-40	**REF:**	AFL	11250				0	**11250**	
71-20-05-350-801-04	RESTORATION NO.2 ENGINE FORWARD MOUNT LOWER VIBRATION ISOLATOR (OVERHAUL)								
	06ND71401-1	MOS					27-OCT-2017		
54.100	LK1948	HRS/MSC					2933.3		
OVERHAUL	**REF:** AMM 71-20-05-350-801	AFL	11250				2258	**13508**	
71-20-09-350-801-01	RESTORATION NO. 1 ENGINE AFT MOUNT VIBRATION ISOLATOR (OVERHAUL)								
	06ND71401-3	MOS					13-DEC-2006		
54.090	LK0245	HRS/MSC					0		
OVERHAUL	**REF:** AMM 71-20-09-350-801	AFL	11250				0	**11250**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-09-350-801-02	RESTORATION NO. 2 ENGINE AFT MOUNT VIBRATION ISOLATOR (OVERHAUL)								
	06ND71401-3	MOS					13-DEC-2006		
54.100	LK0309	HRS/MSC					0		
OVERHAUL	**REF:** AMM 71-20-09-350-801	AFL	11250				0	**11250**	
71-20-10-220-801-01	DETAILED INSPECTION NO. 1 ENGINE OF THE AFT MOUNT UPPER LINK								
		MOS					13-DEC-2006		
71.110		HRS/MSC					0		
	REF: AMM 71-20-10-220-801	AFL	3750	+3%			0	**3750**	3862.5
		APH					0		
71-20-10-220-801-02	DETAILED INSPECTION NO. 1 ENGINE OF THE AFT MOUNT LOWER LINK								
		MOS					13-DEC-2006		
71.110		HRS/MSC					0		
	REF: AMM 71-20-10-220-801	AFL	3750	+3%			0	**3750**	3862.5
		APH					0		
71-20-10-220-801-03	DETAILED INSPECTION NO. 2 ENGINE OF THE AFT MOUNT UPPER LINK								
		MOS					13-DEC-2006		
71.110		HRS/MSC					0		
	REF: AMM 71-20-10-220-801	AFL	3750	+3%			0	**3750**	3862.5
		APH					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-10-220-801-04	DETAILED INSPECTION NO. 2 ENGINE OF THE AFT MOUNT LOWER LINK									
		MOS						13-DEC-2006		
71.110		HRS/MSC						0		
	REF: AMM 71-20-10-220-801	AFL	3750	+3%				0	**3750**	3862.5
		APH						0		
71-50-01-900-801-01	NO. 1 ENGINE CHANNEL A & B MAIN WIRE HARNESS									
	06ND71504-17	MOS			TSN:0			13-DEC-2006		
71.030	06079642	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 71-50-01-900-801	AFL			TSN:0			0		
71-50-01-900-801-02	NO. 2 ENGINE CHANNEL A & B MAIN WIRE HARNESS									
	06ND71504-7	MOS			TSN:0			13-DEC-2006		
71.030	06173169	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 71-50-01-900-801	AFL			TSN:0			0		
71-50-01-900-802-01	NO. 1 ENGINE CHANNEL A HARNESS									
	06ND71504-19	MOS			TSN:0			13-DEC-2006		
71.040	06069319	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 71-50-01-900-802	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-50-01-900-802-02	NO. 2 ENGINE CHANNEL A HARNESS								
	06ND71504-25	MOS		TSN:0			13-DEC-2006		
71.040	06204190	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 71-50-01-900-802	AFL		TSN:0			0		
71-50-01-900-803-01	NO. 1 ENGINE CHANNEL B HARNESS								
	06ND71504-21	MOS		TSN:0			13-DEC-2006		
71.050	06079643	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 71-50-01-900-803	AFL		TSN:0			0		
71-50-01-900-803-02	NO. 2 ENGINE CHANNEL B HARNESS								
	06ND71504-27	MOS		TSN:0			13-DEC-2006		
71.050	06204192	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 71-50-01-900-803	AFL		TSN:0			0		
710801	LH (IPPS) INTEGRATED POWER PLANT SYSTEM								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710802	RH (IPPS) INTEGRATED POWER PLANT SYSTEM								
	PN	MOS		TSN:0			13-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
715817	NO. 1 ENGINE DC GENERATOR CONTROL HARNESS								
	06ND71504-31	MOS		TSN:0			13-DEC-2006		
71.060	06058832	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-36-09-900-801	AFL		TSN:0			0		
715818	NO. 2 ENGINE DC GENERATOR CONTROL HARNESS								
	06ND71504-33	MOS		TSN:0			13-DEC-2006		
71.060	06152746	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 24-36-09-900-801	AFL		TSN:0			0		
71EN1	NO. 1 ENGINE								
	30C3205-02 BS 1047	MOS					10-MAY-2018		
71.EN1	PCE-CF0251	HRS/MSC	E/C	TSN:2947.9			3041.8		
	REF: AMM 71-00-01-900-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN2	NO. 2 ENGINE								
	30C3205-02 BS 1047	MOS					01-NOV-2017		
71.EN2	PCE-CF0250	HRS/MSC	E/C	TSN:2832.2			2933.3		
	REF: AMM 71-00-01-900-801	AFL					2258		

ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047

710000	NO. 1 ENGINE - PERFORM COMPRESSOR DESALINATION WASH								
		MOS					25-JUL-2006		
		HRS/MSC	A/R				0		
	REF: EMM 71-00-00	ENC					0		
710005	NO. 1 ENGINE - WASH FAN								
		MOS					25-JUL-2006		
71.005		HRS/MSC	A/R				0		
	REF:	ENC					0		
710010	NO. 1 ENGINE - CALIBRATION CHECK ENGINE								
		MOS					25-JUL-2006		
		HRS/MSC	A/R				0		
	REF: GENERIC NO REF	ENC					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71W000	NO. 1 ENGINE - COMPRESSOR WASH								
		MOS					01-APR-2015		
		HRS/MSC	O/C				2366.8		
	REF:	ENC					1759		
ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047									
710000	NO. 2 ENGINE - PERFORM COMPRESSOR DESALINATION WASH								
		MOS					18-JUL-2006		
		HRS/MSC	A/R				0		
	REF: EMM 71-00-00	ENC					0		
710005	NO. 2 ENGINE - WASH FAN								
		MOS					18-JUL-2006		
71.005		HRS/MSC	A/R				0		
	REF:	ENC					0		
710010	NO. 2 ENGINE - CALIBRATION CHECK ENGINE								
		MOS					18-JUL-2006		
		HRS/MSC	A/R				0		
	REF: GENERIC NO REF	ENC					0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71W000	NO. 2 ENGINE - COMPRESSOR WASH								
		MOS					01-APR-2015		
		HRS/MSC	O/C				2366.8		
	REF:	ENC					1759		

CHAPTER 72 ENGINE

ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047

720001	NO. 1 ENGINE - PERFORM ENGINE RUN								
		MOS					01-APR-2015		
		HRS/MSC	O/C				2366.8		
	REF: GENERIC NO REF	ENC					1759		
720010	NO. 1 ENGINE - HOT SECTION INSPECTION (HSI)								
		MOS					01-NOV-2017		
		HRS/MSC	O/C				2832.2		
	REF: EMM 72-00-00	ENC					2192		
720012	NO. 1 ENGINE - BORESCOPE ECTM HSI								
		MOS					01-NOV-2017		
		HRS/MSC	600	+200			2832.2	**(3432.2) 3513.5**	3632.2
	REF: GENERIC NO REF	ENC					2192		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#1: S/N PCE-CF0251
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720015	NO. 1 ENGINE - OVERHAUL ENGINE									
		MOS						25-JUL-2006		
		HRS/MSC	7000	+100				0	**(7000) 7081.3**	7100
OVERHAUL	**REF:** GENERIC NO REF	ENC						0		
720020	NO. 1 ENGINE - INSPECTION LOW UTILIZATION ENGINE									
		MOS	168					04-MAY-2007	**04-MAY-2021**	
		HRS/MSC						0		
	REF: EMM 72-00-00	ENC						0		
720030	NO. 1 ENGINE - VISUAL INSPECTION COMPRESSOR INLET (INNER) STATOR VANE									
		MOS						25-JUL-2006		
		HRS/MSC	3500					0	**(3500) 3581.3**	
	REF: EMM 72-30-01	ENC						0		
720040	NO. 1 ENGINE - VISUAL INSPECTION OF FOURTH-STAGE HP COMPRESSOR ROTOR DRUM FOR ABRADABLE COATING LOSS									
		MOS						24-JUN-2017		
		HRS/MSC	2400	+20/-20				2832.2	**(5232.2) 5313.5**	5252.2
	REF: EMM 72-00-00	ENC						2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#1: S/N PCE-CF0251
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720100 (s)	NO. 1 ENGINE - CHECK ENGINE MOUNTS FOR SECURITY AND CONDITION							PKG		
	PKG 1	MOS						21-MAY-2015		
		HRS/MSC	600	+50				2395.7		
	REF: GENERIC NO REF	ENC						1800		
721001	NO. 1 ENGINE - PRESERVATION OF ENGINE									
		MOS						25-JUL-2006		
		HRS/MSC	O/C					0		
	REF: EMM 72-00-00	ENC						0		
721002	NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK									
		MOS						25-JUL-2006		
		HRS/MSC	O/C					0		
	REF: EMM 72-00-00	ENC						0		
721003	NO. 1 ENGINE - DE-PRESERVATION OF ENGINE									
		MOS						25-JUL-2006		
		HRS/MSC	O/C					0		
	REF: EMM 72-00-00	ENC						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#1: S/N PCE-CF0251
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722007	NO. 1 ENGINE - REMOVE AND REPLACE COMBUSTOR DRAIN TUBE PERFORMED-PACKING									
		MOS						01-NOV-2017		
		HRS/MSC	2400	+50				2832.2	**(5232.2) 5313.5**	5282.2
	REF: See Workcard	ENC						2192		
723001	NO. 1 ENGINE - NO. 1 ANNULAR BALL BEARING									
	30C1451-01	MOS			TSN:0			25-JUL-2006		
	FAA0617211	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		
723002	NO. 1 ENGINE - CYLINDRICAL ROLLER BEARING									
	30C1543-01	MOS			TSN:0			25-JUL-2006		
	FAA0618975	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		
723003	NO. 1 ENGINE - GEARBOX DRIVE SPLINED BEVEL GEAR									
	30C5132-01	MOS			TSN:0			25-JUL-2006		
	PKAAA033208	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#1: S/N PCE-CF0251
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723005	NO. 1 ENGINE - HPC INLET SHAFT								
	30C4994-01	MOS		TSN:0			25-JUL-2006		
	AAA000N890	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723010	NO. 1 ENGINE - LP COMPRESSOR SHAFT								
	30C4140-01	MOS		TSN:0			25-JUL-2006		
	A001Y80W	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	16500	TSN:0			0	**(16500) 16562**	
723015	NO. 1 ENGINE - HP COMPRESSOR VANE RING								
	30C2792-01	MOS		TSN:0			25-JUL-2006		
	A500	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723040	NO. 1 ENGINE - NO.3 BEARING FRONT RUNNER SEAL								
	30C5659-01	MOS		TSN:0			22-SEP-2017		
	PKAAA696694	HRS/MSC		TSN:0			2832.2		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	5000	TSN:0			2192	**(7192) 7254**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#1: S/N PCE-CF0251
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723045 (s)	NO. 1 ENGINE - CHECK FAN EXIT STATOR VANES FOR FOD, DEPOSITS, CORROSION AND EROSION							PKG		
	PKG 1	MOS						21-MAY-2015		
		HRS/MSC	800	+50				2395.7		
	REF: EMM 72-30-01	ENC						1800		
723050	NO. 1 ENGINE - INTERMEDIATE CASE									
	30C5172-01	MOS			TSN:0			25-JUL-2006		
	AAMA000A522	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		
723055	NO. 1 ENGINE - HPC VANE									
	30C2793-01	MOS			TSN:0			25-JUL-2006		
	HLAA509	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		
723060	NO. 1 ENGINE - FAN BLADE ASSEMBLY									
	30C3371-01	MOS			TSN:0			25-JUL-2006		
	TNAA013A329	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723061	NO. 1 ENGINE - VISUAL INSPECT THE FAN BLADES (PRESSURE AND SUCTION SURFACES) AND LOW PRESSURE CORE STATORS								
		MOS					25-JUL-2006		
		HRS/MSC	A/R				0		
	REF: EMM 72-30-01	ENC					0		
723065	NO. 1 ENGINE - HP COMPRESSOR VANE-RING								
	30C3624-01	MOS		TSN:0			25-JUL-2006		
	HLAA457	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723070	NO. 1 ENGINE - HP COMPRESSOR REAR CASE ASSEMBLY								
	30C4213-01	MOS		TSN:0			25-JUL-2006		
	A001YPL4	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723075	NO. 1 ENGINE - FAN CASE ASSEMBLY								
	30C4286-01	MOS		TSN:0			25-JUL-2006		
	10L461	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 72-30-01	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723077 (s)	NO. 1 ENGINE - CHECK FAN CASE AND COMPRESSOR INLET FOR CLEANLINESS AND DAMAGE. CHECK LP COMPRESSOR BLADES AND NOSE CONE FOR FOD, DEPOSITS, CORROSION AND EROSION.							PKG		
	PKG 1	MOS						21-MAY-2015		
		HRS/MSC	800	+50				2395.7		
	REF: See Workcard	ENC						1800		
723080	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR TIE SHAFT									
	30C4478-01	MOS			TSN:0			25-JUL-2006		
	EAAA000P727	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		
723085	NO. 1 ENGINE - NO. 2 BALL BEARING									
	30C4521-01	MOS			TSN:0			25-JUL-2006		
	FAA0616869	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		
723090	NO. 1 ENGINE - HIGH PRESSURE DIFFUSER CASE ASSEMBLY									
	30C4656-01	MOS			TSN:0			25-JUL-2006		
	A0020B4A	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723095	NO. 1 ENGINE - HP COMPRESSOR FRONT CASE								
	30C4744-01	MOS		TSN:0			25-JUL-2006		
	27L222	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723100	NO. 1 ENGINE - IMPELLER HOUSING								
	30C4755-01	MOS		TSN:0			25-JUL-2006		
	KWA4034	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723105	NO. 1 ENGINE - NO. 3 REAR BEARING RUNNER SEAL								
	30C5447-01	MOS		TSN:0			22-SEP-2017		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			2832.2		
	REF: GENERIC NO REF	ENC		TSN:0			2192		
723110	NO. 1 ENGINE - NO. 3 ROLLER BEARING								
	30C4843-01	MOS		TSN:0			25-JUL-2006		
	FAA0613662	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724005	NO. 1 ENGINE - COMBUSTION CHAMBER CASE								
	30C3815-01	MOS		TSN:0			25-JUL-2006		
	FACN0228	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
724010	NO. 1 ENGINE - BORESCOPE INSPECTION COMBUSTOR								
		MOS					25-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: See Workcard	ENC					0		
724015	NO. 1 ENGINE - COMBUSTION CHAMBER OUTER LINER ASSEMBLY								
	30C4044-01	MOS		TSN:0			25-JUL-2006		
	A001YT5A	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
724020	NO. 1 ENGINE - COMBUSTION CHAMBER INNER LINER ASSEMBLY								
	30C4567-01	MOS		TSN:0			25-JUL-2006		
	A002085M	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	ENC		TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#1: S/N PCE-CF0251
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724040	NO. 1 ENGINE - DISCARD AND REPLACE BOLTS ON THE FRONT FLANGE OF COMBUSTION CHAMBER CASE								
		MOS					01-NOV-2017		
		HRS/MSC	O/C				2832.2		
	REF: EMM 72-40-01	ENC					2192		
725005	NO. 1 ENGINE - HPT TIE SHAFT								
	30C5133-01	MOS		TSN:0			25-JUL-2006		
	EAAA000R443	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725045 (s)	NO. 1 ENGINE - CHECK LP TURBINE AREA AND EXHAUST FOR ANY OBVIOUS DAMAGE AND/OR DETERIORATION						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 70-00-00	ENC					1800		
725100	NO. 1 ENGINE - FRONT HP TURBINE COVER								
	30C5086-01	MOS		TSN:0			25-JUL-2006		
	A001M1T1	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	15000	TSN:0			0	**(15000) 15062**	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725102	NO. 1 ENGINE - DISCARD FRONT HP TURBINE COVER NUT P/N 30C3236-01								
	30C5086-01	MOS					25-JUL-2006		
	A001M1T1	HRS/MSC	A/R				0		
	REF:	ENC					0		
725104	NO. 1 ENGINE - DISCARD FRONT HP TURBINE COVER COVER KEY WASHER P/N 30C2796-01								
	30C5086-01	MOS					25-JUL-2006		
	A001M1T1	HRS/MSC	A/R				0		
	REF:	ENC					0		
725110	NO. 1 ENGINE - REAR HP TURBINE COVER								
	30C5043-01	MOS		TSN:0			25-JUL-2006		
	A001YPBC	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	15000	TSN:0			0	**(15000) 15062**	
725112	NO. 1 ENGINE - DISCARD REAR HP TURBINE COVER KEY WASHER P/N 30C1703-01								
	30C5043-01	MOS					25-JUL-2006		
	A001YPBC	HRS/MSC	A/R				0		
	REF:	ENC					0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725115	NO. 1 ENGINE - BORESCOPE INSPECTION OF THE HP COMPRESSOR AND HP TURBINE								
		MOS					25-JUL-2006		
		HRS/MSC	A/R				0		
	REF: See Workcard	ENC					0		
725120	NO. 1 ENGINE - BORESCOPE INSPECTION FIRST-STAGE HP TURBINE VANE								
		MOS					25-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: See Workcard	ENC					0		
725130	NO. 1 ENGINE - BORESCOPE INSPECTION FIRST-STAGE HP TURBINE BLADES								
		MOS					25-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: See Workcard	ENC					0		
725140	NO. 1 ENGINE - BORESCOPE INSPECTION SECOND-STAGE HP TURBINE BLADES								
		MOS					25-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: EMM 72-00-00	ENC					0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725150	NO. 1 ENGINE - BORESCOPE INSPECTION THIRD-STAGE LP TURBINE VANE								
		MOS					25-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: EMM 72-50-02	ENC					0		
725160	NO. 1 ENGINE - BORESCOPE INSPECTION FIFTH-STAGE LP TURBINE BLADES								
		MOS					25-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: EMM 72-50-02	ENC					0		
725170	NO. 1 ENGINE - BORESCOPE INSPECTION FIFTH-STAGE LP TURBINE VANE								
		MOS					25-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: EMM 72-50-02	ENC					0		
725180	NO. 1 ENGINE - HP TURBINE VANE SEGMENT ASSEMBLY								
	30C5241CL01	MOS		TSN:0			22-SEP-2017		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			2832.2		
	REF: GENERIC NO REF	ENC		TSN:0			2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725200	NO. 1 ENGINE - ENGINE DIAGNOSTIC UNIT								
	30C3390-06	MOS		TSN:0			25-JUL-2006		
	06031969	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725210	NO. 1 ENGINE - HP TURBINE SEGMENT VANE ASSEMBLY								
	30C3282CL01	MOS		TSN:0			25-JUL-2006		
	HMM67287	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725220	NO. 1 ENGINE - OUTER HPT SHROUD ASSY								
	30C4882-01	MOS		TSN:0			25-JUL-2006		
	RWA27A104	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725225	NO. 1 ENGINE - HP TURBINE SUPPORT CASE ASSEMBLY								
	30C4885-01	MOS		TSN:0			25-JUL-2006		
	EDA00448E	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725230	NO. 1 ENGINE - HP TURBINE AIR NOZZLE ASSEMBLY								
	30C4957-01	MOS		TSN:0			25-JUL-2006		
	AWE008766	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725235	NO. 1 ENGINE - LP TURBINE STAGE 5 ROTOR ASSEMBLY								
	30F1034-12	MOS		TSN:0			25-JUL-2006		
	FAEL9774	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725240	NO. 1 ENGINE - LPT STAGE 3 AIR/OIL MULTIPLE VANE								
	30F1034-07	MOS		TSN:0			25-JUL-2006		
	FAWV0450	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725245	NO. 1 ENGINE - LPT STAGE 4 AIR/OIL MULTIPLE VANE								
	30F1325-04	MOS		TSN:0			25-JUL-2006		
	FAEJ9138	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725250	NO. 1 ENGINE - LP TURBINE STAGE 4 ROTOR ASSEMBLY								
	30F1342-06	MOS		TSN:0			25-JUL-2006		
	FAEL9765	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725255	NO. 1 ENGINE - LP TURBINE STAGE 3 ROTOR ASSEMBLY								
	30F1343-05	MOS		TSN:0			25-JUL-2006		
	FAEL8014	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725260	NO. 1 ENGINE - LPT STAGE 5 AIR/OIL MULTIPLE VANE								
	30F1370-04	MOS		TSN:0			25-JUL-2006		
	FAEL2189	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725265	NO. 1 ENGINE - LPT ROTOR AND STATOR ASSEMBLY								
	30F2900-28	MOS		TSN:0			25-JUL-2006		
	L020313	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725270	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY								
	30F3900-15	MOS		TSN:0			25-JUL-2006		
	E020299	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 72-50-03	ENC		TSN:0			0		
725275	NO. 1 ENGINE - AIR/OIL MIXER								
	30F4000-01	MOS		TSN:0			25-JUL-2006		
	FAWX7247	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726001	NO. 1 ENGINE - ANNULAR BALL BEARING								
	30C1519-01	MOS		TSN:0			25-JUL-2006		
	FAA0612952	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726002	NO. 1 ENGINE - FLANGED ROLLER BEARING								
	30C1522-01	MOS		TSN:0			25-JUL-2006		
	FAA0604762	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726005	NO. 1 ENGINE - IDLER GEARSHAFT SPUR GEAR								
	30C3147-01	MOS		TSN:0			25-JUL-2006		
	PKAAA034789	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726010	NO. 1 ENGINE - STARTER GEARSHAFT BEVEL SPUR GEAR								
	30C5330-01	MOS		TSN:0			25-JUL-2006		
	PKAAA028841	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726015	NO. 1 ENGINE - FLANGED BALL BEARING								
	30C3512-01	MOS		TSN:0			25-JUL-2006		
	FAA0614832	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726020	NO. 1 ENGINE - FUEL PUMP FCU DRIVE GEARSHAFT SPUR GEAR								
	30C3679-01	MOS		TSN:0			25-JUL-2006		
	PKAAA044091	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726025	NO. 1 ENGINE - ROLLER BEARING								
	30C3714-01	MOS		TSN:0			25-JUL-2006		
	FCN163105	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726030	NO. 1 ENGINE - ROLLER BEARING								
	30C1523-01	MOS		TSN:0			25-JUL-2006		
	FAA0608944	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726035	NO. 1 ENGINE - ROLLER BEARING								
	30C3718-01	MOS		TSN:0			25-JUL-2006		
	FCN164228	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726040	NO. 1 ENGINE - HYDRAULIC PUMP DRIVE GEARSHAFT SPUR GEAR								
	30C5316-01	MOS		TSN:0			25-JUL-2006		
	PKAAA044367	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726045	NO. 1 ENGINE - DC GENERATOR GEARSHAFT SPUR GEAR								
	30C5277-01	MOS		TSN:0			25-JUL-2006		
	PKAAA017741	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726050	NO. 1 ENGINE - OPTIONAL ACCESSORY GEARSHAFT SPUR GEAR								
	30C5276-01	MOS		TSN:0			25-JUL-2006		
	PKAAA043693	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726055	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT								
	30C4616-01	MOS		TSN:0			25-JUL-2006		
	RWA29A907	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726060	NO. 1 ENGINE - GEARBOX DRIVE SPLINED BEVELED GEARSHAFT								
	30C4617-01	MOS		TSN:0			25-JUL-2006		
	PKAAA033222	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726065	NO. 1 ENGINE - GEARBOX DRIVE SPIRAL BEVEL GEARSHAFT								
	30C4628-01	MOS		TSN:0			25-JUL-2006		
	PKAAA043514	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726070	NO. 1 ENGINE - ACCESSORY GEARBOX COVER ASSY								
	30C4643-01	MOS		TSN:0			25-JUL-2006		
	LPA02398	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726075 (s)	NO. 1 ENGINE - CHECK AGB PAD SEAL FOR OIL LEAKS						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800 +50				2395.7		
	REF: EMM 05-10-00	ENC					1800		
726080	NO. 1 ENGINE - REPLACE AGB PAD SEALS								
		MOS					10-MAY-2018		
		HRS/MSC	O/C				2960.5		
	REF: EMM 72-60-01	ENC					2266		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727005 (s)	NO. 1 ENGINE - CHECK OUTER BYPASS DUCTS FOR DAMAGE.							PKG		
	PKG 1	MOS						21-MAY-2015		
		HRS/MSC	800	+50				2395.7		
	REF: EMM 72-70-01	ENC						1800		
727010	NO. 1 ENGINE - LEFT UPPER INNER SEGMENTED BYPASS DUCT ASSEMBLY									
	30C4048-01	MOS			TSN:0			25-JUL-2006		
	KYAA001A119	HRS/MSC	O/C		TSN:0			0		
	REF: See Workcard	ENC			TSN:0			0		
727020	NO. 1 ENGINE - CENTER LOWER INNER FRONT SEGMENTED BYPASS DUCT ASSEMBLY									
	30C4057-01	MOS			TSN:0			25-JUL-2006		
	KYAA001A472	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		
727030	NO. 1 ENGINE - RIGHT INNER LOWER REAR SEGMENTED BYPASS DUCT ASSEMBLY									
	30C4429-01	MOS			TSN:0			25-JUL-2006		
	KYAA001A493	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727040	NO. 1 ENGINE - LEFT INNER LOWER REAR SEGMENTED BYPASS DUCT ASSEMBLY								
	30C4511-01	MOS		TSN:0			25-JUL-2006		
	KYAA001A508	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
727050	NO. 1 ENGINE - OUTER LOWER HALF BYPASS DUCT ASSEMBLY								
	30C4554-01	MOS		TSN:0			25-JUL-2006		
	KYAA001A655	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
727060	NO. 1 ENGINE - LEFTHAND UPPER HALF BYPASS DUCT ASSEMBLY								
	30C4695-01	MOS		TSN:0			25-JUL-2006		
	KYAA001A658	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	ENC		TSN:0			0		
727070	NO. 1 ENGINE - RIGHT INNER UPPER SEGMENTED BYPASS DUCT ASSEMBLY								
	30C4712-01	MOS		TSN:0			25-JUL-2006		
	KYAA001A254	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	ENC		TSN:0			0		

ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#2: S/N PCE-CF0250
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720001	NO. 2 ENGINE - PERFORM ENGINE RUN									
		MOS						01-APR-2015		
		HRS/MSC	O/C					2366.8		
	REF: GENERIC NO REF	ENC						1759		
720010	NO. 2 ENGINE - HOT SECTION INSPECTION (HSI)									
		MOS						01-NOV-2017		
		HRS/MSC	O/C					2832.2		
	REF: EMM 72-00-00	ENC						2192		
720012	NO. 2 ENGINE - BORESCOPE ECTM HSI									
		MOS						01-NOV-2017		
		HRS/MSC	600	+200				2832.2	**(3432.2) 3513.5**	3632.2
	REF: GENERIC NO REF	ENC						2192		
720015	NO. 2 ENGINE - OVERHAUL ENGINE									
		MOS						18-JUL-2006		
		HRS/MSC	7000	+100				0	**(7000) 7081.3**	7100
OVERHAUL	**REF:** GENERIC NO REF	ENC						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#2: S/N PCE-CF0250
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720020	NO. 2 ENGINE - INSPECTION LOW UTILIZATION ENGINE								
		MOS	168				04-MAY-2007	**04-MAY-2021**	
		HRS/MSC					0		
	REF: EMM 72-00-00	ENC					0		
720030	NO. 2 ENGINE - VISUAL INSPECTION COMPRESSOR INLET (INNER) STATOR VANE								
		MOS					18-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: EMM 72-30-01	ENC					0		
720040	NO. 2 ENGINE - VISUAL INSPECTION OF FOURTH-STAGE HP COMPRESSOR ROTOR DRUM FOR ABRADABLE COATING LOSS								
		MOS					24-JUN-2017		
		HRS/MSC	2400	+20/-20			2832.2	**(5232.2) 5313.5**	5252.2
	REF: EMM 72-00-00	ENC					2192		
720100 (s)	NO. 2 ENGINE - CHECK ENGINE MOUNTS FOR SECURITY AND CONDITION						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	600	+50			2395.7		
	REF: GENERIC NO REF	ENC					1800		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
721001	NO. 2 ENGINE - PRESERVATION OF ENGINE									
		MOS						18-JUL-2006		
		HRS/MSC	O/C					0		
	REF: EMM 72-00-00	ENC						0		
721002	NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK									
		MOS						18-JUL-2006		
		HRS/MSC	O/C					0		
	REF: EMM 72-00-00	ENC						0		
721003	NO. 2 ENGINE - DE-PRESERVATION OF ENGINE									
		MOS						18-JUL-2006		
		HRS/MSC	O/C					0		
	REF: EMM 72-00-00	ENC						0		
722007	NO. 2 ENGINE - REMOVE AND REPLACE COMBUSTOR DRAIN TUBE PERFORMED-PACKING									
		MOS						01-NOV-2017		
		HRS/MSC	2400	+50				2832.2	**(5232.2) 5313.5**	5282.2
	REF: See Workcard	ENC						2192		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723001	NO. 2 ENGINE - NO. 1 ANNULAR BALL BEARING								
	30C1451-01	MOS		TSN:0			18-JUL-2006		
	FAA0617210	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723002	NO. 2 ENGINE - CYLINDRICAL ROLLER BEARING								
	30C1585-01	MOS		TSN:0			18-JUL-2006		
	FAA0606722	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723003	NO. 2 ENGINE - GEARBOX DRIVE SPLINED BEVEL GEAR								
	30C5132-01	MOS		TSN:0			18-JUL-2006		
	PKAAA033214	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723005	NO. 2 ENGINE - HPC INLET SHAFT								
	30C4994-01	MOS		TSN:0			18-JUL-2006		
	EAAA000R845	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#2: S/N PCE-CF0250
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723010	NO. 2 ENGINE - LP COMPRESSOR SHAFT								
	30C4140-01	MOS		TSN:0			18-JUL-2006		
	A00200A2	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	16500	TSN:0			0	**(16500) 16562**	
723015	NO. 2 ENGINE - HP COMPRESSOR VANE RING								
	30C2792-01	MOS		TSN:0			18-JUL-2006		
	A465	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723040	NO. 2 ENGINE - NO.3 BEARING FRONT RUNNER SEAL								
	30C5659-01	MOS		TSN:0			30-SEP-2017		
	PKAAA696688	HRS/MSC		TSN:0			2832.2		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	5000	TSN:0			2192	**(7192) 7254**	
723045 (s)	NO. 2 ENGINE - CHECK FAN EXIT STATOR VANES FOR FOD, DEPOSITS, CORROSION AND EROSION						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 72-30-01	ENC					1800		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723050	NO. 2 ENGINE - INTERMEDIATE CASE								
	30C5172-01	MOS		TSN:0			18-JUL-2006		
	AAMA000A521	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723055	NO. 2 ENGINE - HPC VANE								
	30C2793-01	MOS		TSN:0			18-JUL-2006		
	HLAA517	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723060	NO. 2 ENGINE - FAN BLADE ASSEMBLY								
	30C3371-01	MOS		TSN:0			18-JUL-2006		
	TNAA011A981	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723061	NO. 2 ENGINE - VISUAL INSPECT THE FAN BLADES (PRESSURE AND SUCTION SURFACES) AND LOW PRESSURE CORE STATORS								
		MOS					18-JUL-2006		
		HRS/MSC	A/R				0		
	REF: EMM 72-30-01	ENC					0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723065	NO. 2 ENGINE - HP COMPRESSOR VANE-RING								
	30C5041CL02	MOS		TSN:0			18-JUL-2006		
	HMM45247	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723070	NO. 2 ENGINE - HP COMPRESSOR REAR CASE ASSEMBLY								
	30C4213-01	MOS		TSN:0			18-JUL-2006		
	A0020C41	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723075	NO. 2 ENGINE - FAN CASE ASSEMBLY								
	30C4286-01	MOS		TSN:0			18-JUL-2006		
	10L452	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 72-30-01	ENC		TSN:0			0		
723077 (s)	NO. 2 ENGINE - CHECK FAN CASE AND COMPRESSOR INLET FOR CLEANLINESS AND DAMAGE. CHECK LP COMPRESSOR BLADES AND NOSE CONE FOR FOD, DEPOSITS, CORROSION AND EROSION.						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: See Workcard	ENC					1800		

?-Insufficient Information **+-Task exists in Inspection Manual** **(s)-Suppressed Requirement** **(EBT)-Estimated Base Time** ***-Estimated Due (New Requirement)** **(EFF)-Effective C/W**
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723080	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR TIE SHAFT								
	30C4478-01	MOS		TSN:0			18-JUL-2006		
	EAAA000R166	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723085	NO. 2 ENGINE - NO. 2 BALL BEARING								
	30C4521-01	MOS		TSN:0			18-JUL-2006		
	FAA0616867	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723090	NO. 2 ENGINE - HIGH PRESSURE DIFFUSER CASE ASSEMBLY								
	30C4656-01	MOS		TSN:0			18-JUL-2006		
	A001YH8P	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723095	NO. 2 ENGINE - HP COMPRESSOR FRONT CASE								
	30C4744-01	MOS		TSN:0			18-JUL-2006		
	27L226	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723100	NO. 2 ENGINE - IMPELLER HOUSING								
	30C4755-01	MOS		TSN:0			18-JUL-2006		
	KWA4273806	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723105	NO. 2 ENGINE - NO. 3 REAR BEARING RUNNER SEAL								
	30C5193-01	MOS		TSN:0			18-JUL-2006		
	AWE008929	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
723110	NO. 2 ENGINE - NO. 3 ROLLER BEARING								
	30C4843-01	MOS		TSN:0			18-JUL-2006		
	FAA0613658	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
724005	NO. 2 ENGINE - COMBUSTION CHAMBER CASE								
	30C3815-01	MOS		TSN:0			18-JUL-2006		
	FACN0221	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724010	NO. 2 ENGINE - BORESCOPE INSPECTION COMBUSTOR								
		MOS					18-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: See Workcard	ENC					0		
724015	NO. 2 ENGINE - COMBUSTION CHAMBER OUTER LINER ASSEMBLY								
	30C4044-01	MOS		TSN:0			18-JUL-2006		
	A00200PA	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
724020	NO. 2 ENGINE - COMBUSTION CHAMBER INNER LINER ASSEMBLY								
	30C4567-01	MOS		TSN:0			30-SEP-2017		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			2832.2		
	REF: See Workcard	ENC		TSN:0			2192		
724040	NO. 2 ENGINE - DISCARD AND REPLACE BOLTS ON THE FRONT FLANGE OF COMBUSTION CHAMBER CASE								
		MOS					01-NOV-2017		
		HRS/MSC	O/C				2832.2		
	REF: EMM 72-40-01	ENC					2192		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#2: S/N PCE-CF0250
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725005	NO. 2 ENGINE - HPT TIE SHAFT								
	30C5133-01	MOS		TSN:0			18-JUL-2006		
	EAAA000R348	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725045 (s)	NO. 2 ENGINE - CHECK LP TURBINE AREA AND EXHAUST FOR ANY OBVIOUS DAMAGE AND/OR DETERIORATION						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800 +50				2395.7		
	REF: EMM 70-00-00	ENC					1800		
725100	NO. 2 ENGINE - FRONT HP TURBINE COVER								
	30C5086-01	MOS		TSN:0			18-JUL-2006		
	A00212YX	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	15000	TSN:0			0	**(15000) 15062**	
725102	NO. 2 ENGINE - DISCARD FRONT HP TURBINE COVER NUT P/N 30C3236-01								
	30C5086-01	MOS					18-JUL-2006		
	A00212YX	HRS/MSC	A/R				0		
	REF:	ENC					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725104	NO. 2 ENGINE - DISCARD FRONT HP TURBINE COVER COVER KEY WASHER P/N 30C2796-01								
	30C5086-01	MOS					18-JUL-2006		
	A00212YX	HRS/MSC	A/R				0		
	REF:	ENC					0		
725110	NO. 2 ENGINE - REAR HP TURBINE COVER								
	30C5043-01	MOS		TSN:0			18-JUL-2006		
	A001YPBE	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	15000	TSN:0			0	**(15000) 15062**	
725112	NO. 2 ENGINE - DISCARD REAR HP TURBINE COVER KEY WASHER P/N 30C1703-01								
	30C5043-01	MOS					18-JUL-2006		
	A001YPBE	HRS/MSC	A/R				0		
	REF:	ENC					0		
725115	NO. 2 ENGINE - BORESCOPE INSPECTION OF THE HP COMPRESSOR AND HP TURBINE								
		MOS					18-JUL-2006		
		HRS/MSC	A/R				0		
	REF: See Workcard	ENC					0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725120	NO. 2 ENGINE - BORESCOPE INSPECTION FIRST-STAGE HP TURBINE VANE								
		MOS					18-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: See Workcard	ENC					0		
725130	NO. 2 ENGINE - BORESCOPE INSPECTION FIRST-STAGE HP TURBINE BLADES								
		MOS					18-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: See Workcard	ENC					0		
725140	NO. 2 ENGINE - BORESCOPE INSPECTION SECOND-STAGE HP TURBINE BLADES								
		MOS					18-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: EMM 72-00-00	ENC					0		
725150	NO. 2 ENGINE - BORESCOPE INSPECTION THIRD-STAGE LP TURBINE VANE								
		MOS					18-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: EMM 72-50-02	ENC					0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725160	NO. 2 ENGINE - BORESCOPE INSPECTION FIFTH-STAGE LP TURBINE BLADES								
		MOS					18-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: EMM 72-50-02	ENC					0		
725170	NO. 2 ENGINE - BORESCOPE INSPECTION FIFTH-STAGE LP TURBINE VANE								
		MOS					18-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: EMM 72-50-02	ENC					0		
725180	NO. 2 ENGINE - HP TURBINE VANE SEGMENT ASSEMBLY								
	30C5241CL02	MOS		TSN:0			30-SEP-2017		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			2832.2		
	REF: GENERIC NO REF	ENC		TSN:0			2192		
725200	NO. 2 ENGINE - ENGINE DIAGNOSTIC UNIT								
	30C3390-06	MOS		TSN:0			18-JUL-2006		
	04097910	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725210	NO. 2 ENGINE - HP TURBINE SEGMENT VANE ASSEMBLY								
	30C3282CL01	MOS		TSN:0			18-JUL-2006		
	HMM11486	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725220	NO. 2 ENGINE - OUTER HPT SHROUD ASSY								
	30C4882-01	MOS		TSN:0			18-JUL-2006		
	RWA27A106	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725225	NO. 2 ENGINE - HP TURBINE SUPPORT CASE ASSEMBLY								
	30C4885-01	MOS		TSN:0			18-JUL-2006		
	EDA00467L	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725230	NO. 2 ENGINE - HP TURBINE AIR NOZZLE ASSEMBLY								
	30C4957-01	MOS		TSN:0			18-JUL-2006		
	AWE008763	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725235	NO. 2 ENGINE - LP TURBINE STAGE 5 ROTOR ASSEMBLY								
	30F1034-12	MOS		TSN:0			18-JUL-2006		
	FAEL6022	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725240	NO. 2 ENGINE - LPT STAGE 3 AIR/OIL MULTIPLE VANE								
	30F1322-07	MOS		TSN:0			18-JUL-2006		
	FAWV0430	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725245	NO. 2 ENGINE - LPT STAGE 4 AIR/OIL MULTIPLE VANE								
	30F1325-04	MOS		TSN:0			18-JUL-2006		
	FAEJ9115	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725250	NO. 2 ENGINE - LP TURBINE STAGE 4 ROTOR ASSEMBLY								
	30F1342-06	MOS		TSN:0			18-JUL-2006		
	FAEL6018	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725255	NO. 2 ENGINE - LP TURBINE STAGE 3 ROTOR ASSEMBLY								
	30F1343-05	MOS		TSN:0			18-JUL-2006		
	FAEL6013	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725260	NO. 2 ENGINE - LPT STAGE 5 AIR/OIL MULTIPLE VANE								
	30F1370-04	MOS		TSN:0			18-JUL-2006		
	FAEL2212	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725265	NO. 2 ENGINE - LPT ROTOR AND STATOR ASSEMBLY								
	30F2900-28	MOS		TSN:0			18-JUL-2006		
	L020310	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725270	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY								
	30F3900-15	MOS		TSN:0			18-JUL-2006		
	E020317	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 72-50-03	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725275	NO. 2 ENGINE - AIR/OIL MIXER								
	30F4000-01	MOS		TSN:0			18-JUL-2006		
	FAWX7243	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726001	NO. 2 ENGINE - ANNULAR BALL BEARING								
	30C1519-01	MOS		TSN:0			18-JUL-2006		
	FAA0609081	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726002	NO. 2 ENGINE - FLANGED ROLLER BEARING								
	30C1522-01	MOS		TSN:0			18-JUL-2006		
	FAA0604759	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726005	NO. 2 ENGINE - IDLER GEARSHAFT SPUR GEAR								
	30C3147-01	MOS		TSN:0			18-JUL-2006		
	PKAAA034788	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726010	NO. 2 ENGINE - STARTER GEARSHAFT BEVEL SPUR GEAR								
	30C5330-01	MOS		TSN:0			18-JUL-2006		
	PKAAA028846	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726015	NO. 2 ENGINE - FLANGED BALL BEARING								
	30C3512-01	MOS		TSN:0			18-JUL-2006		
	FAA0614834	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726020	NO. 2 ENGINE - FUEL PUMP FCU DRIVE GEARSHAFT SPUR GEAR								
	30C3679-01	MOS		TSN:0			18-JUL-2006		
	PKAAA030156	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726025	NO. 2 ENGINE - ROLLER BEARING								
	30C3716-01	MOS		TSN:0			18-JUL-2006		
	FCN169348	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726030	NO. 2 ENGINE - ROLLER BEARING								
	30C1543-01	MOS		TSN:0			18-JUL-2006		
	FAA0618972	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726035	NO. 2 ENGINE - ROLLER BEARING								
	30C3718-01	MOS		TSN:0			18-JUL-2006		
	FCN164227	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726040	NO. 2 ENGINE - HYDRAULIC PUMP DRIVE GEARSHAFT SPUR GEAR								
	30C5316-01	MOS		TSN:0			18-JUL-2006		
	PKAAA044370	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726045	NO. 2 ENGINE - DC GENERATOR GEARSHAFT SPUR GEAR								
	30C5277-01	MOS		TSN:0			18-JUL-2006		
	PKAAA043463	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726050	NO. 2 ENGINE - OPTIONAL ACCESSORY GEARSHAFT SPUR GEAR								
	30C5276-01	MOS		TSN:0			18-JUL-2006		
	PKAAA043691	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726055	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT								
	30C4616-01	MOS		TSN:0			18-JUL-2006		
	RWA29A904	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726060	NO. 2 ENGINE - GEARBOX DRIVE SPLINED BEVELED GEARSHAFT								
	30C4617-01	MOS		TSN:0			18-JUL-2006		
	PKAA033218	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
726065	NO. 2 ENGINE - GEARBOX DRIVE SPIRAL BEVEL GEARSHAFT								
	30C4628-01	MOS		TSN:0			18-JUL-2006		
	PKAAA043511	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726070	NO. 2 ENGINE - ACCESSORY GEARBOX COVER ASSY								
	30C5405-01	MOS		TSN:0			30-SEP-2017		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			2832.2		
	REF: GENERIC NO REF	ENC		TSN:0			2192		
726075 (s)	NO. 2 ENGINE - CHECK AGB PAD SEAL FOR OIL LEAKS						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800 +50				2395.7		
	REF: EMM 05-10-00	ENC					1800		
726080	NO. 2 ENGINE - REPLACE AGB PAD SEALS								
		MOS					01-NOV-2017		
		HRS/MSC	O/C				2832.2		
	REF: EMM 72-60-01	ENC					2192		
727005 (s)	NO. 2 ENGINE - CHECK OUTER BYPASS DUCTS FOR DAMAGE.						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800 +50				2395.7		
	REF: EMM 72-70-01	ENC					1800		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727010	NO. 2 ENGINE - LEFT UPPER INNER SEGMENTED BYPASS DUCT ASSEMBLY								
	30C4048-01	MOS		TSN:0			18-JUL-2006		
	KYAA001A529	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	ENC		TSN:0			0		
727020	NO. 2 ENGINE - CENTER LOWER INNER FRONT SEGMENTED BYPASS DUCT ASSEMBLY								
	30C4057-01	MOS		TSN:0			18-JUL-2006		
	KYAA001A469	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
727030	NO. 2 ENGINE - RIGHT INNER LOWER REAR SEGMENTED BYPASS DUCT ASSEMBLY								
	30C4429-01	MOS		TSN:0			18-JUL-2006		
	KYAA001A489	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
727040	NO. 2 ENGINE - LEFT INNER LOWER REAR SEGMENTED BYPASS DUCT ASSEMBLY								
	30C4511-01	MOS		TSN:0			18-JUL-2006		
	KYAA001A506	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727050	NO. 2 ENGINE - OUTER LOWER HALF BYPASS DUCT ASSEMBLY								
	30C4554-01	MOS		TSN:0			18-JUL-2006		
	KYAA001A553	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
727060	NO. 2 ENGINE - LEFTHAND UPPER HALF BYPASS DUCT ASSEMBLY								
	30C4695-01	MOS		TSN:0			18-JUL-2006		
	KYAA001A656	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	ENC		TSN:0			0		
727070	NO. 2 ENGINE - RIGHT INNER UPPER SEGMENTED BYPASS DUCT ASSEMBLY								
	30C4712-01	MOS		TSN:0			18-JUL-2006		
	KYAA001A581	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	ENC		TSN:0			0		
CHAPTER 72-20	**ENGINE**								
ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047									
722010	NO. 1 ENGINE - FAN HUB								
	30C4154-01	MOS		TSN:0			25-JUL-2006		
	BE100456	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	15000	TSN:0			0	**(15000) 15062**	
ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047									

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722010	NO. 2 ENGINE - FAN HUB								
	30C4154-01	MOS		TSN:0			18-JUL-2006		
	BE100443	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	15000	TSN:0			0	**(15000) 15062**	

CHAPTER 72-30 ENGINE

ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047

723020	NO. 1 ENGINE - INDUCER IMPELLER								
	30C4475-01	MOS		TSN:0			25-JUL-2006		
	A00209MT	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	15000	TSN:0			0	**(15000) 15062**	
723030	NO. 1 ENGINE - EXDUCER IMPELLER								
	30C5049-01	MOS					22-SEP-2017		
	A003LDFL	HRS/MSC		TSN:0			2832.2		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	5000	TSN:0			2192	**(7192) 7254**	

ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047

723020	NO. 2 ENGINE - INDUCER IMPELLER								
	30C4475-01	MOS		TSN:0			18-JUL-2006		
	A00209MW	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	15000	TSN:0			0	**(15000) 15062**	

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723030	NO. 2 ENGINE - EXDUCER IMPELLER								
	30C5049-01	MOS		TSN:0			30-SEP-2017		
	A0042WD9	HRS/MSC		TSN:0			2832.2		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	5000	TSN:0			2192	**(7192) 7254**	

CHAPTER 72-50 ENGINE

ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047

725010	NO. 1 ENGINE - HP COMPRESSOR (1ST STAGE) ROTOR								
	30C5331-01	MOS		TSN:0			25-JUL-2006		
	A0020K6X	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	15000	TSN:0			0	**(15000) 15062**	
725020	NO. 1 ENGINE - HP COMPRESSOR (2ND STAGE) ROTOR								
	30C2132-01	MOS		TSN:0			25-JUL-2006		
	A0020LPX	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	15000	TSN:0			0	**(15000) 15062**	
725030	NO. 1 ENGINE - HP COMPRESSOR (3RD STAGE) ROTOR								
	30C2133-01	MOS		TSN:0			25-JUL-2006		
	TXA1A9177	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	8500	TSN:0			0	**(8500) 8562**	

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 1 ENGINE - HP COMPRESSOR (4TH STAGE) ROTOR								
	30C3454-01	MOS		TSN:0			25-JUL-2006		
	TXA1A9369	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	8500	TSN:0			0	**(8500) 8562**	
725050	NO. 1 ENGINE - HP TURBINE (1ST STAGE) DISK								
	30C5141-01	MOS		TSN:0			25-JUL-2006		
	A001XM15	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	6100	TSN:0			0	**(6100) 6162**	
725060	NO. 1 ENGINE - HP TURBINE (2ND STAGE) DISK								
	30C4342-01	MOS		TSN:0			25-JUL-2006		
	A0020TY0	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	9500	TSN:0			0	**(9500) 9562**	
725070	NO. 1 ENGINE - LP TURBINE (3RD STAGE) DISK								
	30F1337-05	MOS		TSN:0			25-JUL-2006		
	FAEJ8448	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	12000	TSN:0			0	**(12000) 12062**	

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725080	NO. 1 ENGINE - LP TURBINE (4TH STAGE) DISK								
	30F1336-06	MOS		TSN:0			25-JUL-2006		
	FAEK2180	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	12000	TSN:0			0	**(12000) 12062**	
725090	NO. 1 ENGINE - LP TURBINE (5TH STAGE) DISK								
	30F1006-10	MOS		TSN:0			25-JUL-2006		
	FAEK4295	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	12000	TSN:0			0	**(12000) 12062**	
ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047									
725010	NO. 2 ENGINE - HP COMPRESSOR (1ST STAGE) ROTOR								
	30C5331-01	MOS		TSN:0			18-JUL-2006		
	A0020K6W	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	15000	TSN:0			0	**(15000) 15062**	
725020	NO. 2 ENGINE - HP COMPRESSOR (2ND STAGE) ROTOR								
	30C2132-01	MOS		TSN:0			18-JUL-2006		
	A00209MP	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	15000	TSN:0			0	**(15000) 15062**	

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725030	NO. 2 ENGINE - HP COMPRESSOR (3RD STAGE) ROTOR								
	30C2133-01	MOS		TSN:0			18-JUL-2006		
	TXA1A9176	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	8500	TSN:0			0	**(8500) 8562**	
725040	NO. 2 ENGINE - HP COMPRESSOR (4TH STAGE) ROTOR								
	30C3454-01	MOS		TSN:0			18-JUL-2006		
	TXA1A9370	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	8500	TSN:0			0	**(8500) 8562**	
725050	NO. 2 ENGINE - HP TURBINE (1ST STAGE) DISK								
	30C5141-01	MOS		TSN:0			18-JUL-2006		
	A001XM18	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	6100	TSN:0			0	**(6100) 6162**	
725060	NO. 2 ENGINE - HP TURBINE (2ND STAGE) DISK								
	30C4342-01	MOS		TSN:0			18-JUL-2006		
	A0020X8E	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	9500	TSN:0			0	**(9500) 9562**	

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725070	NO. 2 ENGINE - LP TURBINE (3RD STAGE) DISK								
	30F1337-05	MOS		TSN:0			18-JUL-2006		
	FAEJ7903	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	12000	TSN:0			0	**(12000) 12062**	
725080	NO. 2 ENGINE - LP TURBINE (4TH STAGE) DISK								
	30F1336-06	MOS		TSN:0			18-JUL-2006		
	FAEK2187	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	12000	TSN:0			0	**(12000) 12062**	
725090	NO. 2 ENGINE - LP TURBINE (5TH STAGE) DISK								
	30F1006-10	MOS		TSN:0			18-JUL-2006		
	FAEK4273	HRS/MSC		TSN:0			0		
LIFE LIMIT	**REF:** GENERIC NO REF	ENC	12000	TSN:0			0	**(12000) 12062**	
CHAPTER 73	**ENGINE FUEL AND CONTROL**								
73-20-01-700-801-01	CHECK OF THE FADEC/AIRCRAFT INTERFACES								
		MOS					13-DEC-2006		
73.040		HRS/MSC	A/R				0		
	REF: AMM 73-20-01-700-801	AFL					0		
		APH					0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-30-07-900-801-01	LH FUEL PRESSURE SWITCH									
	12H0043G	MOS			TSN:0			13-DEC-2006		
73.030	0231	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 73-30-07-900-801	AFL			TSN:0			0		
73-30-07-900-801-02	RH FUEL PRESSURE SWITCH									
	12H0043G	MOS			TSN:0			13-DEC-2006		
73.030	0227	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 73-30-07-900-801	AFL			TSN:0			0		
73-40-00-700-801-01 (s)	INDICATION TEST OF APR							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				16-APR-2018		
73.020		HRS/MSC	400	+40				3041.8		
	REF: AMM 73-40-00-700-801	AFL						2328		
73-40-00-700-801-01A	INDICATION TEST OF APR (MANDATORY 5-40)									
		MOS						16-APR-2018		
73.020		HRS/MSC	450					3041.8	**3491.8**	
CMR	**REF:** AMM 73-40-00-700-801	AFL						2328		

ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005 (s)	NO. 1 ENGINE - REMOVE AND CHECK FUEL FILTER FOR FOREIGN MATTER AND DAMAGE. REPLACE IF DIRTY OR DAMAGED.							PKG		
	PKG 1	MOS						21-MAY-2015		
		HRS/MSC	800	+50				2395.7		
	REF: See Workcard	ENC						1800		
731010	NO. 1 ENGINE - REPLACE FUEL FILTER									
		MOS						22-SEP-2017		
		HRS/MSC	1200	+50				2832.2	**(4032.2) 4113.5**	4082.2
	REF: EMM 73-10-03	ENC						2192		
731011	NO. 1 ENGINE - LH DUPLEX FUEL NOZZLE									
	30C4420-01	MOS			TSN:134 TSO:0			22-SEP-2017		
	A0020F6X	HRS/MSC	O/C		TSN:2832.2 TSO:0			2832.2		
	REF: EMM 73-10-04	ENC			TSN:2192 TSO:0			2192		
731012	NO. 1 ENGINE - RH DUPLEX FUEL NOZZLE									
	30C4420-01	MOS			TSO:0			22-SEP-2017		
	A0020N7N	HRS/MSC	O/C		TSO:0			2832.2		
	REF: EMM 73-10-04	ENC			TSO:0			2192		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#1: S/N PCE-CF0251
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731020	NO. 1 ENGINE - PERFORM ADJUSTMENT OF FUEL SHUT OFF VALVE (FSOV)									
		MOS						25-JUL-2006		
		HRS/MSC	3500	+150				0	**(3500) 3581.3**	3650
	REF: EMM 73-10-05	ENC						0		
731030	NO. 1 ENGINE - FUEL WASTE EJECTOR									
	30C3471-07	MOS			TSN:0			25-JUL-2006		
	00312	HRS/MSC	O/C		TSN:0			0		
	REF: EMM 73-10-06	ENC			TSN:0			0		
731035 (s)	NO. 1 ENGINE - CHECK FUEL WASTE EJECTOR FOR SECURITY AND LEAKAGE.							PKG		
	30C3471-07 PKG 1	MOS						21-MAY-2015		
	00312	HRS/MSC	800	+50				2395.7		
	REF: EMM 70-00-00	ENC						1800		
731040	NO. 1 ENGINE - FUEL START AND DUMP VALVE									
	30C3472-01	MOS			TSN:0			25-JUL-2006		
	14761119	HRS/MSC	O/C		TSN:0			0		
	REF: EMM 73-10-05	ENC			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731050	NO. 1 ENGINE - BORESCOPE INSPECTION FUEL NOZZLES								
		MOS					25-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: EMM 72-00-00	ENC					0		
731060	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER								
	30C3539-02	MOS		TSN:0			25-JUL-2006		
	1793	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-10-02	ENC		TSN:0			0		
731065 (s)	NO. 1 ENGINE - CHECK FUEL/OIL HEAT EXCHANGER FOR SECURITY AND LEAKAGE						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 70-00-00	ENC					1800		
731070	NO. 1 ENGINE - SIMPLEX FUEL (LONG FUEL TUBE) NOZZLE ASSEMBLY								
	30C4327-01	MOS		TSN:0			25-JUL-2006		
	A0020DLN	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-10-04	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731080	NO. 1 ENGINE - SIMPLEX FUEL (SHORT FUEL TUBE) NOZZLE ASSEMBLY								
	30C4328-01	MOS		TSN:0			25-JUL-2006		
	A001YF3C	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-10-04	ENC		TSN:0			0		
731090	NO. 1 ENGINE - IGV SERVICE FAIRING ASSEMBLY								
	30C4400-01	MOS		TSN:0			25-JUL-2006		
	KYAA001A173	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
732005	NO. 1 ENGINE - P3 PRESSURE TRANSDUCER								
	30C1135-02	MOS		TSN:0			25-JUL-2006		
	KL06035064	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-20-05	ENC		TSN:0			0		
732010	NO. 1 ENGINE - FUEL CONTROL UNIT HYDROMECHANICAL								
	30C3470-04	MOS		TSN:0			25-JUL-2006		
	F65077	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-20-01	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732012 (s)	NO. 1 ENGINE - CHECK FUEL CONTROL UNIT HYDROMECHANICAL FOR SECURITY, LEAKAGE, AND FUEL LEAKS AT THE TUBE CONNECTIONS.							PKG		
	PKG 1	MOS						21-MAY-2015		
		HRS/MSC	800	+50				2395.7		
	REF: EMM 73-20-01	ENC						1800		
732015	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) UNIT									
	30C3438-16	MOS			TSN:57			15-APR-2011		
	06050002	HRS/MSC	O/C		TSN:1238.5			1238.5		
	REF: EMM 73-20-02	ENC			TSN:863			863		
732020	NO. 1 ENGINE - OUTER ELECTRICAL WIRING HARNESS									
	30C3463-08	MOS			TSN:0			25-JUL-2006		
	EF00334	HRS/MSC	O/C		TSN:0			0		
	REF: EMM 73-20-03	ENC			TSN:0			0		
732025	NO. 1 ENGINE - FRONT ELECTRICAL WIRING ASSEMBLY									
	30C3464-04	MOS			TSN:0			25-JUL-2006		
	EF00273	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732030	NO. 1 ENGINE - AC GENERATOR STATOR								
	30C3467-02	MOS		TSN:0			25-JUL-2006		
	0298	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
732035	NO. 1 ENGINE - AC GENERATOR ROTOR								
	30C3468-01	MOS		TSN:0			25-JUL-2006		
	0290	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
733001	NO. 1 ENGINE - FUEL FLOWMETER								
	9-127-93	MOS		TSN:0			30-APR-2008		
	107052399	HRS/MSC	O/C	TSN:0			345.6		
	REF: GENERIC NO REF	ENC		TSN:0			252		
ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047									
731005 (s)	NO. 2 ENGINE - REMOVE AND CHECK FUEL FILTER FOR FOREIGN MATTER AND DAMAGE. REPLACE IF DIRTY OR DAMAGED.						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: See Workcard	ENC					1800		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#2: S/N PCE-CF0250
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 2 ENGINE - REPLACE FUEL FILTER									
		MOS						30-SEP-2017		
		HRS/MSC	1200	+50				2832.2	**(4032.2) 4113.5**	4082.2
	REF: EMM 73-10-03	ENC						2192		
731011	NO. 2 ENGINE - LH DUPLEX FUEL NOZZLE									
	30C4420-01	MOS			TSN:134 TSO:0			30-SEP-2017		
	A0020EFX	HRS/MSC	O/C		TSN:2832.2 TSO:0			2832.2		
	REF: EMM 73-10-04	ENC			TSN:2192 TSO:0			2192		
731012	NO. 2 ENGINE - RH DUPLEX FUEL NOZZLE									
	30C4420-01	MOS			TSO:0			30-SEP-2017		
	A0020KWL	HRS/MSC	O/C		TSO:0			2832.2		
	REF: EMM 73-10-04	ENC			TSO:0			2192		
731020	NO. 2 ENGINE - PERFORM ADJUSTMENT OF FUEL SHUT OFF VALVE (FSOV)									
		MOS						18-JUL-2006		
		HRS/MSC	3500	+150				0	**(3500) 3581.3**	3650
	REF: EMM 73-10-05	ENC						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731030	NO. 2 ENGINE - FUEL WASTE EJECTOR								
	30C3471-04	MOS		TSN:0			18-JUL-2006		
	314	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-10-06	ENC		TSN:0			0		
731035 (s)	NO. 2 ENGINE - CHECK FUEL WASTE EJECTOR FOR SECURITY AND LEAKAGE.						PKG		
	30C3471-04 PKG 1	MOS					21-MAY-2015		
	314	HRS/MSC	800 +50				2395.7		
	REF: EMM 70-00-00	ENC					1800		
731040	NO. 2 ENGINE - FUEL START AND DUMP VALVE								
	30C3472-01	MOS		TSN:0			18-JUL-2006		
	14695758	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-10-05	ENC		TSN:0			0		
731050	NO. 2 ENGINE - BORESCOPE INSPECTION FUEL NOZZLES								
		MOS					18-JUL-2006		
		HRS/MSC	3500				0	**(3500) 3581.3**	
	REF: EMM 72-00-00	ENC					0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731060	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER								
	30C3539-02	MOS		TSN:0			18-JUL-2006		
	1785	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-10-02	ENC		TSN:0			0		
731065 (s)	NO. 2 ENGINE - CHECK FUEL/OIL HEAT EXCHANGER FOR SECURITY AND LEAKAGE						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 70-00-00	ENC					1800		
731070	NO. 2 ENGINE - SIMPLEX FUEL (LONG FUEL TUBE) NOZZLE ASSEMBLY								
	30C4327-01	MOS		TSN:0			18-JUL-2006		
	A0020DLM	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-10-04	ENC		TSN:0			0		
731080	NO. 2 ENGINE - SIMPLEX FUEL (SHORT FUEL TUBE) NOZZLE ASSEMBLY								
	30C4328-01	MOS		TSN:0			18-JUL-2006		
	A001YF3B	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-10-04	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731090	NO. 2 ENGINE - IGV SERVICE FAIRING ASSEMBLY								
	30C4400-01	MOS		TSN:0			18-JUL-2006		
	KYAA001A172	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
732005	NO. 2 ENGINE - P3 PRESSURE TRANSDUCER								
	30C1135-02	MOS		TSN:0			18-JUL-2006		
	KL06045190	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-20-05	ENC		TSN:0			0		
732010	NO. 2 ENGINE - FUEL CONTROL UNIT HYDROMECHANICAL								
	30C3470-04	MOS		TSN:0			18-JUL-2006		
	F62271	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-20-01	ENC		TSN:0			0		
732012 (s)	NO. 2 ENGINE - CHECK FUEL CONTROL UNIT HYDROMECHANICAL FOR SECURITY, LEAKAGE, AND FUEL LEAKS AT THE TUBE CONNECTIONS.						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 73-20-01	ENC					1800		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732015	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) UNIT								
	30C3438-16	MOS		TSN:57			15-APR-2011		
	06046302	HRS/MSC	O/C	TSN:1238.5			1238.5		
	REF: EMM 73-20-02	ENC		TSN:863			863		
732020	NO. 2 ENGINE - OUTER ELECTRICAL WIRING HARNESS								
	30C3463-08	MOS		TSN:0			18-JUL-2006		
	EF00325	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-20-03	ENC		TSN:0			0		
732025	NO. 2 ENGINE - FRONT ELECTRICAL WIRING ASSEMBLY								
	30C3464-04	MOS		TSN:0			18-JUL-2006		
	EF00287	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
732030	NO. 2 ENGINE - AC GENERATOR STATOR								
	30C3467-02	MOS		TSN:0			18-JUL-2006		
	290	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732035	NO. 2 ENGINE - AC GENERATOR ROTOR								
	30C3468-01	MOS		TSN:0			18-JUL-2006		
	279	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
733001	NO. 2 ENGINE - FUEL FLOWMETER								
	9-127-93	MOS		TSN:0			18-JUL-2006		
	107052282	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
CHAPTER 74	**IGNITION**								
ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047									
741001	NO. 1 ENGINE - IGNITION EXCITER								
	30C1132-05	MOS					08-NOV-2017		
	162043	HRS/MSC	O/C				2835.8		
	REF: EMM 74-10-01	ENC					836		
741003 (s)	NO. 1 ENGINE - INSPECTION IGNITION EXCITER FOR SECURITY AND CORROSION						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 74-10-01	ENC					1800		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741005	NO. 1 ENGINE - IGNITION CABLE								
	30C1133-03	MOS		TSN:0			25-JUL-2006		
	CL060495	HRS/MSC	O/C	TSN:0			0		
	REF:	ENC		TSN:0			0		
741007 (s)	NO. 1 ENGINE - INSPECTION IGNITION CABLE FOR CHAFING, WEAR AND SECURITY						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 74-10-01	ENC					1800		
741010	NO. 1 ENGINE - EXCITER TO IGNITER IGNITION CABLE								
	30C2172-04	MOS		TSN:0			25-JUL-2006		
	CL061664	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 74-10-01	ENC		TSN:0			0		
741020 (s)	NO. 1 ENGINE - OPERATIONAL TEST SPARK IGNITERS						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 74-10-01	ENC					1800		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741801	NO. 1 ENGINE - 4 O'CLOCK SPARK IGNITER									
	30C1356-05	MOS			TSN:0			08-NOV-2017		
	NSN	HRS/MSC	1600	+50	TSN:0			2835.8	**(4435.8) 4517.1**	4485.8
LIFE LIMIT	**REF:** GENERIC NO REF	ENC			TSN:0			836		
741802	NO. 1 ENGINE - 7 O'CLOCK SPARK IGNITER									
	30C1356-05	MOS			TSN:0			08-NOV-2017		
	NSN	HRS/MSC	1600	+50	TSN:0			2835.8	**(4435.8) 4517.1**	4485.8
LIFE LIMIT	**REF:** GENERIC NO REF	ENC			TSN:0			836		
741803 (s)	NO. 1 ENGINE - INSPECTION 4 O'CLOCK SPARK IGNITER FOR CLEANLINESS AND EROSION							PKG		
	30C1356-05 PKG 1	MOS						08-NOV-2017		
	NSN	HRS/MSC	800	+50				2835.8		
	REF: EMM 74-10-01	ENC						836		
741804 (s)	NO. 1 ENGINE - INSPECTION 7 O'CLOCK SPARK IGNITER FOR CLEANLINESS AND EROSION							PKG		
	30C1356-05 PKG 1	MOS						08-NOV-2017		
	NSN	HRS/MSC	800	+50				2835.8		
	REF: EMM 74-10-01	ENC						836		

ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741001	NO. 2 ENGINE - IGNITION EXCITER								
	CH92051-4	MOS		TSN:5			31-MAY-2018		
	13007256	HRS/MSC	O/C	TSN:0			2948.7		
	REF: EMM 74-10-01	ENC							
741003 (s)	NO. 2 ENGINE - INSPECTION IGNITION EXCITER FOR SECURITY AND CORROSION						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 74-10-01	ENC					1800		
741005	NO. 2 ENGINE - IGNITION CABLE								
	30C1133-03	MOS		TSN:0			18-JUL-2006		
	CL060494	HRS/MSC	O/C	TSN:0			0		
	REF:	ENC		TSN:0			0		
741007 (s)	NO. 2 ENGINE - INSPECTION IGNITION CABLE FOR CHAFING, WEAR AND SECURITY						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 74-10-01	ENC					1800		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#2: S/N PCE-CF0250
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741010	NO. 2 ENGINE - EXCITER TO IGNITER IGNITION CABLE									
	30C2172-04	MOS			TSN:0			18-JUL-2006		
	CL061668	HRS/MSC	O/C		TSN:0			0		
	REF: EMM 74-10-01	ENC			TSN:0			0		
741020 (s)	NO. 2 ENGINE - OPERATIONAL TEST SPARK IGNITERS							PKG		
	PKG 1	MOS						21-MAY-2015		
		HRS/MSC	800	+50				2395.7		
	REF: EMM 74-10-01	ENC						1800		
741801	NO. 2 ENGINE - 4 O'CLOCK SPARK IGNITER									
	30C1356-05	MOS			TSN:0			01-NOV-2017		
	SN-UNKNOWN	HRS/MSC	1600	+50	TSN:0			2832.2	**(4432.2) 4513.5**	4482.2
LIFE LIMIT	**REF:** GENERIC NO REF	ENC			TSN:0			2192		
741802	NO. 2 ENGINE - 7 O'CLOCK SPARK IGNITER									
	30C1356-05	MOS			TSN:0			01-NOV-2017		
	SN-UNKNOWN	HRS/MSC	1600	+50	TSN:0			2832.2	**(4432.2) 4513.5**	4482.2
LIFE LIMIT	**REF:** GENERIC NO REF	ENC			TSN:0			2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741803 (s)	NO. 2 ENGINE - INSPECTION 4 O'CLOCK SPARK IGNITER FOR CLEANLINESS AND EROSION						PKG		
	30C1356-05 PKG 1	MOS					01-NOV-2017		
	SN-UNKNOWN	HRS/MSC	800	+50			2832.2		
	REF: EMM 74-10-01	ENC					2192		
741804 (s)	NO. 2 ENGINE - INSPECTION 7 O'CLOCK SPARK IGNITER FOR CLEANLINESS AND EROSION						PKG		
	30C1356-05 PKG 1	MOS					01-NOV-2017		
	SN-UNKNOWN	HRS/MSC	800	+50			2832.2		
	REF: EMM 74-10-01	ENC					2192		
CHAPTER 75	**AIR**								
ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047									
753000	NO. 1 ENGINE - LEFT COMPRESSOR BLEED VALVE ASSEMBLY								
	PN	MOS		TSN:0			25-JUL-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
753001	NO. 1 ENGINE - RIGHT COMPRESSOR BLEED VALVE ASSEMBLY								
	30C1364-02	MOS		TSN:0			25-JUL-2006		
	1018	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#1: S/N PCE-CF0251
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753002	NO. 1 ENGINE - BLEED AIR CONTROL SOLENOID VALVE									
	30C2009-03	MOS			TSN:0			25-JUL-2006		
	1558	HRS/MSC	O/C		TSN:0			0		
	REF: EMM 75-30-02	ENC			TSN:0			0		
753004	NO. 1 ENGINE - LINEAR ACTUATOR									
	30C1266-01	MOS			TSO:0			22-SEP-2017		
	553	HRS/MSC	O/C		TSO:0			2832.2		
	REF: GENERIC NO REF	ENC			TSO:0			2192		
753007 (s)	NO. 1 ENGINE - CHECK P1 AIR TUBES-DRAIN CONDESATION TRAP. CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION.							PKG		
	PKG 1	MOS						21-MAY-2015		
		HRS/MSC	800	+50				2395.7		
	REF: EMM 70-00-00	ENC						1800		
753010	NO. 1 ENGINE - REMOVE AND INSPECT P2.5 AND P2.8 BLEED VALVES FOR GENERAL CONDITION AND WEAR									
		MOS						25-JUL-2006		
		HRS/MSC	3500	+150				0	**(3500) 3581.3**	3650
	REF: EMM 75-30-01	ENC						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753020	NO. 1 ENGINE - REMOVE AND INSPECT BLEED VALVE CONTROL UNIT CARTRIDGE SCREEN									
		MOS						25-JUL-2006		
		HRS/MSC	3500	+150				0	**(3500) 3581.3**	3650
	REF: EMM 75-30-02	ENC						0		
753030	NO. 1 ENGINE - P3 AIR BOV FAIRING ASSEMBLY									
	30C4403-01	MOS			TSN:0			25-JUL-2006		
	KYAA001A446	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		
ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047										
753000	NO. 2 ENGINE - LEFT COMPRESSOR BLEED VALVE ASSEMBLY									
	PN	MOS			TSN:0			18-JUL-2006		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		
753001	NO. 2 ENGINE - RIGHT COMPRESSOR BLEED VALVE ASSEMBLY									
	30C1364-02	MOS			TSN:0			18-JUL-2006		
	1010	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753002	NO. 2 ENGINE - BLEED AIR CONTROL SOLENOID VALVE									
	30C2009-03	MOS			TSN:0			18-JUL-2006		
	1555	HRS/MSC	O/C		TSN:0			0		
	REF: EMM 75-30-02	ENC			TSN:0			0		
753004	NO. 2 ENGINE - LINEAR ACTUATOR									
	30C1266-01	MOS			TSN:134 TSO:0			30-SEP-2017		
	417	HRS/MSC	O/C		TSO:0			2832.2		
	REF: GENERIC NO REF	ENC			TSO:0			2192		
753007 (s)	NO. 2 ENGINE - CHECK P1 AIR TUBES-DRAIN CONDESATION TRAP. CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION.							PKG		
	PKG 1	MOS						21-MAY-2015		
		HRS/MSC	800	+50				2395.7		
	REF: EMM 70-00-00	ENC						1800		
753010	NO. 2 ENGINE - REMOVE AND INSPECT P2.5 AND P2.8 BLEED VALVES FOR GENERAL CONDITION AND WEAR									
		MOS						18-JUL-2006		
		HRS/MSC	3500	+150				0	**(3500) 3581.3**	3650
	REF: EMM 75-30-01	ENC						0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753020	NO. 2 ENGINE - REMOVE AND INSPECT BLEED VALVE CONTROL UNIT CARTRIDGE SCREEN									
		MOS						18-JUL-2006		
		HRS/MSC	3500	+150				0	**(3500) 3581.3**	3650
	REF: EMM 75-30-02	ENC						0		
753030	NO. 2 ENGINE - P3 AIR BOV FAIRING ASSEMBLY									
	30C4403-01	MOS			TSN:0			18-JUL-2006		
	KYAA001A447	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		
CHAPTER 76	**ENGINE CONTROLS**									
76-10-01-900-801-01	THROTTLE CONTROL UNIT									
	222500-3M03	MOS						31-OCT-2017		
76.020	040	HRS/MSC	O/C					2933.3		
	REF: AMM 76-10-01-900-801	AFL						2258		
ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047										
76E001	NO. 1 ENGINE - DOWNLOAD ENGINE TREND MONITORING (ECTM)									
		MOS						24-JUN-2017		
		HRS/MSC	A/R					2832.2		
	REF: See Workcard	ENC						2192		
ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047										

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76E001	NO. 2 ENGINE - DOWNLOAD ENGINE TREND MONITORING (ECTM)								
		MOS					24-JUN-2017		
		HRS/MSC	A/R				2832.2		
	REF: See Workcard	ENC					2192		

CHAPTER 77 ENGINE INDICATING

77-30-01-900-801-01	ENGINE VIBRATION MONITORING (EVMC) COMPUTER								
	241-293-000-012	MOS		TSR:0			04-MAR-2015		
77.040	AD16343	HRS/MSC	O/C	TSN:1105 TSR:0			2332.8		
	REF: AMM 77-30-01-900-801	AFL		TSN:491 TSR:0			1730		

ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047

770A01	NO. 1 ENGINE - N1 ROTATIONAL SPEED SENSOR								
	30C5304-01	MOS		TSN:0			20-MAR-2008		
	CH1121	HRS/MSC	O/C	TSN:0			320.9		
	REF:	ENC		TSN:0			221		
772010	NO. 1 ENGINE - T4.8 THERMOCOUPLE WIRING HARNESS								
	30C3466-02	MOS		TSN:0			25-JUL-2006		
	EM88290	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
773001	NO. 1 ENGINE - VIBRATION SENSOR								
	30C2185-03	MOS		TSN:0			25-JUL-2006		
	AB56747	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 77-30-01	ENC		TSN:0			0		
773010 (s)	NO. 1 ENGINE - VISUAL CHECK P1/T1 SENSORS, N1 SPEED SENSOR, T4.8 PROBES FOR CONDITION OF ACCESSIBLE WIRING HARNESSES AND SECURITY OF CONNECTORS						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 77-20-01	ENC					1800		
ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047									
770A01	NO. 2 ENGINE - N1 ROTATIONAL SPEED SENSOR								
	30C55304-04	MOS		TSN:0			24-OCT-2011		
	CH1086	HRS/MSC	O/C	TSN:0			1377.4		
	REF:	ENC		TSN:0			951		
772010	NO. 2 ENGINE - T4.8 THERMOCOUPLE WIRING HARNESS								
	30C3466-02	MOS		TSN:0			18-JUL-2006		
	EM88026	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	ENC		TSN:0			0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
773001	NO. 2 ENGINE - VIBRATION SENSOR									
	30C2185-03	MOS			TSN:0			18-JUL-2006		
	AB61426	HRS/MSC	O/C		TSN:0			0		
	REF: EMM 77-30-01	ENC			TSN:0			0		
773010 (s)	NO. 2 ENGINE - VISUAL CHECK P1/T1 SENSORS, N1 SPEED SENSOR, T4.8 PROBES FOR CONDITION OF ACCESSIBLE WIRING HARNESSES AND SECURITY OF CONNECTORS							PKG		
	PKG 1	MOS						21-MAY-2015		
		HRS/MSC	800	+50				2395.7		
	REF: EMM 77-20-01	ENC						1800		
CHAPTER 78	**EXHAUST**									
78-30-00-210-801-03 (s)	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - ENGINE 1 THRUST REVERSER AND MECHANISMS							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				18-APR-2018		
78.010		HRS/MSC	400	+40				3041.8		
	REF: AMM 78-30-00-210-801	AFL						2328		
78-30-00-210-801-03A	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - ENGINE 1 THRUST REVERSER AND MECHANISMS (MANDATORY 5-40)									
		MOS						18-APR-2018		
78.190		HRS/MSC	1800					3041.8	**4841.8**	
	REF: AMM 78-30-00-210-801	AFL						2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-30-00-210-801-04 (s)	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - ENGINE 2 THRUST REVERSER AND MECHANISMS							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				18-APR-2018		
78.010		HRS/MSC	400	+40				3041.8		
	REF: AMM 78-30-00-210-801	AFL						2328		
78-30-00-210-801-04A	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER - ENGINE 2 THRUST REVERSER AND MECHANISMS (MANDATORY 5-40)									
		MOS						18-APR-2018		
78.190		HRS/MSC	1800					3041.8	**4841.8**	
	REF: AMM 78-30-00-210-801	AFL						2328		
78-30-00-720-801-01 (s)	FUNCTIONAL TEST OF THE THRUST REVERSER SYSTEM WITH ENGINE SHUT DOWN							PKG		
	PKG 21	MOS						17-APR-2018		
		HRS/MSC	1600	+40				3041.8		
	REF: AMM 78-30-00-720-801	AFL						2328		
78-30-01-100-801-01 (s)	CLEANING OF THE NO.1 ENGINE THRUST REVERSER ASSEMBLY							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				18-APR-2018		
78.090		HRS/MSC	400	+40				3041.8		
	REF: AMM 78-30-01-100-801	AFL						2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-30-01-100-801-02 (s)	CLEANING OF THE NO.2 ENGINE THRUST REVERSER ASSEMBLY							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				18-APR-2018		
78.100		HRS/MSC	400	+40				3041.8		
	REF: AMM 78-30-01-100-801	AFL						2328		
78-30-01-900-801-01	ENGINE NO.1 THRUST REVERSER									
	06ND78001-7	MOS			TSR:0			15-JUL-2013		
	AX78-1-042M	HRS/MSC	O/C		TSN:1872.8 TSR:0			1872.8		
	REF: AMM 78-30-01-900-801	AFL			TSN:1323 TSR:0			1323		
78-30-01-900-801-02	ENGINE NO.2 THRUST REVERSER									
	06ND78001-8M	MOS			TSR:0			17-MAY-2018		
	AX78-2-048M	HRS/MSC	O/C		TSR:0			3041.8		
	REF: AMM 78-30-01-900-801	AFL			TSR:0			2328		
78-31-00-640-801-01 (s)	GREASING LEFT THRUST REVERSER ASSEMBLY							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				23-APR-2018		
78.030		HRS/MSC	400	+40				3041.8		
	REF: AMM 78-31-00-640-801	AFL						2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-31-00-640-801-02 (s)	GREASING RIGHT THRUST REVERSER ASSEMBLY							PKG		
	PKG 1 ,2 ,31	MOS	8	+1m				23-APR-2018		
78.030		HRS/MSC	400	+40				3041.8		
	REF: AMM 78-31-00-640-801	AFL						2328		
78-31-01-900-802-01	NO. 1 ENGINE UPPER THRUST REVERSER DOOR									
	06ND78007-1	MOS			TSN:0			13-DEC-2006		
78.240	MOREG042	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 78-31-01-900-802	AFL			TSN:0			0		
78-31-01-900-802-02	NO. 2 ENGINE UPPER THRUST REVERSER DOOR									
	06ND78007-2	MOS			TSN:0			13-DEC-2006		
78.240	MOREG048	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 78-31-01-900-802	AFL			TSN:0			0		
78-31-01-900-803-01	NO. 1 ENGINE LOWER THRUST REVERSER DOOR									
	06ND78008-1	MOS			TSN:0			13-DEC-2006		
78.250	MOREG042	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 78-31-01-900-803	AFL			TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-31-01-900-803-02	NO. 2 ENGINE LOWER THRUST REVERSER DOOR								
	06ND78008-2	MOS		TSN:37 TSR:0			04-JAN-2010		
78.250	MOREG048	HRS/MSC	O/C	TSN:802.8 TSR:0			802.8		
	REF: AMM 78-31-01-900-803	AFL		TSN:584 TSR:0			584		
78-31-03-220-801-01 (s)	DETAILED INSPECTION OF NO. 1 ENGINE THRUST REVERSER PIVOT LINK ASSEMBLIES						PKG		
	PKG 24	MOS					13-DEC-2006		
78.040		HRS/MSC	6400	+40			0		
	REF: AMM 78-31-03-220-801	AFL					0		
78-31-03-220-801-01A	DETAILED INSPECTION OF NO. 1 ENGINE THRUST REVERSER PIVOT LINK ASSEMBLIES (MANDATORY 5-40)								
		MOS					13-DEC-2006		
78.040		HRS/MSC	7500				0	**7500**	
CMR	**REF:** AMM 78-31-03-220-801	AFL					0		
78-31-03-220-801-02 (s)	DETAILED INSPECTION OF NO. 2 ENGINE THRUST REVERSER PIVOT LINK ASSEMBLIES						PKG		
	PKG 24	MOS					13-DEC-2006		
78.040		HRS/MSC	6400	+40			0		
	REF: AMM 78-31-03-220-801	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-31-03-220-801-02A	DETAILED INSPECTION OF NO. 2 ENGINE THRUST REVERSER PIVOT LINK ASSEMBLIES (MANDATORY 5-40)								
		MOS					13-DEC-2006		
78.040		HRS/MSC	7500				0	**7500**	
CMR	**REF:** AMM 78-31-03-220-801	AFL					0		
78-31-09-100-801-01 (s)	CLEANING OF THE NO.1 ENGINE THRUST REVERSER UPPER DOOR SEAL						PKG		
	PKG 2 ,31	MOS	16	+1m			20-APR-2018		
		HRS/MSC	800	+40			3041.8		
	REF: AMM 78-31-09-100-801	AFL					2328		
78-31-09-100-801-02 (s)	CLEANING OF THE NO.1 ENGINE THRUST REVERSER LOWER DOOR SEAL						PKG		
	PKG 2 ,31	MOS	16	+1m			20-APR-2018		
		HRS/MSC	800	+40			3041.8		
	REF: AMM 78-31-09-100-801	AFL					2328		
78-31-09-100-801-03 (s)	CLEANING OF THE NO.2 ENGINE THRUST REVERSER UPPER DOOR SEAL						PKG		
	PKG 2 ,31	MOS	16	+1m			20-APR-2018		
		HRS/MSC	800	+40			3041.8		
	REF: AMM 78-31-09-100-801	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-31-09-100-801-04 (s)	CLEANING OF THE NO.2 ENGINE THRUST REVERSER LOWER DOOR SEAL							PKG		
	PKG 2 ,31	MOS	16	+1m				20-APR-2018		
		HRS/MSC	800	+40				3041.8		
	REF: AMM 78-31-09-100-801	AFL						2328		
78-31-13-900-801-01	NO. 1 ENGINE OUTBOARD THRUST REVERSER DOOR ACTUATOR									
	06ND78100-5	MOS			TSN:0			13-DEC-2006		
78.120	MOREG042	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 78-31-13-900-801	AFL			TSN:0			0		
78-31-13-900-801-02	NO. 1 ENGINE INBOARD THRUST REVERSER DOOR ACTUATOR									
	06ND78100-9	MOS			TSN:0			13-DEC-2006		
78.110	MOREG042	HRS/MSC	O/C		TSN:0			0		
	REF: AMM 78-31-13-900-801	AFL			TSN:0			0		
78-31-13-900-801-03	NO. 2 ENGINE INBOARD THRUST REVERSER DOOR ACTUATOR									
	06ND78100-10	MOS			TSN:79 TSO:0			15-JUL-2013		
78.110	MOREG048	HRS/MSC	O/C		TSN:1872.8 TSO:0			1872.8		
	REF: AMM 78-31-13-900-801	AFL			TSN:1323 TSO:0			1323		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-31-13-900-801-04	NO. 2 ENGINE OUTBOARD THRUST REVERSER DOOR ACTUATOR								
	06ND78100-6	MOS		TSN:79 TSO:0			15-JUL-2013		
78.120	MOREG048	HRS/MSC	O/C	TSN:1872.8 TSO:0			1872.8		
	REF: AMM 78-31-13-900-801	AFL		TSN:1323 TSO:0			1323		
78-32-00-100-801-01 (s)	CLEANING OF THE LH THRUST REVERSER SWITCH ASSEMBLY						PKG		
	PKG 2 ,31	MOS	16	+1m			14-MAY-2018		
78.090		HRS/MSC	800	+40			3041.8		
	REF: AMM 78-32-00-100-801	AFL					2328		
78-32-00-100-801-02 (s)	CLEANING OF THE RH THRUST REVERSER SWITCH ASSEMBLY						PKG		
	PKG 2 ,31	MOS	16	+1m			14-MAY-2018		
78.100		HRS/MSC	800	+40			3041.8		
	REF: AMM 78-32-00-100-801	AFL					2328		
78-32-00-760-802-01 (s)	TEST OF THE LH TRCU CONTROL INPUT CIRCUITS						PKG		
	PKG 21	MOS					20-APR-2018		
		HRS/MSC	1600	+40			3041.8		
	REF: AMM 78-32-00-760-802	AFL					2328		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-32-00-760-802-01A	TEST OF THE LH TRCU CONTROL INPUT CIRCUITS (MANDATORY 5-40)								
		MOS					20-APR-2018		
		HRS/MSC	1800				3041.8	**4841.8**	
CMR	**REF:** AMM 78-32-00-760-802	AFL					2328		
78-32-00-760-802-02 (s)	TEST OF THE RH TRCU CONTROL INPUT CIRCUITS						PKG		
	PKG 21	MOS					20-APR-2018		
		HRS/MSC	1600 +40				3041.8		
	REF: AMM 78-32-00-760-802	AFL					2328		
78-32-00-760-802-02A	TEST OF THE RH TRCU CONTROL INPUT CIRCUITS (MANDATORY 5-40)								
		MOS					20-APR-2018		
		HRS/MSC	1800				3041.8	**4841.8**	
CMR	**REF:** AMM 78-32-00-760-802	AFL					2328		
78-32-01-900-801-01	LH THRUST REVERSER ELECTRICAL HARNESS								
	06ND78302-5	MOS		TSR:0			30-JUN-2015		
78.280	962938RX	HRS/MSC	O/C	TSN:255 TSR:0			2409.6		
	REF: AMM 78-32-01-900-801	AFL		TSN:115 TSR:0			1816		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-32-01-900-801-02	RH THRUST REVERSER ELECTRICAL HARNESS								
	06ND78302-6	MOS		TSR:0			13-JAN-2012		
78.280	AX0040-740	HRS/MSC	O/C	TSR:0			1422.9		
	REF: AMM 78-32-01-900-801	AFL		TSR:0			984		
78-32-09-780-801-01 (s)	CHECK OF THE LH THRUST REVERSER HYDRAULIC ACCUMULATOR CAPACITY						PKG		
	PKG 2 ,31	MOS	16	+1m			17-APR-2018		
		HRS/MSC	800	+40			3041.8		
	REF: AMM 78-32-09-780-801	AFL					2328		
78-32-09-780-801-02 (s)	CHECK OF THE RH THRUST REVERSER HYDRAULIC ACCUMULATOR CAPACITY						PKG		
	PKG 2 ,31	MOS	16	+1m			17-APR-2018		
78.150		HRS/MSC	800	+40			3041.8		
	REF: AMM 78-32-09-780-801	AFL					2328		
78-32-09-900-801-01	LH THRUST REVERSER HYDRAULIC ACCUMULATOR								
	06ND78212-1	MOS		TSN:0			13-DEC-2006		
78.150	229	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 78-32-09-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-32-09-900-801-02	RH THRUST REVERSER HYDRAULIC ACCUMULATOR								
	06ND78212-1	MOS		TSN:0			13-DEC-2006		
78.150	247	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 78-32-09-900-801	AFL		TSN:0			0		
78-32-25-900-801-01	LH INBOARD THRUST REVERSER PIN LOCK ACTUATOR								
	06ND78206-5	MOS		TSN:0			13-DEC-2006		
78.260	0495	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 78-32-25-900-801	AFL		TSN:0			0		
78-32-25-900-801-02	RH INBOARD THRUST REVERSER PIN LOCK ACTUATOR								
	06ND78206-5	MOS		TSN:0			13-DEC-2006		
78.260	0463	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 78-32-25-900-801	AFL		TSN:0			0		
78-32-25-900-801-03	LH OUTBOARD THRUST REVERSER PIN LOCK ACTUATOR								
	06ND78206-5	MOS		TSN:0			13-DEC-2006		
78.270	0498	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 78-32-25-900-801	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-32-25-900-801-04	RH OUTBOARD THRUST REVERSER PIN LOCK ACTUATOR								
	06ND78206-5	MOS		TSN:0			13-DEC-2006		
78.270	0470	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 78-32-25-900-801	AFL		TSN:0			0		
78-32-45-700-801-01 (s)	TEST OF THE LH THRUST REVERSER CONTROL UNIT						PKG		
	PKG 24	MOS					13-DEC-2006		
78.050		HRS/MSC	6400	+40			0		
	REF: AMM 78-32-45-700-801	AFL					0		
78-32-45-700-801-01A	TEST OF THE LH THRUST REVERSER CONTROL UNIT (MANDATORY 5-40)								
		MOS					13-DEC-2006		
78.050		HRS/MSC	7500				0	**7500**	
CMR	**REF:** AMM 78-32-45-700-801	AFL					0		
78-32-45-700-801-02 (s)	TEST OF THE RH THRUST REVERSER CONTROL UNIT						PKG		
	PKG 24	MOS					13-DEC-2006		
78.050		HRS/MSC	6400	+40			0		
	REF: AMM 78-32-45-700-801	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-32-45-700-801-02A	TEST OF THE RH THRUST REVERSER CONTROL UNIT (MANDATORY 5-40)								
		MOS					13-DEC-2006		
78.050		HRS/MSC	7500				0	**7500**	
CMR	**REF:** AMM 78-32-45-700-801	AFL					0		
78-32-45-900-801-01	LH THRUST REVERSER CONTROL UNIT								
	06ND78305-5	MOS		TSN:100			18-APR-2015		
78.220	03060273	HRS/MSC	O/C	TSN:2377.1			2377.1		
	REF: AMM 78-32-45-900-801	AFL		TSN:1771			1771		
78-32-45-900-801-02	RH THRUST REVERSER CONTROL UNIT								
	06ND78307-1	DAYS		TSN:0					
78.220	3739020	HRS/MSC	O/C	TSN:0			3041.8		
	REF: AMM 78-32-45-900-801	AFL		TSN:0			2328		
783831	LH THRUST REVERSER ISOLATION VALVE								
	06ND78207-5	MOS		TSN:0			13-DEC-2006		
78.200	139	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 78-32-13-900-802	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783832	RH THRUST REVERSER ISOLATION VALVE								
	06ND78207-5	MOS		TSN:0			13-DEC-2006		
78.200	140	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 78-32-13-900-802	AFL		TSN:0			0		
783841	LH THRUST REVERSER CONTROL VALVE								
	06ND78209-5	MOS		TSN:0			13-DEC-2006		
78.210	228	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 78-32-17-900-802	AFL		TSN:0			0		
783842	RH THRUST REVERSER CONTROL VALVE								
	06ND78209-5	MOS		TSN:0			13-DEC-2006		
78.210	231	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 78-32-17-900-802	AFL		TSN:0			0		
783861	LH THRUST REVERSER CHECK VALVE								
	01ND78210-1	MOS		TSN:0			13-DEC-2006		
78.230	302	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783862	RH THRUST REVERSER CHECK VALVE								
	01ND78210-1	MOS		TSN:0			13-DEC-2006		
78.230	304	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
783871	LH THRUST REVERSER NOZZLE ASSEMBLY								
	06ND78400-5	MOS		TSN:0			13-DEC-2006		
78.130	MOREG042	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
783876	RH THRUST REVERSER NOZZLE ASSEMBLY								
	06ND78400-6	MOS		TSN:0			13-DEC-2006		
78.130	MOREG048	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 79	**OIL**								
79-30-01-820-801-01	ACCOMPLISH NO. 1 ENGINE CALIBRATION OF THE ENGINE OIL LEVEL GAUGES								
		MOS					13-DEC-2006		
79.080		HRS/MSC	A/R				0		
	REF: AMM 79-30-01-820-801	AFL					0		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-30-01-820-801-02	ACCOMPLISH NO. 2 ENGINE CALIBRATION OF THE ENGINE OIL LEVEL GAUGES								
		MOS					13-DEC-2006		
79.090		HRS/MSC	A/R				0		
	REF: AMM 79-30-01-820-801	AFL					0		

ENGINE NO. 1 Model : PW308C Serial # PCE-CF0251 Part # 30C3205-02 BS 1047

792000	NO. 1 ENGINE - OIL FILTER ASSEMBLY								
	30C5455-01	MOS		TSN:0			22-SEP-2017		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			2832.2		
	REF: GENERIC NO REF	ENC		TSN:0			2192		
792005 (s)	NO. 1 ENGINE - REMOVE/INSPECT/CHECK OIL FILTER ASSEMBLY ELEMENT FOR FOREIGN MATTER AND DAMAGE						PKG		
	30C5455-01 PKG 1	MOS					22-SEP-2017		
	SN-UNKNOWN	HRS/MSC	800	+50			2832.2		
	REF: See Workcard	ENC					2192		
792010	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT								
	30C5455-01	MOS					22-SEP-2017		
	SN-UNKNOWN	HRS/MSC	800				2832.2	**(3632.2) 3713.5**	
	REF: EMM 79-20-01	ENC					2192		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792015 (s)	NO. 1 ENGINE - CHECK OIL QUANTITY POST FLIGHT: CHECK OIL LEVEL AND REPLENISH IF REQUIRED (REF. 72-00-00, SERVICING). CHECK CONDITION AND SECURITY OF OIL FILLER CAP							PKG		
	PKG 1	MOS						25-MAY-2018		
		HRS/MSC	800	+50				2947.9		
	REF: EMM 72-00-00	ENC						2266		
792020	NO. 1 ENGINE - VISUAL CHECK NO. 3 BEARING SCAVENGE OIL TUBE FOR LEAKAGE									
		MOS						25-JUL-2006		
		HRS/MSC	3500	+150				0	**(3500) 3581.3**	3650
	REF: EMM 79-20-03	ENC						0		
792025	NO. 1 ENGINE - VISUALLY CHECK NO.4 BEARING PRESSURE OIL TUBE FOR LEAKAGE									
		MOS						25-JUL-2006		
		HRS/MSC	N/R					0		
	REF: EMM 72-50-03	ENC						0		
792030	NO. 1 ENGINE - CHANGE OIL									
		MOS	18	+30d				21-MAY-2018	**21-NOV-2019**	21-DEC-2019
		HRS/MSC	800	+50/-50				2960.5	**(3760.5) 3841.8**	3810.5
	REF: EMM 72-00-00	ENC								

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#1: S/N PCE-CF0251
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792035	NO. 1 ENGINE - GEAR SHAFT SPUR GEAR								
	30C3670-01	MOS		TSN:0			25-JUL-2006		
	PKAAA029713	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
792050	NO. 1 ENGINE - PERFORM OIL ANALYSIS (TAN AND WATER CONTENT)								
		MOS					25-JUL-2006		
		HRS/MSC	O/C				0		
	REF: EMM 72-00-00	ENC					0		
793005	NO. 1 ENGINE - OIL FILLER CAP								
	30C1509-01	MOS		TSN:0			25-JUL-2006		
	HA1619	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 79-30-05	ENC		TSN:0			0		
793010	NO. 1 ENGINE - OIL LEVEL (ELECTRICAL) INDICATOR								
	30C3469-02	MOS					22-SEP-2017		
	AKA0081R	HRS/MSC	O/C				2832.2		
	REF: EMM 79-30-07	ENC					2192		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#1: S/N PCE-CF0251
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793020 (s)	NO. 1 ENGINE - INSPECT/FUNCTIONAL CHECK CHIP DETECTOR CHIP DETECTOR							PKG		
	PKG 1	MOS						21-MAY-2015		
		HRS/MSC	800	+50				2395.7		
	REF: EMM 79-30-01	ENC						1800		
793A05	NO. 1 ENGINE - MAGNETIC CHIP DETECTOR									
	30C4931-01	MOS			TSN:0			22-MAY-2018		
	AB2042	HRS/MSC	A/R		TSN:0			2960.5		
	REF:	ENC			TSN:0			2238		
793A08	NO. 1 ENGINE - IMPENDING BY PASS OIL FILTER SWITCH									
	30C1781-02	MOS			TSN:0			25-AUG-2009		
	HE2058	HRS/MSC	A/R		TSN:0			715.2		
CUSTOMER CODE	**REF:**	ENC			TSN:0			522		
79NP01	NO. 1 ENGINE - INSPECT OIL FILTER (P&W REQUEST)									
		MOS						18-MAY-2009		
		HRS/MSC	-					638.1		
CUSTOMER CODE	**REF:**	ENC						468		

ENGINE NO. 2 Model : PW308C Serial # PCE-CF0250 Part # 30C3205-02 BS 1047

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792000	NO. 2 ENGINE - OIL FILTER ASSEMBLY								
	PN-UNKNOWN	MOS		TSN:0			30-SEP-2017		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			2832.2		
	REF: GENERIC NO REF	ENC		TSN:0			2192		
792005 (s)	NO. 2 ENGINE - REMOVE/INSPECT/CHECK OIL FILTER ASSEMBLY ELEMENT FOR FOREIGN MATTER AND DAMAGE						PKG		
	PN-UNKNOWN PKG 1	MOS					30-SEP-2017		
	SN-UNKNOWN	HRS/MSC	800	+50			2832.2		
	REF: See Workcard	ENC					2192		
792010	NO. 2 ENGINE - REPLACE OIL FILTER ELEMENT								
	PN-UNKNOWN	MOS					30-SEP-2017		
	SN-UNKNOWN	HRS/MSC	800				2832.2	**(3632.2) 3713.5**	
	REF: EMM 79-20-01	ENC					2192		
792015 (s)	NO. 2 ENGINE - CHECK OIL QUANTITY POST FLIGHT: CHECK OIL LEVEL AND REPLENISH IF REQUIRED (REF. 72-00-00, SERVICING). CHECK CONDITION AND SECURITY OF OIL FILLER CAP						PKG		
	PKG 1	MOS					25-MAY-2018		
		HRS/MSC	800	+50			2947.9		
	REF: EMM 72-00-00	ENC					2266		

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792020	NO. 2 ENGINE - VISUAL CHECK NO. 3 BEARING SCAVENGE OIL TUBE FOR LEAKAGE									
		MOS						18-JUL-2006		
		HRS/MSC	3500	+150				0	**(3500) 3581.3**	3650
	REF: EMM 79-20-03	ENC						0		
792025	NO. 2 ENGINE - VISUALLY CHECK NO.4 BEARING PRESSURE OIL TUBE FOR LEAKAGE									
		MOS						18-JUL-2006		
		HRS/MSC	N/R					0		
	REF: EMM 72-50-03	ENC						0		
792030	NO. 2 ENGINE - CHANGE OIL									
		MOS	18	+30d				25-MAY-2018	**25-NOV-2019**	25-DEC-2019
		HRS/MSC	800	+50/-50				2947.9	**(3747.9) 3829.2**	3797.9
	REF: EMM 72-00-00	ENC						2266		
792035	NO. 2 ENGINE - GEAR SHAFT SPUR GEAR									
	30C3670-01	MOS			TSN:0			18-JUL-2006		
	PKAAA029707	HRS/MSC	O/C		TSN:0			0		
	REF: GENERIC NO REF	ENC			TSN:0			0		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

ENGINE#2: S/N PCE-CF0250
2960.5 HRS, 2266 ENC

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792050	NO. 2 ENGINE - PERFORM OIL ANALYSIS (TAN AND WATER CONTENT)								
		MOS					18-JUL-2006		
		HRS/MSC	O/C				0		
	REF: EMM 72-00-00	ENC					0		
793005	NO. 2 ENGINE - OIL FILLER CAP								
	30C1509-01	MOS		TSN:0			18-JUL-2006		
	HA1599	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 79-30-05	ENC		TSN:0			0		
793010	NO. 2 ENGINE - OIL LEVEL (ELECTRICAL) INDICATOR								
	30C3469-02	MOS					30-SEP-2017		
	AKA0082R	HRS/MSC	O/C				2832.2		
	REF: EMM 79-30-07	ENC					2192		
793020 (s)	NO. 2 ENGINE - INSPECT/FUNCTIONAL CHECK CHIP DETECTOR CHIP DETECTOR						PKG		
	PKG 1	MOS					21-MAY-2015		
		HRS/MSC	800	+50			2395.7		
	REF: EMM 79-30-01	ENC					1800		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793A05	NO. 2 ENGINE - MAGNETIC CHIP DETECTOR								
	30C4931-01	MOS		TSN:0			18-MAY-2018		
	N/A	HRS/MSC	A/R	TSN:0			2947.8		
	REF:	ENC		TSN:0			2266		
CHAPTER 80	**STARTING**								
80-10-01-900-801-01	MODE START SELECTOR								
	PN	MOS		TSN:0			13-DEC-2006		
76.040	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
80-10-05-610-801-01 (s)	SERVICING OF THE LH ENGINE PNEUMATIC STARTER OIL						PKG		
	PKG 2 ,31,39	MOS	16	+1m			18-APR-2018		
80.010		HRS/MSC	800	+40			3041.8		
	REF: AMM 80-10-05-610-801	AFL					2328		
80-10-05-610-801-02 (s)	SERVICING OF THE RH ENGINE PNEUMATIC STARTER OIL						PKG		
	PKG 2 ,31,39	MOS	16	+1m			18-APR-2018		
80.010		HRS/MSC	800	+40			3041.8		
	REF: AMM 80-10-05-610-801	AFL					2328		

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
80-10-05-900-801-01	LH ENGINE PNEUMATIC STARTER								
	821600-6	MOS		TSN:0			13-DEC-2006		
80.010	200606039L4	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 80-10-05-900-801	AFL		TSN:0			0		
80-10-05-900-801-02	RH ENGINE PNEUMATIC STARTER								
	821600-6	MOS		TSN:0			13-DEC-2006		
80.010	200606042L4	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 80-10-05-900-801	AFL		TSN:0			0		
80-10-13-900-801-01	LH STARTER CONTROL VALVE								
	1006409-3	MOS		TSR:0			03-NOV-2010		
80.020	0128	HRS/MSC	O/C	TSR:0			1087.9		
	REF: AMM 80-10-13-900-801	AFL		TSR:0			774		
80-10-13-900-801-02	RH STARTER CONTROL VALVE								
	1006409-3	MOS		TSR:0			03-NOV-2010		
80.020	0322D	HRS/MSC	O/C	TSR:0			1087.9		
	REF: AMM 80-10-13-900-801	AFL		TSR:0			774		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS

Status Report

FALCON 2000EX EASY S/N 112 (N619SM): 3041.8 HRS, 2328 AFL as of 25-May-2018

Owner: DEUX AVIAN PARTNERS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 02-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
80-10-13-960-801-01	DISCARD LH STARTER CONTROL VALVE								
	1006409-3	MOS					03-NOV-2010		
80.020	0128	HRS/MSC	O/C				1087.9		
	REF: AMM 80-10-13-960-801	AFL					774		
80-10-13-960-801-02	DISCARD RH STARTER CONTROL VALVE								
	1006409-3	MOS					03-NOV-2010		
80.020	0322D	HRS/MSC	O/C				1087.9		
	REF: AMM 80-10-13-960-801	AFL					774		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

© CAMP SYSTEMS